

Installation and Setup

Driver Installation/Removal Procedure For Realtek High Definition Audio Codec:

=

<<< For Windows 2000, XP, Vista, Windows7, Windows 8, Windows 8.1, Windows 10
x86/x64 Driver >>>

Setup Driver at first time:

Windows 2000 , XP :

Step 1. Before installing the Realtek High Definition Audio Driver, Press the
[Cancel] button if Windows detect the Multimedia Audio device.

Step 2. Run the setup.exe program to start the installation.

Step 3. Click on [Next] to continue the procedure. If the screen resolution is
lower
than 1024*768,press [Yes] to continue the installation. If the Windows
popup
"Digital Signature Not Found" message, press [Yes] to continue the
installation.

Step 4. Finally, select to restart the system and press [Finish] to complete
the installation.

Windows Vista, Windows7, Windows 8, Windows 8.1, Windows 10 :

Step 1. Run the setup.exe program to start the installation.

Step 2. Click on [Next] to continue the procedure. If the screen resolution is
lower
than 1024*768,press [Yes] to continue the installation. If the Windows
popup
"Windows can't verify the publisher of this driver software" message,
press "Install this driver software anyway" to continue the
installation.

Step 3. Finally, select to restart the system and press [Finish] to complete
the installation.

Manual driver install by INF :

Step 1. Go to "Control Panel" and select "Hardware and Sound".

Step 2. Select "Device Manager" on Devices and Printers

Step 3. Right click on the "High Definition Audio Device" of Device Manager and
select "Update Driver Software" on pop up menu.

Step 4. Select "Browse my computer for driver software" option.

Step 5. Browse Realtek Audio driver location and press "Next" button.

Step 6. Installing Realtek Audio driver.

Step 7. Windows has finished installing the Realtek audio driver.

Readme.txt

Update Driver:

Windows 2000 , XP :

Step 1. Follow Step 2,3,4 described in [Setup at first time] above to complete the procedure.

Windows Vista, Windows7, Windows 8, Windows 8.1, Windows 10 :

Step 1. Run setup.exe, it will remove the original driver in your system.

Step 2. Click "Next" to remove the original audio driver in your system.

Step 3. Once after the original driver removed , reboot the computer.

Step 4. It will install audio driver automatically after computer restarted.

Remove Driver:

Windows 2000 , XP :

Step 1. Go to Start\Settings\Control Panel.

Step 2. Select [Add or Remove Programs] icon.

Step 3. Select "Realtek High Definition Audio Driver" and press [Remove] button.

Step 4. Click on [Yes] to finish the uninstallation.

Step 5. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

Windows Vista, Windows7 :

Step 1. Go to Start\Control Panel.

Step 2. Select [Programs] icon.

Step 3. Select [Programs and Features] icon.

Step 4. Select "Realtek High Definition Audio Driver" and press [uninstall] button.

Step 5. Click on [Yes] to finish the uninstallation.

Step 6. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

Windows 8, Windows 8.1, Windows 10 :

Step 1. Go to Apps.

Step 2. Select "Control Panel" in "Windows System"

Step 3. Select [Programs and Features] icon.

Step 4. Select "Realtek High Definition Audio Driver" and press [uninstall]

Readme.txt

button.

Step 5. Click on [Yes] to finish the uninstallation.

Step 6. At the end of the procedure, select to restart the system and press [Finish] to complete the uninstallation.

Driver uninstall in Device Manager :

Step 1. Go to "Control Panel" and select "Hardware and Sound".

Step 2. Select "Device Manager" on Devices and Printers

Step 3. Right click on the "Realtek High Definition Audio" of Device Manager and select "Uninstall" on pop up menu.

Step 4. Select the option "Delete the driver software for this device" and press "OK" button on dialog "Confirm Device Uninstall".

Step 5. Reboot system.

<< Other Information >>

Silent Installation:

Run "Setup.exe /s /f2<path\LogFile> /z[-rp<path\LogFile>]"
e.g. setup.exe /s /f2c:\mylog.log /z[-rpC:\RHDSetup.log]

Silent Uninstallation:

Run "Setup.exe /removeonly /s /f1<path\USetup.iss> /f2<path\LogFile>
/z[-rp<path\LogFile>]"
e.g. setup.exe /removeonly /s /f1C:\AudioDriver\USetup.iss /f2c:\mylog.log
/z[-rpC:\RHDSetup.log]

Note: 1. Please update Directx version to DirectX8.1 or above.

Version Informations:

If driver package include below drivers :

Vista, Win7, Win8, Win8.1, Win10 :

Vista, Win7, Win8, Win8.1, Win10 driver for x86

RTKVHDA.sys	: 6.0.1.8036
AERTSrv.exe	: 1.0.32.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent.exe	: 1.1.0.0
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.11
MaxxAudioMeters.exe	: 4.1.8.0
RtHDVBg.exe	: 1.0.0.258

Readme.txt

RtHDVCpl.exe : 1.0.0.1056
 RtkAudioService.exe : 1.0.0.81
 RtkNGUI.exe : 1.0.608.1
 Rt1Upd.exe : 3.0.0.6
 vncutil.exe : 1.0.0.45
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.56
 AERTACap.d11 : 2.12.32.0
 AERTARen.d11 : 1.0.32.11
 AudioLibW10.d11 : 1.0.2.0
 BlackBlueSkinImages.d11 : 1.0.608.1
 BlackSkinImages.d11 : 1.0.608.1
 Caf32api.d11 : 1.0.0.4
 Caf32APO2.d11 : 2.34.0.0
 CONEQMSAPO.d11 : 1.0.0.19
 CONEQMSAPOGUILibrary.d11 : 1.0.0.4
 CX32APO.d11 : 1.68.0.0
 CX32Proxy.d11 : 1.2.0.0
 DarkSkinImages.d11 : 1.0.608.1
 DAX3APOProp.d11 : 1.0.0.5
 DAX3APOv251.d11 : 1.0.0.5
 DDP32.d11 : 7.6.5.1
 DDPD32A.d11 : 7.6.5.1
 DDPO32A.d11 : 7.6.5.1
 DDPP32A.d11 : 7.6.5.1
 Do1byDAX2APOProp.d11 : 0.7.5.31
 Do1byDAX2APOv201.d11 : 0.7.5.31
 Do1byDAX2APOv211.d11 : 0.7.5.31
 Do1byDAX2APOv11dp.d11 : 1.0.0.5
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.1.1.0
 DTSU2PLFX32.d11 : 2.1.1.0
 DTSU2PREC32.d11 : 2.1.1.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 70.5.5.69
 FMAPP.d11 : 1.32.0.1
 GrayJadeSkinImages.d11 : 1.0.608.1
 HarmanAudioInterface.d11 : 1.2.0.0
 HiFiDAX2API.d11 : 0.7.5.65
 HiFiDAX2APIPCLL.d11 : 1.0.0.5
 HMAPO.d11 : 6.3.9600.17246
 HMC1ariFi.d11 : 1.4.0.0
 HMEQ.d11 : 1.4.0.0
 HMEQ_Voice.d11 : 1.4.0.0
 HMHVS.d11 : 1.4.0.0
 HMLimiter.d11 : 1.4.0.0

Readme.txt

HMUI.d11 : 1.4.0.0
 ICEsoundAPO.d11 : 1.0.0.26
 KAAPORT.d11 : 4.1105.6000.53
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO40.d11 : 4.5.8.0
 MaxxAudioAPO50.d11 : 5.6.5.0
 MaxxAudioAPO60.d11 : 6.1.17.0
 MaxxAudioAPO70.d11 : 7.0.24.0
 MaxxAudioAPOShell.d11 : 4.10.8.0
 MaxxAudioCapture.d11 : 4.1.29.0
 MaxxAudioEQ.d11 : 4.1.1.0
 MaxxAudioRealtek.d11 : 4.4.10.0
 MaxxAudioRender.d11 : 7.1.60.0
 MaxxAudioRenderAVX.d11 : 7.1.60.0
 MaxxAudioVienna2.d11 : 1.0.7.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxVoiceAPO20.d11 : 2.6.2.0
 MaxxVoiceAPO30.d11 : 3.1.14.0
 MaxxVoiceAPO40.d11 : 4.0.19.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.131
 MBAPO32.d11 : 1.0.62.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBWrp32.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAPO1fx.d11 : 6.3.9600.17246
 NahimicAPONSControl.d11 : 1.0.0.14866
 NAHIMICV2apo.d11 : 6.3.9600.17246
 NAHIMICV3apo.d11 : 6.3.9600.17246
 OrangeBlackSkinImages.d11 : 1.0.608.1
 PremiumBlack2SkinImages.d11 : 1.0.608.1
 PremiumBlackSkinImages.d11 : 1.0.608.1
 R4EEA32A.d11 : 7.2.8000.17
 R4EED32A.d11 : 7.2.8000.17
 R4EEG32A.d11 : 7.2.8000.17
 R4EEL32A.d11 : 7.2.8000.17
 R4EEP32A.d11 : 7.2.8000.17
 R1tkAPO.d11 : 11.0.6000.544
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.182
 RtDataProc.d11 : 1.0.0.16
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkApoApi.d11 : 1.0.1.90
 RtkCfg.d11 : 1.0.0.7
 RtkCoInstII.d11 : 2.3.4.2
 RtkCoLDR.d11 : 1.0.0.1
 RtkPgExt.d11 : 6.0.6000.346
 RtkXInterface.d11 : 1.0.0.13

Readme.txt

Rt1CPAPI.d11	: 1.0.2.6
SEAPO32.d11	: 2.0.7.30
SECOMN32.d11	: 2.0.7.30
SEHDHF32.d11	: 2.0.7.30
SEHDRA32.d11	: 2.0.7.30
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAP0.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.5.14.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.5.14.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.5.14.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRAPO.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRRPTR.d11	: 4.0.0.59
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.2.0
tbb_waves.d11	: 4.4.2015.728
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tosasfapo32.d11	: 2.1.0.0
toseaeapo32.d11	: 2.1.0.0
tossaeapo32.d11	: 2.1.1.0
tossaemaxapo32.d11	: 1.1.1.1
WavesGUILib.d11	: 4.4.5.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.608.1
RCORES.dat	: 1.5.6.9
Vista, Win7, Win8, Win8.1, Win10 driver for x64	
RTKVHD64.sys	: 6.0.1.8036
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1

Readme.txt

CXAPOAgent64.exe	: 1.1.0.0
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.1.0
FMAPP.exe	: 1.64.0.11
ICEsoundService.exe	: 1.0.0.26
MaxxAudioMeters64.exe	: 4.1.8.0
RAVBg64.exe	: 1.0.0.258
RAVCp164.exe	: 1.0.0.1056
RtkAudioService64.exe	: 1.0.0.81
RtkNGUI64.exe	: 1.0.608.1
RtlUpd64.exe	: 3.0.0.6
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.56
AERTAC64.d11	: 2.12.64.0
AERTAR64.d11	: 1.0.64.11
AudioLibW1064.d11	: 1.0.2.0
AudysseyEfx.d11	: 1.0.0.30
BlackBlueSkinImages64.d11	: 1.0.608.1
BlackJadeSkinImages64.d11	: 1.0.461.0
BlackSkinImages64.d11	: 1.0.608.1
Caf64api.d11	: 1.0.0.4
CAF64APO2.d11	: 2.34.0.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
CX32APO.d11	: 1.68.0.0
CX64APO.d11	: 1.68.0.0
CX64Proxy.d11	: 1.2.0.0
DarkSkinImages64.d11	: 1.0.608.1
DAX3APOProp.d11	: 1.0.0.5
DAX3APOv251.d11	: 1.0.0.5
DDPA64.d11	: 7.6.5.1
DDPA64F3.d11	: 7.6.7.2
DDPD64A.d11	: 7.6.5.1
DDPD64AF3.d11	: 7.6.7.2
DDPO64A.d11	: 7.6.5.1
DDPO64AF3.d11	: 7.6.7.2
DDPP64A.d11	: 7.6.5.1
DDPP64AF3.d11	: 7.6.7.2
Do1byDAX2APOProp.d11	: 0.7.5.31
Do1byDAX2APOv201.d11	: 0.7.5.31
Do1byDAX2APOv211.d11	: 0.7.5.31
Do1byDAX2APOv11dp.d11	: 1.0.0.5
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.1.1.0

Readme.txt

DTSU2PLFX64.d11 : 2.1.1.0
 DTSU2PREC64.d11 : 2.1.1.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO32.d11 : 50.5.4.68
 FMAPO64.d11 : 70.6.5.69
 FMAPP.d11 : 1.64.0.1
 GrayJadeSkinImages64.d11 : 1.0.608.1
 HarmanAudioInterface.d11 : 1.2.0.0
 HiFiDAX2API.d11 : 0.7.5.65
 HiFiDAX2APIPCLL.d11 : 1.0.0.5
 HMAPO.d11 : 6.3.9600.17336
 HMCleriFi.d11 : 1.4.0.0
 HMEQ.d11 : 1.4.0.0
 HMEQ_Voice.d11 : 1.4.0.0
 HMHVS.d11 : 1.4.0.0
 HMLimiter.d11 : 1.4.0.0
 HMUI.d11 : 1.4.0.0
 ICESoundAPO64.d11 : 1.0.0.26
 IntelSSTAPO.d11 : 1.1.37.0
 IntelSstCApoPropPage.d11 : 1.1.37.0
 KAAPORT64.d11 : 4.1105.6000.53
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO4064.d11 : 4.5.8.0
 MaxxAudioAPO5064.d11 : 5.6.5.0
 MaxxAudioAPO6064.d11 : 6.1.17.0
 MaxxAudioAPO7064.d11 : 7.0.24.0
 MaxxAudioAPOShell164.d11 : 4.10.8.0
 MaxxAudioCapture64.d11 : 4.1.29.0
 MaxxAudioEQ64.d11 : 4.1.1.0
 MaxxAudioRealtek64.d11 : 4.4.10.0
 MaxxAudioRender64.d11 : 7.1.60.0
 MaxxAudioRenderAVX64.d11 : 7.1.60.0
 MaxxAudioVienna264.d11 : 1.0.7.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxSpeechAPO64.d11 : 1.1.4.0
 MaxxVoiceAPO2064.d11 : 2.6.2.0
 MaxxVoiceAPO30.d11 : 3.1.14.0
 MaxxVoiceAPO3064.d11 : 3.1.14.0
 MaxxVoiceAPO4064.d11 : 4.0.19.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.131
 MBAPO264.d11 : 1.2.16.131
 MBAPO32.d11 : 1.0.62.0
 MBAPO64.d11 : 1.0.62.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBTHX64.d11 : 1.0.15.175
 MBWrp64.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAPO1fx.d11 : 6.3.9600.17246
 NahimicAPONSControl.d11 : 1.0.0.14866
 NAHIMICV2apo.d11 : 6.3.9600.17246
 NAHIMICV3apo.d11 : 6.3.9600.17246
 OrangeBlackSkinImages64.d11 : 1.0.608.1

Readme.txt

PremiumBlack2SkinImages64.d11	: 1.0.608.1
PremiumBlackSkinImages64.d11	: 1.0.608.1
R4EEA64A.d11	: 7.2.8000.17
R4EED64A.d11	: 7.2.8000.17
R4EEG64A.d11	: 7.2.8000.17
R4EEL64A.d11	: 7.2.8000.17
R4EEP64A.d11	: 7.2.8000.17
RCoInstII64.d11	: 2.3.4.2
R1tkAPO.d11	: 11.0.6000.544
R1tkAPO64.d11	: 11.0.6000.544
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.182
RTCOMDLL.d11	: 2.0.0.182
RtDataProc.d11	: 1.0.0.15
RtDataProc64.d11	: 1.0.0.16
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.1.90
RtkCfg.d11	: 1.0.0.6
RtkCfg64.d11	: 1.0.0.7
RtkCoLDR64.d11	: 1.0.0.1
RtkXInterface.d11	: 1.0.0.13
RtkXInterface64.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
Rt1CPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.346
SEAPO64.d11	: 2.0.7.30
SECOMN32.d11	: 2.0.7.30
SECOMN64.d11	: 2.0.7.30
SEHDHF32.d11	: 2.0.7.30
SEHDHF64.d11	: 2.0.7.30
SEHDRA64.d11	: 2.0.7.30
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.6.0.7270
sl3apo64.d11	: 3.5.14.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.5.14.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1

Readme.txt

sltech64.d11 : 3.5.14.0
sltshd64.d11 : 1.2.0.0
sluapo64.d11 : 2.3.24.0
slvipp64.d11 : 1.0.1.0
slviq64.d11 : 2.1.0.0
SRAPO64.d11 : 4.0.0.59
SRCOM.d11 : 4.0.0.59
SRCOM64.d11 : 4.0.0.59
SRRPTR64.d11 : 4.0.0.59
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo264.d11 : 1.2.2.0
tbb_waves.d11 : 4.4.2015.728
tepeqapo64.d11 : 1.1.0.0
ToastD1164.d11 : 1.0.0.2
tosade.d11 : 1.0.1.12
tosasfapo64.d11 : 2.1.0.0
toseaeapo64.d11 : 2.1.0.0
tossaeapo64.d11 : 2.1.1.0
tossaemaxapo64.d11 : 1.1.1.1
WavesGUILib64.d11 : 4.4.5.0
WhiteJadeSkinImages64.d11 : 1.0.608.1
YamahaAE.d11 : 1.1.3.0
YamahaAE2.d11 : 4.0.0.0
YamahaAE3.d11 : 5.0.4.0
RCORES64.dat : 1.5.6.9

Driver Setup Program : 4.54

History:

Driver Package R2.81

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1, Windows 10 – x86/x64

2. Add/Fix

- 1.) Driver :
 1. Customizations.
 2. Bug fix.

Vista, Win7, Win8, Win8.1, Win10 :

Vista, Win7, Win8, Win8.1, Win10 driver for x86
RTKVHDA.sys : 6.0.1.8036
AERTSrv.exe : 1.0.32.10
CreateRtkToastLnk.exe : 1.0.0.1
CXAPOAgent.exe : 1.1.0.0
DTSAudioService.exe : 1.0.0.0

Readme.txt

DTSU2PAuSrv32.exe : 2.1.1.0
 FMAPP.exe : 1.32.0.11
 MaxxAudioMeters.exe : 4.1.8.0
 RtHDVBg.exe : 1.0.0.258
 RtHDVCpl.exe : 1.0.0.1056
 RtkAudioService.exe : 1.0.0.81
 RtkNGUI.exe : 1.0.608.1
 Rt1Upd.exe : 3.0.0.6
 vncutil.exe : 1.0.0.45
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.56
 AERTACap.d11 : 2.12.32.0
 AERTARen.d11 : 1.0.32.11
 AudioLibW10.d11 : 1.0.2.0
 BlackBlueSkinImages.d11 : 1.0.608.1
 BlackSkinImages.d11 : 1.0.608.1
 Caf32api.d11 : 1.0.0.4
 Caf32APO2.d11 : 2.34.0.0
 CONEQMSAPO.d11 : 1.0.0.19
 CONEQMSAPOGUILibrary.d11 : 1.0.0.4
 CX32APO.d11 : 1.68.0.0
 CX32Proxy.d11 : 1.2.0.0
 DarkSkinImages.d11 : 1.0.608.1
 DAX3APOProp.d11 : 1.0.0.5
 DAX3APOv251.d11 : 1.0.0.5
 DDP32.d11 : 7.6.5.1
 DDPD32A.d11 : 7.6.5.1
 DDPO32A.d11 : 7.6.5.1
 DDPP32A.d11 : 7.6.5.1
 Do1byDAX2APOProp.d11 : 0.7.5.31
 Do1byDAX2APOv201.d11 : 0.7.5.31
 Do1byDAX2APOv211.d11 : 0.7.5.31
 Do1byDAX2APOv11dp.d11 : 1.0.0.5
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.1.1.0
 DTSU2PLFX32.d11 : 2.1.1.0
 DTSU2PREC32.d11 : 2.1.1.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 70.5.5.69
 FMAPP.d11 : 1.32.0.1
 GrayJadeSkinImages.d11 : 1.0.608.1
 HarmanAudioInterface.d11 : 1.2.0.0
 HiFiDAX2API.d11 : 0.7.5.65
 HiFiDAX2APIPCLL.d11 : 1.0.0.5
 HMAPO.d11 : 6.3.9600.17246
 HMC1ariFi.d11 : 1.4.0.0

Readme.txt

HMEQ.d11	: 1.4.0.0
HMEQ_Voice.d11	: 1.4.0.0
HMHVS.d11	: 1.4.0.0
HMLimiter.d11	: 1.4.0.0
HMUI.d11	: 1.4.0.0
ICESoundAPO.d11	: 1.0.0.26
KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO40.d11	: 4.5.8.0
MaxxAudioAPO50.d11	: 5.6.5.0
MaxxAudioAPO60.d11	: 6.1.17.0
MaxxAudioAPO70.d11	: 7.0.24.0
MaxxAudioAPOShell.d11	: 4.10.8.0
MaxxAudioCapture.d11	: 4.1.29.0
MaxxAudioEQ.d11	: 4.1.1.0
MaxxAudioRealtek.d11	: 4.4.10.0
MaxxAudioRender.d11	: 7.1.60.0
MaxxAudioRenderAVX.d11	: 7.1.60.0
MaxxAudioVienna2.d11	: 1.0.7.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxVoiceAPO20.d11	: 2.6.2.0
MaxxVoiceAPO30.d11	: 3.1.14.0
MaxxVoiceAPO40.d11	: 4.0.19.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.131
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBWrp32.d11	: 1.0.0.270
MISS_APO.d11	: 1.5.0.16020
NAHIMICAPO1fx.d11	: 6.3.9600.17246
NahimicAPONSControl.d11	: 1.0.0.14866
NAHIMICV2apo.d11	: 6.3.9600.17246
NAHIMICV3apo.d11	: 6.3.9600.17246
OrangeBlackSkinImages.d11	: 1.0.608.1
PremiumBlack2SkinImages.d11	: 1.0.608.1
PremiumBlackSkinImages.d11	: 1.0.608.1
R4EEA32A.d11	: 7.2.8000.17
R4EED32A.d11	: 7.2.8000.17
R4EEG32A.d11	: 7.2.8000.17
R4EEL32A.d11	: 7.2.8000.17
R4EEP32A.d11	: 7.2.8000.17
R1tkAPO.d11	: 11.0.6000.544
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.182
RtDataProc.d11	: 1.0.0.16
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkApoApi.d11	: 1.0.1.90
RtkCfg.d11	: 1.0.0.7

Readme.txt

RtkCoInstII.d11 : 2.3.4.2
 RtkCoLDR.d11 : 1.0.0.1
 RtkPgExt.d11 : 6.0.6000.346
 RtkXInterface.d11 : 1.0.0.13
 Rt1CPAPI.d11 : 1.0.2.6
 SEAPO32.d11 : 2.0.7.30
 SECOMN32.d11 : 2.0.7.30
 SEHDHF32.d11 : 2.0.7.30
 SEHDRA32.d11 : 2.0.7.30
 SFAPO.d11 : 3.0.0.16
 SFCOM.d11 : 3.0.0.16
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13
 SFFXHAP0.d11 : 2.0.0.13
 SFFXProc.d11 : 2.0.0.13
 SFFXSAPO.d11 : 2.0.0.13
 SFNHK.d11 : 3.0.0.16
 SFSS_APO.d11 : 1.6.0.7270
 sl3apo32.d11 : 3.5.14.0
 slcc3d32.d11 : 1.0.0.100
 slcnt32.d11 : 3.5.14.0
 slcshp32.d11 : 1.0.3.0
 slcsii32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slhlim32.d11 : 2.1.0.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.2.1.0
 slprp32.d11 : 1.0.0.1
 sltech32.d11 : 3.5.14.0
 sltshd32.d11 : 1.2.0.0
 sluapo32.d11 : 2.3.24.0
 slvipp32.d11 : 1.0.1.0
 slviq32.d11 : 2.1.0.0
 SRAPO.d11 : 4.0.0.59
 SRCOM.d11 : 4.0.0.59
 SRRPTR.d11 : 4.0.0.59
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 tadefxapo.d11 : 1.0.1.12
 tadefxapo2.d11 : 1.2.2.0
 tbb_waves.d11 : 4.4.2015.728
 TepeqAPO.d11 : 1.1.0.0
 ToastD11.d11 : 1.0.0.2
 tosade.d11 : 1.0.1.12
 tosasfapo32.d11 : 2.1.0.0
 toseaeapo32.d11 : 2.1.0.0
 tossaeapo32.d11 : 2.1.1.0
 tossaemaxapo32.d11 : 1.1.1.1
 WavesGUILib.d11 : 4.4.5.0
 WavesLib.d11 : 5.9.7.0
 WhiteJadeSkinImages.d11 : 1.0.608.1
 RCORES.dat : 1.5.6.9

Readme.txt

Vista, Win7, Win8, Win8.1, Win10 driver for x64

RTKVHD64.sys	: 6.0.1.8036
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent64.exe	: 1.1.0.0
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.1.0
FMAPP.exe	: 1.64.0.11
ICESoundService.exe	: 1.0.0.26
MaxxAudioMeters64.exe	: 4.1.8.0
RAVBg64.exe	: 1.0.0.258
RAVCp164.exe	: 1.0.0.1056
RtkAudioService64.exe	: 1.0.0.81
RtkNGUI64.exe	: 1.0.608.1
RtlUpd64.exe	: 3.0.0.6
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.56
AERTAC64.d11	: 2.12.64.0
AERTAR64.d11	: 1.0.64.11
AudioLibW1064.d11	: 1.0.2.0
AudysseyEfx.d11	: 1.0.0.30
BlackBlueSkinImages64.d11	: 1.0.608.1
BlackJadeSkinImages64.d11	: 1.0.461.0
BlackSkinImages64.d11	: 1.0.608.1
Caf64api.d11	: 1.0.0.4
CAF64APO2.d11	: 2.34.0.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
CX32APO.d11	: 1.68.0.0
CX64APO.d11	: 1.68.0.0
CX64Proxy.d11	: 1.2.0.0
DarkSkinImages64.d11	: 1.0.608.1
DAX3APOProp.d11	: 1.0.0.5
DAX3APOv251.d11	: 1.0.0.5
DDPA64.d11	: 7.6.5.1
DDPA64F3.d11	: 7.6.7.2
DDPD64A.d11	: 7.6.5.1
DDPD64AF3.d11	: 7.6.7.2
DDPO64A.d11	: 7.6.5.1
DDPO64AF3.d11	: 7.6.7.2
DDPP64A.d11	: 7.6.5.1
DDPP64AF3.d11	: 7.6.7.2
Do1byDAX2APOProp.d11	: 0.7.5.31
Do1byDAX2APOv201.d11	: 0.7.5.31
Do1byDAX2APOv211.d11	: 0.7.5.31
Do1byDAX2APOv11dp.d11	: 1.0.0.5
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1

Readme.txt

DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSU2PGFX64.d11 : 2.1.1.0
 DTSU2PLFX64.d11 : 2.1.1.0
 DTSU2PREC64.d11 : 2.1.1.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO32.d11 : 50.5.4.68
 FMAPO64.d11 : 70.6.5.69
 FMAPP.d11 : 1.64.0.1
 GrayJadeSkinImages64.d11 : 1.0.608.1
 HarmanAudioInterface.d11 : 1.2.0.0
 HiFiDAX2API.d11 : 0.7.5.65
 HiFiDAX2APIPCLL.d11 : 1.0.0.5
 HMAPO.d11 : 6.3.9600.17336
 HMCleriFi.d11 : 1.4.0.0
 HMEQ.d11 : 1.4.0.0
 HMEQ_Voice.d11 : 1.4.0.0
 HMHVS.d11 : 1.4.0.0
 HMLimiter.d11 : 1.4.0.0
 HMUI.d11 : 1.4.0.0
 ICESoundAPO64.d11 : 1.0.0.26
 IntelSSTAPO.d11 : 1.1.37.0
 IntelSstCApoPropPage.d11 : 1.1.37.0
 KAAPORT64.d11 : 4.1105.6000.53
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO4064.d11 : 4.5.8.0
 MaxxAudioAPO5064.d11 : 5.6.5.0
 MaxxAudioAPO6064.d11 : 6.1.17.0
 MaxxAudioAPO7064.d11 : 7.0.24.0
 MaxxAudioAPOShell164.d11 : 4.10.8.0
 MaxxAudioCapture64.d11 : 4.1.29.0
 MaxxAudioEQ64.d11 : 4.1.1.0
 MaxxAudioRealtek64.d11 : 4.4.10.0
 MaxxAudioRender64.d11 : 7.1.60.0
 MaxxAudioRenderAVX64.d11 : 7.1.60.0
 MaxxAudioVienna264.d11 : 1.0.7.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxSpeechAPO64.d11 : 1.1.4.0
 MaxxVoiceAPO2064.d11 : 2.6.2.0
 MaxxVoiceAPO30.d11 : 3.1.14.0
 MaxxVoiceAPO3064.d11 : 3.1.14.0
 MaxxVoiceAPO4064.d11 : 4.0.19.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.131
 MBAPO264.d11 : 1.2.16.131
 MBAPO32.d11 : 1.0.62.0
 MBAPO64.d11 : 1.0.62.0
 MBPPCn64.d11 : 1.0.0.110
 MBpp1d64.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBTHX64.d11 : 1.0.15.175
 MBWrp64.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAP01fx.d11 : 6.3.9600.17246

Readme.txt

NahimicAPONSControl.d11 : 1.0.0.14866
 NAHIMICV2apo.d11 : 6.3.9600.17246
 NAHIMICV3apo.d11 : 6.3.9600.17246
 OrangeBlackSkinImages64.d11 : 1.0.608.1
 PremiumBlack2SkinImages64.d11 : 1.0.608.1
 PremiumBlackSkinImages64.d11 : 1.0.608.1
 R4EEA64A.d11 : 7.2.8000.17
 R4EED64A.d11 : 7.2.8000.17
 R4EEG64A.d11 : 7.2.8000.17
 R4EEL64A.d11 : 7.2.8000.17
 R4EEP64A.d11 : 7.2.8000.17
 RCoInstII64.d11 : 2.3.4.2
 R1tkAPO.d11 : 11.0.6000.544
 R1tkAPO64.d11 : 11.0.6000.544
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.182
 RTCOMDLL.d11 : 2.0.0.182
 RtDataProc.d11 : 1.0.0.15
 RtDataProc64.d11 : 1.0.0.16
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.1.90
 RtkCfg.d11 : 1.0.0.6
 RtkCfg64.d11 : 1.0.0.7
 RtkCoLDR64.d11 : 1.0.0.1
 RtkXInterface.d11 : 1.0.0.13
 RtkXInterface64.d11 : 1.0.0.13
 Rt1CPAPI.d11 : 1.0.2.6
 Rt1CPAPI64.d11 : 1.0.2.6
 RtPgEx64.d11 : 6.0.6000.346
 SEAPO64.d11 : 2.0.7.30
 SECOMN32.d11 : 2.0.7.30
 SECOMN64.d11 : 2.0.7.30
 SEHDHF32.d11 : 2.0.7.30
 SEHDHF64.d11 : 2.0.7.30
 SEHDRA64.d11 : 2.0.7.30
 SFAPO64.d11 : 3.0.0.16
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.16
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13
 SFHAPO64.d11 : 2.0.0.13
 SFNHK64.d11 : 3.0.0.16
 SFProc64.d11 : 2.0.0.13
 SFSAPO64.d11 : 2.0.0.13
 SFSS_APO.d11 : 1.6.0.7270
 sl3apo64.d11 : 3.5.14.0
 slcc3d64.d11 : 1.0.0.100
 slcnt64.d11 : 3.5.14.0
 slcshp64.d11 : 1.0.3.0
 slcsii64.d11 : 1.0.3.0
 slgeq64.d11 : 1.0.1.0
 slh36064.d11 : 1.0.2.0

Readme.txt

slhlim64.d11 : 2.1.0.0
slInit64.d11 : 1.1.3.0
slmaxv64.d11 : 1.2.1.0
slprp64.d11 : 1.0.0.1
sltech64.d11 : 3.5.14.0
sltshd64.d11 : 1.2.0.0
sluapo64.d11 : 2.3.24.0
slvipp64.d11 : 1.0.1.0
slviq64.d11 : 2.1.0.0
SRAPO64.d11 : 4.0.0.59
SRCOM.d11 : 4.0.0.59
SRCOM64.d11 : 4.0.0.59
SRRPTR64.d11 : 4.0.0.59
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo264.d11 : 1.2.2.0
tbb_waves.d11 : 4.4.2015.728
tepeqapo64.d11 : 1.1.0.0
ToastD1164.d11 : 1.0.0.2
tosade.d11 : 1.0.1.12
tosasfapo64.d11 : 2.1.0.0
toseaeapo64.d11 : 2.1.0.0
tossaeapo64.d11 : 2.1.1.0
tossaemaxapo64.d11 : 1.1.1.1
WavesGUILib64.d11 : 4.4.5.0
WhiteJadeSkinImages64.d11 : 1.0.608.1
YamahaAE.d11 : 1.1.3.0
YamahaAE2.d11 : 4.0.0.0
YamahaAE3.d11 : 5.0.4.0
RCORES64.dat : 1.5.6.9

Driver Setup Program : 4.54

//=====

Driver Package R2.80

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1, Windows 10 - x86/x64

2. Add/Fix

1.) Driver :

1. Customizations.
2. Bug fix.

Vista, Win7, Win8, Win8.1, Win10 :

Vista, Win7, Win8, Win8.1, Win10 driver for x86
RTKVHDA.sys : 6.0.1.8004
AERTSrv.exe : 1.0.32.10
CreateRtkToastLnk.exe : 1.0.0.1

Readme.txt

CXAPOAgent.exe	: 1.1.0.0
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.11
MaxxAudioMeters.exe	: 4.1.8.0
RtHDVBg.exe	: 1.0.0.254
RtHDVCpl.exe	: 1.0.0.1048
RtkAudioService.exe	: 1.0.0.80
RtkNGUI.exe	: 1.0.602.1
RtlUpd.exe	: 3.0.0.5
vncutil.exe	: 1.0.0.45
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.56
AERTACap.d11	: 2.12.32.0
AERTARen.d11	: 1.0.32.11
AudioLibW10.d11	: 1.0.1.0
BlackBlueSkinImages.d11	: 1.0.602.1
BlackSkinImages.d11	: 1.0.602.1
Caf32api.d11	: 1.0.0.4
Caf32APO2.d11	: 2.34.0.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
CX32APO.d11	: 1.68.0.0
CX32Proxy.d11	: 1.2.0.0
DarkSkinImages.d11	: 1.0.602.1
DAX3APOProp.d11	: 1.0.0.5
DAX3APOv251.d11	: 1.0.0.5
DDPA32.d11	: 7.6.5.1
DDPD32A.d11	: 7.6.5.1
DDPO32A.d11	: 7.6.5.1
DDPP32A.d11	: 7.6.5.1
Do1byDAX2APOProp.d11	: 0.7.5.31
Do1byDAX2APOv201.d11	: 0.7.5.31
Do1byDAX2APOv211.d11	: 0.7.5.31
Do1byDAX2APOv11dp.d11	: 1.0.0.5
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3
DTSLFXAPO.d11	: 1.0.0.3
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSU2PGFX32.d11	: 2.1.1.0
DTSU2PLFX32.d11	: 2.1.1.0
DTSU2PREC32.d11	: 2.1.1.0
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 70.5.5.68
FMAPP.d11	: 1.32.0.1
GrayJadeSkinImages.d11	: 1.0.602.1
HarmanAudioInterface.d11	: 1.2.0.0
HiFiDAX2API.d11	: 0.7.5.65
HiFiDAX2APIPCLL.d11	: 1.0.0.5

Readme.txt

HMAPO.d11	: 6.3.9600.17246
HMC1ariFi.d11	: 1.4.0.0
HMEQ.d11	: 1.4.0.0
HMEQ_Voice.d11	: 1.4.0.0
HMHVS.d11	: 1.4.0.0
HMLimiter.d11	: 1.4.0.0
HMUI.d11	: 1.4.0.0
ICEsoundAPO.d11	: 1.0.0.26
KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO40.d11	: 4.5.8.0
MaxxAudioAPO50.d11	: 5.6.5.0
MaxxAudioAPO60.d11	: 6.1.17.0
MaxxAudioAPO70.d11	: 7.0.24.0
MaxxAudioAPOShell.d11	: 4.10.8.0
MaxxAudioCapture.d11	: 4.1.29.0
MaxxAudioEQ.d11	: 4.1.1.0
MaxxAudioRealtek.d11	: 4.4.10.0
MaxxAudioRender.d11	: 7.1.60.0
MaxxAudioRenderAVX.d11	: 7.1.60.0
MaxxAudioVienna2.d11	: 1.0.7.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxVoiceAPO20.d11	: 2.6.2.0
MaxxVoiceAPO30.d11	: 3.1.14.0
MaxxVoiceAPO40.d11	: 4.0.19.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.129
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBWrp32.d11	: 1.0.0.270
MISS_APO.d11	: 1.5.0.16020
NAHIMICAPO1fx.d11	: 6.3.9600.17246
NahimicAPONSControl.d11	: 1.0.0.14866
NAHIMICV2apo.d11	: 6.3.9600.17246
NAHIMICV3apo.d11	: 6.3.9600.17246
OrangeBlackSkinImages.d11	: 1.0.602.1
PremiumBlack2SkinImages.d11	: 1.0.602.1
PremiumBlackSkinImages.d11	: 1.0.602.1
R4EEA32A.d11	: 7.2.8000.17
R4EED32A.d11	: 7.2.8000.17
R4EEG32A.d11	: 7.2.8000.17
R4EEL32A.d11	: 7.2.8000.17
R4EEP32A.d11	: 7.2.8000.17
R1tkAPO.d11	: 11.0.6000.539
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.180
RtDataProc.d11	: 1.0.0.16
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33

Readme.txt

RtkApoApi.d11	: 1.0.1.90
RtkCfg.d11	: 1.0.0.7
RtkCoInstII.d11	: 2.3.3.9
RtkCoLDR.d11	: 1.0.0.1
RtkPgExt.d11	: 6.0.6000.344
RtkXInterface.d11	: 1.0.0.13
RtlCPAPI.d11	: 1.0.2.6
SEAPO32.d11	: 2.0.7.19
SECOMN32.d11	: 2.0.7.19
SEHDF32.d11	: 2.0.7.19
SEHDRA32.d11	: 2.0.7.19
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAP0.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.5.13.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.5.13.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.5.13.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRAPO.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRRPTR.d11	: 4.0.0.59
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.2.0
tbb_waves.d11	: 4.4.2015.728
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tosasfapo32.d11	: 2.1.0.0
toseaeapo32.d11	: 2.1.0.0
tossaeapo32.d11	: 2.1.1.0
tossaemaxapo32.d11	: 1.1.1.1
WavesGUILib.d11	: 4.4.5.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.602.1

Readme.txt

RCORES.dat : 1.5.6.9

Vista, Win7, Win8, Win8.1, Win10 driver for x64

RTKVHD64.sys : 6.0.1.8004

AERTSr64.exe : 1.0.64.10

CreateRtkToastLnk.exe : 1.0.0.1

CXAPOAgent64.exe : 1.1.0.0

DTSAudioService64.exe : 1.0.0.0

DTSU2PAuSrv64.exe : 2.1.1.0

FMAPP.exe : 1.64.0.11

ICESoundService.exe : 1.0.0.26

MaxxAudioMeters64.exe : 4.1.8.0

RAVBg64.exe : 1.0.0.254

RAVCp164.exe : 1.0.0.1048

RtkAudioService64.exe : 1.0.0.80

RtkNGUI64.exe : 1.0.602.1

RtlUpd64.exe : 3.0.0.5

vncutil64.exe : 1.0.0.45

GWfilt64.sys : 6.10.0.3

mbfilt64.sys : 6.10.0.8

RTSnMg64.cpl : 1.0.0.56

AERTAC64.d11 : 2.12.64.0

AERTAR64.d11 : 1.0.64.11

AudioLibW1064.d11 : 1.0.1.0

AudysseyEfx.d11 : 1.0.0.30

BlackBlueSkinImages64.d11 : 1.0.602.1

BlackJadeSkinImages64.d11 : 1.0.461.0

BlackSkinImages64.d11 : 1.0.602.1

Caf64api.d11 : 1.0.0.4

CAF64APO2.d11 : 2.34.0.0

CONEQMSAPO.d11 : 1.0.0.19

CONEQMSAPOGUILibrary.d11 : 1.0.0.4

CX32APO.d11 : 1.68.0.0

CX64APO.d11 : 1.68.0.0

CX64Proxy.d11 : 1.2.0.0

DarkSkinImages64.d11 : 1.0.602.1

DAX3APOProp.d11 : 1.0.0.5

DAX3APOv251.d11 : 1.0.0.5

DDPA64.d11 : 7.6.5.1

DDPA64F3.d11 : 7.6.7.2

DDPD64A.d11 : 7.6.5.1

DDPD64AF3.d11 : 7.6.7.2

DDPO64A.d11 : 7.6.5.1

DDPO64AF3.d11 : 7.6.7.2

DDPP64A.d11 : 7.6.5.1

DDPP64AF3.d11 : 7.6.7.2

Do1byDAX2APOProp.d11 : 0.7.5.31

Do1byDAX2APOv201.d11 : 0.7.5.31

Do1byDAX2APOv211.d11 : 0.7.5.31

Do1byDAX2APOv11dp.d11 : 1.0.0.5

DTSBassEnhancementDLL64.d11 : 1.0.0.1

DTSBoostDLL64.d11 : 1.0.0.1

DTSGainCompensatorDLL64.d11 : 1.0.0.1

DTSGFXAPO64.d11 : 1.0.0.3

DTSGFXAPONS64.d11 : 1.0.0.3

DTSLFXAPO64.d11 : 1.0.0.3

Readme.txt

DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.1.1.0
DTSU2PLFX64.d11	: 2.1.1.0
DTSU2PREC64.d11	: 2.1.1.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO32.d11	: 50.5.4.68
FMAPO64.d11	: 70.6.5.68
FMAPP.d11	: 1.64.0.1
GrayJadeSkinImages64.d11	: 1.0.602.1
HarmanAudioInterface.d11	: 1.2.0.0
HiFiDAX2API.d11	: 0.7.5.65
HiFiDAX2APIPCLL.d11	: 1.0.0.5
HMAPO.d11	: 6.3.9600.17336
HMCleriFi.d11	: 1.4.0.0
HMEQ.d11	: 1.4.0.0
HMEQ_Voice.d11	: 1.4.0.0
HMHVS.d11	: 1.4.0.0
HMLimiter.d11	: 1.4.0.0
HMUI.d11	: 1.4.0.0
ICESoundAPO64.d11	: 1.0.0.26
IntelSSTAPO.d11	: 1.1.30.0
IntelSstCApoPropPage.d11	: 1.1.30.0
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO4064.d11	: 4.5.8.0
MaxxAudioAPO5064.d11	: 5.6.5.0
MaxxAudioAPO6064.d11	: 6.1.17.0
MaxxAudioAPO7064.d11	: 7.0.24.0
MaxxAudioAPOShell164.d11	: 4.10.8.0
MaxxAudioCapture64.d11	: 4.1.29.0
MaxxAudioEQ64.d11	: 4.1.1.0
MaxxAudioRealtek64.d11	: 4.4.10.0
MaxxAudioRender64.d11	: 7.1.60.0
MaxxAudioRenderAVX64.d11	: 7.1.60.0
MaxxAudioVienna264.d11	: 1.0.7.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxSpeechAPO64.d11	: 1.1.4.0
MaxxVoiceAPO2064.d11	: 2.6.2.0
MaxxVoiceAPO30.d11	: 3.1.14.0
MaxxVoiceAPO3064.d11	: 3.1.14.0
MaxxVoiceAPO4064.d11	: 4.0.19.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.129
MBAPO264.d11	: 1.2.16.129
MBAPO32.d11	: 1.0.62.0
MBAPO64.d11	: 1.0.62.0
MBPPCn64.d11	: 1.0.0.110
MBpp1d64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBTHX64.d11	: 1.0.15.175
MBWrp64.d11	: 1.0.0.270

Readme.txt

MISS_APO.d11 : 1.5.0.16020
 NAHIMICAP01fx.d11 : 6.3.9600.17246
 NahimicAPONSControl.d11 : 1.0.0.14866
 NAHIMICV2apo.d11 : 6.3.9600.17246
 NAHIMICV3apo.d11 : 6.3.9600.17246
 OrangeBlackSkinImages64.d11 : 1.0.602.1
 PremiumBlack2SkinImages64.d11 : 1.0.602.1
 PremiumBlackSkinImages64.d11 : 1.0.602.1
 R4EEA64A.d11 : 7.2.8000.17
 R4EED64A.d11 : 7.2.8000.17
 R4EEG64A.d11 : 7.2.8000.17
 R4EEL64A.d11 : 7.2.8000.17
 R4EEP64A.d11 : 7.2.8000.17
 RCoInstII64.d11 : 2.3.3.9
 R1tkAPO.d11 : 11.0.6000.539
 R1tkAPO64.d11 : 11.0.6000.539
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.180
 RTCOMDLL.d11 : 2.0.0.180
 RtDataProc.d11 : 1.0.0.15
 RtDataProc64.d11 : 1.0.0.16
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.1.90
 RtkCfg.d11 : 1.0.0.6
 RtkCfg64.d11 : 1.0.0.7
 RtkCoLDR64.d11 : 1.0.0.1
 RtkXInterface.d11 : 1.0.0.13
 RtkXInterface64.d11 : 1.0.0.13
 Rt1CPAPI.d11 : 1.0.2.6
 Rt1CPAPI64.d11 : 1.0.2.6
 RtPgEx64.d11 : 6.0.6000.344
 SEAPO64.d11 : 2.0.7.19
 SECOMN32.d11 : 2.0.7.19
 SECOMN64.d11 : 2.0.7.19
 SEHDHF32.d11 : 2.0.7.19
 SEHDHF64.d11 : 2.0.7.19
 SEHDRA64.d11 : 2.0.7.19
 SFAPO64.d11 : 3.0.0.16
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.16
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13
 SFHAPO64.d11 : 2.0.0.13
 SFNHK64.d11 : 3.0.0.16
 SFProc64.d11 : 2.0.0.13
 SFSAPO64.d11 : 2.0.0.13
 SFSS_APO.d11 : 1.6.0.7270
 sl3apo64.d11 : 3.5.13.0
 slcc3d64.d11 : 1.0.0.100
 slcnt64.d11 : 3.5.13.0
 slcshp64.d11 : 1.0.3.0
 slcsii64.d11 : 1.0.3.0

Readme.txt

slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slhlim64.d11 : 2.1.0.0
slInit64.d11 : 1.1.3.0
slmaxv64.d11 : 1.2.1.0
slprp64.d11 : 1.0.0.1
sltech64.d11 : 3.5.13.0
sltshd64.d11 : 1.2.0.0
sluapo64.d11 : 2.3.24.0
slvipp64.d11 : 1.0.1.0
slviq64.d11 : 2.1.0.0
SRAPO64.d11 : 4.0.0.59
SRCOM.d11 : 4.0.0.59
SRCOM64.d11 : 4.0.0.59
SRRPTR64.d11 : 4.0.0.59
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo264.d11 : 1.2.2.0
tbb_waves.d11 : 4.4.2015.728
tepeqapo64.d11 : 1.1.0.0
ToastD1164.d11 : 1.0.0.2
tosade.d11 : 1.0.1.12
tosasfapo64.d11 : 2.1.0.0
toseaeapo64.d11 : 2.1.0.0
tossaeapo64.d11 : 2.1.1.0
tossaemaxapo64.d11 : 1.1.1.1
WavesGUILib64.d11 : 4.4.5.0
WhiteJadeSkinImages64.d11 : 1.0.602.1
YamahaAE.d11 : 1.1.3.0
YamahaAE2.d11 : 4.0.0.0
YamahaAE3.d11 : 5.0.4.0
RCORES64.dat : 1.5.6.9

Driver Setup Program : 4.54

//=====

Driver Package R2.79

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8, Windows 8.1, Windows 10 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC891, ALC900

ALC660, ALC662, ALC663, ALC665, ALC667, ALC668, ALC670, ALC671,
ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC236, ALC255, ALC256, ALC260,
ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280,
ALC282, ALC283, ALC284, ALC286, ALC288, ALC290, ALC292, ALC293, ALC298, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC, ALC861VD, ALC891, ALC900

ALC660, ALC662, ALC663, ALC665, ALC667, ALC668, ALC670, ALC671,
ALC672, ALC676, ALC680

Readme.txt

ALC221, ALC231, ALC233, ALC235, ALC236, ALC255, ALC256, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283, ALC284, ALC286, ALC290, ALC292, ALC293, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1, Windows 10 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Vista, Win7, Win8, Win8.1, Win10 :

Vista, Win7, Win8, Win8.1, Win10 driver for x86

RTKVHDA.sys	: 6.0.1.7541
AERTSrv.exe	: 1.0.32.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent.exe	: 1.1.0.0
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.5
MaxxAudioMeters.exe	: 4.1.6.0
RtHDVBg.exe	: 1.0.0.220
RtHDVCpl.exe	: 1.0.0.968
RtkAudioService.exe	: 1.0.0.66
RtkNGUI.exe	: 1.0.483.0
RtlUpd.exe	: 3.0.0.0
vncutil.exe	: 1.0.0.45
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.43
AERTACap.d11	: 2.10.32.0
AERTARen.d11	: 1.0.32.11
BlackBlueSkinImages.d11	: 1.0.483.0
BlackSkinImages.d11	: 1.0.483.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
CX32APO.d11	: 1.28.0.0
DarkSkinImages.d11	: 1.0.483.0
DDPA32.d11	: 7.6.5.1
DDPD32A.d11	: 7.6.5.1
DDPO32A.d11	: 7.6.5.1
DDPP32A.d11	: 7.6.5.1
DolbyDAX2APOProp.d11	: 0.4.0.18
DolbyDAX2APOv201.d11	: 0.4.0.18
DolbyDAX2APOv211.d11	: 0.4.0.18
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3
DTSLFXAPO.d11	: 1.0.0.3
DTSLimitterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1

Readme.txt

DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.1.1.0
 DTSU2PLFX32.d11 : 2.1.1.0
 DTSU2PREC32.d11 : 2.1.1.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 70.5.3.65
 GrayJadeSkinImages.d11 : 1.0.483.0
 HiFiDAX2API.d11 : 0.4.0.20
 ICESoundAPO.d11 : 1.0.0.15
 KAAPORT.d11 : 4.1105.6000.53
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO40.d11 : 4.5.8.0
 MaxxAudioAPO50.d11 : 5.6.5.0
 MaxxAudioAPO60.d11 : 6.1.12.0
 MaxxAudioAPO70.d11 : 7.0.10.0
 MaxxAudioAPOShell.d11 : 4.10.8.0
 MaxxAudioEQ.d11 : 4.1.1.0
 MaxxAudioRealtek.d11 : 4.4.10.0
 MaxxAudioVienna2.d11 : 1.0.7.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxVoiceAPO20.d11 : 2.6.2.0
 MaxxVoiceAPO30.d11 : 3.1.13.0
 MaxxVoiceAPO40.d11 : 4.0.8.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.81
 MBAPO32.d11 : 1.0.62.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBWrp32.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAP01fx.d11 : 6.3.9600.17231
 NahimicAPONSControl.d11 : 1.0.0.14866
 NAHIMICV2apo.d11 : 6.3.9600.16384
 OrangeBlackSkinImages.d11 : 1.0.483.0
 PremiumBlackSkinImages.d11 : 1.0.483.0
 R4EEA32A.d11 : 7.2.8000.17
 R4EED32A.d11 : 7.2.8000.17
 R4EEG32A.d11 : 7.2.8000.17
 R4EEL32A.d11 : 7.2.8000.17
 R4EEP32A.d11 : 7.2.8000.17
 R1tkAPO.d11 : 11.0.6000.433
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.169
 RtDataProc.d11 : 1.0.0.14
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkApoApi.d11 : 1.0.1.87
 RtkCfg.d11 : 1.0.0.5

Readme.txt

RtkCoInstII.d11	: 2.2.5.6
RtkCoLDR.d11	: 1.0.0.1
RtkPgExt.d11	: 6.0.6000.320
RtkXInterface.d11	: 1.0.0.13
RtlCPAPI.d11	: 1.0.2.6
SEAPO32.d11	: 2.0.5.4
SECOMN32.d11	: 2.0.5.4
SEHDRA32.d11	: 2.0.5.4
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.1.38.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.1.38.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.1.38.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRAPO.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRRPTR.d11	: 4.0.0.59
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.2.0
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tossaemaxapo32.d11	: 1.0.0.0
WavesGUILib.d11	: 4.4.5.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.483.0
RCORES.dat	: 1.5.6.6
Vista, Win7, Win8, Win8.1, Win10 driver for x64	
RTKVHD64.sys	: 6.0.1.7541
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent64.exe	: 1.1.0.0

Readme.txt

DTSAudioService64.exe : 1.0.0.0
 DTSU2PAuSrv64.exe : 2.1.1.0
 FMAPP.exe : 1.64.0.5
 MaxxAudioMeters64.exe : 4.1.6.0
 RAVBg64.exe : 1.0.0.220
 RAVCp164.exe : 1.0.0.968
 RtkAudioService64.exe : 1.0.0.66
 RtkNGUI64.exe : 1.0.483.0
 RtlUpd64.exe : 3.0.0.0
 vncutil64.exe : 1.0.0.45
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.43
 AERTAC64.d11 : 2.10.64.0
 AERTAR64.d11 : 1.0.64.11
 BlackBlueSkinImages64.d11 : 1.0.483.0
 BlackJadeSkinImages64.d11 : 1.0.461.0
 BlackSkinImages64.d11 : 1.0.483.0
 CONEQMSAPO.d11 : 1.0.0.19
 CONEQMSAPOGUILibrary.d11 : 1.0.0.4
 CX32APO.d11 : 1.28.0.0
 CX64APO.d11 : 1.28.0.0
 DarkSkinImages64.d11 : 1.0.483.0
 DDPA64.d11 : 7.6.5.1
 DDPA64F3.d11 : 7.6.7.1
 DDPD64A.d11 : 7.6.5.1
 DDPD64AF3.d11 : 7.6.7.1
 DDPO64A.d11 : 7.6.5.1
 DDPO64AF3.d11 : 7.6.7.1
 DDPP64A.d11 : 7.6.5.1
 DDPP64AF3.d11 : 7.6.7.1
 Do1byDAX2APOProp.d11 : 0.4.0.18
 Do1byDAX2APOv201.d11 : 0.4.0.18
 Do1byDAX2APOv211.d11 : 0.4.0.18
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSU2PGFX64.d11 : 2.1.1.0
 DTSU2PLFX64.d11 : 2.1.1.0
 DTSU2PREC64.d11 : 2.1.1.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAP032.d11 : 50.5.4.68
 FMAP064.d11 : 70.6.3.65
 GrayJadeSkinImages64.d11 : 1.0.483.0
 HiFiDAX2API.d11 : 0.4.0.20
 ICESoundAPO64.d11 : 1.0.0.15
 IntelSSTAPO.d11 : 1.0.461.0
 IntelSstCApoPropPage.d11 : 1.0.0.10

Readme.txt

KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO4064.d11	: 4.5.8.0
MaxxAudioAPO5064.d11	: 5.6.5.0
MaxxAudioAPO6064.d11	: 6.1.12.0
MaxxAudioAPO7064.d11	: 7.0.10.0
MaxxAudioAPOShe1164.d11	: 4.10.8.0
MaxxAudioEQ64.d11	: 4.1.1.0
MaxxAudioRealtek64.d11	: 4.4.10.0
MaxxAudioVienna264.d11	: 1.0.7.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxSpeechAPO64.d11	: 1.1.4.0
MaxxVoiceAPO2064.d11	: 2.6.2.0
MaxxVoiceAPO30.d11	: 3.1.13.0
MaxxVoiceAPO3064.d11	: 3.1.13.0
MaxxVoiceAPO4064.d11	: 4.0.8.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.81
MBAPO264.d11	: 1.2.16.81
MBAPO32.d11	: 1.0.62.0
MBAPO64.d11	: 1.0.62.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBTHX64.d11	: 1.0.15.175
MBWrp64.d11	: 1.0.0.270
MISS_APO.d11	: 1.5.0.16020
NAHIMICAPO1fx.d11	: 6.3.9600.17231
NahimicAPONSControl.d11	: 1.0.0.14866
NAHIMICV2apo.d11	: 6.3.9600.16384
OrangeBlackSkinImages64.d11	: 1.0.483.0
PremiumBlackSkinImages64.d11	: 1.0.483.0
R4EEA64A.d11	: 7.2.8000.17
R4EED64A.d11	: 7.2.8000.17
R4EEG64A.d11	: 7.2.8000.17
R4EEL64A.d11	: 7.2.8000.17
R4EEP64A.d11	: 7.2.8000.17
RCoInstII64.d11	: 2.2.5.6
R1tkAPO.d11	: 11.0.6000.433
R1tkAPO64.d11	: 11.0.6000.433
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.169
RTCOMDLL.d11	: 2.0.0.169
RtDataProc.d11	: 1.0.0.14
RtDataProc64.d11	: 1.0.0.14
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.1.87
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.5
RtkCoLDR64.d11	: 1.0.0.1
RtkXInterface.d11	: 1.0.0.13

Readme.txt

RtkXInterface64.d11	: 1.0.0.13
RtlCPAPI.d11	: 1.0.2.6
RtlCPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.320
SEAPO64.d11	: 2.0.5.4
SECOMN32.d11	: 2.0.5.4
SECOMN64.d11	: 2.0.5.4
SEHDRA64.d11	: 2.0.5.4
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.6.0.7270
s13apo64.d11	: 3.1.38.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.1.38.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1
sltech64.d11	: 3.1.38.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.24.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRAPO64.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRCOM64.d11	: 4.0.0.59
SRRPTR64.d11	: 4.0.0.59
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.2.2.0
tepeqapo64.d11	: 1.1.0.0
ToastD1164.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tosasfapo64.d11	: 2.0.4.0
toseaeapo64.d11	: 2.0.4.0
tossaeapo64.d11	: 2.0.4.0
tossaemaxapo64.d11	: 1.0.0.0
WavesGUILib64.d11	: 4.4.5.0
WhiteJadeSkinImages64.d11	: 1.0.483.0
YamahaAE.d11	: 1.1.3.0
YamahaAE2.d11	: 4.0.0.0
RCORES64.dat	: 1.5.6.6

Readme.txt

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys : 5.10.0.6519

Rtaupd.exe : 2.8.0.5

RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys : 5.10.0.6519

Rtaupd64.exe : 2.8.0.5

RHCoInst64XP.d11 : 1.1.5.1

Vista, Win7, Win8 x86 :

RtHDMIV.sys : 6.0.1.6650

RtkAudioSrvATI.exe : 1.0.0.23

RtkUpd.exe : 2.8.0.6

R4EEA32H.d11 : 7.2.8000.13

R4EED32H.d11 : 7.2.8000.13

R4EEG32H.d11 : 7.2.8000.13

R4EEL32H.d11 : 7.2.8000.13

R4EEP32H.d11 : 7.2.8000.13

RH3DAA32.d11 : 6.0.6001.18

RH3DHT32.d11 : 6.0.6001.18

RHCoInst.d11 : 1.1.5.1

RHDMIExt.d11 : 6.0.6000.228

RTEED32H.d11 : 6.1.6001.33

RTEEG32H.d11 : 6.1.6001.33

RTEEL32H.d11 : 6.1.6001.33

RTEEP32H.d11 : 6.1.6001.33

RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :

RtHDMIVX.sys : 6.0.1.6650

RtkAudioSrvATI64.exe : 1.0.0.23

RtkUpd64.exe : 2.8.0.6

R4EEA64H.d11 : 7.2.8000.13

R4EED64H.d11 : 7.2.8000.13

R4EEG64H.d11 : 7.2.8000.13

R4EEL64H.d11 : 7.2.8000.13

R4EEP64H.d11 : 7.2.8000.13

RH3DAA64.d11 : 6.0.6001.18

RH3DHT64.d11 : 6.0.6001.18

RHCoInst64.d11 : 1.1.5.1

RHDMEx64.d11 : 6.0.6000.228

RTEED64H.d11 : 6.1.6001.33

RTEEG64H.d11 : 6.1.6001.33

RTEEL64H.d11 : 6.1.6001.33

RTEEP64H.d11 : 6.1.6001.33

RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 4.27

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudiobus.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R2.78

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8, Windows 8.1, Windows 10 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC891, ALC900

ALC660, ALC662, ALC663, ALC665, ALC667, ALC668, ALC670, ALC671,
ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC236, ALC255, ALC256, ALC260,
ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280,
ALC282, ALC283, ALC284, ALC286, ALC288, ALC290, ALC292, ALC293, ALC298, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC, ALC861VD, ALC891, ALC900

ALC660, ALC662, ALC663, ALC665, ALC667, ALC668, ALC670, ALC671,
ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC236, ALC255, ALC256, ALC260,
ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280,
ALC282, ALC283, ALC284, ALC286, ALC290, ALC292, ALC293, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows 7, Windows 8, Windows 8.1, Windows 10 -
x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Vista, Win7, Win8, Win8.1, Win10 :

Vista, Win7, Win8, Win8.1, Win10 driver for x86	
RTKVHDA.sys	: 6.0.1.7512
AERTSrv.exe	: 1.0.32.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent.exe	: 1.1.0.0
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.5
MaxxAudioMeters.exe	: 4.1.6.0
RtHDVBg.exe	: 1.0.0.220
RtHDVCpl.exe	: 1.0.0.966
RtkAudioService.exe	: 1.0.0.64
RtkNGUI.exe	: 1.0.478.0
RtlUpd.exe	: 3.0.0.0
vncutil.exe	: 1.0.0.45
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.42
AERTACap.dll	: 2.10.32.0
AERTARen.dll	: 1.0.32.11
BlackBlueSkinImages.dll	: 1.0.478.0
BlackSkinImages.dll	: 1.0.478.0
CONEQMSAPO.dll	: 1.0.0.19
CONEQMSAPOGUILibrary.dll	: 1.0.0.4

Readme.txt

CX32APO.d11	: 1.25.0.0
DarkSkinImages.d11	: 1.0.478.0
DDPA32.d11	: 7.6.5.1
DDPD32A.d11	: 7.6.5.1
DDPO32A.d11	: 7.6.5.1
DDPP32A.d11	: 7.6.5.1
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.3
DTS GFXAPONS.d11	: 1.0.0.3
DTS LFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTS S2HeadphoneDLL.d11	: 1.0.0.1
DTS S2SpeakerDLL.d11	: 1.0.0.1
DTS SymmetryDLL.d11	: 1.0.0.1
DTS U2PGFX32.d11	: 2.1.1.0
DTS U2PLFX32.d11	: 2.1.1.0
DTS U2PREC32.d11	: 2.1.1.0
DTS VoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 70.5.1.66
GrayJadeSkinImages.d11	: 1.0.478.0
ICEsoundAPO.d11	: 1.0.0.15
KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO40.d11	: 4.5.5.0
MaxxAudioAPO50.d11	: 5.6.0.0
MaxxAudioAPO60.d11	: 6.1.11.0
MaxxAudioAPO70.d11	: 7.0.10.0
MaxxAudioAPOShell.d11	: 4.10.8.0
MaxxAudioEQ.d11	: 4.1.1.0
MaxxAudioRealtek.d11	: 4.4.10.0
MaxxAudioVienna2.d11	: 1.0.7.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxVoiceAPO20.d11	: 2.6.0.0
MaxxVoiceAPO30.d11	: 3.1.7.0
MaxxVoiceAPO40.d11	: 4.0.8.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.81
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBWrp32.d11	: 1.0.0.270
MISS_APO.d11	: 1.5.0.16020
NAHIMICAPO1fx.d11	: 6.3.9600.17231
NahimicAPONSControl.d11	: 1.0.0.14866
NAHIMICV2apo.d11	: 6.3.9600.16384
OrangeBlackSkinImages.d11	: 1.0.478.0
PremiumBlackSkinImages.d11	: 1.0.478.0
R4EEA32A.d11	: 7.2.8000.17
R4EED32A.d11	: 7.2.8000.17
R4EEG32A.d11	: 7.2.8000.17

Readme.txt

R4EEL32A.d11	: 7.2.8000.17
R4EEP32A.d11	: 7.2.8000.17
R1tkAPO.d11	: 11.0.6000.426
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.169
RtDataProc.d11	: 1.0.0.14
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkApoApi.d11	: 1.0.1.85
RtkCfg.d11	: 1.0.0.4
RtkCoInstII.d11	: 2.2.4.7
RtkCoLDR.d11	: 1.0.0.1
RtkPgExt.d11	: 6.0.6000.320
RtkXInterface.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
SEAPO32.d11	: 2.0.5.4
SECOMN32.d11	: 2.0.5.4
SEHDRA32.d11	: 2.0.5.4
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.1.38.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.1.38.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.1.38.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRAPO.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRRPTR.d11	: 4.0.0.59
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.2.0
TepeqAPO.d11	: 1.1.0.0

Readme.txt

ToastD11.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tossaemaxapo32.d11	: 1.0.0.0
WavesGUILib.d11	: 4.4.5.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.478.0
RCORES.dat	: 1.5.6.6
Vista, Win7, Win8, Win8.1, Win10 driver for x64	
RTKVHD64.sys	: 6.0.1.7512
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent64.exe	: 1.1.0.0
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.1.0
FMAPP.exe	: 1.64.0.5
MaxxAudioMeters64.exe	: 4.1.6.0
RAVBg64.exe	: 1.0.0.220
RAVCp164.exe	: 1.0.0.966
RtkAudioService64.exe	: 1.0.0.64
RtkNGUI64.exe	: 1.0.478.0
RtlUpd64.exe	: 3.0.0.0
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.42
AERTAC64.d11	: 2.10.64.0
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.478.0
BlackSkinImages64.d11	: 1.0.478.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
CX32APO.d11	: 1.25.0.0
CX64APO.d11	: 1.25.0.0
DarkSkinImages64.d11	: 1.0.478.0
DDPA64.d11	: 7.6.5.1
DDPA64F3.d11	: 7.6.7.1
DDPD64A.d11	: 7.6.5.1
DDPD64AF3.d11	: 7.6.7.1
DDPO64A.d11	: 7.6.5.1
DDPO64AF3.d11	: 7.6.7.1
DDPP64A.d11	: 7.6.5.1
DDPP64AF3.d11	: 7.6.7.1
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.1.1.0
DTSU2PLFX64.d11	: 2.1.1.0

Readme.txt

DTSU2PREC64.d11 : 2.1.1.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO32.d11 : 50.5.4.68
 FMAPO64.d11 : 70.6.1.66
 GrayJadeSkinImages64.d11 : 1.0.478.0
 ICEsoundAPO64.d11 : 1.0.0.15
 KAAPORT64.d11 : 4.1105.6000.53
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO4064.d11 : 4.5.5.0
 MaxxAudioAPO5064.d11 : 5.6.0.0
 MaxxAudioAPO6064.d11 : 6.1.11.0
 MaxxAudioAPO7064.d11 : 7.0.10.0
 MaxxAudioAPOShell164.d11 : 4.10.8.0
 MaxxAudioEQ64.d11 : 4.1.1.0
 MaxxAudioRealtek64.d11 : 4.4.10.0
 MaxxAudioVienna264.d11 : 1.0.7.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxSpeechAPO64.d11 : 1.1.4.0
 MaxxVoiceAPO2064.d11 : 2.6.0.0
 MaxxVoiceAPO30.d11 : 3.1.7.0
 MaxxVoiceAPO3064.d11 : 3.1.7.0
 MaxxVoiceAPO4064.d11 : 4.0.8.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.81
 MBAPO264.d11 : 1.2.16.81
 MBAPO32.d11 : 1.0.62.0
 MBAPO64.d11 : 1.0.62.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBTHX64.d11 : 1.0.15.175
 MBWrp64.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAPO1fx.d11 : 6.3.9600.17231
 NahimicAPONSControl.d11 : 1.0.0.14866
 NAHIMICV2apo.d11 : 6.3.9600.16384
 OrangeBlackSkinImages64.d11 : 1.0.478.0
 PremiumBlackSkinImages64.d11 : 1.0.478.0
 R4EEA64A.d11 : 7.2.8000.17
 R4EED64A.d11 : 7.2.8000.17
 R4EEG64A.d11 : 7.2.8000.17
 R4EEL64A.d11 : 7.2.8000.17
 R4EEP64A.d11 : 7.2.8000.17
 RCoInstII64.d11 : 2.2.4.7
 R1tkAPO.d11 : 11.0.6000.426
 R1tkAPO64.d11 : 11.0.6000.426
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.169
 RTCOMDLL.d11 : 2.0.0.169
 RtDataProc.d11 : 1.0.0.14
 RtDataProc64.d11 : 1.0.0.14
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33

Readme.txt

RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.1.85
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.4
RtkCoLDR64.d11	: 1.0.0.1
RtkXInterface.d11	: 1.0.0.13
RtkXInterface64.d11	: 1.0.0.13
RtlCPAPI.d11	: 1.0.2.6
RtlCPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.320
SEAPO64.d11	: 2.0.5.4
SECOMN32.d11	: 2.0.5.4
SECOMN64.d11	: 2.0.5.4
SEHDRA64.d11	: 2.0.5.4
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.6.0.7270
sl3apo64.d11	: 3.1.38.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.1.38.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1
sltech64.d11	: 3.1.38.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.24.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRAPO64.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRCOM64.d11	: 4.0.0.59
SRRPTR64.d11	: 4.0.0.59
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.2.2.0
tepeqapo64.d11	: 1.1.0.0
ToastD1164.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tosasfapo64.d11	: 2.0.4.0
toseaeapo64.d11	: 2.0.4.0
tossaeapo64.d11	: 2.0.4.0

Readme.txt

tossaemaxapo64.d11 : 1.0.0.0
WavesGUILib64.d11 : 4.4.5.0
WhiteJadeSkinImages64.d11 : 1.0.478.0
YamahaAE.d11 : 1.1.3.0
YamahaAE2.d11 : 4.0.0.0
RCORES64.dat : 1.5.6.6

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys : 5.10.0.6519
Rtaupd.exe : 2.8.0.5
RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.d11 : 1.1.5.1

Vista, Win7, Win8 x86 :

RtHDMIV.sys : 6.0.1.6650
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.6
R4EEA32H.d11 : 7.2.8000.13
R4EED32H.d11 : 7.2.8000.13
R4EEG32H.d11 : 7.2.8000.13
R4EEL32H.d11 : 7.2.8000.13
R4EEP32H.d11 : 7.2.8000.13
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :

RtHDMIVX.sys : 6.0.1.6650
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.6
R4EEA64H.d11 : 7.2.8000.13
R4EED64H.d11 : 7.2.8000.13
R4EEG64H.d11 : 7.2.8000.13
R4EEL64H.d11 : 7.2.8000.13
R4EEP64H.d11 : 7.2.8000.13
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDMEx64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 4.24

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.77

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8, Windows 8.1, Windows 10 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
 ALC899, ALC861VD, ALC891, ALC900
 ALC660, ALC662, ALC663, ALC665, ALC667, ALC668, ALC670, ALC671,
 ALC672, ALC676, ALC680
 ALC221, ALC231, ALC233, ALC235, ALC236, ALC255, ALC256, ALC260,
 ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280,
 ALC282, ALC283, ALC284, ALC286, ALC288, ALC290, ALC292, ALC293, ALC298, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
 ALC892, ALC899, ALC861VC, ALC861VD, ALC891, ALC900
 ALC660, ALC662, ALC663, ALC665, ALC667, ALC668, ALC670, ALC671,
 ALC672, ALC676, ALC680
 ALC221, ALC231, ALC233, ALC235, ALC236, ALC255, ALC256, ALC260,
 ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280,
 ALC282, ALC283, ALC284, ALC286, ALC290, ALC292, ALC293, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
 Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1, Windows 10 –
 x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.
2. Support Windows 10

Windows 2000/XP : _____

Vista, Win7, Win8, Win8.1, Win10 driver for x86

RTKVHDA.sys	: 6.0.1.7503
AERTSrv.exe	: 1.0.32.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent.exe	: 1.1.0.0
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.5
MaxxAudioMeters.exe	: 4.1.6.0
RtHDVBg.exe	: 1.0.0.220
RtHDVCpl.exe	: 1.0.0.965
RtkAudioService.exe	: 1.0.0.64
RtkNGUI.exe	: 1.0.476.0
RtlUpd.exe	: 3.0.0.0
vncutil.exe	: 1.0.0.45
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.42
AERTACap.dll	: 2.10.32.0

Readme.txt

AERTARen.d11	: 1.0.32.11
BlackBlueSkinImages.d11	: 1.0.476.0
BlackSkinImages.d11	: 1.0.476.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
CX32APO.d11	: 1.25.0.0
DarkSkinImages.d11	: 1.0.476.0
DDPA32.d11	: 7.6.5.1
DDPD32A.d11	: 7.6.5.1
DDPO32A.d11	: 7.6.5.1
DDPP32A.d11	: 7.6.5.1
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.3
DTS GFXAPONS.d11	: 1.0.0.3
DTS LFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSU2PGFX32.d11	: 2.1.1.0
DTSU2PLFX32.d11	: 2.1.1.0
DTSU2PREC32.d11	: 2.1.1.0
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 70.5.1.66
GrayJadeSkinImages.d11	: 1.0.476.0
ICESoundAPO.d11	: 1.0.0.15
KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO40.d11	: 4.5.5.0
MaxxAudioAPO50.d11	: 5.6.0.0
MaxxAudioAPO60.d11	: 6.1.6.0
MaxxAudioAPO70.d11	: 7.0.10.0
MaxxAudioAPOShell.d11	: 4.10.8.0
MaxxAudioEQ.d11	: 4.1.1.0
MaxxAudioRealtek.d11	: 4.4.10.0
MaxxAudioVienna2.d11	: 1.0.7.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxVoiceAPO20.d11	: 2.6.0.0
MaxxVoiceAPO30.d11	: 3.1.7.0
MaxxVoiceAPO40.d11	: 4.0.8.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.81
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBWrp32.d11	: 1.0.0.270
MISS_APO.d11	: 1.5.0.16020
NAHIMICAPO1fx.d11	: 6.3.9600.17231
NahimicAPONSControl.d11	: 1.0.0.14866
NAHIMICV2apo.d11	: 6.3.9600.16384

Readme.txt

OrangeBlackSkinImages.d11	: 1.0.476.0
PremiumBlackSkinImages.d11	: 1.0.476.0
R4EEA32A.d11	: 7.2.8000.17
R4EED32A.d11	: 7.2.8000.17
R4EEG32A.d11	: 7.2.8000.17
R4EEL32A.d11	: 7.2.8000.17
R4EEP32A.d11	: 7.2.8000.17
R1tkAPO.d11	: 11.0.6000.423
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.168
RtDataProc.d11	: 1.0.0.14
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkApoApi.d11	: 1.0.1.85
RtkCfg.d11	: 1.0.0.4
RtkCoInstII.d11	: 2.2.4.6
RtkCoLDR.d11	: 1.0.0.1
RtkPgExt.d11	: 6.0.6000.319
RtkXInterface.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
SEAPO32.d11	: 2.0.5.2
SECOMN32.d11	: 2.0.5.2
SEHDRA32.d11	: 2.0.5.2
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.1.38.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.1.38.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.1.38.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRAPO.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRRPTR.d11	: 4.0.0.59
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0

Readme.txt

SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.2.0
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tossaemaxapo32.d11	: 1.0.0.0
WavesGUILib.d11	: 4.4.5.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.476.0
RCORES.dat	: 1.5.6.6
Vista, Win7, Win8, Win8.1, Win10 driver for x64	
RTKVHD64.sys	: 6.0.1.7503
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent64.exe	: 1.1.0.0
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.1.0
FMAPP.exe	: 1.64.0.5
MaxxAudioMeters64.exe	: 4.1.6.0
RAVBg64.exe	: 1.0.0.220
RAVCp164.exe	: 1.0.0.965
RtkAudioService64.exe	: 1.0.0.64
RtkNGUI64.exe	: 1.0.476.0
RtlUpd64.exe	: 3.0.0.0
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.42
AERTAC64.d11	: 2.10.64.0
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.476.0
BlackSkinImages64.d11	: 1.0.476.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
CX32APO.d11	: 1.25.0.0
CX64APO.d11	: 1.25.0.0
DarkSkinImages64.d11	: 1.0.476.0
DDPA64.d11	: 7.6.5.1
DDPA64F3.d11	: 7.6.7.1
DDPD64A.d11	: 7.6.5.1
DDPD64AF3.d11	: 7.6.7.1
DDPO64A.d11	: 7.6.5.1
DDPO64AF3.d11	: 7.6.7.1
DDPP64A.d11	: 7.6.5.1
DDPP64AF3.d11	: 7.6.7.1
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1

Readme.txt

DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSU2PGFX64.d11 : 2.1.1.0
 DTSU2PLFX64.d11 : 2.1.1.0
 DTSU2PREC64.d11 : 2.1.1.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO32.d11 : 50.5.4.68
 FMAPO64.d11 : 70.6.1.66
 GrayJadeSkinImages64.d11 : 1.0.476.0
 ICEsoundAPO64.d11 : 1.0.0.15
 KAAPORT64.d11 : 4.1105.6000.53
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO4064.d11 : 4.5.5.0
 MaxxAudioAPO5064.d11 : 5.6.0.0
 MaxxAudioAPO6064.d11 : 6.1.6.0
 MaxxAudioAPO7064.d11 : 7.0.10.0
 MaxxAudioAPOShe1164.d11 : 4.10.8.0
 MaxxAudioEQ64.d11 : 4.1.1.0
 MaxxAudioRealtek64.d11 : 4.4.10.0
 MaxxAudioVienna264.d11 : 1.0.7.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxSpeechAPO64.d11 : 1.1.4.0
 MaxxVoiceAPO2064.d11 : 2.6.0.0
 MaxxVoiceAPO30.d11 : 3.1.7.0
 MaxxVoiceAPO3064.d11 : 3.1.7.0
 MaxxVoiceAPO4064.d11 : 4.0.8.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.81
 MBAPO264.d11 : 1.2.16.81
 MBAPO32.d11 : 1.0.62.0
 MBAPO64.d11 : 1.0.62.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBTHX64.d11 : 1.0.15.175
 MBWrp64.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAPO1fx.d11 : 6.3.9600.17231
 NahimicAPONSControl.d11 : 1.0.0.14866
 NAHIMICV2apo.d11 : 6.3.9600.16384
 OrangeBlackSkinImages64.d11 : 1.0.476.0
 PremiumBlackSkinImages64.d11 : 1.0.476.0
 R4EEA64A.d11 : 7.2.8000.17
 R4EED64A.d11 : 7.2.8000.17
 R4EEG64A.d11 : 7.2.8000.17
 R4EEL64A.d11 : 7.2.8000.17
 R4EEP64A.d11 : 7.2.8000.17
 RCoInstII64.d11 : 2.2.4.6
 R1tkAPO.d11 : 11.0.6000.423
 R1tkAPO64.d11 : 11.0.6000.423
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.168
 RTCOMDLL.d11 : 2.0.0.168

Readme.txt

RtDataProc.d11	: 1.0.0.14
RtDataProc64.d11	: 1.0.0.14
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.1.85
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.4
RtkCoLDR64.d11	: 1.0.0.1
RtkXInterface.d11	: 1.0.0.13
RtkXInterface64.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
Rt1CPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.319
SEAPO64.d11	: 2.0.5.2
SECOMN32.d11	: 2.0.5.2
SECOMN64.d11	: 2.0.5.2
SEHDRA64.d11	: 2.0.5.2
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.6.0.7270
sl3apo64.d11	: 3.1.38.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.1.38.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1
sltech64.d11	: 3.1.38.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.24.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRAPO64.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRCOM64.d11	: 4.0.0.59
SRPTR64.d11	: 4.0.0.59
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.2.2.0
tepeqapo64.d11	: 1.1.0.0

Readme.txt

ToastD1164.d11 : 1.0.0.2
 tosade.d11 : 1.0.1.12
 tosasfapo64.d11 : 2.0.4.0
 toseaeapo64.d11 : 2.0.4.0
 tossaeapo64.d11 : 2.0.4.0
 tossaemaxapo64.d11 : 1.0.0.0
 WavesGUILib64.d11 : 4.4.5.0
 WhiteJadeSkinImages64.d11 : 1.0.476.0
 YamahaAE.d11 : 1.1.3.0
 YamahaAE2.d11 : 4.0.0.0
 RCORES64.dat : 1.5.6.6

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys : 5.10.0.6519
 Rtaupd.exe : 2.8.0.5
 RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys : 5.10.0.6519
 Rtaupd64.exe : 2.8.0.5
 RHCoInst64XP.d11 : 1.1.5.1

Vista, Win7, Win8 x86 :

RtHDMIV.sys : 6.0.1.6650
 RtkAudioSrvATI.exe : 1.0.0.23
 RtkUpd.exe : 2.8.0.6
 R4EEA32H.d11 : 7.2.8000.13
 R4EED32H.d11 : 7.2.8000.13
 R4EEG32H.d11 : 7.2.8000.13
 R4EEL32H.d11 : 7.2.8000.13
 R4EEP32H.d11 : 7.2.8000.13
 RH3DAA32.d11 : 6.0.6001.18
 RH3DHT32.d11 : 6.0.6001.18
 RHCoInst.d11 : 1.1.5.1
 RHDMIExt.d11 : 6.0.6000.228
 RTEED32H.d11 : 6.1.6001.33
 RTEEG32H.d11 : 6.1.6001.33
 RTEEL32H.d11 : 6.1.6001.33
 RTEEP32H.d11 : 6.1.6001.33
 RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :

RtHDMIVX.sys : 6.0.1.6650
 RtkAudioSrvATI64.exe : 1.0.0.23
 RtkUpd64.exe : 2.8.0.6
 R4EEA64H.d11 : 7.2.8000.13
 R4EED64H.d11 : 7.2.8000.13
 R4EEG64H.d11 : 7.2.8000.13
 R4EEL64H.d11 : 7.2.8000.13
 R4EEP64H.d11 : 7.2.8000.13
 RH3DAA64.d11 : 6.0.6001.18
 RH3DHT64.d11 : 6.0.6001.18
 RHCoInst64.d11 : 1.1.5.1
 RHDMEx64.d11 : 6.0.6000.228
 RTEED64H.d11 : 6.1.6001.33

Readme.txt

RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 4.24

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.76

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8, Windows 8.1 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC891, ALC900

ALC660, ALC662, ALC663, ALC665, ALC667, ALC668, ALC670, ALC671,
ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC236, ALC255, ALC256, ALC260,
ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280,
ALC282, ALC283, ALC284, ALC286, ALC288, ALC290, ALC292, ALC293, ALC298, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC, ALC861VD, ALC891, ALC900

ALC660, ALC662, ALC663, ALC665, ALC667, ALC668, ALC670, ALC671,
ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC236, ALC255, ALC256, ALC260,
ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280,
ALC282, ALC283, ALC284, ALC286, ALC290, ALC292, ALC293, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

2. Add Codec ALC667, ALC256, ALC236, ALC293

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.7111

RTKHDAUD.sys : 5.10.0.7111

Alcmtr.exe : 1.6.0.4

AlcWzrd.exe : 1.1.0.37

MicCal.exe : 1.1.2.4

RTHDCPL.exe : 2.4.2.2

RtkAudioService.exe : 1.0.0.19

RtkAudioService64.exe : 1.0.0.19

RTLCPLEX.exe : 1.0.1.66

RtlUpd.exe : 2.9.0.1

RtlUpd64.exe : 2.9.0.1

SoundMan.exe : 1.0.0.32

vncutil.exe : 1.0.0.38

Readme.txt

vncutil64.exe : 1.0.0.38
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Monfilt.sys : 5.10.0.4112
Monft64.sys : 5.10.0.4115
OAO17Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.9
RCoInstII64XP.d11 : 2.1.6.3
RTCOMDLL.d11 : 1.0.0.116
RtkCoInstIIXP.d11 : 2.1.6.3
RtkCoLDR64XP.d11 : 1.0.0.1
RtkCoLDRXP.d11 : 1.0.0.1
RtlCPAPI.d11 : 1.0.2.6

Vista, Win7, Win8, Win8.1 driver :

Vista, Win7, Win8, Win8.1 driver for x86
RTKVHDA.sys : 6.0.1.7487
AERTSrv.exe : 1.0.32.10
CreateRtkToastLnk.exe : 1.0.0.1
CXAPOAgent.exe : 1.1.0.0
DTSAudioService.exe : 1.0.0.0
DTSU2PAuSrv32.exe : 2.1.1.0
FMAPP.exe : 1.32.0.5
MaxxAudioMeters.exe : 4.1.6.0
RtHDVBg.exe : 1.0.0.218
RtHDVCpl.exe : 1.0.0.965
RtkAudioService.exe : 1.0.0.62
RtkNGUI.exe : 1.0.469.1
RtlUpd.exe : 2.9.0.8
vncutil.exe : 1.0.0.45
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.42
AERTACap.d11 : 2.10.32.0
AERTARen.d11 : 1.0.32.11
BlackBlueSkinImages.d11 : 1.0.469.1
BlackSkinImages.d11 : 1.0.469.1
CONEQMSAPO.d11 : 1.0.0.19
CONEQMSAPOGUILibrary.d11 : 1.0.0.4
CX32APO.d11 : 1.25.0.0
DarkSkinImages.d11 : 1.0.469.1
DDPA32.d11 : 7.6.5.1
DDPD32A.d11 : 7.6.5.1
DDPO32A.d11 : 7.6.5.1
DDPP32A.d11 : 7.6.5.1
DTSBassEnhancementDLL.d11 : 1.0.0.1
DTSBoostDLL.d11 : 1.0.0.1
DTSGainCompensatorDLL.d11 : 1.0.0.1
DTSGFXAPO.d11 : 1.0.0.3
DTSGFXAPONS.d11 : 1.0.0.3
DTSLFXAPO.d11 : 1.0.0.3
DTSLimiterDLL.d11 : 1.0.0.1
DTSSNeoPCDLL.d11 : 1.0.0.1
DTSS2HeadphoneDLL.d11 : 1.0.0.1
DTSS2SpeakerDLL.d11 : 1.0.0.1

Readme.txt

DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.1.1.0
 DTSU2PLFX32.d11 : 2.1.1.0
 DTSU2PREC32.d11 : 2.1.1.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 70.5.1.66
 GrayJadeSkinImages.d11 : 1.0.469.1
 ICESoundAPO.d11 : 1.0.0.14
 KAAPORT.d11 : 4.1105.6000.53
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO40.d11 : 4.5.5.0
 MaxxAudioAPO50.d11 : 5.6.0.0
 MaxxAudioAPO60.d11 : 6.1.6.0
 MaxxAudioAPO70.d11 : 7.0.10.0
 MaxxAudioAPOShell.d11 : 4.10.8.0
 MaxxAudioEQ.d11 : 4.1.1.0
 MaxxAudioRealtek.d11 : 4.4.10.0
 MaxxAudioVienna2.d11 : 1.0.7.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxVoiceAPO20.d11 : 2.6.0.0
 MaxxVoiceAPO30.d11 : 3.1.7.0
 MaxxVoiceAPO40.d11 : 4.0.8.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.79
 MBAPO32.d11 : 1.0.62.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBWrp32.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAP01fx.d11 : 6.3.9600.17231
 NahimicAPONSControl.d11 : 1.0.0.14866
 NAHIMICV2apo.d11 : 6.3.9600.16384
 OrangeBlackSkinImages.d11 : 1.0.469.1
 PremiumBlackSkinImages.d11 : 1.0.469.1
 R4EEA32A.d11 : 7.2.8000.17
 R4EED32A.d11 : 7.2.8000.17
 R4EEG32A.d11 : 7.2.8000.17
 R4EEL32A.d11 : 7.2.8000.17
 R4EEP32A.d11 : 7.2.8000.17
 R1tkAPO.d11 : 11.0.6000.422
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.167
 RtDataProc.d11 : 1.0.0.14
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkApoApi.d11 : 1.0.1.85
 RtkCfg.d11 : 1.0.0.4
 RtkCoInstII.d11 : 2.2.4.0
 RtkCoLDR.d11 : 1.0.0.1
 RtkPgExt.d11 : 6.0.6000.319

Readme.txt

RtkXInterface.d11	: 1.0.0.13
RtlCPAPI.d11	: 1.0.2.6
SEAPO32.d11	: 2.0.5.2
SECOMN32.d11	: 2.0.5.2
SEHDRA32.d11	: 2.0.5.2
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.1.38.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.1.38.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.1.38.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRAPO.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRRPTR.d11	: 4.0.0.59
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.2.0
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tossaemaxapo32.d11	: 1.0.0.0
WavesGUILib.d11	: 4.4.5.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.469.1
RCORES.dat	: 1.5.6.6
Vista, Win7, Win8, Win8.1 driver for x64	
RTKVHD64.sys	: 6.0.1.7487
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
CXAPOAgent64.exe	: 1.1.0.0
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.1.0
FMAPP.exe	: 1.64.0.5

Readme.txt

MaxxAudioMeters64.exe	: 4.1.6.0
RAVBg64.exe	: 1.0.0.218
RAVCp164.exe	: 1.0.0.965
RtkAudioService64.exe	: 1.0.0.62
RtkNGUI64.exe	: 1.0.469.1
RtlUpd64.exe	: 2.9.0.8
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.42
AERTAC64.d11	: 2.10.64.0
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.469.1
BlackSkinImages64.d11	: 1.0.469.1
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
CX32APO.d11	: 1.25.0.0
CX64APO.d11	: 1.25.0.0
DarkSkinImages64.d11	: 1.0.469.1
DDPA64.d11	: 7.6.5.1
DDPA64F3.d11	: 7.6.7.1
DDPD64A.d11	: 7.6.5.1
DDPD64AF3.d11	: 7.6.7.1
DDPO64A.d11	: 7.6.5.1
DDPO64AF3.d11	: 7.6.7.1
DDPP64A.d11	: 7.6.5.1
DDPP64AF3.d11	: 7.6.7.1
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTS S2HeadphoneDLL64.d11	: 1.0.0.1
DTS S2SpeakerDLL64.d11	: 1.0.0.1
DTS SymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.1.1.0
DTSU2PLFX64.d11	: 2.1.1.0
DTSU2PREC64.d11	: 2.1.1.0
DTS VoiceClarityDLL64.d11	: 1.0.0.1
FMAPO32.d11	: 50.5.4.68
FMAPO64.d11	: 70.6.1.66
GrayJadeSkinImages64.d11	: 1.0.469.1
ICESoundAPO64.d11	: 1.0.0.14
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO4064.d11	: 4.5.5.0
MaxxAudioAPO5064.d11	: 5.6.0.0
MaxxAudioAPO6064.d11	: 6.1.6.0
MaxxAudioAPO7064.d11	: 7.0.10.0
MaxxAudioAPOShell64.d11	: 4.10.8.0
MaxxAudioEQ64.d11	: 4.1.1.0
MaxxAudioRealtek64.d11	: 4.4.10.0

Readme.txt

MaxxAudioVienna264.d11	: 1.0.7.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxSpeechAPO64.d11	: 1.1.4.0
MaxxVoiceAPO2064.d11	: 2.6.0.0
MaxxVoiceAPO30.d11	: 3.1.7.0
MaxxVoiceAPO3064.d11	: 3.1.7.0
MaxxVoiceAPO4064.d11	: 4.0.8.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.79
MBAPO264.d11	: 1.2.16.79
MBAPO32.d11	: 1.0.62.0
MBAPO64.d11	: 1.0.62.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBTHX64.d11	: 1.0.15.175
MBWrp64.d11	: 1.0.0.270
MISS_APO.d11	: 1.5.0.16020
NAHIMICAP01fx.d11	: 6.3.9600.17231
NahimicAPONSControl.d11	: 1.0.0.14866
NAHIMICV2apo.d11	: 6.3.9600.16384
OrangeBlackSkinImages64.d11	: 1.0.469.1
PremiumBlackSkinImages64.d11	: 1.0.469.1
R4EEA64A.d11	: 7.2.8000.17
R4EED64A.d11	: 7.2.8000.17
R4EEG64A.d11	: 7.2.8000.17
R4EEL64A.d11	: 7.2.8000.17
R4EEP64A.d11	: 7.2.8000.17
RCoInstII64.d11	: 2.2.4.0
R1tkAPO.d11	: 11.0.6000.422
R1tkAPO64.d11	: 11.0.6000.422
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.167
RTCOMDLL.d11	: 2.0.0.167
RtDataProc.d11	: 1.0.0.14
RtDataProc64.d11	: 1.0.0.14
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.1.85
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.4
RtkCoLDR64.d11	: 1.0.0.1
RtkXInterface.d11	: 1.0.0.13
RtkXInterface64.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
Rt1CPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.319
SEAPO64.d11	: 2.0.5.2
SECOMN32.d11	: 2.0.5.2
SECOMN64.d11	: 2.0.5.2
SEHDRA64.d11	: 2.0.5.2
SFAP064.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11

Readme.txt

SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.6.0.7270
sl3apo64.d11	: 3.1.38.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.1.38.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1
sltech64.d11	: 3.1.38.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.24.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRAPO64.d11	: 4.0.0.59
SRCOM.d11	: 4.0.0.59
SRCOM64.d11	: 4.0.0.59
SRRPTR64.d11	: 4.0.0.59
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.2.2.0
tepeqapo64.d11	: 1.1.0.0
ToastD1164.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tosasfapo64.d11	: 2.0.4.0
toseaeapo64.d11	: 2.0.4.0
tossaeapo64.d11	: 2.0.4.0
tossaemaxapo64.d11	: 1.0.0.0
WavesGUILib64.d11	: 4.4.5.0
WhiteJadeSkinImages64.d11	: 1.0.469.1
YamahaAE.d11	: 1.1.3.0
YamahaAE2.d11	: 3.2.0.0
RCORES64.dat	: 1.5.6.6

HDMI Driver :

Windows 2000/XP x86 :	
RtkHDMI.sys	: 5.10.0.6519
Rtaupd.exe	: 2.8.0.5
RHCoInstXP.d11	: 1.1.5.1
Windows XP x64 :	
RtkHDMIX.sys	: 5.10.0.6519
Rtaupd64.exe	: 2.8.0.5

Readme.txt

RHCoInst64XP.d11 : 1.1.5.1

Vista, Win7, Win8 x86 :

RtHDMIV.sys : 6.0.1.6650

RtkAudioSrvATI.exe : 1.0.0.23

RtkUpd.exe : 2.8.0.6

R4EEA32H.d11 : 7.2.8000.13

R4EED32H.d11 : 7.2.8000.13

R4EEG32H.d11 : 7.2.8000.13

R4EEL32H.d11 : 7.2.8000.13

R4EEP32H.d11 : 7.2.8000.13

RH3DAA32.d11 : 6.0.6001.18

RH3DHT32.d11 : 6.0.6001.18

RHCoInst.d11 : 1.1.5.1

RHDMIExt.d11 : 6.0.6000.228

RTEED32H.d11 : 6.1.6001.33

RTEEG32H.d11 : 6.1.6001.33

RTEEL32H.d11 : 6.1.6001.33

RTEEP32H.d11 : 6.1.6001.33

RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :

RtHDMIVX.sys : 6.0.1.6650

RtkAudioSrvATI64.exe : 1.0.0.23

RtkUpd64.exe : 2.8.0.6

R4EEA64H.d11 : 7.2.8000.13

R4EED64H.d11 : 7.2.8000.13

R4EEG64H.d11 : 7.2.8000.13

R4EEL64H.d11 : 7.2.8000.13

R4EEP64H.d11 : 7.2.8000.13

RH3DAA64.d11 : 6.0.6001.18

RH3DHT64.d11 : 6.0.6001.18

RHCoInst64.d11 : 1.1.5.1

RHDMEx64.d11 : 6.0.6000.228

RTEED64H.d11 : 6.1.6001.33

RTEEG64H.d11 : 6.1.6001.33

RTEEL64H.d11 : 6.1.6001.33

RTEEP64H.d11 : 6.1.6001.33

RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 4.23

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.75

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8, Windows 8.1 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC867, ALC900

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672,
ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC255, ALC260, ALC262, ALC267,

Readme.txt

ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283, ALC284, ALC286, ALC288, ALC290, ALC292, ALC298, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC867, ALC900

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC255, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283, ALC284, ALC286, ALC290, ALC292, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.7111
RTKHDAUD.sys	: 5.10.0.7111
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.2.2
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.9.0.1
RtlUpd64.exe	: 2.9.0.1
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.9
RCoInstII64XP.d11	: 2.1.6.3
RTCOMDLL.d11	: 1.0.0.116
RtkCoInstII64XP.d11	: 2.1.6.3
RtkCoLDR64XP.d11	: 1.0.0.1
RtkCoLDRXP.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.6

Vista, Win7, Win8, Win8.1 driver :

Vista, Win7, Win8, Win8.1 driver for x86	
RTKVHDA.sys	: 6.0.1.7246
AERTSrv.exe	: 1.0.32.10
CreateRtkToastLnk.exe	: 1.0.0.1
DTSAudioService.exe	: 1.0.0.0

Readme.txt

DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.3
MaxxAudioControl.exe	: 3.14.1.0
MaxxAudioMeters.exe	: 4.1.6.0
RtHDVBg.exe	: 1.0.0.193
RtHDVCpl.exe	: 1.0.0.927
RtkAudioService.exe	: 1.0.0.55
RtkNGUI.exe	: 1.0.378.0
RtlUpd.exe	: 2.9.0.1
vncutil.exe	: 1.0.0.45
WavesSvc.exe	: 1.4.9.0
WavesSysSvc.exe	: 1.1.0.0
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.38
AERTACap.d11	: 2.9.32.0
AERTARen.d11	: 1.0.32.11
BlackBlueSkinImages.d11	: 1.0.378.0
BlackSkinImages.d11	: 1.0.378.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
DarkSkinImages.d11	: 1.0.378.0
DDPA32.d11	: 7.6.3.1
DDPD32A.d11	: 7.6.3.1
DDPO32A.d11	: 7.6.3.1
DDPP32A.d11	: 7.6.3.1
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.3
DTS GFXAPONS.d11	: 1.0.0.3
DTS LFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSU2PGFX32.d11	: 2.1.1.0
DTSU2PLFX32.d11	: 2.1.1.0
DTSU2PREC32.d11	: 2.1.1.0
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 50.5.5.66
GrayJadeSkinImages.d11	: 1.0.378.0
ICESoundAPO.d11	: 1.0.0.4
KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO40.d11	: 4.5.5.0
MaxxAudioAPO50.d11	: 5.5.1.0
MaxxAudioAPO60.d11	: 6.0.15.0
MaxxAudioAPOShell.d11	: 4.15.0.0
MaxxAudioEQ.d11	: 4.1.1.0
MaxxAudioRealtek.d11	: 4.5.7.0
MaxxAudioRealtek2.d11	: 5.2.21.0
MaxxAudioRealtek3.d11	: 1.6.12.0
MaxxAudioVienna2.d11	: 1.0.7.0

Readme.txt

MaxxAudioVnA.d11	: 1.7.11.0
MaxxAudioVnN.d11	: 1.4.5.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxVoiceAPO20.d11	: 2.5.0.0
MaxxVoiceAPO30.d11	: 3.0.15.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.62
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBWrp32.d11	: 1.0.0.270
MISS_APO.d11	: 1.5.0.16020
NAHIMICAPO1fx.d11	: 6.3.9600.16384
NAHIMICAPOSettingsIPC.d11	: 1.0.0.14866
OrangeBlackSkinImages.d11	: 1.0.378.0
PremiumBlackSkinImages.d11	: 1.0.378.0
R4EEA32A.d11	: 7.2.8000.17
R4EED32A.d11	: 7.2.8000.17
R4EEG32A.d11	: 7.2.8000.17
R4EEL32A.d11	: 7.2.8000.17
R4EEP32A.d11	: 7.2.8000.17
R1tkAPO.d11	: 11.0.6000.373
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.160
RtDataProc.d11	: 1.0.0.12
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkApoApi.d11	: 1.0.0.77
RtkCfg.d11	: 1.0.0.2
RtkCoInstII.d11	: 2.1.9.1
RtkCoLDR.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.6
RtkPgExt.d11	: 6.0.6000.305
RtkXInterface.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.1.23.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.1.23.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0

Readme.txt

slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.1.23.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRAPO.d11	: 4.0.0.54
SRCOM.d11	: 4.0.0.54
SRRPTR.d11	: 4.0.0.54
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.1.0
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 4.4.5.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.378.0
RCORES.dat	: 1.5.0.3
Vista, Win7, Win8, Win8.1 driver for x64	
RTKVHD64.sys	: 6.0.1.7246
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.1.0
FMAPP.exe	: 1.64.0.3
MaxxAudioControl64.exe	: 3.14.1.0
MaxxAudioMeters64.exe	: 4.1.6.0
RAVBg64.exe	: 1.0.0.193
RAVCp164.exe	: 1.0.0.927
RtHDVBg.exe	: 1.0.0.190
RtkAudioService64.exe	: 1.0.0.55
RtkNGUI64.exe	: 1.0.378.0
RtlUpd64.exe	: 2.9.0.1
vncutil64.exe	: 1.0.0.45
WavesSvc.exe	: 1.1.4.0
WavesSvc64.exe	: 1.4.9.0
WavesSysSvc64.exe	: 1.1.0.0
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.38
AERTAC64.d11	: 2.9.64.0
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.378.0
BlackSkinImages64.d11	: 1.0.378.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
DarkSkinImages64.d11	: 1.0.378.0
DDPA64.d11	: 7.6.3.1
DDPD64A.d11	: 7.6.3.1

Readme.txt

DDPO64A.d11 : 7.6.3.1
 DDPP64A.d11 : 7.6.3.1
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSU2PGFX64.d11 : 2.1.1.0
 DTSU2PLFX64.d11 : 2.1.1.0
 DTSU2PREC64.d11 : 2.1.1.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO32.d11 : 50.5.4.68
 FMAPO64.d11 : 50.6.5.66
 GrayJadeSkinImages64.d11 : 1.0.378.0
 ICESoundAPO64.d11 : 1.0.0.4
 KAAPORT64.d11 : 4.1105.6000.53
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO4064.d11 : 4.5.5.0
 MaxxAudioAPO5064.d11 : 5.5.1.0
 MaxxAudioAPO6064.d11 : 6.0.15.0
 MaxxAudioAPOShell.d11 : 4.15.0.0
 MaxxAudioAPOShell64.d11 : 4.15.0.0
 MaxxAudioEQ64.d11 : 4.1.1.0
 MaxxAudioRealtek264.d11 : 5.2.21.0
 MaxxAudioRealtek364.d11 : 1.6.12.0
 MaxxAudioRealtek64.d11 : 4.5.7.0
 MaxxAudioVienna264.d11 : 1.0.7.0
 MaxxAudioVnA64.d11 : 1.7.11.0
 MaxxAudioVnN64.d11 : 1.4.5.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxSpeechAPO64.d11 : 1.1.4.0
 MaxxVoiceAPO2064.d11 : 2.5.0.0
 MaxxVoiceAPO30.d11 : 3.0.15.0
 MaxxVoiceAPO3064.d11 : 3.0.15.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.62
 MBAPO264.d11 : 1.2.16.62
 MBAPO32.d11 : 1.0.62.0
 MBAPO64.d11 : 1.0.62.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBTHX64.d11 : 1.0.15.175
 MBWrp64.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAPO1fx.d11 : 6.3.9600.16384
 NAHIMICAPOSettingsIPC.d11 : 1.0.0.14866
 OrangeBlackSkinImages64.d11 : 1.0.378.0
 PremiumBlackSkinImages64.d11 : 1.0.378.0

Readme.txt

R4EEA64A.d11	: 7.2.8000.17
R4EED64A.d11	: 7.2.8000.17
R4EEG64A.d11	: 7.2.8000.17
R4EEL64A.d11	: 7.2.8000.17
R4EEP64A.d11	: 7.2.8000.17
RCoInstII64.d11	: 2.1.9.1
R1tkAPO64.d11	: 11.0.6000.373
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.160
RTCOMDLL.d11	: 2.0.0.160
RtDataProc.d11	: 1.0.0.12
RtDataProc64.d11	: 1.0.0.12
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.77
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkCoLDR64.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.6
RtkXInterface.d11	: 1.0.0.13
RtkXInterface64.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
Rt1CPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.305
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.6.0.7270
sl3apo64.d11	: 3.1.23.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.1.23.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1
sltech64.d11	: 3.1.23.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.24.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRAPO64.d11	: 4.0.0.54
SRCOM.d11	: 4.0.0.54
SRCOM64.d11	: 4.0.0.54

Readme.txt

SRRPTR64.d11 : 4.0.0.54
SRSH64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo264.d11 : 1.2.1.0
tepeqapo64.d11 : 1.1.0.0
ToastD1164.d11 : 1.0.0.2
tosade.d11 : 1.0.1.12
tosafapo64.d11 : 2.0.4.0
toseaeapo64.d11 : 2.0.4.0
tossaeapo64.d11 : 2.0.4.0
WavesGUILib64.d11 : 4.4.5.0
WhiteJadeSkinImages64.d11 : 1.0.378.0
YamahaAE.d11 : 1.1.3.0
RCORES64.dat : 1.5.0.3

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys : 5.10.0.6519
Rtaupd.exe : 2.8.0.5
RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.d11 : 1.1.5.1

Vista, Win7, Win8 x86 :

RtHDMIV.sys : 6.0.1.6650
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.6
R4EEA32H.d11 : 7.2.8000.13
R4EED32H.d11 : 7.2.8000.13
R4EEG32H.d11 : 7.2.8000.13
R4EEL32H.d11 : 7.2.8000.13
R4EEP32H.d11 : 7.2.8000.13
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :

RtHDMIVX.sys : 6.0.1.6650
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.6
R4EEA64H.d11 : 7.2.8000.13
R4EED64H.d11 : 7.2.8000.13
R4EEG64H.d11 : 7.2.8000.13
R4EEL64H.d11 : 7.2.8000.13

Readme.txt

R4EEP64H.d11 : 7.2.8000.13
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDME64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 3.91

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.74

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8, Windows 8.1 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC867, ALC900

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672,
ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC255, ALC260, ALC262, ALC267,
ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283,
ALC284, ALC286, ALC288, ALC290, ALC292, ALC298, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC, ALC861VD, ALC867, ALC900

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672,
ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC255, ALC260, ALC262, ALC267,
ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283,
ALC284, ALC286, ALC290, ALC292, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.7111

RTKHDAUD.sys : 5.10.0.7111

Alcmtr.exe : 1.6.0.4

AlcWzrd.exe : 1.1.0.37

MicCal.exe : 1.1.2.4

RTHDCPL.exe : 2.4.2.2

RtkAudioService.exe : 1.0.0.19

RtkAudioService64.exe : 1.0.0.19

Readme.txt

RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.9.0.1
RtlUpd64.exe	: 2.9.0.1
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.9
RCoInstII64XP.d11	: 2.1.6.3
RTCOMDLL.d11	: 1.0.0.116
RtkCoInstIIXP.d11	: 2.1.6.3
RtkCoLDR64XP.d11	: 1.0.0.1
RtkCoLDRXP.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.6

Vista, Win7, Win8, Win8.1 driver :

Vista, Win7, Win8, Win8.1 driver for x86	
RTKVHDA.sys	: 6.0.1.7240
AERTSrv.exe	: 1.0.32.10
CreateRtkToastLnk.exe	: 1.0.0.1
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.3
MaxxAudioControl.exe	: 3.14.1.0
MaxxAudioMeters.exe	: 4.1.6.0
RtHDVBg.exe	: 1.0.0.192
RtHDVCpl.exe	: 1.0.0.926
RtkAudioService.exe	: 1.0.0.55
RtkNGUI.exe	: 1.0.375.0
RtlUpd.exe	: 2.9.0.1
vncutil.exe	: 1.0.0.45
WavesSvc.exe	: 1.4.9.0
WavesSysSvc.exe	: 1.1.0.0
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.38
AERTACap.d11	: 2.9.32.0
AERTARen.d11	: 1.0.32.11
BlackBlueSkinImages.d11	: 1.0.375.0
BlackSkinImages.d11	: 1.0.375.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
DarkSkinImages.d11	: 1.0.375.0
DDPA32.d11	: 7.6.3.1
DDPD32A.d11	: 7.6.3.1
DDPO32A.d11	: 7.6.3.1
DDPP32A.d11	: 7.6.3.1
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3

Readme.txt

DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.1.1.0
 DTSU2PLFX32.d11 : 2.1.1.0
 DTSU2PREC32.d11 : 2.1.1.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 50.5.5.66
 GrayJadeSkinImages.d11 : 1.0.375.0
 ICESoundAPO.d11 : 1.0.0.4
 KAAPORT.d11 : 4.1105.6000.53
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.6.0.0
 MaxxAudioAPO40.d11 : 4.5.5.0
 MaxxAudioAPO50.d11 : 5.5.1.0
 MaxxAudioAPO60.d11 : 6.0.15.0
 MaxxAudioAPOShell.d11 : 4.15.0.0
 MaxxAudioEQ.d11 : 4.1.1.0
 MaxxAudioRealtek.d11 : 4.5.7.0
 MaxxAudioRealtek2.d11 : 5.2.21.0
 MaxxAudioRealtek3.d11 : 1.6.12.0
 MaxxAudioVienna2.d11 : 1.0.7.0
 MaxxAudioVnA.d11 : 1.7.11.0
 MaxxAudioVnN.d11 : 1.4.5.0
 MaxxSpeechAPO.d11 : 1.1.4.0
 MaxxVoiceAPO20.d11 : 2.5.0.0
 MaxxVoiceAPO30.d11 : 3.0.15.0
 MaxxVolumeSDAPO.d11 : 3.6.0.0
 MBAPO232.d11 : 1.2.16.60
 MBAPO32.d11 : 1.0.62.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.175
 MBWrp32.d11 : 1.0.0.270
 MISS_APO.d11 : 1.5.0.16020
 NAHIMICAPO1fx.d11 : 6.3.9600.16384
 NAHIMICAPOSettingsIPC.d11 : 1.0.0.14866
 PremiumBlackSkinImages.d11 : 1.0.375.0
 R4EEA32A.d11 : 7.2.8000.17
 R4EED32A.d11 : 7.2.8000.17
 R4EEG32A.d11 : 7.2.8000.17
 R4EEL32A.d11 : 7.2.8000.17
 R4EEP32A.d11 : 7.2.8000.17
 R1tkAPO.d11 : 11.0.6000.373
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.160
 RtDataProc.d11 : 1.0.0.11
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33

Readme.txt

RtkApoApi.d11	: 1.0.0.77
RtkCfg.d11	: 1.0.0.2
RtkCoInstII.d11	: 2.1.9.1
RtkCoLDR.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.6
RtkPgExt.d11	: 6.0.6000.305
RtkXInterface.d11	: 1.0.0.13
RtlCPAPI.d11	: 1.0.2.6
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.1.23.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.1.23.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.1.23.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRAPO.d11	: 4.0.0.54
SRCOM.d11	: 4.0.0.54
SRRPTR.d11	: 4.0.0.54
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.1.0
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 4.4.5.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.375.0
RCORES.dat	: 1.4.9.9
Vista, Win7, Win8, Win8.1 driver for x64	
RTKVHD64.sys	: 6.0.1.7240
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.1.0

Readme.txt

FMAPP.exe	: 1.64.0.3
MaxxAudioControl64.exe	: 3.14.1.0
MaxxAudioMeters64.exe	: 4.1.6.0
RAVBg64.exe	: 1.0.0.192
RAVCp164.exe	: 1.0.0.926
RtHDVBg.exe	: 1.0.0.190
RtkAudioService64.exe	: 1.0.0.55
RtkNGUI64.exe	: 1.0.375.0
RtlUpd64.exe	: 2.9.0.1
vncutil64.exe	: 1.0.0.45
WavesSvc.exe	: 1.1.4.0
WavesSvc64.exe	: 1.4.9.0
WavesSysSvc64.exe	: 1.1.0.0
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.38
AERTAC64.d11	: 2.9.64.0
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.375.0
BlackSkinImages64.d11	: 1.0.375.0
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
DarkSkinImages64.d11	: 1.0.375.0
DDPA64.d11	: 7.6.3.1
DDPD64A.d11	: 7.6.3.1
DDPO64A.d11	: 7.6.3.1
DDPP64A.d11	: 7.6.3.1
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.1.1.0
DTSU2PLFX64.d11	: 2.1.1.0
DTSU2PREC64.d11	: 2.1.1.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO32.d11	: 50.5.4.68
FMAPO64.d11	: 50.6.5.66
GrayJadeSkinImages64.d11	: 1.0.375.0
ICESoundAPO64.d11	: 1.0.0.4
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO4064.d11	: 4.5.5.0
MaxxAudioAPO5064.d11	: 5.5.1.0
MaxxAudioAPO6064.d11	: 6.0.15.0
MaxxAudioAPOShell.d11	: 4.15.0.0
MaxxAudioAPOShell64.d11	: 4.15.0.0
MaxxAudioEQ64.d11	: 4.1.1.0
MaxxAudioRealtek264.d11	: 5.2.21.0

Readme.txt

MaxxAudioRealtek364.d11	: 1.6.12.0
MaxxAudioRealtek64.d11	: 4.5.7.0
MaxxAudioVienna264.d11	: 1.0.7.0
MaxxAudioVnA64.d11	: 1.7.11.0
MaxxAudioVnN64.d11	: 1.4.5.0
MaxxSpeechAPO.d11	: 1.1.4.0
MaxxSpeechAPO64.d11	: 1.1.4.0
MaxxVoiceAPO2064.d11	: 2.5.0.0
MaxxVoiceAPO30.d11	: 3.0.15.0
MaxxVoiceAPO3064.d11	: 3.0.15.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.60
MBAPO264.d11	: 1.2.16.60
MBAPO32.d11	: 1.0.62.0
MBAPO64.d11	: 1.0.62.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBTHX64.d11	: 1.0.15.175
MBWrp64.d11	: 1.0.0.270
MISS_APO.d11	: 1.5.0.16020
NAHIMICAPO1fx.d11	: 6.3.9600.16384
NAHIMICAPOSettingsIPC.d11	: 1.0.0.14866
PremiumBlackSkinImages64.d11	: 1.0.375.0
R4EEA64A.d11	: 7.2.8000.17
R4EED64A.d11	: 7.2.8000.17
R4EEG64A.d11	: 7.2.8000.17
R4EEL64A.d11	: 7.2.8000.17
R4EEP64A.d11	: 7.2.8000.17
RCoInstII64.d11	: 2.1.9.1
R1tkAPO64.d11	: 11.0.6000.373
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.160
RTCOMDLL.d11	: 2.0.0.160
RtDataProc.d11	: 1.0.0.11
RtDataProc64.d11	: 1.0.0.11
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.77
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkCoLDR64.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.6
RtkXInterface.d11	: 1.0.0.13
RtkXInterface64.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
Rt1CPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.305
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13

Readme.txt

SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.6.0.7270
sl3apo64.d11	: 3.1.23.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.1.23.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1
sltech64.d11	: 3.1.23.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.24.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRAPO64.d11	: 4.0.0.54
SRCOM.d11	: 4.0.0.54
SRCOM64.d11	: 4.0.0.54
SRRPTR64.d11	: 4.0.0.54
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.2.1.0
tepeqapo64.d11	: 1.1.0.0
ToastD1164.d11	: 1.0.0.2
tosade.d11	: 1.0.1.12
tosafapo64.d11	: 2.0.4.0
toseaeapo64.d11	: 2.0.4.0
tossaeapo64.d11	: 2.0.4.0
WavesGUILib64.d11	: 4.4.5.0
WhiteJadeSkinImages64.d11	: 1.0.375.0
YamahaAE.d11	: 1.1.3.0
RCORES64.dat	: 1.4.9.9

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys	: 5.10.0.6519
Rtaupd.exe	: 2.8.0.5
RHCoInstXP.d11	: 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys	: 5.10.0.6519
Rtaupd64.exe	: 2.8.0.5
RHCoInst64XP.d11	: 1.1.5.1

Vista, Win7, Win8 x86 :

RtHDMIV.sys	: 6.0.1.6650
RtkAudioSrvATI.exe	: 1.0.0.23

Readme.txt

RtkUpd.exe : 2.8.0.6
R4EEA32H.d11 : 7.2.8000.13
R4EED32H.d11 : 7.2.8000.13
R4EEG32H.d11 : 7.2.8000.13
R4EEL32H.d11 : 7.2.8000.13
R4EEP32H.d11 : 7.2.8000.13
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :

RtHDMIVX.sys : 6.0.1.6650
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.6
R4EEA64H.d11 : 7.2.8000.13
R4EED64H.d11 : 7.2.8000.13
R4EEG64H.d11 : 7.2.8000.13
R4EEL64H.d11 : 7.2.8000.13
R4EEP64H.d11 : 7.2.8000.13
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDMEx64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 3.90

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.73

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8, Windows 8.1 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC867, ALC900

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672,
ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC255, ALC260, ALC262, ALC267,
ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283,
ALC284, ALC286, ALC290, ALC292, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC, ALC861VD, ALC867, ALC900

Readme.txt

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC255, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283, ALC284, ALC286 ALC290, ALC292, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.7083
RTKHDAUD.sys	: 5.10.0.7083
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.2.2
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.9.0.0
RtlUpd64.exe	: 2.9.0.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.9
RCoInstII64XP.d11	: 2.1.4.5
RTCOMDLL.d11	: 1.0.0.116
RtkCoInstIIXP.d11	: 2.1.4.5
RtkCoLDR64XP.d11	: 1.0.0.1
RtkCoLDRXP.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.6

Vista, Win7, Win8, Win8.1 driver :

Vista, Win7, Win8, Win8.1 driver for x86	
RTKVHDA.sys	: 6.0.1.7083
AERTSrv.exe	: 1.0.32.10
CreateRtkToastLnk.exe	: 1.0.0.1
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.2
MaxxAudioControl.exe	: 3.11.0.0
MaxxAudioMeters.exe	: 4.1.5.0
RtHDVbg.exe	: 1.0.0.170

Readme.txt

RtHDVCpl.exe	: 1.0.0.910
RtkAudioService.exe	: 1.0.0.52
RtkNGUI.exe	: 1.0.0.321
RtlUpd.exe	: 2.9.0.0
vncutil.exe	: 1.0.0.45
WavesSvc.exe	: 1.3.3.0
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.36
AERTACap.d11	: 2.9.32.0
AERTARen.d11	: 1.0.32.11
BlackBlueSkinImages.d11	: 1.0.0.321
BlackSkinImages.d11	: 1.0.0.321
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
DarkSkinImages.d11	: 1.0.0.321
DDPA32.d11	: 7.5.1.1
DDPD32A.d11	: 7.5.1.1
DDPO32A.d11	: 7.5.1.1
DDPP32A.d11	: 7.5.1.1
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.3
DTS GFXAPONS.d11	: 1.0.0.3
DTS LFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTS S2HeadphoneDLL.d11	: 1.0.0.1
DTS S2SpeakerDLL.d11	: 1.0.0.1
DTS SymmetryDLL.d11	: 1.0.0.1
DTS U2PGFX32.d11	: 2.1.1.0
DTS U2PLFX32.d11	: 2.1.1.0
DTS U2PREC32.d11	: 2.1.1.0
DTS VoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 50.5.4.72
GrayJadeSkinImages.d11	: 1.0.0.321
KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO40.d11	: 4.4.0.0
MaxxAudioAPO50.d11	: 5.3.1.0
MaxxAudioAPOShell.d11	: 4.12.5.0
MaxxAudioEQ.d11	: 4.1.0.0
MaxxAudioRealtek.d11	: 4.5.1.0
MaxxAudioRealtek2.d11	: 5.2.16.0
MaxxAudioRealtek3.d11	: 1.4.4.0
MaxxAudioVienna2.d11	: 1.0.7.0
MaxxAudioVnA.d11	: 1.7.2.0
MaxxAudioVnN.d11	: 1.3.1.0
MaxxSpeechAPO.d11	: 1.1.1.0
MaxxVoiceAPO20.d11	: 2.4.0.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.37
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110

Readme.txt

MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBWrp32.d11	: 1.0.0.240
MISS_APO.d11	: 1.5.0.16020
NAHIMICAP01fx.d11	: 6.3.9600.16384
NAHIMICAP0SettingsIPC.d11	: 1.0.0.14112
PremiumBlackSkinImages.d11	: 1.0.0.321
R4EEA32A.d11	: 7.2.8000.17
R4EED32A.d11	: 7.2.8000.17
R4EEG32A.d11	: 7.2.8000.17
R4EEL32A.d11	: 7.2.8000.17
R4EEP32A.d11	: 7.2.8000.17
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.158
RtDataProc.d11	: 1.0.0.3
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.347
RtkApoApi.d11	: 1.0.0.70
RtkCfg.d11	: 1.0.0.2
RtkCoInstII.d11	: 2.1.5.5
RtkCoLDR.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.6
RtkPgExt.d11	: 6.0.6000.297
RtkXInterface.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.1.10.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.1.10.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.1.10.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.24.0
slvip32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0

Readme.txt

SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.1.0
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.1
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 4.4.3.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.0.321
RCORES.dat	: 1.4.1.0
Vista, Win7, Win8, Win8.1 driver for x64	
RTKVHD64.sys	: 6.0.1.7083
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.1.0
FMAPP.exe	: 1.64.0.2
MaxxAudioControl64.exe	: 3.11.0.0
MaxxAudioMeters64.exe	: 4.1.5.0
RAVBg64.exe	: 1.0.0.170
RAVCp164.exe	: 1.0.0.910
RtHDVBg.exe	: 1.0.0.163
RtkAudioService64.exe	: 1.0.0.52
RtkNGUI64.exe	: 1.0.0.321
RtlUpd64.exe	: 2.9.0.0
vncutil64.exe	: 1.0.0.45
WavesSvc.exe	: 1.1.4.0
WavesSvc64.exe	: 1.3.3.0
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.36
AERTAC64.d11	: 2.9.64.0
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.0.321
BlackSkinImages64.d11	: 1.0.0.321
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
DarkSkinImages64.d11	: 1.0.0.321
DDPA64.d11	: 7.5.1.1
DDPD64A.d11	: 7.5.1.1
DDPO64A.d11	: 7.5.1.1
DDPP64A.d11	: 7.5.1.1
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.1.1.0

Readme.txt

DTSU2PLFX64.d11	: 2.1.1.0
DTSU2PREC64.d11	: 2.1.1.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO32.d11	: 50.5.4.68
FMAPO64.d11	: 50.6.4.72
GrayJadeSkinImages64.d11	: 1.0.0.321
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO4064.d11	: 4.4.0.0
MaxxAudioAPO5064.d11	: 5.3.1.0
MaxxAudioAPOShell.d11	: 4.10.8.0
MaxxAudioAPOShell64.d11	: 4.12.5.0
MaxxAudioEQ64.d11	: 4.1.0.0
MaxxAudioRealtek264.d11	: 5.2.16.0
MaxxAudioRealtek364.d11	: 1.4.4.0
MaxxAudioRealtek64.d11	: 4.5.1.0
MaxxAudioVienna264.d11	: 1.0.7.0
MaxxAudioVnA64.d11	: 1.7.2.0
MaxxAudioVnN64.d11	: 1.3.1.0
MaxxSpeechAPO.d11	: 1.1.1.0
MaxxSpeechAPO64.d11	: 1.1.1.0
MaxxVoiceAPO2064.d11	: 2.4.0.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.37
MBAPO264.d11	: 1.2.16.37
MBAPO32.d11	: 1.0.62.0
MBAPO64.d11	: 1.0.62.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBTHX64.d11	: 1.0.15.175
MBWrp64.d11	: 1.0.0.240
MISS_APO.d11	: 1.5.0.16020
NAHIMICAPO1fx.d11	: 6.3.9431.0
NAHIMICAPOSettingsIPC.d11	: 1.0.0.14112
PremiumBlackSkinImages64.d11	: 1.0.0.321
R4EEA64A.d11	: 7.2.8000.17
R4EED64A.d11	: 7.2.8000.17
R4EEG64A.d11	: 7.2.8000.17
R4EEL64A.d11	: 7.2.8000.17
R4EEP64A.d11	: 7.2.8000.17
RCoInstII64.d11	: 2.1.5.5
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.158
RTCOMDLL.d11	: 2.0.0.158
RtDataProc.d11	: 1.0.0.3
RtDataProc64.d11	: 1.0.0.3
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.70
RtkAPO64.d11	: 11.0.6000.347
RtkCfg.d11	: 1.0.0.1

Readme.txt

RtkCfg64.d11 : 1.0.0.2
RtkCoLDR64.d11 : 1.0.0.1
RtkGuiCompLib.d11 : 1.0.0.6
RtkXInterface.d11 : 1.0.0.13
RtkXInterface64.d11 : 1.0.0.13
RtlCPAPI.d11 : 1.0.2.6
RtlCPAPI64.d11 : 1.0.2.6
RtPgEx64.d11 : 6.0.6000.297
SFAP064.d11 : 3.0.0.16
SFCOM.d11 : 3.0.0.11
SFCOM64.d11 : 3.0.0.16
SFComm64.d11 : 2.0.0.13
SFDAPO64.d11 : 2.0.0.13
SFHAPO64.d11 : 2.0.0.13
SFNHK64.d11 : 3.0.0.16
SFProc64.d11 : 2.0.0.13
SFSAP064.d11 : 2.0.0.13
SFSS_APO.d11 : 1.6.0.7270
sl3apo64.d11 : 3.1.10.0
slcc3d64.d11 : 1.0.0.100
slcnt64.d11 : 3.1.10.0
slcshp64.d11 : 1.0.3.0
slcsii64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slhlim64.d11 : 2.1.0.0
slInit64.d11 : 1.1.3.0
slmaxv64.d11 : 1.2.1.0
slprp64.d11 : 1.0.0.1
sltech64.d11 : 3.1.10.0
sltshd64.d11 : 1.2.0.0
sluapo64.d11 : 2.3.24.0
slvipp64.d11 : 1.0.1.0
slviq64.d11 : 2.1.0.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo264.d11 : 1.2.1.0
tepeqapo64.d11 : 1.1.0.0
ToastD1164.d11 : 1.0.0.1
tosade.d11 : 1.0.1.12
tosasfapo64.d11 : 2.0.4.0
toseaeapo64.d11 : 2.0.4.0
tossaeapo64.d11 : 2.0.4.0
WavesGUILib64.d11 : 4.4.3.0
WhiteJadeSkinImages64.d11 : 1.0.0.321
RCORES64.dat : 1.4.1.0

HDMI Driver : _____
Windows 2000/XP x86 :
RtkHDMI.sys : 5.10.0.6519
Rtaupd.exe : 2.8.0.5
RHCoInstXP.d11 : 1.1.5.1

Readme.txt

Windows XP x64 :
RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.d11 : 1.1.5.1

Vista, Win7, Win8 x86 :
RtHDMIV.sys : 6.0.1.6650
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.6
R4EEA32H.d11 : 7.2.8000.13
R4EED32H.d11 : 7.2.8000.13
R4EEG32H.d11 : 7.2.8000.13
R4EEL32H.d11 : 7.2.8000.13
R4EEP32H.d11 : 7.2.8000.13
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :
RtHDMIVX.sys : 6.0.1.6650
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.6
R4EEA64H.d11 : 7.2.8000.13
R4EED64H.d11 : 7.2.8000.13
R4EEG64H.d11 : 7.2.8000.13
R4EEL64H.d11 : 7.2.8000.13
R4EEP64H.d11 : 7.2.8000.13
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDMEx64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 3.78

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.72

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8, Windows 8.1 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC867, ALC900

Readme.txt

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC255, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283, ALC284, ALC286, ALC290, ALC292, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC867, ALC900

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672, ALC676, ALC680

ALC221, ALC231, ALC233, ALC235, ALC255, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283, ALC284, ALC286, ALC290, ALC292, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7, Windows 8, Windows 8.1 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

- 1. Customizations.
- 2. Add Codec ALC255, ALC235, ALC867.
- 3. Support Windows 8.1.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.7071
RTKHDAUD.sys	: 5.10.0.7071
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.2.2
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPLEX.exe	: 1.0.1.66
RtlUpd.exe	: 2.9.0.0
RtlUpd64.exe	: 2.9.0.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.9
RCoInstII64XP.d11	: 2.1.4.5
RTCOMDLL.d11	: 1.0.0.116
RtkCoInstIIXP.d11	: 2.1.4.5
RtkCoLDR64XP.d11	: 1.0.0.1
RtkCoLDRXP.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.6

Vista, Win7, Win8, Win8.1 driver :

Readme.txt

Vista, Win7, Win8, Win8.1 driver for x86

RTKVHDA.sys	: 6.0.1.7071
AERTSrv.exe	: 1.0.32.10
CreateRtkToastLnk.exe	: 1.0.0.1
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.1.1.0
FMAPP.exe	: 1.32.0.2
MaxxAudioControl.exe	: 3.11.0.0
MaxxAudioMeters.exe	: 4.1.5.0
RtHDVBg.exe	: 1.0.0.168
RtHDVCpl.exe	: 1.0.0.908
RtkAudioService.exe	: 1.0.0.52
RtkNGUI.exe	: 1.0.0.318
RtlUpd.exe	: 2.9.0.0
vncutil.exe	: 1.0.0.45
WavesSvc.exe	: 1.1.4.0
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.36
AERTACap.d11	: 2.9.32.0
AERTARen.d11	: 1.0.32.11
BlackBlueSkinImages.d11	: 1.0.0.318
BlackSkinImages.d11	: 1.0.0.318
CONEQMSAPO.d11	: 1.0.0.19
CONEQMSAPOGUILibrary.d11	: 1.0.0.4
DarkSkinImages.d11	: 1.0.0.318
DDPA32.d11	: 7.5.1.1
DDPD32A.d11	: 7.5.1.1
DDPO32A.d11	: 7.5.1.1
DDPP32A.d11	: 7.5.1.1
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.3
DTS GFXAPONS.d11	: 1.0.0.3
DTS LFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSU2PGFX32.d11	: 2.1.1.0
DTSU2PLFX32.d11	: 2.1.1.0
DTSU2PREC32.d11	: 2.1.1.0
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 50.5.4.72
GrayJadeSkinImages.d11	: 1.0.0.318
KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO40.d11	: 4.4.0.0
MaxxAudioAPO50.d11	: 5.2.0.0
MaxxAudioAPOShell.d11	: 4.10.8.0
MaxxAudioEQ.d11	: 4.1.0.0
MaxxAudioRealtek.d11	: 4.4.10.0
MaxxAudioRealtek2.d11	: 5.2.16.0

Readme.txt

MaxxAudioRealtek3.d11	: 1.3.3.0
MaxxAudioVienna2.d11	: 1.0.7.0
MaxxAudioVnA.d11	: 1.7.0.0
MaxxAudioVnN.d11	: 1.2.0.0
MaxxSpeechAPO.d11	: 1.0.24.0
MaxxVoiceAPO20.d11	: 2.4.0.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.37
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBWrp32.d11	: 1.0.0.240
MISS_APO.d11	: 1.5.0.16020
PremiumBlackSkinImages.d11	: 1.0.0.318
R4EEA32A.d11	: 7.2.8000.17
R4EED32A.d11	: 7.2.8000.17
R4EEG32A.d11	: 7.2.8000.17
R4EEL32A.d11	: 7.2.8000.17
R4EEP32A.d11	: 7.2.8000.17
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.158
RtDataProc.d11	: 1.0.0.3
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.346
RtkApoApi.d11	: 1.0.0.69
RtkCfg.d11	: 1.0.0.2
RtkCoInstII.d11	: 2.1.5.1
RtkCoLDR.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.6
RtkPgExt.d11	: 6.0.6000.297
RTKSM1fx.d11	: 6.3.9431.0
RTKSMSettingsIPC.d11	: 1.1.2.13796
RtkXInterface.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.6.0.7270
sl3apo32.d11	: 3.1.10.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.1.10.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0

Readme.txt

slInit32.d11 : 1.1.3.0
slmaxv32.d11 : 1.2.1.0
slprp32.d11 : 1.0.0.1
sltech32.d11 : 3.1.10.0
sltshd32.d11 : 1.2.0.0
sluapo32.d11 : 2.3.24.0
slvipp32.d11 : 1.0.1.0
slviq32.d11 : 2.1.0.0
SRSHP360.d11 : 1.1.0.0
SRSTSHD.d11 : 1.1.4.0
SRSTSXT.d11 : 3.2.0.0
SRSWOW.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo2.d11 : 1.2.1.0
TepeqAPO.d11 : 1.1.0.0
ToastD11.d11 : 1.0.0.1
tosade.d11 : 1.0.1.12
WavesGUILib.d11 : 4.4.3.0
WavesLib.d11 : 5.9.7.0
WhiteJadeSkinImages.d11 : 1.0.0.318
RCORES.dat : 1.4.0.3

Vista, Win7, Win8, Win8.1 driver for x64

RTKVHD64.sys : 6.0.1.7071
AERTSr64.exe : 1.0.64.10
CreateRtkToastLnk.exe : 1.0.0.1
DTSAudioService64.exe : 1.0.0.0
DTSU2PAuSrv64.exe : 2.1.1.0
FMAPP.exe : 1.64.0.2
MaxxAudioControl64.exe : 3.11.0.0
MaxxAudioMeters64.exe : 4.1.5.0
RAVBg64.exe : 1.0.0.168
RAVCp164.exe : 1.0.0.908
RtHDVBg.exe : 1.0.0.163
RtkAudioService64.exe : 1.0.0.52
RtkNGUI64.exe : 1.0.0.318
RtlUpd64.exe : 2.9.0.0
vncutil64.exe : 1.0.0.45
WavesSvc.exe : 1.1.4.0
WavesSvc64.exe : 1.1.4.0
GWfilt64.sys : 6.10.0.3
mbfilt64.sys : 6.10.0.8
RTSnMg64.cpl : 1.0.0.36
AERTAC64.d11 : 2.9.64.0
AERTAR64.d11 : 1.0.64.11
BlackBlueSkinImages64.d11 : 1.0.0.318
BlackSkinImages64.d11 : 1.0.0.318
CONEQMSAPO.d11 : 1.0.0.19
CONEQMSAPOGUILibrary.d11 : 1.0.0.4
DarkSkinImages64.d11 : 1.0.0.318
DDPA64.d11 : 7.5.1.1
DDPD64A.d11 : 7.5.1.1
DDPO64A.d11 : 7.5.1.1
DDPP64A.d11 : 7.5.1.1
DTSBassEnhancementDLL64.d11 : 1.0.0.1
DTSBoostDLL64.d11 : 1.0.0.1

Readme.txt

DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.1.1.0
DTSU2PLFX64.d11	: 2.1.1.0
DTSU2PREC64.d11	: 2.1.1.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO32.d11	: 50.5.4.68
FMAPO64.d11	: 50.6.4.72
GrayJadeSkinImages64.d11	: 1.0.0.318
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.6.0.0
MaxxAudioAPO4064.d11	: 4.4.0.0
MaxxAudioAPO5064.d11	: 5.2.0.0
MaxxAudioAPOShe11.d11	: 4.10.8.0
MaxxAudioAPOShe1164.d11	: 4.10.8.0
MaxxAudioEQ64.d11	: 4.1.0.0
MaxxAudioRealtek264.d11	: 5.2.16.0
MaxxAudioRealtek364.d11	: 1.3.3.0
MaxxAudioRealtek64.d11	: 4.4.10.0
MaxxAudioVienna264.d11	: 1.0.7.0
MaxxAudioVnA64.d11	: 1.7.0.0
MaxxAudioVnN64.d11	: 1.2.0.0
MaxxSpeechAPO.d11	: 1.0.24.0
MaxxSpeechAPO64.d11	: 1.0.24.0
MaxxVoiceAPO2064.d11	: 2.4.0.0
MaxxVolumeSDAPO.d11	: 3.6.0.0
MBAPO232.d11	: 1.2.16.37
MBAPO264.d11	: 1.2.16.37
MBAPO32.d11	: 1.0.62.0
MBAPO64.d11	: 1.0.62.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBTHX64.d11	: 1.0.15.175
MBWrp64.d11	: 1.0.0.240
MISS_APO.d11	: 1.5.0.16020
PremiumBlackSkinImages64.d11	: 1.0.0.318
R4EEA64A.d11	: 7.2.8000.17
R4EED64A.d11	: 7.2.8000.17
R4EEG64A.d11	: 7.2.8000.17
R4EEL64A.d11	: 7.2.8000.17
R4EEP64A.d11	: 7.2.8000.17
RCoInstII64.d11	: 2.1.5.1
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.158
RTCOMDLL.d11	: 2.0.0.158
RtDataProc.d11	: 1.0.0.3

Readme.txt

RtDataProc64.d11	: 1.0.0.3
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.69
RtkAPO64.d11	: 11.0.6000.346
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkCoLDR64.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.6
RTKSM1fx.d11	: 6.3.9431.0
RTKSMSettingsIPC.d11	: 1.1.2.13796
RtkXInterface.d11	: 1.0.0.13
RtkXInterface64.d11	: 1.0.0.13
Rt1CPAPI.d11	: 1.0.2.6
Rt1CPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.297
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAPO64.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.6.0.7270
sl3apo64.d11	: 3.1.10.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.1.10.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1
sltech64.d11	: 3.1.10.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.24.0
slvip64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.2.1.0
tepeqapo64.d11	: 1.1.0.0
ToastD1164.d11	: 1.0.0.1
tosade.d11	: 1.0.1.12
tosasfapo64.d11	: 2.0.4.0
toseaeapo64.d11	: 2.0.4.0
tossaeapo64.d11	: 2.0.4.0

Readme.txt

WavesGUILib64.d11 : 4.4.3.0
WhiteJadeSkinImages64.d11 : 1.0.0.318
RCORES64.dat : 1.4.0.3

HDMI Driver :

Windows 2000/XP x86 :
RtkHDMI.sys : 5.10.0.6519
Rtaupd.exe : 2.8.0.5
RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :
RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.d11 : 1.1.5.1

Vista, Win7, Win8 x86 :
RtHDMIV.sys : 6.0.1.6650
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.6
R4EEA32H.d11 : 7.2.8000.13
R4EED32H.d11 : 7.2.8000.13
R4EEG32H.d11 : 7.2.8000.13
R4EEL32H.d11 : 7.2.8000.13
R4EEP32H.d11 : 7.2.8000.13
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :
RtHDMIVX.sys : 6.0.1.6650
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.6
R4EEA64H.d11 : 7.2.8000.13
R4EED64H.d11 : 7.2.8000.13
R4EEG64H.d11 : 7.2.8000.13
R4EEL64H.d11 : 7.2.8000.13
R4EEP64H.d11 : 7.2.8000.13
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDMEx64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 3.77

Windows 2000/XP Operate on :

Readme.txt

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.71

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC900

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672,
ALC676, ALC680

ALC221, ALC231, ALC233, ALC260, ALC262, ALC267, ALC268, ALC269,
ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283, ALC284, ALC286,
ALC290, ALC292, ALC383

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC, ALC861VD, ALC900

ALC660, ALC662, ALC663, ALC665, ALC668, ALC670, ALC671, ALC672,
ALC676, ALC680

ALC221, ALC231, ALC233, ALC260, ALC262, ALC267, ALC268, ALC269,
ALC270, ALC272, ALC273, ALC275, ALC276, ALC280, ALC282, ALC283, ALC284, ALC286
ALC290, ALC292, ALC383

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

2. Add Codec ALC233, ALC284, ALC286, ALC292, ALC383, ALC668, ALC900

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6873
RTKHDAUD.sys	: 5.10.0.6873
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.1.9
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.8
RtlUpd64.exe	: 2.8.0.8
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3

Readme.txt

ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.9
 RCoInstII64XP.d11 : 2.0.9.6
 RTCOMDLL.d11 : 1.0.0.116
 RtkCoInstIIXP.d11 : 2.0.9.6
 RtkCoLDR64XP.d11 : 1.0.0.1
 RtkCoLDRXP.d11 : 1.0.0.1
 Rt1CPAPI.d11 : 1.0.2.6

Vista, Win7, Win8 driver :

Vista, Win7, Win8 driver for x86

RTKVHDA.sys : 6.0.1.6873
 AERTSrv.exe : 1.0.32.10
 CreateRtkToastLnk.exe : 1.0.0.1
 DTSAudioService.exe : 1.0.0.0
 DTSU2PAuSrv32.exe : 2.1.0.0
 FMAPP.exe : 1.32.0.2
 MaxxAudioControl.exe : 3.8.0.0
 MaxxAudioMeters.exe : 4.1.4.0
 RtHDVBg.exe : 1.0.0.136
 RtHDVCpl.exe : 1.0.0.851
 RtkAudioService.exe : 1.0.0.41
 RtkNGUI.exe : 1.0.0.271
 Rt1Upd.exe : 2.8.0.8
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.45
 WavesSvc.exe : 1.0.2.0
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.35
 AERTACap.d11 : 2.4.32.0
 AERTARen.d11 : 1.0.32.11
 BlackBlueSkinImages.d11 : 1.0.0.271
 BlackSkinImages.d11 : 1.0.0.271
 CONEQMSAPO.d11 : 1.0.0.15
 CONEQMSAPOGUILibrary.d11 : 1.0.0.2
 DarkSkinImages.d11 : 1.0.0.271
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.1.0.0
 DTSU2PLFX32.d11 : 2.1.0.0
 DTSU2PREC32.d11 : 2.1.0.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 50.5.4.66
 GrayJadeSkinImages.d11 : 1.0.0.271
 KAAPORT.d11 : 4.1105.6000.53
 MaxxAudioAPO.d11 : 1.2.2.0

Readme.txt

MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.4.1.0
MaxxAudioAPO40.d11	: 4.2.4.0
MaxxAudioAPO50.d11	: 5.0.9.0
MaxxAudioAPOShe11.d11	: 4.8.0.0
MaxxAudioEQ.d11	: 4.1.0.0
MaxxAudioRealtek.d11	: 4.4.9.0
MaxxAudioRealtek2.d11	: 5.2.11.0
MaxxAudioRealtek3.d11	: 1.1.13.0
MaxxAudioVnA.d11	: 1.2.2.0
MaxxVoiceAPO20.d11	: 2.2.1.0
MaxxVolumeSDAPO.d11	: 3.4.0.0
MBAPO232.d11	: 1.2.16.17
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBWrp32.d11	: 1.0.0.200
MISS_APO.d11	: 1.5.0.15070
PremiumBlackSkinImages.d11	: 1.0.0.271
R4EEA32A.d11	: 7.2.8000.17
R4EED32A.d11	: 7.2.8000.17
R4EEG32A.d11	: 7.2.8000.17
R4EEL32A.d11	: 7.2.8000.17
R4EEP32A.d11	: 7.2.8000.17
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.157
RtDataProc.d11	: 1.0.0.1
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.319
RtkApoApi.d11	: 1.0.0.60
RtkCfg.d11	: 1.0.0.2
RtkCoInstII.d11	: 2.0.9.6
RtkCoLDR.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.6
RtkPgExt.d11	: 6.0.6000.286
RTKSM1fx.d11	: 6.2.9200.20550
RTKSMSettingsIPC.d11	: 1.1.0.11461
Rt1CPAPI.d11	: 1.0.2.6
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.5.0.15292
sl3apo32.d11	: 3.0.27.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.0.27.0
slcshp32.d11	: 1.0.3.0

Readme.txt

slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.0.27.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.11.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.1.0
TepeqAPO.d11	: 1.1.0.0
ToastD11.d11	: 1.0.0.1
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 4.4.0.0
WavesLib.d11	: 5.9.7.0
WhiteJadeSkinImages.d11	: 1.0.0.271
RCORES.dat	: 1.3.0.4
Vista, Win7, Win8 driver for x64	
RTKVHD64.sys	: 6.0.1.6873
AERTSr64.exe	: 1.0.64.10
CreateRtkToastLnk.exe	: 1.0.0.1
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.1.0.0
FMAPP.exe	: 1.64.0.2
MaxxAudioControl64.exe	: 3.8.0.0
MaxxAudioMeters64.exe	: 4.1.4.0
RAVBg64.exe	: 1.0.0.136
RAVCp164.exe	: 1.0.0.851
RtkAudioService64.exe	: 1.0.0.41
RtkNGUI64.exe	: 1.0.0.271
RtlUpd64.exe	: 2.8.0.8
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.45
WavesSvc64.exe	: 1.0.2.0
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.35
AERTAC64.d11	: 2.4.64.0
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.0.271
BlackSkinImages64.d11	: 1.0.0.271
CONEQMSAPO.d11	: 1.0.0.15
CONEQMSAPOGUILibrary.d11	: 1.0.0.2
DarkSkinImages64.d11	: 1.0.0.271
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1

Readme.txt

DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.1.0.0
DTSU2PLFX64.d11	: 2.1.0.0
DTSU2PREC64.d11	: 2.1.0.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 50.6.4.66
GrayJadeSkinImages64.d11	: 1.0.0.271
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.4.1.0
MaxxAudioAPO4064.d11	: 4.2.4.0
MaxxAudioAPO5064.d11	: 5.0.9.0
MaxxAudioAPOShe1164.d11	: 4.8.0.0
MaxxAudioEQ64.d11	: 4.1.0.0
MaxxAudioRealtek264.d11	: 5.2.11.0
MaxxAudioRealtek364.d11	: 1.1.13.0
MaxxAudioRealtek64.d11	: 4.4.9.0
MaxxAudioVnA64.d11	: 1.2.2.0
MaxxVoiceAPO2064.d11	: 2.2.1.0
MaxxVolumeSDAPO.d11	: 3.4.0.0
MBAPO232.d11	: 1.2.16.17
MBAPO264.d11	: 1.2.16.17
MBAPO32.d11	: 1.0.62.0
MBAPO64.d11	: 1.0.62.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.175
MBTHX64.d11	: 1.0.15.175
MBWrp64.d11	: 1.0.0.200
MISS_APO.d11	: 1.5.0.15070
PremiumBlackSkinImages64.d11	: 1.0.0.271
R4EEA64A.d11	: 7.2.8000.17
R4EED64A.d11	: 7.2.8000.17
R4EEG64A.d11	: 7.2.8000.17
R4EEL64A.d11	: 7.2.8000.17
R4EEP64A.d11	: 7.2.8000.17
RCoInstII64.d11	: 2.0.9.6
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.157
RTCOMDLL.d11	: 2.0.0.157
RtDataProc.d11	: 1.0.0.1
RtDataProc64.d11	: 1.0.0.1
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.60
RtkAPO64.d11	: 11.0.6000.319

Readme.txt

RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtkCoLDR64.dll	: 1.0.0.1
RtkGuiCompLib.dll	: 1.0.0.6
RTKSM1fx.dll	: 6.2.9200.20550
RTKSMSettingsIPC.dll	: 1.1.0.11461
RtlCPAPI.dll	: 1.0.2.6
RtlCPAPI64.dll	: 1.0.2.6
RtPgEx64.dll	: 6.0.6000.286
SFAPO64.dll	: 3.0.0.16
SFCOM.dll	: 3.0.0.11
SFCOM64.dll	: 3.0.0.16
SFComm64.dll	: 2.0.0.13
SFDAPO64.dll	: 2.0.0.13
SFHAP064.dll	: 2.0.0.13
SFNHK64.dll	: 3.0.0.16
SFProc64.dll	: 2.0.0.13
SFSAPO64.dll	: 2.0.0.13
SFSS_APO.dll	: 1.5.0.15292
s13apo64.dll	: 3.0.27.0
slcc3d64.dll	: 1.0.0.100
slcnt64.dll	: 3.0.27.0
slcshp64.dll	: 1.0.3.0
slcsii64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slhlim64.dll	: 2.1.0.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.2.1.0
slprp64.dll	: 1.0.0.1
sltech64.dll	: 3.0.27.0
sltshd64.dll	: 1.2.0.0
sluapo64.dll	: 2.3.11.0
slvipp64.dll	: 1.0.1.0
slviq64.dll	: 2.1.0.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
tadefxapo.dll	: 1.0.1.12
tadefxapo264.dll	: 1.2.1.0
tepeqapo64.dll	: 1.1.0.0
ToastD1164.dll	: 1.0.0.1
tosade.dll	: 1.0.1.12
tosasfapo64.dll	: 2.0.0.1
toseaeapo64.dll	: 2.0.0.1
tossaeapo64.dll	: 2.0.0.1
WavesGUILib64.dll	: 4.4.0.0
WhiteJadeSkinImages64.dll	: 1.0.0.271
RCORES64.dat	: 1.3.0.4

HDMI Driver : _____

Windows 2000/XP x86 :	
RtkHDMI.sys	: 5.10.0.6519
Rtaupd.exe	: 2.8.0.5
RHCoInstXP.dll	: 1.1.5.1

Readme.txt

Windows XP x64 :
RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.d11 : 1.1.5.1

Vista, Win7, Win8 x86 :
RtHDMIV.sys : 6.0.1.6650
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.6
R4EEA32H.d11 : 7.2.8000.13
R4EED32H.d11 : 7.2.8000.13
R4EEG32H.d11 : 7.2.8000.13
R4EEL32H.d11 : 7.2.8000.13
R4EEP32H.d11 : 7.2.8000.13
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista, Win7, Win8 x64 :
RtHDMIVX.sys : 6.0.1.6650
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.6
R4EEA64H.d11 : 7.2.8000.13
R4EED64H.d11 : 7.2.8000.13
R4EEG64H.d11 : 7.2.8000.13
R4EEL64H.d11 : 7.2.8000.13
R4EEP64H.d11 : 7.2.8000.13
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDMEx64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 3.65

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.70
Realtek HD Audio Driver support all of Realtek HD Audio Codec .
1. Vista, Windows 7, Windows 8 WHQL Supporting:
ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,

Readme.txt

ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC671, ALC672, ALC676, ALC680,
ALC221, ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276,
ALC280, ALC282, ALC283, ALC290
2. Windows 2000/XP WHQL Supporting:
ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC671, ALC672,
ALC676, ALC680, ALC221, ALC231,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276, ALC280, ALC282, ALC283, ALC290
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.
6. Add/Fix
1.) Driver :
1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.6662
RtkHDAud.sys	: 5.10.0.6662
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.1.0
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPLEX.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.6
RtlUpd.exe	: 2.8.0.6
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.7
ALSndMgr.cpl	: 1.0.0.11
RCoInstII64XP.d11	: 2.0.2.0
RTCOMDLL.d11	: 1.0.0.116
RtkCoInstIIXP.d11	: 2.0.2.0
RtkCoLDR64XP.d11	: 1.0.0.1
RtkCoLDRXP.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.6

Vista, Win7, Win8 driver :

Vista, Win7, Win8 driver for x86

Readme.txt

RTKVHDA.sys	: 6.0.1.6662
AERTSrv.exe	: 1.0.32.10
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.0.20.0
FMAPP.exe	: 1.32.0.2
MaxxAudioControl.exe	: 3.2.0.0
MaxxAudioMeters.exe	: 4.0.5.0
RtHDVBg.exe	: 1.0.0.97
RtHDVCpl.exe	: 1.0.0.791
RtkAudioService.exe	: 1.0.0.31
RtkNGUI.exe	: 1.0.0.196
RtlUpd.exe	: 2.8.0.6
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.45
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.26
AERTACap.d11	: 2.0.32.15
AERTARen.d11	: 1.0.32.11
BlackBlueSkinImages.d11	: 1.0.0.196
BlackSkinImages.d11	: 1.0.0.196
DarkSkinImages.d11	: 1.0.0.196
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.3
DTS GFXAPONS.d11	: 1.0.0.3
DTS LFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSU2PGFX32.d11	: 2.0.20.0
DTSU2PLFX32.d11	: 2.0.20.0
DTSU2PREC32.d11	: 2.0.20.0
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 44.5.5.65
GrayJadeSkinImages.d11	: 1.0.0.196
KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioAPO40.d11	: 4.1.0.4
MaxxAudioAPOShell.d11	: 4.2.2.0
MaxxAudioEQ.d11	: 4.0.3.1
MaxxAudioRealtek.d11	: 4.0.5.0
MaxxAudioRealtek2.d11	: 4.0.7.2
MaxxVolumeSDAPO.d11	: 3.2.1.1
MBAPO32.d11	: 1.0.62.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.166
MBWrp32.d11	: 1.0.0.200
PremiumBlackSkinImages.d11	: 1.0.0.196
R4EEA32A.d11	: 7.2.8000.13
R4EED32A.d11	: 7.2.8000.13

Readme.txt

R4EEG32A.d11	: 7.2.8000.13
R4EEL32A.d11	: 7.2.8000.13
R4EEP32A.d11	: 7.2.8000.13
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.150
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.284
RtkApoApi.d11	: 1.0.0.53
RtkCfg.d11	: 1.0.0.2
RtkCoInstII.d11	: 2.0.2.4
RtkCoLDR.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.5
RtkPgExt.d11	: 6.0.6000.262
Rt1CPAPI.d11	: 1.0.2.6
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.1.0.12190
sl3apo32.d11	: 3.0.2.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.0.2.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.0.2.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.11.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.1.0
TepeqAPO.d11	: 1.1.0.0
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 4.0.5.0
WavesLib.d11	: 5.9.7.0
RCORES.dat	: 1.1.8.1

Vista, Win7, Win8 driver for x64

Readme.txt

RTKVHD64.sys	: 6.0.1.6662
AERTSr64.exe	: 1.0.64.10
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.0.20.0
FMAPP.exe	: 1.64.0.2
MaxxAudioControl64.exe	: 3.2.0.0
MaxxAudioMeters64.exe	: 4.0.5.0
RAVBg64.exe	: 1.0.0.97
RAVCp164.exe	: 1.0.0.791
RtkAudioService64.exe	: 1.0.0.31
RtkNGUI64.exe	: 1.0.0.196
RtlUpd64.exe	: 2.8.0.6
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.26
AERTAC64.d11	: 2.0.64.15
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.0.196
BlackSkinImages64.d11	: 1.0.0.196
DarkSkinImages64.d11	: 1.0.0.196
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.0.20.0
DTSU2PLFX64.d11	: 2.0.20.0
DTSU2PREC64.d11	: 2.0.20.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 44.6.5.65
GrayJadeSkinImages64.d11	: 1.0.0.196
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioAPO4064.d11	: 4.1.0.4
MaxxAudioAPOShell64.d11	: 4.2.2.0
MaxxAudioEQ.d11	: 4.0.3.1
MaxxAudioRealtek.d11	: 4.0.5.0
MaxxAudioRealtek264.d11	: 4.0.7.2
MaxxVolumeSDAPO.d11	: 3.2.1.1
MBAPO32.d11	: 1.0.62.0
MBAPO64.d11	: 1.0.62.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.166
MBTHX64.d11	: 1.0.15.166
MBWrp64.d11	: 1.0.0.200
PremiumBlackSkinImages64.d11	: 1.0.0.196

Readme.txt

R4EEA64A.d11	: 7.2.8000.13
R4EED64A.d11	: 7.2.8000.13
R4EEG64A.d11	: 7.2.8000.13
R4EEL64A.d11	: 7.2.8000.13
R4EEP64A.d11	: 7.2.8000.13
RCoInstII64.d11	: 2.0.2.4
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.150
RTCOMDLL.d11	: 2.0.0.150
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.53
RtkAPO64.d11	: 11.0.6000.284
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkCoLDR64.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.5
Rt1CPAPI.d11	: 1.0.2.6
Rt1CPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.262
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAPO64.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.1.0.12190
sl3apo64.d11	: 3.0.2.0
slcc3d64.d11	: 1.0.0.100
slcnt64.d11	: 3.0.2.0
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
slprp64.d11	: 1.0.0.1
sltech64.d11	: 3.0.2.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.11.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.2.1.0
tepeqapo64.d11	: 1.1.0.0

Readme.txt

tosade.dll : 1.0.1.12
WavesGUILib.dll : 4.0.5.0
RCORES64.dat : 1.1.8.1

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys : 5.10.0.6519
Rtaupd.exe : 2.8.0.5
RHCoInstXP.dll : 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.dll : 1.1.5.1

Vista, Win7, Win8 x86 :

RtHDMIV.sys : 6.0.1.6650
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.6
R4EEA32H.dll : 7.2.8000.13
R4EED32H.dll : 7.2.8000.13
R4EEG32H.dll : 7.2.8000.13
R4EEL32H.dll : 7.2.8000.13
R4EEP32H.dll : 7.2.8000.13
RH3DAA32.dll : 6.0.6001.18
RH3DHT32.dll : 6.0.6001.18
RHCoInst.dll : 1.1.5.1
RHDMIExt.dll : 6.0.6000.228
RTEED32H.dll : 6.1.6001.33
RTEEG32H.dll : 6.1.6001.33
RTEEL32H.dll : 6.1.6001.33
RTEEP32H.dll : 6.1.6001.33
RtkHDMI.dll : 11.0.6000.259

Vista, Win7, Win8 x64 :

RtHDMIVX.sys : 6.0.1.6650
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.6
R4EEA64H.dll : 7.2.8000.13
R4EED64H.dll : 7.2.8000.13
R4EEG64H.dll : 7.2.8000.13
R4EEL64H.dll : 7.2.8000.13
R4EEP64H.dll : 7.2.8000.13
RH3DAA64.dll : 6.0.6001.18
RH3DHT64.dll : 6.0.6001.18
RHCoInst64.dll : 1.1.5.1
RHDME64.dll : 6.0.6000.228
RTEED64H.dll : 6.1.6001.33
RTEEG64H.dll : 6.1.6001.33
RTEEL64H.dll : 6.1.6001.33
RTEEP64H.dll : 6.1.6001.33
RtkHDM64.dll : 11.0.6000.259

Driver Setup Program : 3.50

Windows 2000/XP Operate on :

Readme.txt

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.69

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista, Windows 7, Windows 8 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,

ALC662, ALC663, ALC665, ALC670, ALC671, ALC672, ALC676, ALC680,
ALC221, ALC231, ALC260, ALC262,

ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276,
ALC280, ALC282, ALC283, ALC290

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,

ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC671, ALC672,
ALC676, ALC680, ALC221, ALC231,

ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276, ALC280, ALC282, ALC283, ALC290

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

- 1. Customizations.
- 2. Windows 8 WHQLed Driver.
- 3. Add ALC283.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6649
RtkHDAud.sys	: 5.10.0.6649
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.0.9
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.6
RtlUpd.exe	: 2.8.0.6
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
RTSndMgr.cpl	: 1.0.1.7
ALSndMgr.cpl	: 1.0.0.11

Readme.txt

RCoInstII64XP.d11 : 2.0.2.0
 RTCOMDLL.d11 : 1.0.0.116
 RtkCoInstIIXP.d11 : 2.0.2.0
 RtkCoLDR64XP.d11 : 1.0.0.1
 RtkCoLDRXP.d11 : 1.0.0.1
 Rt1CPAPI.d11 : 1.0.2.6

Vista, Win7, Win8 driver :

Vista, Win7, Win8 driver for x86

RTKVHDA.sys : 6.0.1.6649
 AERTSrv.exe : 1.0.32.10
 DTSAudioService.exe : 1.0.0.0
 DTSU2PAuSrv32.exe : 2.0.20.0
 FMAPP.exe : 1.32.0.2
 MaxxAudioControl.exe : 3.2.0.0
 MaxxAudioMeters.exe : 4.0.5.0
 RtHDVBg.exe : 1.0.0.93
 RtHDVCpl.exe : 1.0.0.787
 RtkAudioService.exe : 1.0.0.31
 RtkNGUI.exe : 1.0.0.190
 Rt1Upd.exe : 2.8.0.6
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.45
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.26
 AERTACap.d11 : 2.0.32.15
 AERTARen.d11 : 1.0.32.11
 BlackBlueSkinImages.d11 : 1.0.0.190
 BlackSkinImages.d11 : 1.0.0.190
 DarkSkinImages.d11 : 1.0.0.190
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.0.20.0
 DTSU2PLFX32.d11 : 2.0.20.0
 DTSU2PREC32.d11 : 2.0.20.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 44.5.5.65
 GrayJadeSkinImages.d11 : 1.0.0.190
 KAAPORT.d11 : 4.1105.6000.53
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioAPO40.d11 : 4.1.0.4
 MaxxAudioAPOShell.d11 : 4.2.2.0
 MaxxAudioEQ.d11 : 4.0.3.1
 MaxxAudioRealtek.d11 : 4.0.5.0

Readme.txt

MaxxAudioRealtek2.d11	: 4.0.7.2
MaxxVolumeSDAPO.d11	: 3.2.1.1
MBAPO32.d11	: 1.0.58.0
MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.165
MBWrp32.d11	: 1.0.0.180
PremiumBlackSkinImages.d11	: 1.0.0.190
R4EEA32A.d11	: 7.2.8000.13
R4EED32A.d11	: 7.2.8000.13
R4EEG32A.d11	: 7.2.8000.13
R4EEL32A.d11	: 7.2.8000.13
R4EEP32A.d11	: 7.2.8000.13
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.150
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.283
RtkApoApi.d11	: 1.0.0.52
RtkCfg.d11	: 1.0.0.2
RtkCoInstII.d11	: 2.0.2.4
RtkCoLDR.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.5
RtkPgExt.d11	: 6.0.6000.261
Rt1CPAPI.d11	: 1.0.2.6
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.1.0.12190
sl3apo32.d11	: 3.0.2.0
slcc3d32.d11	: 1.0.0.100
slcnt32.d11	: 3.0.2.0
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
slprp32.d11	: 1.0.0.1
sltech32.d11	: 3.0.2.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.11.0
slvip32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0

Readme.txt

SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.1.0
TepeqAPO.d11	: 1.1.0.0
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 4.0.5.0
WavesLib.d11	: 5.9.7.0
RCORES.dat	: 1.1.7.9
Vista, Win7, Win8 driver for x64	
RTKVHD64.sys	: 6.0.1.6649
AERTSr64.exe	: 1.0.64.10
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.0.20.0
FMAPP.exe	: 1.64.0.2
MaxxAudioControl64.exe	: 3.2.0.0
MaxxAudioMeters64.exe	: 4.0.5.0
RAVBg64.exe	: 1.0.0.93
RAVCp164.exe	: 1.0.0.787
RtkAudioService64.exe	: 1.0.0.31
RtkNGUI64.exe	: 1.0.0.190
RtlUpd64.exe	: 2.8.0.6
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.26
AERTAC64.d11	: 2.0.64.15
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.0.190
BlackSkinImages64.d11	: 1.0.0.190
DarkSkinImages64.d11	: 1.0.0.190
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.0.20.0
DTSU2PLFX64.d11	: 2.0.20.0
DTSU2PREC64.d11	: 2.0.20.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 44.6.5.65
GrayJadeSkinImages64.d11	: 1.0.0.190
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioAPO4064.d11	: 4.1.0.4
MaxxAudioAPOShell64.d11	: 4.2.2.0
MaxxAudioEQ.d11	: 4.0.3.1
MaxxAudioRealtek.d11	: 4.0.5.0

Readme.txt

MaxxAudioRealtek264.d11 : 4.0.7.2
 MaxxVolumeSDAPO.d11 : 3.2.1.1
 MBAPO32.d11 : 1.0.58.0
 MBAPO64.d11 : 1.0.58.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.58.0
 MBTHX32.d11 : 1.0.15.165
 MBTHX64.d11 : 1.0.15.165
 MBWrp64.d11 : 1.0.0.180
 PremiumBlackSkinImages64.d11 : 1.0.0.190
 R4EEA64A.d11 : 7.2.8000.13
 R4EED64A.d11 : 7.2.8000.13
 R4EEG64A.d11 : 7.2.8000.13
 R4EEL64A.d11 : 7.2.8000.13
 R4EEP64A.d11 : 7.2.8000.13
 RCoInstII64.d11 : 2.0.2.4
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.150
 RTCOMDLL.d11 : 2.0.0.150
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.52
 RtkAPO64.d11 : 11.0.6000.283
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 RtkCoLDR64.d11 : 1.0.0.1
 RtkGuiCompLib.d11 : 1.0.0.5
 Rt1CPAPI.d11 : 1.0.2.6
 Rt1CPAPI64.d11 : 1.0.2.6
 RtPgEx64.d11 : 6.0.6000.261
 SFAPO64.d11 : 3.0.0.16
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.16
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13
 SFHAPO64.d11 : 2.0.0.13
 SFNHK64.d11 : 3.0.0.16
 SFProc64.d11 : 2.0.0.13
 SFSAPO64.d11 : 2.0.0.13
 SFSS_APO.d11 : 1.1.0.12190
 sl3apo64.d11 : 3.0.2.0
 slcc3d64.d11 : 1.0.0.100
 slcnt64.d11 : 3.0.2.0
 slcshp64.d11 : 1.0.3.0
 slcsii64.d11 : 1.0.3.0
 slgeq64.d11 : 1.0.1.0
 slh36064.d11 : 1.0.2.0
 slhlim64.d11 : 2.1.0.0
 slInit64.d11 : 1.1.3.0
 slmaxv64.d11 : 1.2.1.0
 slprp64.d11 : 1.0.0.1
 sltech64.d11 : 3.0.2.0
 sltshd64.d11 : 1.2.0.0

Readme.txt

sluapo64.d11 : 2.3.11.0
slvipp64.d11 : 1.0.1.0
slviq64.d11 : 2.1.0.0
SRSHp64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo264.d11 : 1.2.1.0
tepeqapo64.d11 : 1.1.0.0
tosade.d11 : 1.0.1.12
WavesGUILib.d11 : 4.0.5.0
RCORES64.dat : 1.1.7.9

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys : 5.10.0.6519
Rtaupd.exe : 2.8.0.5
RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.d11 : 1.1.5.1

Vista/Win7 x86 :

RtHDMIV.sys : 6.0.1.6519
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.5
R4EEA32H.d11 : 7.2.7000.6
R4EED32H.d11 : 7.2.7000.6
R4EEG32H.d11 : 7.2.7000.6
R4EEL32H.d11 : 7.2.7000.6
R4EEP32H.d11 : 7.2.7000.6
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista/Win7 x64 :

RtHDMIVX.sys : 6.0.1.6519
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.5
R4EEA64H.d11 : 7.2.7000.6
R4EED64H.d11 : 7.2.7000.6
R4EEG64H.d11 : 7.2.7000.6
R4EEL64H.d11 : 7.2.7000.6
R4EEP64H.d11 : 7.2.7000.6
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1

Readme.txt

RHDMEx64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 3.50

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.68

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC671, ALC672, ALC676, ALC680,
ALC221, ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276,
ALC280, ALC282, ALC290

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC671, ALC672,
ALC676, ALC680, ALC221, ALC231,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276, ALC280, ALC282, ALC290

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.
2. Add ALC282.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6602
RtkHDAud.sys : 5.10.0.6602
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.4.0.8
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.5
RtlUpd.exe : 2.8.0.5
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32

Readme.txt

vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
AMBFilt.sys : 5.10.0.4240
AMBFt64.sys : 5.10.0.4240
Monfilt.sys : 5.10.0.4112
Monft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.7
RCoInstII64XP.d11 : 2.0.1.4
RTCOMDLL.d11 : 1.0.0.116
RtkCoInstIIXP.d11 : 2.0.1.4
RtkCoLDR64XP.d11 : 1.0.0.1
RtkCoLDRXP.d11 : 1.0.0.1
Rt1CPAPI.d11 : 1.0.2.6

Vista/Win7 driver :

Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6602
AERTSrv.exe : 1.0.32.10
DTSAudioService.exe : 1.0.0.0
DTSU2PAuSrv32.exe : 2.0.20.0
FMAPP.exe : 1.32.0.1
MaxxAudioControl.exe : 3.2.0.0
MaxxAudioMeters.exe : 4.0.5.0
RtHDVBg.exe : 1.0.0.84
RtHDVCpl.exe : 1.0.0.772
RtkAudioService.exe : 1.0.0.29
RtkNGUI.exe : 1.0.0.183
Rt1Upd.exe : 2.8.0.5
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.45
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.26
AERTACap.d11 : 2.0.32.15
AERTARen.d11 : 1.0.32.11
BlackBlueSkinImages.d11 : 1.0.0.183
BlackSkinImages.d11 : 1.0.0.183
DarkSkinImages.d11 : 1.0.0.183
DTSBassEnhancementDLL.d11 : 1.0.0.1
DTSBoostDLL.d11 : 1.0.0.1
DTSGainCompensatorDLL.d11 : 1.0.0.1
DTSGFXAPO.d11 : 1.0.0.3
DTSGFXAPONS.d11 : 1.0.0.3
DTSLFXAPO.d11 : 1.0.0.3
DTSLimiterDLL.d11 : 1.0.0.1
DTSNeoPCDLL.d11 : 1.0.0.1
DTSS2HeadphoneDLL.d11 : 1.0.0.1
DTSS2SpeakerDLL.d11 : 1.0.0.1
DTSSymmetryDLL.d11 : 1.0.0.1
DTSU2PGFX32.d11 : 2.0.20.0
DTSU2PLFX32.d11 : 2.0.20.0
DTSU2PREC32.d11 : 2.0.20.0
DTSVoiceClarityDLL.d11 : 1.0.0.1
FMAPO.d11 : 44.5.4.68
GrayJadeSkinImages.d11 : 1.0.0.183

Readme.txt

KAAPORT.d11	: 4.1105.6000.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioAPO40.d11	: 4.0.3.4
MaxxAudioAPOShe11.d11	: 4.1.6.0
MaxxAudioEQ.d11	: 4.0.3.1
MaxxAudioRealtek.d11	: 4.0.5.0
MaxxAudioRealtek2.d11	: 4.0.6.2
MaxxVolumeSDAPO.d11	: 3.2.1.1
MBAPO32.d11	: 1.0.58.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.162
MBWrp32.d11	: 1.0.0.180
PremiumBlackSkinImages.d11	: 1.0.0.183
R4EEA32A.d11	: 7.2.7000.11
R4EED32A.d11	: 7.2.7000.11
R4EEG32A.d11	: 7.2.7000.11
R4EEL32A.d11	: 7.2.7000.11
R4EEP32A.d11	: 7.2.7000.11
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.148
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.280
RtkApoApi.d11	: 1.0.0.51
RtkCfg.d11	: 1.0.0.2
RtkCoInstII.d11	: 2.0.1.4
RtkCoLDR.d11	: 1.0.0.1
RtkGuiCompLib.d11	: 1.0.0.5
RtkPgExt.d11	: 6.0.6000.258
Rt1CPAPI.d11	: 1.0.2.6
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
SFSS_APO.d11	: 1.1.0.12190
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.11.0
slvipp32.d11	: 1.0.1.0

Readme.txt

s1viq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.2.1.0
TepeqAPO.d11	: 1.1.0.0
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 4.0.5.0
WavesLib.d11	: 5.9.7.0
RCORES.dat	: 1.1.6.9
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6602
AERTSr64.exe	: 1.0.64.10
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.0.20.0
FMAPP.exe	: 1.64.0.1
MaxxAudioControl64.exe	: 3.2.0.0
MaxxAudioMeters64.exe	: 4.0.5.0
RAVBg64.exe	: 1.0.0.84
RAVCp164.exe	: 1.0.0.772
RtkAudioService64.exe	: 1.0.0.29
RtkNGUI64.exe	: 1.0.0.183
RtlUpd64.exe	: 2.8.0.5
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.26
AERTAC64.d11	: 2.0.64.15
AERTAR64.d11	: 1.0.64.11
BlackBlueSkinImages64.d11	: 1.0.0.183
BlackSkinImages64.d11	: 1.0.0.183
DarkSkinImages64.d11	: 1.0.0.183
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.0.20.0
DTSU2PLFX64.d11	: 2.0.20.0
DTSU2PREC64.d11	: 2.0.20.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 44.6.4.68
GrayJadeSkinImages64.d11	: 1.0.0.183
KAAPORT64.d11	: 4.1105.6000.53
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1

Readme.txt

MaxxAudioAPO4064.d11	: 4.0.3.4
MaxxAudioAPOSHe1164.d11	: 4.1.6.0
MaxxAudioEQ.d11	: 4.0.3.1
MaxxAudioRealtek.d11	: 4.0.5.0
MaxxAudioRealtek264.d11	: 4.0.6.2
MaxxVolumeSDAPO.d11	: 3.2.1.1
MBAPO32.d11	: 1.0.58.0
MBAPO64.d11	: 1.0.58.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.58.0
MBTHX32.d11	: 1.0.15.162
MBTHX64.d11	: 1.0.15.162
MBWrp64.d11	: 1.0.0.180
PremiumBlackSkinImages64.d11	: 1.0.0.183
R4EEA64A.d11	: 7.2.7000.11
R4EED64A.d11	: 7.2.7000.11
R4EEG64A.d11	: 7.2.7000.11
R4EEL64A.d11	: 7.2.7000.11
R4EEP64A.d11	: 7.2.7000.11
RCoInstII64.d11	: 2.0.1.4
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.148
RTCOMDLL.d11	: 2.0.0.148
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.51
RtkAPO64.d11	: 11.0.6000.280
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkCoLDR64.d11	: 1.0.0.1
RtkGuiComplib.d11	: 1.0.0.5
Rt1CPAPI.d11	: 1.0.2.6
Rt1CPAPI64.d11	: 1.0.2.6
RtPgEx64.d11	: 6.0.6000.258
SFAPO64.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.16
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.16
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.1.0.12190
slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0

Readme.txt

sluapo64.d11 : 2.3.11.0
slvipp64.d11 : 1.0.1.0
slviq64.d11 : 2.1.0.0
SRSHp64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo264.d11 : 1.2.1.0
tepeqapo64.d11 : 1.1.0.0
tosade.d11 : 1.0.1.12
WavesGUILib.d11 : 4.0.5.0
RCORES64.dat : 1.1.6.9

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys : 5.10.0.6519
Rtaupd.exe : 2.8.0.5
RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.d11 : 1.1.5.1

Vista/Win7 x86 :

RtHDMIV.sys : 6.0.1.6519
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.5
R4EEA32H.d11 : 7.2.7000.6
R4EED32H.d11 : 7.2.7000.6
R4EEG32H.d11 : 7.2.7000.6
R4EEL32H.d11 : 7.2.7000.6
R4EEP32H.d11 : 7.2.7000.6
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista/Win7 x64 :

RtHDMIVX.sys : 6.0.1.6519
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.5
R4EEA64H.d11 : 7.2.7000.6
R4EED64H.d11 : 7.2.7000.6
R4EEG64H.d11 : 7.2.7000.6
R4EEL64H.d11 : 7.2.7000.6
R4EEP64H.d11 : 7.2.7000.6
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1

Readme.txt

RHDMEx64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 3.44

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.67

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC671, ALC672, ALC676, ALC680,
ALC221, ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276,
ALC280, ALC290

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC671, ALC672,
ALC676, ALC680, ALC221, ALC231,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276, ALC280, ALC290

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.
2. Add ALC280.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6526
RtkHDAud.sys : 5.10.0.6526
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.4.0.5
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.5
RtlUpd.exe : 2.8.0.5
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32

Readme.txt

vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
AMBFilt.sys : 5.10.0.4240
AMBFt64.sys : 5.10.0.4240
Monfilt.sys : 5.10.0.4112
Monft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.7
RCoInstII64XP.d11 : 2.0.0.6
RTCOMDLL.d11 : 1.0.0.115
RtkCoInstIIXP.d11 : 2.0.0.6
RtkCoLDR64XP.d11 : 1.0.0.1
RtkCoLDRXP.d11 : 1.0.0.1
Rt1CPAPI.d11 : 1.0.2.5

Vista/Win7 driver :

Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.6526
AERTSrv.exe : 1.0.32.10
DTSAudioService.exe : 1.0.0.0
DTSU2PAuSrv32.exe : 2.0.15.0
FMAPP.exe : 1.32.0.1
RtHDVBg.exe : 1.0.0.82
RtHDVCpl.exe : 1.0.0.756
RtkAudioService.exe : 1.0.0.29
RtkNGUI.exe : 1.0.0.164
Rt1Upd.exe : 2.8.0.5
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.45
mbfilt32.sys : 6.10.0.8
RTSndMgr.cpl : 1.0.0.26
AERTACap.d11 : 2.0.32.13
AERTARen.d11 : 1.0.32.9
BlackBlueSkinImages.d11 : 1.0.0.164
BlackJadeSkinImages.d11 : 1.0.0.164
BlackSkinImages.d11 : 1.0.0.164
DarkSkinImages.d11 : 1.0.0.164
DTSBassEnhancementDLL.d11 : 1.0.0.1
DTSBoostDLL.d11 : 1.0.0.1
DTSGainCompensatorDLL.d11 : 1.0.0.1
DTSGFXAPO.d11 : 1.0.0.3
DTSGFXAPONS.d11 : 1.0.0.3
DTSLFXAPO.d11 : 1.0.0.3
DTSLimiterDLL.d11 : 1.0.0.1
DTSNeoPCDLL.d11 : 1.0.0.1
DTSS2HeadphoneDLL.d11 : 1.0.0.1
DTSS2SpeakerDLL.d11 : 1.0.0.1
DTSSymmetryDLL.d11 : 1.0.0.1
DTSU2PGFX32.d11 : 2.0.15.0
DTSU2PLFX32.d11 : 2.0.15.0
DTSU2PREC32.d11 : 2.0.15.0
DTSVoiceClarityDLL.d11 : 1.0.0.1
FMAPO.d11 : 43.5.16.65
GrayJadeSkinImages.d11 : 1.0.0.164
KAAPORT.d11 : 4.1105.6000.53

Readme.txt

LightSkinImages.d11 : 1.0.0.164
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 2.0.0.0
 MaxxAudioRealtek.d11 : 1.3.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.56.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.51.0
 MBTHX32.d11 : 1.0.15.156
 MBWrp32.d11 : 1.0.0.180
 PremiumBlackSkinImages.d11 : 1.0.0.164
 R4EEA32A.d11 : 7.2.7000.6
 R4EED32A.d11 : 7.2.7000.6
 R4EEG32A.d11 : 7.2.7000.6
 R4EEL32A.d11 : 7.2.7000.6
 R4EEP32A.d11 : 7.2.7000.6
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.146
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.261
 RtkApoApi.d11 : 1.0.0.49
 RtkCfg.d11 : 1.0.0.2
 RtkCoInstII.d11 : 2.0.0.6
 RtkCoLDR.d11 : 1.0.0.1
 RtkGuiCompLib.d11 : 1.0.0.2
 RtkPgExt.d11 : 6.0.6000.245
 Rt1CPAPI.d11 : 1.0.2.5
 SFAPO.d11 : 3.0.0.16
 SFCOM.d11 : 3.0.0.16
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13
 SFFXHAPO.d11 : 2.0.0.13
 SFFXProc.d11 : 2.0.0.13
 SFFXSAPO.d11 : 2.0.0.13
 SFNHK.d11 : 3.0.0.16
 SFSS_APO.d11 : 1.1.0.11180
 slcc3d32.d11 : 1.0.0.100
 slcshp32.d11 : 1.0.3.0
 slcsii32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slhlim32.d11 : 2.1.0.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.2.1.0
 sltshd32.d11 : 1.2.0.0
 sluapo32.d11 : 2.3.11.0
 slvip32.d11 : 1.0.1.0
 slviq32.d11 : 2.1.0.0
 SRSHP360.d11 : 1.1.0.0

Readme.txt

SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.1.0.31
TepeqAPO.d11	: 1.0.0.3
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 2.0.0.0
WavesLib.d11	: 5.9.7.0
RCORES.dat	: 1.1.4.6
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6526
AERTSr64.exe	: 1.0.64.10
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.0.15.0
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.82
RAVCp164.exe	: 1.0.0.756
RtkAudioService64.exe	: 1.0.0.29
RtkNGUI64.exe	: 1.0.0.164
RtlUpd64.exe	: 2.8.0.5
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.26
AERTAC64.d11	: 2.0.64.13
AERTAR64.d11	: 1.0.64.9
BlackBlueSkinImages64.d11	: 1.0.0.164
BlackJadeSkinImages64.d11	: 1.0.0.164
BlackSkinImages64.d11	: 1.0.0.164
DarkSkinImages64.d11	: 1.0.0.164
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSU2PGFX64.d11	: 2.0.15.0
DTSU2PLFX64.d11	: 2.0.15.0
DTSU2PREC64.d11	: 2.0.15.0
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 43.6.16.65
GrayJadeSkinImages64.d11	: 1.0.0.164
KAAPORT64.d11	: 4.1105.6000.53
LightSkinImages64.d11	: 1.0.0.164
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 2.0.0.0
MaxxAudioRealtek.d11	: 1.3.0.0

Readme.txt

MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.56.0
 MBAPO64.d11 : 1.0.56.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.51.0
 MBTHX32.d11 : 1.0.15.156
 MBTHX64.d11 : 1.0.15.156
 MBWrp64.d11 : 1.0.0.180
 PremiumBlackSkinImages64.d11 : 1.0.0.164
 R4EEA64A.d11 : 7.2.7000.6
 R4EED64A.d11 : 7.2.7000.6
 R4EEG64A.d11 : 7.2.7000.6
 R4EEL64A.d11 : 7.2.7000.6
 R4EEP64A.d11 : 7.2.7000.6
 RCoInstII64.d11 : 2.0.0.6
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.146
 RTCOMDLL.d11 : 2.0.0.146
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.49
 RtkAPO64.d11 : 11.0.6000.261
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 RtkCoLDR64.d11 : 1.0.0.1
 RtkGuiCompLib.d11 : 1.0.0.2
 Rt1CPAPI.d11 : 1.0.2.5
 Rt1CPAPI64.d11 : 1.0.2.5
 RtPgEx64.d11 : 6.0.6000.245
 SFAPO64.d11 : 3.0.0.16
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.16
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13
 SFHAPO64.d11 : 2.0.0.13
 SFNHK64.d11 : 3.0.0.16
 SFProc64.d11 : 2.0.0.13
 SFSAPO64.d11 : 2.0.0.13
 SFSS_APO.d11 : 1.1.0.11180
 slcc3d64.d11 : 1.0.0.100
 slcshp64.d11 : 1.0.3.0
 slcsii64.d11 : 1.0.3.0
 slgeq64.d11 : 1.0.1.0
 slh36064.d11 : 1.0.2.0
 slhlim64.d11 : 2.1.0.0
 slInit64.d11 : 1.1.3.0
 slmaxv64.d11 : 1.2.1.0
 sltshd64.d11 : 1.2.0.0
 sluapo64.d11 : 2.3.11.0
 slvipp64.d11 : 1.0.1.0
 slviq64.d11 : 2.1.0.0
 SRSHp64.d11 : 1.1.0.0

Readme.txt

SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tadefxapo264.d11 : 1.1.0.31
tepeqapo64.d11 : 1.0.0.3
tosade.d11 : 1.0.1.12
WavesGUILib.d11 : 2.0.0.0
RCORES64.dat : 1.1.4.6

HDMI Driver :

Windows 2000/XP x86 :

RtkHDMI.sys : 5.10.0.6519
Rtaupd.exe : 2.8.0.5
RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :

RtkHDMIX.sys : 5.10.0.6519
Rtaupd64.exe : 2.8.0.5
RHCoInst64XP.d11 : 1.1.5.1

Vista/Win7 x86 :

RtHDMIV.sys : 6.0.1.6519
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.5
R4EEA32H.d11 : 7.2.7000.6
R4EED32H.d11 : 7.2.7000.6
R4EEG32H.d11 : 7.2.7000.6
R4EEL32H.d11 : 7.2.7000.6
R4EEP32H.d11 : 7.2.7000.6
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.228
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.259

Vista/Win7 x64 :

RtHDMIVX.sys : 6.0.1.6519
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.5
R4EEA64H.d11 : 7.2.7000.6
R4EED64H.d11 : 7.2.7000.6
R4EEG64H.d11 : 7.2.7000.6
R4EEL64H.d11 : 7.2.7000.6
R4EEP64H.d11 : 7.2.7000.6
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDME64.d11 : 6.0.6000.228
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33

Readme.txt

RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.259

Driver Setup Program : 3.44

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.66

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,

ALC662, ALC663, ALC665, ALC670, ALC671, ALC672, ALC676, ALC680,
ALC221, ALC231, ALC260, ALC262,

ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276,
ALC290

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,

ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC671, ALC672,
ALC676, ALC680, ALC221, ALC231,

ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276, ALC290

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

2. Support ALC290.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6482

RtkHDAud.sys : 5.10.0.6482

MicCal.exe : 1.1.2.4

RTHDCPL.exe : 2.4.0.4

RtkAudioService64.exe : 1.0.0.19

RtkAudioService.exe : 1.0.0.19

RTLCPLEX.exe : 1.0.1.66

RtlUpd64.exe : 2.8.0.5

RtlUpd.exe : 2.8.0.5

SkyTel.exe : 2.0.2.0

SoundMan.exe : 1.0.0.32

vncutil64.exe : 1.0.0.38

vncutil.exe : 1.0.0.38

Alcmtr.exe : 1.6.0.4

AlcWzrd.exe : 1.1.0.37

AMBft64.sys : 5.10.0.4240

Monfilt.sys : 5.10.0.4112

Readme.txt

Monft64.sys : 5.10.0.4115
 OAO17Afx.sys : 1.0.7.3
 AMBFilt.sys : 5.10.0.4240
 RTSndMgr.cpl : 1.0.1.7
 ALSndMgr.cpl : 1.0.0.11
 RCoInst64XP.d11 : 1.1.7.8
 RTCOMDLL.d11 : 1.0.0.113
 RtkCoInstXP.d11 : 1.1.7.8
 Rt1CPAPI.d11 : 1.0.2.5

Vista/Win7 driver : _____

Vista/Win7 driver for x86
 RTKVHDA.sys : 6.0.1.6482
 AERTSrv.exe : 1.0.32.10
 DTSAudioService.exe : 1.0.0.0
 DTSU2PAuSrv32.exe : 2.0.15.0
 FMAPP.exe : 1.32.0.1
 RtHDV Bg.exe : 1.0.0.79
 RtHDVCpl.exe : 1.0.0.738
 RtkAudioService.exe : 1.0.0.29
 RtkNGUI.exe : 1.0.0.143
 Rt1Upd.exe : 2.8.0.5
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.45
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.25
 AERTACap.d11 : 2.0.32.13
 AERTARen.d11 : 1.0.32.9
 BlackBlueSkinImages.d11 : 1.0.0.141
 BlackJadeSkinImages.d11 : 1.0.0.124
 BlackSkinImages.d11 : 1.0.0.143
 DarkSkinImages.d11 : 1.0.0.143
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.0.15.0
 DTSU2PLFX32.d11 : 2.0.15.0
 DTSU2PREC32.d11 : 2.0.15.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 43.5.16.65
 GrayJadeSkinImages.d11 : 1.0.0.143
 KAAPORT.d11 : 4.1105.6000.53
 LightSkinImages.d11 : 1.0.0.143
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 2.0.0.0
 MaxxAudioRealtek.d11 : 1.3.0.0

Readme.txt

MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.51.0
MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.51.0
MBTHX32.d11	: 1.0.15.152
MBWrp32.d11	: 1.0.0.180
PremiumBlackSkinImages.d11	: 1.0.0.143
R4EEA32A.d11	: 7.2.7000.6
R4EED32A.d11	: 7.2.7000.6
R4EEG32A.d11	: 7.2.7000.6
R4EEL32A.d11	: 7.2.7000.6
R4EEP32A.d11	: 7.2.7000.6
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.146
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.244
RtkApoApi.d11	: 1.0.0.43
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.7.8
RtkGuiCompLib.d11	: 1.0.0.2
RtkPgExt.d11	: 6.0.6000.234
Rt1CPAPI.d11	: 1.0.2.5
SFAPO.d11	: 3.0.0.16
SFCOM.d11	: 3.0.0.16
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.16
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.8.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.1.0.31
TepeqAPO.d11	: 1.0.0.3
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 2.0.0.0

Readme.txt

WavesLib.d11 : 5.9.7.0
 RCORES.dat : 1.1.2.7

 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6482
 AERTSr64.exe : 1.0.64.10
 DTSAudioService64.exe : 1.0.0.0
 DTSU2PAuSrv64.exe : 2.0.15.0
 FMAPP.exe : 1.64.0.1
 RAVBg64.exe : 1.0.0.79
 RAVCp164.exe : 1.0.0.738
 RtkAudioService64.exe : 1.0.0.29
 RtkNGUI64.exe : 1.0.0.143
 RtlUpd64.exe : 2.8.0.5
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.45
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.25
 AERTAC64.d11 : 2.0.64.13
 AERTAR64.d11 : 1.0.64.9
 BlackBlueSkinImages64.d11 : 1.0.0.141
 BlackJadeSkinImages64.d11 : 1.0.0.124
 BlackSkinImages64.d11 : 1.0.0.143
 DarkSkinImages64.d11 : 1.0.0.143
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSU2PGFX64.d11 : 2.0.15.0
 DTSU2PLFX64.d11 : 2.0.15.0
 DTSU2PREC64.d11 : 2.0.15.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 43.6.16.65
 GrayJadeSkinImages64.d11 : 1.0.0.143
 KAAPORT64.d11 : 4.1105.6000.53
 LightSkinImages64.d11 : 1.0.0.143
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 2.0.0.0
 MaxxAudioRealtek.d11 : 1.3.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.51.0
 MBAPO64.d11 : 1.0.51.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.51.0
 MBTHX32.d11 : 1.0.15.152
 MBTHX64.d11 : 1.0.15.152

Readme.txt

MBWrp64.dll	: 1.0.0.180
PremiumBlackSkinImages64.dll	: 1.0.0.143
R4EEA64A.dll	: 7.2.7000.6
R4EED64A.dll	: 7.2.7000.6
R4EEG64A.dll	: 7.2.7000.6
R4EEL64A.dll	: 7.2.7000.6
R4EEP64A.dll	: 7.2.7000.6
RCoInst64.dll	: 1.1.7.8
RP3DAA64.dll	: 6.0.6001.18
RP3DHT64.dll	: 6.0.6001.18
RtCOM64.dll	: 2.0.0.146
RTCOMDLL.dll	: 2.0.0.146
RTEED64A.dll	: 6.1.6001.33
RTEEG64A.dll	: 6.1.6001.33
RTEEL64A.dll	: 6.1.6001.33
RTEEP64A.dll	: 6.1.6001.33
RtkApi64.dll	: 1.0.0.43
RtkAPO64.dll	: 11.0.6000.244
RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtkGuiCompLib.dll	: 1.0.0.2
Rt1CPAPI.dll	: 1.0.2.5
Rt1CPAPI64.dll	: 1.0.2.5
RtPgEx64.dll	: 6.0.6000.234
SFAPO64.dll	: 3.0.0.16
SFCOM.dll	: 3.0.0.11
SFCOM64.dll	: 3.0.0.16
SFComm64.dll	: 2.0.0.13
SFDAPO64.dll	: 2.0.0.13
SFHAPO64.dll	: 2.0.0.13
SFNHK64.dll	: 3.0.0.16
SFProc64.dll	: 2.0.0.13
SFSAPO64.dll	: 2.0.0.13
SFSS_APO.dll	: 1.0.0.11110
slcc3d64.dll	: 1.0.0.100
slcshp64.dll	: 1.0.3.0
slcsii64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slhlim64.dll	: 2.1.0.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.2.1.0
sltshd64.dll	: 1.2.0.0
sluapo64.dll	: 2.3.8.0
slvipp64.dll	: 1.0.1.0
slviq64.dll	: 2.1.0.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
tadefxapo.dll	: 1.0.1.12
tadefxapo264.dll	: 1.1.0.31
tepeqapo64.dll	: 1.0.0.3
tosade.dll	: 1.0.1.12
WavesGUILib.dll	: 2.0.0.0
RCORES64.dat	: 1.1.2.7

Readme.txt

HDMI Driver : _____

Windows 2000/XP x86 :
RtkHDMI.sys : 5.10.0.6409
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.5.1

Windows XP x64 :
RtkHDMIX.sys : 5.10.0.6409
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.5.1

Vista/Win7 x86 :
RtHDMIV.sys : 6.0.1.6409
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
R4EEA32H.d11 : 7.2.7000.6
R4EED32H.d11 : 7.2.7000.6
R4EEG32H.d11 : 7.2.7000.6
R4EEL32H.d11 : 7.2.7000.6
R4EEP32H.d11 : 7.2.7000.6
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.213
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.224

Vista/Win7 x64 :
RtHDMIVX.sys : 6.0.1.6409
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
R4EEA64H.d11 : 7.2.7000.6
R4EED64H.d11 : 7.2.7000.6
R4EEG64H.d11 : 7.2.7000.6
R4EEL64H.d11 : 7.2.7000.6
R4EEP64H.d11 : 7.2.7000.6
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDMEx64.d11 : 6.0.6000.213
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.224

Driver Setup Program : 3.37

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R2.65

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,

ALC662, ALC663, ALC665, ALC670, ALC671, ALC672, ALC676, ALC680,
ALC221, ALC231, ALC260, ALC262,

ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,

ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC671, ALC672,
ALC676, ALC680, ALC221, ALC231,

ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6449
RtkHDAud.sys	: 5.10.0.6449
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.0.3
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.5
RtlUpd.exe	: 2.8.0.5
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.7
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.1.6.8
RTCOMDLL.d11	: 1.0.0.113
RtkCoInstXP.d11	: 1.1.6.8
Rt1CPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

Readme.txt

RTKVHDA.sys : 6.0.1.6449
 AERTSrv.exe : 1.0.32.10
 DTSAudioService.exe : 1.0.0.0
 DTSU2PAuSrv32.exe : 2.0.15.0
 FMAPP.exe : 1.32.0.1
 RtHDVBg.exe : 1.0.0.75
 RtHDVCpl.exe : 1.0.0.725
 RtkAudioService.exe : 1.0.0.29
 RtkNGUI.exe : 1.0.0.134
 Rt1Upd.exe : 2.8.0.5
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.45
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.25
 AERTACap.d11 : 2.0.32.13
 AERTARen.d11 : 1.0.32.9
 BlackSkinImages.d11 : 1.0.0.134
 DarkSkinImages.d11 : 1.0.0.134
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.0.15.0
 DTSU2PLFX32.d11 : 2.0.15.0
 DTSU2PREC32.d11 : 2.0.15.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 43.5.16.65
 GrayJadeSkinImages.d11 : 1.0.0.134
 KAAPORT.d11 : 4.1105.6000.53
 LightSkinImages.d11 : 1.0.0.134
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 2.0.0.0
 MaxxAudioRealtek.d11 : 1.3.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.51.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.51.0
 MBTHX32.d11 : 1.0.15.147
 MBWrp32.d11 : 1.0.0.180
 PremiumBlackSkinImages.d11 : 1.0.0.134
 R4EEA32A.d11 : 7.2.7000.6
 R4EED32A.d11 : 7.2.7000.6
 R4EEG32A.d11 : 7.2.7000.6
 R4EEL32A.d11 : 7.2.7000.6
 R4EEP32A.d11 : 7.2.7000.6
 RP3DAA32.d11 : 6.0.6001.18

Readme.txt

RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.146
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.235
 RtkApoApi.d11 : 1.0.0.42
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.1.6.8
 RtkGuiCompLib.d11 : 1.0.0.2
 RtkPgExt.d11 : 6.0.6000.224
 Rt1CPAPI.d11 : 1.0.2.4
 SFAPO.d11 : 3.0.0.14
 SFCOM.d11 : 3.0.0.14
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13
 SFFXHAPO.d11 : 2.0.0.13
 SFFXProc.d11 : 2.0.0.13
 SFFXSAPO.d11 : 2.0.0.13
 SFNHK.d11 : 3.0.0.14
 slcc3d32.d11 : 1.0.0.100
 slcshp32.d11 : 1.0.3.0
 slcsii32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slhlim32.d11 : 2.1.0.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.2.1.0
 sltshd32.d11 : 1.2.0.0
 sluapo32.d11 : 2.3.8.0
 slvipp32.d11 : 1.0.1.0
 slviq32.d11 : 2.1.0.0
 SRSH360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 tadefxapo.d11 : 1.0.1.12
 tadefxapo2.d11 : 1.1.0.31
 tosade.d11 : 1.0.1.12
 WavesGUILib.d11 : 2.0.0.0
 WavesLib.d11 : 5.9.7.0
 RCORES.dat : 1.1.1.8

Vista/Win7 driver for x64

RTKVHD64.sys : 6.0.1.6449
 AERTSr64.exe : 1.0.64.10
 DTSAudioService64.exe : 1.0.0.0
 DTSU2PAuSrv64.exe : 2.0.15.0
 FMAPP.exe : 1.64.0.1
 RAVBg64.exe : 1.0.0.75
 RAVCp164.exe : 1.0.0.725
 RtkAudioService64.exe : 1.0.0.29
 RtkNGUI64.exe : 1.0.0.134
 Rt1Upd64.exe : 2.8.0.5
 SkyTel.exe : 2.0.2.2

Readme.txt

vncutil64.exe : 1.0.0.45
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.25
 AERTAC64.d11 : 2.0.64.13
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.134
 DarkSkinImages64.d11 : 1.0.0.134
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSU2PGFX64.d11 : 2.0.15.0
 DTSU2PLFX64.d11 : 2.0.15.0
 DTSU2PREC64.d11 : 2.0.15.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 43.6.16.65
 GrayJadeSkinImages64.d11 : 1.0.0.134
 KAAPORT64.d11 : 4.1105.6000.53
 LightSkinImages64.d11 : 1.0.0.134
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 2.0.0.0
 MaxxAudioRealtek.d11 : 1.3.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.51.0
 MBAPO64.d11 : 1.0.51.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.51.0
 MBTHX32.d11 : 1.0.15.147
 MBTHX64.d11 : 1.0.15.147
 MBWrp64.d11 : 1.0.0.180
 PremiumBlackSkinImages64.d11 : 1.0.0.134
 R4EEA64A.d11 : 7.2.7000.6
 R4EED64A.d11 : 7.2.7000.6
 R4EEG64A.d11 : 7.2.7000.6
 R4EEL64A.d11 : 7.2.7000.6
 R4EEP64A.d11 : 7.2.7000.6
 RCoInst64.d11 : 1.1.6.8
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.146
 RTCOMDLL.d11 : 2.0.0.146
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.42

Readme.txt

RtkAPO64.d11	: 11.0.6000.235
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkGuiCompLib.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.224
SFAPO64.d11	: 3.0.0.14
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.14
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.14
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.11110
slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.8.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.1.0.31
tepeqapo64.d11	: 1.0.0.3
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 2.0.0.0
RCORES64.dat	: 1.1.1.8
<hr/>	
HDMI Driver :	
Windows 2000/XP x86 :	
RtkHDMI.sys	: 5.10.0.6409
Rtaupd.exe	: 2.8.0.3
RHCoInstXP.d11	: 1.1.5.1
Windows XP x64 :	
RtkHDMIX.sys	: 5.10.0.6409
Rtaupd64.exe	: 2.8.0.3
RHCoInst64XP.d11	: 1.1.5.1
Vista/Win7 x86 :	
RtHDMIV.sys	: 6.0.1.6409
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
R4EEA32H.d11	: 7.2.7000.6
R4EED32H.d11	: 7.2.7000.6

Readme.txt

R4EEG32H.d11 : 7.2.7000.6
R4EEL32H.d11 : 7.2.7000.6
R4EEP32H.d11 : 7.2.7000.6
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.5.1
RHDMIExt.d11 : 6.0.6000.213
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.224

Vista/Win7 x64 :

RtHDMIVX.sys : 6.0.1.6409
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
R4EEA64H.d11 : 7.2.7000.6
R4EED64H.d11 : 7.2.7000.6
R4EEG64H.d11 : 7.2.7000.6
R4EEL64H.d11 : 7.2.7000.6
R4EEP64H.d11 : 7.2.7000.6
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDMEx64.d11 : 6.0.6000.213
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.224

Driver Setup Program : 3.34

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.64

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,

ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221,
ALC231, ALC260, ALC262,

ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,

ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676,
ALC680 ALC221, ALC231,

ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276

3. HDMI Device WHQL Support: ATI HDMI Devices

Readme.txt

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP :

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6438
RtkHDAud.sys	: 5.10.0.6438
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.4.0.2
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.4
RtlUpd64.exe	: 2.8.0.4
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.7
RCoInst64XP.d11	: 1.1.6.3
RTCOMDLL.d11	: 1.0.0.113
RtkCoInstXP.d11	: 1.1.6.3
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver :

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6438
AERTSrv.exe	: 1.0.32.10
DTSAudioService.exe	: 1.0.0.0
DTSU2PAuSrv32.exe	: 2.0.15.0
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.75
RtHDVCpl.exe	: 1.0.0.723
RtkAudioService.exe	: 1.0.0.29
RtkNGUI.exe	: 1.0.0.130
RtlUpd.exe	: 2.8.0.4
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.45
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.25
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.130

Readme.txt

DarkSkinImages.d11 : 1.0.0.130
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSU2PGFX32.d11 : 2.0.15.0
 DTSU2PLFX32.d11 : 2.0.15.0
 DTSU2PREC32.d11 : 2.0.15.0
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 43.5.16.65
 GrayJadeSkinImages.d11 : 1.0.0.130
 KAAPORT.d11 : 4.1104.6000.52
 LightSkinImages.d11 : 1.0.0.130
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 2.0.0.0
 MaxxAudioRealtek.d11 : 1.3.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.48.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.48.0
 MBTHX32.d11 : 1.0.15.146
 MBWrp32.d11 : 1.0.0.180
 PremiumBlackSkinImages.d11 : 1.0.0.130
 R4EEA32A.d11 : 7.2.7000.6
 R4EED32A.d11 : 7.2.7000.6
 R4EEG32A.d11 : 7.2.7000.6
 R4EEL32A.d11 : 7.2.7000.6
 R4EEP32A.d11 : 7.2.7000.6
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.146
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.233
 RtkApoApi.d11 : 1.0.0.41
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.1.6.3
 RtkGuiCompLib.d11 : 1.0.0.2
 RtkPgExt.d11 : 6.0.6000.221
 Rt1CPAPI.d11 : 1.0.2.4
 SFAPO.d11 : 3.0.0.14
 SFCOM.d11 : 3.0.0.14
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13

Readme.txt

SFFXHAP0.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.14
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.3.8.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo2.d11	: 1.1.0.31
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 2.0.0.0
WavesLib.d11	: 5.9.7.0
RCORES.dat	: 1.1.1.6
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6438
AERTSr64.exe	: 1.0.64.10
DTSAudioService64.exe	: 1.0.0.0
DTSU2PAuSrv64.exe	: 2.0.15.0
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.75
RAVCp164.exe	: 1.0.0.723
RtkAudioService64.exe	: 1.0.0.29
RtkNGUI64.exe	: 1.0.0.130
RtlUpd64.exe	: 2.8.0.4
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.45
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.25
AERTAC64.d11	: 2.0.64.13
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.130
DarkSkinImages64.d11	: 1.0.0.130
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1

Readme.txt

DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSU2PGFX64.d11 : 2.0.15.0
 DTSU2PLFX64.d11 : 2.0.15.0
 DTSU2PREC64.d11 : 2.0.15.0
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 43.6.16.65
 GrayJadeSkinImages64.d11 : 1.0.0.130
 KAAPORT64.d11 : 4.1104.6000.52
 LightSkinImages64.d11 : 1.0.0.130
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 2.0.0.0
 MaxxAudioRealtek.d11 : 1.3.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.48.0
 MBAPO64.d11 : 1.0.48.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.48.0
 MBTHX32.d11 : 1.0.15.146
 MBTHX64.d11 : 1.0.15.146
 MBWrp64.d11 : 1.0.0.180
 PremiumBlackSkinImages64.d11 : 1.0.0.130
 R4EEA64A.d11 : 7.2.7000.6
 R4EED64A.d11 : 7.2.7000.6
 R4EEG64A.d11 : 7.2.7000.6
 R4EEL64A.d11 : 7.2.7000.6
 R4EEP64A.d11 : 7.2.7000.6
 RCoInst64.d11 : 1.1.6.3
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.146
 RTCOMDLL.d11 : 2.0.0.146
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.41
 RtkAPO64.d11 : 11.0.6000.233
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 RtkGuiCompLib.d11 : 1.0.0.2
 Rt1CPAPI.d11 : 1.0.2.4
 Rt1CPAPI64.d11 : 1.0.2.4
 RtPgEx64.d11 : 6.0.6000.221
 SFAPO64.d11 : 3.0.0.14
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.14
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13
 SFHAPO64.d11 : 2.0.0.13
 SFNHK64.d11 : 3.0.0.14
 SFProc64.d11 : 2.0.0.13
 SFSAPO64.d11 : 2.0.0.13
 SFSS_APO.d11 : 1.0.0.11110

Readme.txt

slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.3.8.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.1.0.31
tepeqapo64.d11	: 1.0.0.3
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 2.0.0.0
RCORES64.dat	: 1.1.1.6
<hr/>	
HDMI Driver :	
Windows 2000/XP x86 :	
RtkHDMI.sys	: 5.10.0.6409
Rtaupd.exe	: 2.8.0.3
RHCoInstXP.d11	: 1.1.5.1
Windows XP x64 :	
RtkHDMIX.sys	: 5.10.0.6409
Rtaupd64.exe	: 2.8.0.3
RHCoInst64XP.d11	: 1.1.5.1
Vista/Win7 x86 :	
RtHDMIV.sys	: 6.0.1.6409
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
R4EEA32H.d11	: 7.2.7000.6
R4EED32H.d11	: 7.2.7000.6
R4EEG32H.d11	: 7.2.7000.6
R4EEL32H.d11	: 7.2.7000.6
R4EEP32H.d11	: 7.2.7000.6
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.1.5.1
RHDMIExt.d11	: 6.0.6000.213
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.224
Vista/Win7 x64 :	
RtHDMIVX.sys	: 6.0.1.6409
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3

Readme.txt

R4EEA64H.d11 : 7.2.7000.6
R4EED64H.d11 : 7.2.7000.6
R4EEG64H.d11 : 7.2.7000.6
R4EEL64H.d11 : 7.2.7000.6
R4EEP64H.d11 : 7.2.7000.6
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.5.1
RHDME64.d11 : 6.0.6000.213
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.224

Driver Setup Program : 3.31

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.63

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221,
ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676,
ALC680 ALC221, ALC231,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6410
RtkHDAud.sys : 5.10.0.6410
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.9.9
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66

Readme.txt

RtlUpd64.exe : 2.8.0.3
 RtlUpd.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.0
 SoundMan.exe : 1.0.0.32
 vncutil64.exe : 1.0.0.38
 vncutil.exe : 1.0.0.38
 Alcmtr.exe : 1.6.0.4
 AlcWzrd.exe : 1.1.0.37
 AMBFilt.sys : 5.10.0.4240
 AMBFt64.sys : 5.10.0.4240
 Monfilt.sys : 5.10.0.4112
 Monft64.sys : 5.10.0.4115
 OAO17Afx.sys : 1.0.7.3
 ALSndMgr.cpl : 1.0.0.11
 RTSndMgr.cpl : 1.0.1.7
 RCoInst64XP.d11 : 1.1.5.1
 RTCOMDLL.d11 : 1.0.0.112
 RtkCoInstXP.d11 : 1.1.5.1
 RtlCPAPI.d11 : 1.0.2.3

Vista/Win7 driver :

Vista/Win7 driver for x86
 RTKVHDA.sys : 6.0.1.6410
 AERTSrv.exe : 1.0.32.10
 DTSAudioService.exe : 1.0.0.0
 FMAPP.exe : 1.32.0.1
 RtHDVBg.exe : 1.0.0.70
 RtHDVCpl.exe : 1.0.0.710
 RtkAudioService.exe : 1.0.0.29
 RtkNGUI.exe : 1.0.0.122
 RtlUpd.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.44
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.25
 AERTACap.d11 : 2.0.32.13
 AERTARen.d11 : 1.0.32.9
 BlackSkinImages.d11 : 1.0.0.122
 DarkSkinImages.d11 : 1.0.0.122
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 43.5.16.65
 GrayJadeSkinImages.d11 : 1.0.0.122
 KAAPORT.d11 : 4.1104.6000.51
 LightSkinImages.d11 : 1.0.0.122
 MaxxAudioAPO.d11 : 1.2.2.0

Readme.txt

MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.3.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.43.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.43.0
 MBTHX32.d11 : 1.0.15.142
 MBWrp32.d11 : 1.0.0.180
 PremiumBlackSkinImages.d11 : 1.0.0.122
 R4EEA32A.d11 : 7.2.7000.6
 R4EED32A.d11 : 7.2.7000.6
 R4EEG32A.d11 : 7.2.7000.6
 R4EEL32A.d11 : 7.2.7000.6
 R4EEP32A.d11 : 7.2.7000.6
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.145
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.222
 RtkApoApi.d11 : 1.0.0.39
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.1.5.1
 RtkGuiCompLib.d11 : 1.0.0.2
 RtkPgExt.d11 : 6.0.6000.212
 Rt1CPAPI.d11 : 1.0.2.4
 SFAPO.d11 : 3.0.0.14
 SFCOM.d11 : 3.0.0.14
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13
 SFFXHAPO.d11 : 2.0.0.13
 SFFXProc.d11 : 2.0.0.13
 SFFXSAPO.d11 : 2.0.0.13
 SFNHK.d11 : 3.0.0.14
 slcc3d32.d11 : 1.0.0.100
 slcshp32.d11 : 1.0.3.0
 slcsii32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slhlim32.d11 : 2.1.0.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.2.1.0
 sltshd32.d11 : 1.2.0.0
 sluapo32.d11 : 2.2.2.0
 slvipp32.d11 : 1.0.1.0
 slviq32.d11 : 2.1.0.0
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 tadefxapo.d11 : 1.0.1.12

Readme.txt

tadefxapo2.d11	: 1.1.0.31
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 1.1.0.0
WavesLib.d11	: 5.9.7.0
RCORES.dat	: 1.1.1.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6410
AERTSr64.exe	: 1.0.64.10
DTSAudioService64.exe	: 1.0.0.0
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.70
RAVCp164.exe	: 1.0.0.710
RtkAudioService64.exe	: 1.0.0.29
RtkNGUI64.exe	: 1.0.0.122
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.44
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.25
AERTAC64.d11	: 2.0.64.13
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.122
DarkSkinImages64.d11	: 1.0.0.122
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 43.6.16.65
GrayJadeSkinImages64.d11	: 1.0.0.122
KAAPORT64.d11	: 4.1104.6000.51
LightSkinImages64.d11	: 1.0.0.122
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.3.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBAPO64.d11	: 1.0.43.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.142
MBTHX64.d11	: 1.0.15.142
MBWrp64.d11	: 1.0.0.180
PremiumBlackSkinImages64.d11	: 1.0.0.122
R4EEA64A.d11	: 7.2.7000.6

Readme.txt

R4EED64A.d11	: 7.2.7000.6
R4EEG64A.d11	: 7.2.7000.6
R4EEL64A.d11	: 7.2.7000.6
R4EEP64A.d11	: 7.2.7000.6
RCoInst64.d11	: 1.1.5.1
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.145
RTCOMDLL.d11	: 2.0.0.145
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.39
RtkAPO64.d11	: 11.0.6000.222
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkGuiCompLib.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.212
SFAPO64.d11	: 3.0.0.14
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.14
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.14
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.11110
slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.2.2.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tadefxapo264.d11	: 1.1.0.31
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 1.1.0.0
RCORES64.dat	: 1.1.1.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6358
RtkAudioSrvATI.exe	: 1.0.0.23

Readme.txt

RtkUpd.exe : 2.8.0.3
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.1.2
RHDMIExt.d11 : 6.0.6000.172
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.183

Vista/Win7 x64:

RtHDMIVX.sys : 6.0.1.6358
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.1.2
RHDMEx64.d11 : 6.0.6000.172
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.183

XP/2K x86:

RtkHDMI.sys : 5.10.0.6358
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.1.2

XP/2K x64:

RtkHDMIX.sys : 5.10.0.6358
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2

Driver Setup Program : 3.30

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.62

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221,
ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676,
ALC680 ALC221, ALC231,

Readme.txt

ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6392
RtkHDAud.sys	: 5.10.0.6392
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.9.5
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.3
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64XP.d11	: 1.1.3.8
RTCOMDLL.d11	: 1.0.0.112
RtkCoInstXP.d11	: 1.1.3.8
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6392
AERTSrv.exe	: 1.0.32.10
DTSAudioService.exe	: 1.0.0.0
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.70
RtHDVCpl.exe	: 1.0.0.700
RtkAudioService.exe	: 1.0.0.29
RtkNGUI.exe	: 1.0.0.116
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.44
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.24
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9

Readme.txt

BlackSkinImages.d11 : 1.0.0.116
 DarkSkinImages.d11 : 1.0.0.116
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.3
 DTSGFXAPONS.d11 : 1.0.0.3
 DTSLFXAPO.d11 : 1.0.0.3
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 43.5.16.65
 GrayJadeSkinImages.d11 : 1.0.0.116
 KAAPORT.d11 : 4.1104.6000.51
 LightSkinImages.d11 : 1.0.0.116
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.2.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.43.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.43.0
 MBTHX32.d11 : 1.0.15.141
 MBWrp32.d11 : 1.0.0.180
 PremiumBlackSkinImages.d11 : 1.0.0.116
 R4EEA32A.d11 : 7.2.7000.6
 R4EED32A.d11 : 7.2.7000.6
 R4EEG32A.d11 : 7.2.7000.6
 R4EEL32A.d11 : 7.2.7000.6
 R4EEP32A.d11 : 7.2.7000.6
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.145
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.216
 RtkApoApi.d11 : 1.0.0.38
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.1.4.5
 RtkGuiCompLib.d11 : 1.0.0.2
 RtkPgExt.d11 : 6.0.6000.204
 Rt1CPAPI.d11 : 1.0.2.4
 SFAPO.d11 : 3.0.0.14
 SFCOM.d11 : 3.0.0.14
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13
 SFFXHAPO.d11 : 2.0.0.13
 SFFXProc.d11 : 2.0.0.13

Readme.txt

SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.14
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.2.2.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 1.2.0.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6392
AERTSr64.exe	: 1.0.64.10
DTSAudioService64.exe	: 1.0.0.0
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.70
RAVCp164.exe	: 1.0.0.700
RtkAudioService64.exe	: 1.0.0.29
RtkNGUI64.exe	: 1.0.0.116
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.44
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.24
AERTAC64.d11	: 2.0.64.13
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.116
DarkSkinImages64.d11	: 1.0.0.116
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 43.6.16.65
GrayJadeSkinImages64.d11	: 1.0.0.116
KAAPORT64.d11	: 4.1104.6000.51

Readme.txt

LightSkinImages64.d11 : 1.0.0.116
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.2.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.43.0
 MBAPO64.d11 : 1.0.43.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.43.0
 MBTHX32.d11 : 1.0.15.141
 MBTHX64.d11 : 1.0.15.141
 MBWrp64.d11 : 1.0.0.180
 PremiumBlackSkinImages64.d11 : 1.0.0.116
 R4EEA64A.d11 : 7.2.7000.6
 R4EED64A.d11 : 7.2.7000.6
 R4EEG64A.d11 : 7.2.7000.6
 R4EEL64A.d11 : 7.2.7000.6
 R4EEP64A.d11 : 7.2.7000.6
 RCoInst64.d11 : 1.1.4.5
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.145
 RTCOMDLL.d11 : 2.0.0.145
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.38
 RtkAPO64.d11 : 11.0.6000.216
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 RtkGuiComplib.d11 : 1.0.0.2
 Rt1CPAPI.d11 : 1.0.2.4
 Rt1CPAPI64.d11 : 1.0.2.4
 RtPgEx64.d11 : 6.0.6000.204
 SFAPO64.d11 : 3.0.0.14
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.14
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13
 SFHAPO64.d11 : 2.0.0.13
 SFNHK64.d11 : 3.0.0.14
 SFProc64.d11 : 2.0.0.13
 SFSAPO64.d11 : 2.0.0.13
 SFSS_APO.d11 : 1.0.0.11110
 slcc3d64.d11 : 1.0.0.100
 slcshp64.d11 : 1.0.3.0
 slcsii64.d11 : 1.0.3.0
 slgeq64.d11 : 1.0.1.0
 slh36064.d11 : 1.0.2.0
 slhlim64.d11 : 2.1.0.0
 slInit64.d11 : 1.1.3.0
 slmaxv64.d11 : 1.2.1.0
 sltshd64.d11 : 1.2.0.0

Readme.txt

sluapo64.d11 : 2.2.2.0
slvipp64.d11 : 1.0.1.0
slviq64.d11 : 2.1.0.0
SRSHp64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tosade.d11 : 1.0.1.12
WavesGUILib.d11 : 1.2.0.0

HDMI Driver :

Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.6358
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.1.1.2
RHDMIExt.d11 : 6.0.6000.172
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.183

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.6358
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.1.2
RHDMEx64.d11 : 6.0.6000.172
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.183

XP/2K x86:
RtkHDMI.sys : 5.10.0.6358
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6358
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2

Driver Setup Program : 3.25

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R2.61

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,

ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221,
ALC231, ALC260, ALC262,

ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,

ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676,
ALC680 ALC221, ALC231,

ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6383
RtkHDAud.sys	: 5.10.0.6383
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.9.5
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64XP.d11	: 1.1.3.8
RTCOMDLL.d11	: 1.0.0.112
RtkCoInstXP.d11	: 1.1.3.8
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6383
-------------	--------------

Readme.txt

AERTSrv.exe	: 1.0.32.10
DTSAudioService.exe	: 1.0.0.0
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.69
RtHDVCpl.exe	: 1.0.0.667
RtkAudioService.exe	: 1.0.0.29
RtkNGUI.exe	: 1.0.0.113
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.44
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.22
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.113
DarkSkinImages.d11	: 1.0.0.113
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.3
DTS GFXAPONS.d11	: 1.0.0.3
DTS LFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 43.5.16.65
GrayJadeSkinImages.d11	: 1.0.0.113
KAAPORT.d11	: 4.1102.6000.49
LightSkinImages.d11	: 1.0.0.113
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.138
MBWrp32.d11	: 1.0.0.180
PremiumBlackSkinImages.d11	: 1.0.0.113
R4EEA32A.d11	: 7.2.7000.6
R4EED32A.d11	: 7.2.7000.6
R4EEG32A.d11	: 7.2.7000.6
R4EEL32A.d11	: 7.2.7000.6
R4EEP32A.d11	: 7.2.7000.6
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.145
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33

Readme.txt

RTEEP32A.d11 : 6.1.6001.33
RtkAPO.d11 : 11.0.6000.216
RtkApoApi.d11 : 1.0.0.36
RtkCfg.d11 : 1.0.0.2
RtkCoInst.d11 : 1.1.4.4
RtkGuiCompLib.d11 : 1.0.0.2
RtkPgExt.d11 : 6.0.6000.203
RtlCPAPI.d11 : 1.0.2.4
SFAPO.d11 : 3.0.0.14
SFCOM.d11 : 3.0.0.14
SFFXComm.d11 : 2.0.0.13
SFFXDAPO.d11 : 2.0.0.13
SFFXHAPO.d11 : 2.0.0.13
SFFXProc.d11 : 2.0.0.13
SFFXSAPO.d11 : 2.0.0.13
SFNHK.d11 : 3.0.0.14
slcc3d32.d11 : 1.0.0.100
slcshp32.d11 : 1.0.3.0
slcsii32.d11 : 1.0.3.0
slgeq32.d11 : 1.0.1.0
slh36032.d11 : 1.0.2.0
slhlim32.d11 : 2.1.0.0
slInit32.d11 : 1.1.3.0
slmaxv32.d11 : 1.2.1.0
sltshd32.d11 : 1.2.0.0
sluapo32.d11 : 2.2.2.0
slvipp32.d11 : 1.0.1.0
slviq32.d11 : 2.1.0.0
SRSHP360.d11 : 1.1.0.0
SRSTSHD.d11 : 1.1.4.0
SRSTSXT.d11 : 3.2.0.0
SRSWOW.d11 : 1.1.3.0
tadefxapo.d11 : 1.0.1.12
tosade.d11 : 1.0.1.12
WavesGUILib.d11 : 1.2.0.0
WavesLib.d11 : 5.9.7.0
Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.6383
AERTSr64.exe : 1.0.64.10
DTSAudioService64.exe : 1.0.0.0
FMAPP.exe : 1.64.0.1
RAVBg64.exe : 1.0.0.69
RAVCp164.exe : 1.0.0.667
RtkAudioService64.exe : 1.0.0.29
RtkNGUI64.exe : 1.0.0.113
RtlUpd64.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.44
GWfilt64.sys : 6.10.0.3
mbfilt64.sys : 6.10.0.8
RTSnMg64.cpl : 1.0.0.22
AERTAC64.d11 : 2.0.64.13
AERTAR64.d11 : 1.0.64.9
BlackSkinImages64.d11 : 1.0.0.113
DarkSkinImages64.d11 : 1.0.0.113
DTSBassEnhancementDLL64.d11 : 1.0.0.1

Readme.txt

DTSTBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 43.6.16.65
 GrayJadeSkinImages64.d11 : 1.0.0.113
 KAAPORT64.d11 : 4.1102.6000.49
 LightSkinImages64.d11 : 1.0.0.113
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.2.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.43.0
 MBAPO64.d11 : 1.0.43.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.43.0
 MBTHX32.d11 : 1.0.15.138
 MBTHX64.d11 : 1.0.15.138
 MBWrp64.d11 : 1.0.0.180
 PremiumBlackSkinImages64.d11 : 1.0.0.113
 R4EEA64A.d11 : 7.2.7000.6
 R4EED64A.d11 : 7.2.7000.6
 R4EEG64A.d11 : 7.2.7000.6
 R4EEL64A.d11 : 7.2.7000.6
 R4EEP64A.d11 : 7.2.7000.6
 RCoInst64.d11 : 1.1.4.4
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.145
 RTCOMDLL.d11 : 2.0.0.145
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.36
 RtkAPO64.d11 : 11.0.6000.216
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 RtkGuiCompLib.d11 : 1.0.0.2
 Rt1CPAPI.d11 : 1.0.2.4
 Rt1CPAPI64.d11 : 1.0.2.4
 RtPgEx64.d11 : 6.0.6000.203
 SFAPO64.d11 : 3.0.0.14
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.14
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13

Readme.txt

SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.14
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.11110
slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.2.2.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 1.2.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6358
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.1.1.2
RHDMIExt.d11	: 6.0.6000.172
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.183
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6358
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.1.1.2
RHDMEx64.d11	: 6.0.6000.172
RTEED64H.d11	: 6.1.6001.33
RTEEG64H.d11	: 6.1.6001.33
RTEEL64H.d11	: 6.1.6001.33
RTEEP64H.d11	: 6.1.6001.33
RtkHDM64.d11	: 11.0.6000.183
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.6358
Rtaupd.exe	: 2.8.0.3

Readme.txt

RHCoInstXP.d11 : 1.1.1.2
XP/2K x64:
RtkHDMIX.sys : 5.10.0.6358
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2
Driver Setup Program : 3.25

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.60

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting:

ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892,
ALC899, ALC861VD, ALC660,
ALC662, ALC663, ALC665, ALC670, ALC672, ALC676, ALC680, ALC221,
ALC231, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275, ALC276

2. Windows 2000/XP WHQL Supporting:

ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889,
ALC892, ALC899, ALC861VC,
ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC676,
ALC680 ALC221, ALC231,
ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273,
ALC275, ALC276

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003,
Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000
SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6363
RtkHDAud.sys : 5.10.0.6363
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.9.4
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37

Readme.txt

AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
RTSndMgr.cpl	: 1.0.1.6
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.1.2.4
RTCOMDLL.d11	: 1.0.0.112
RtkCoInstXP.d11	: 1.1.2.4
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : _____	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6363
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.65
RtHDVCpl.exe	: 1.0.0.660
RtkAudioService.exe	: 1.0.0.28
RtkNGUI.exe	: 1.0.0.107
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.44
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.107
DarkSkinImages.d11	: 1.0.0.107
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.3
DTS GFXAPONS.d11	: 1.0.0.3
DTS LFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 43.5.14.65
GrayJadeSkinImages.d11	: 1.0.0.107
LightSkinImages.d11	: 1.0.0.107
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.136
MBWrp32.d11	: 1.0.0.180

Readme.txt

R4EEA32A.d11	: 7.2.7000.5
R4EED32A.d11	: 7.2.7000.5
R4EEG32A.d11	: 7.2.7000.5
R4EEL32A.d11	: 7.2.7000.5
R4EEP32A.d11	: 7.2.7000.5
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.144
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.210
RtkApoApi.d11	: 1.0.0.36
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.3.2
RtkGuiCompLib.d11	: 1.0.0.2
RtkPgExt.d11	: 6.0.6000.200
RtlCPAPI.d11	: 1.0.2.4
SFAPO.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.11
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.2.2.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 1.2.0.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6363
AERTSr64.exe	: 1.0.64.10
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.65
RAVCp164.exe	: 1.0.0.660
RtkAudioService64.exe	: 1.0.0.28
RtkNGUI64.exe	: 1.0.0.107
RtlUpd64.exe	: 2.8.0.3

Readme.txt

SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.44
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.d11 : 2.0.64.13
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.107
 DarkSkinImages64.d11 : 1.0.0.107
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 43.6.14.65
 GrayJadeSkinImages64.d11 : 1.0.0.107
 LightSkinImages64.d11 : 1.0.0.107
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.2.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.43.0
 MBAPO64.d11 : 1.0.43.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.43.0
 MBTHX32.d11 : 1.0.15.136
 MBTHX64.d11 : 1.0.15.136
 MBWrp64.d11 : 1.0.0.180
 R4EEA64A.d11 : 7.2.7000.5
 R4EED64A.d11 : 7.2.7000.5
 R4EEG64A.d11 : 7.2.7000.5
 R4EEL64A.d11 : 7.2.7000.5
 R4EEP64A.d11 : 7.2.7000.5
 RCoInst64.d11 : 1.1.3.2
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.144
 RTCOMDLL.d11 : 2.0.0.144
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.36
 RtkAPO64.d11 : 11.0.6000.210
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 RtkGuiCompLib.d11 : 1.0.0.2

Readme.txt

Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.200
SFAPO64.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.11
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.11
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.11110
slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.2.2.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 1.2.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6251
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.1.1.2
RHDMIExt.d11	: 6.0.6000.172
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.183
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6251
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.1.1.2
RHDMEx64.d11	: 6.0.6000.172
RTEED64H.d11	: 6.1.6001.33

Readme.txt

RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.183

XP/2K x86:
RtkHDMI.sys : 5.10.0.6251
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2

Driver Setup Program : 3.21

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.59

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC680, ALC221, ALC231, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC672, ALC680, ALC221, ALC231, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6343
RTKHDAUD.sys : 5.10.0.6343
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.9.2
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.3
RtlUpd64.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0

Readme.txt

SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64XP.d11	: 1.1.2.2
RTCOMDLL.d11	: 1.0.0.112
RtkCoInstXP.d11	: 1.1.2.2
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : -----	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6343
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.63
RtHDVCpl.exe	: 1.0.0.653
RtkAudioService.exe	: 1.0.0.28
RtkNGUI.exe	: 1.0.0.102
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.43
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.102
DarkSkinImages.d11	: 1.0.0.102
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3
DTSLFXAPO.d11	: 1.0.0.3
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 43.5.14.65
GrayJadeSkinImages.d11	: 1.0.0.102
LightSkinImages.d11	: 1.0.0.102
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBPPCn32.d11	: 1.0.0.110

Readme.txt

MBpp1d32.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.132
MBWrp32.d11	: 1.0.0.180
R4EEA32A.d11	: 7.2.7000.5
R4EED32A.d11	: 7.2.7000.5
R4EEG32A.d11	: 7.2.7000.5
R4EEL32A.d11	: 7.2.7000.5
R4EEP32A.d11	: 7.2.7000.5
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.144
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.209
RtkApoApi.d11	: 1.0.0.36
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.2.2
RtkGuiCompLib.d11	: 1.0.0.2
RtkPgExt.d11	: 6.0.6000.198
Rt1CPAPI.d11	: 1.0.2.4
SFAPO.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.11
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.2.2.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
tadefxapo.d11	: 1.0.1.12
tosade.d11	: 1.0.1.12
WavesGUILib.d11	: 1.2.0.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6343
AERTSr64.exe	: 1.0.64.10
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.63
RAVCp164.exe	: 1.0.0.653

Readme.txt

RtkAudioService64.exe	: 1.0.0.28
RtkNGUI64.exe	: 1.0.0.102
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.43
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.19
AERTAC64.d11	: 2.0.64.13
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.102
DarkSkinImages64.d11	: 1.0.0.102
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 43.6.14.65
GrayJadeSkinImages64.d11	: 1.0.0.102
LightSkinImages64.d11	: 1.0.0.102
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBAPO64.d11	: 1.0.43.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.132
MBTHX64.d11	: 1.0.15.132
MBWrp64.d11	: 1.0.0.180
R4EEA64A.d11	: 7.2.7000.5
R4EED64A.d11	: 7.2.7000.5
R4EEG64A.d11	: 7.2.7000.5
R4EEL64A.d11	: 7.2.7000.5
R4EEP64A.d11	: 7.2.7000.5
RCoInst64.d11	: 1.1.2.2
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.144
RTCOMDLL.d11	: 2.0.0.144
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.36
RtkAPO64.d11	: 11.0.6000.209

Readme.txt

RtkCfg.dll	: 1.0.0.1
RtkCfg64.dll	: 1.0.0.2
RtkGuiCompLib.dll	: 1.0.0.2
Rt1CPAPI.dll	: 1.0.2.4
Rt1CPAPI64.dll	: 1.0.2.4
RtPgEx64.dll	: 6.0.6000.198
SFAPO64.dll	: 3.0.0.11
SFCOM.dll	: 3.0.0.11
SFCOM64.dll	: 3.0.0.11
SFComm64.dll	: 2.0.0.13
SFDAPO64.dll	: 2.0.0.13
SFHAP064.dll	: 2.0.0.13
SFNHK64.dll	: 3.0.0.11
SFProc64.dll	: 2.0.0.13
SFSAP064.dll	: 2.0.0.13
SFSS_APO.dll	: 1.0.0.11110
slcc3d64.dll	: 1.0.0.100
slcshp64.dll	: 1.0.3.0
slcsii64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slhlim64.dll	: 2.1.0.0
slInit64.dll	: 1.1.3.0
slmaxv64.dll	: 1.2.1.0
sltshd64.dll	: 1.2.0.0
sluapo64.dll	: 2.2.2.0
slvipp64.dll	: 1.0.1.0
slviq64.dll	: 2.1.0.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
tadefxapo.dll	: 1.0.1.12
tosade.dll	: 1.0.1.12
WavesGUILib.dll	: 1.2.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6251
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.dll	: 6.0.6001.18
RH3DHT32.dll	: 6.0.6001.18
RHCoInst.dll	: 1.1.1.2
RHDMIExt.dll	: 6.0.6000.172
RTEED32H.dll	: 6.1.6001.33
RTEEG32H.dll	: 6.1.6001.33
RTEEL32H.dll	: 6.1.6001.33
RTEEP32H.dll	: 6.1.6001.33
RtkHDMI.dll	: 11.0.6000.183
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6251
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.dll	: 6.0.6001.18
RH3DHT64.dll	: 6.0.6001.18

Readme.txt

RHCoInst64.d11 : 1.1.1.2
RHDMEx64.d11 : 6.0.6000.172
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.183

XP/2K x86:
RtkHDMI.sys : 5.10.0.6251
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2

Driver Setup Program : 3.20

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package –KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.58

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262,ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267,ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013) For Windows 2000 SP4, XP SP1, XP SP2, Server 2003 SP1.

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6316
RtkHDAud.sys : 5.10.0.6316
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.8.7
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3

Readme.txt

RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64XP.d11	: 1.1.1.2
RTCOMDLL.d11	: 1.0.0.112
RtkCoInstXP.d11	: 1.1.1.2
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : _____	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6316
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.58
RtHDVCpl.exe	: 1.0.0.647
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.99
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.41
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.99
DarkSkinImages.d11	: 1.0.0.99
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3
DTSLFXAPO.d11	: 1.0.0.3
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 43.5.14.65
GrayJadeSkinImages.d11	: 1.0.0.99
LightSkinImages.d11	: 1.0.0.99
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0

Readme.txt

MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.130
MBWrp32.d11	: 1.0.0.180
R4EEA32A.d11	: 7.1.7000.5
R4EED32A.d11	: 7.1.7000.5
R4EEG32A.d11	: 7.1.7000.5
R4EEL32A.d11	: 7.1.7000.5
R4EEP32A.d11	: 7.1.7000.5
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.143
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.201
RtkApoApi.d11	: 1.0.0.34
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.1.6
RtkGuiCompLib.d11	: 1.0.0.2
RtkPgExt.d11	: 6.0.6000.192
Rt1CPAPI.d11	: 1.0.2.4
SFAPO.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.11
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.2.2.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.0.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6316
AERTSr64.exe	: 1.0.64.10
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.58

Readme.txt

RAVCp164.exe : 1.0.0.647
 RtkAudioService64.exe : 1.0.0.27
 RtkNGUI64.exe : 1.0.0.99
 RtlUpd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.41
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.d11 : 2.0.64.13
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.99
 DarkSkinImages64.d11 : 1.0.0.99
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 43.6.14.65
 GrayJadeSkinImages64.d11 : 1.0.0.99
 LightSkinImages64.d11 : 1.0.0.99
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.2.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.43.0
 MBAPO64.d11 : 1.0.43.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.43.0
 MBTHX32.d11 : 1.0.15.130
 MBTHX64.d11 : 1.0.15.130
 MBWrp64.d11 : 1.0.0.180
 R4EEA64A.d11 : 7.1.7000.5
 R4EED64A.d11 : 7.1.7000.5
 R4EEG64A.d11 : 7.1.7000.5
 R4EEL64A.d11 : 7.1.7000.5
 R4EEP64A.d11 : 7.1.7000.5
 RCoInst64.d11 : 1.1.1.6
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.143
 RTCOMDLL.d11 : 2.0.0.143
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.34

Readme.txt

RtkAPO64.d11	: 11.0.6000.201
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkGuiCompLib.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.192
SFAPO64.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.11
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.11
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.11110
slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.2.2.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6251
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.1.1.2
RHDMIExt.d11	: 6.0.6000.172
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.183
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6251
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.1.1.2

Readme.txt

RHDMEx64.d11 : 6.0.6000.172
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.183

XP/2K x86:
RtkHDMI.sys : 5.10.0.6251
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2

Driver Setup Program : 3.18

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.57

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262,ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267,ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

- 1.) Driver :
 - 1. Customizations.
- 2.) Package :

1. Realtek Setup program will update audio driver automatically in update Realtek audio driver case under Vista/Windows 7.

Realtek setup program will un-install the previous version

Realatek audio driver on the system first.

And it will re-install Realtek audio driver automatically after system re-boot.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6299
RtkHDAud.sys : 5.10.0.6299
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37

Readme.txt

MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.8.5
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64XP.d11	: 1.1.1.2
RTCOMDLL.d11	: 1.0.0.112
RtkCoInstXP.d11	: 1.1.1.2
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : _____	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6299
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.58
RtHDVCpl.exe	: 1.0.0.637
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.96
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.96
DarkSkinImages.d11	: 1.0.0.96
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3
DTSLFXAPO.d11	: 1.0.0.3
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.38.65
GrayJadeSkinImages.d11	: 1.0.0.96
LightSkinImages.d11	: 1.0.0.96
MaxxAudioAPO.d11	: 1.2.2.0

Readme.txt

MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.129
MBWrp32.d11	: 1.0.0.180
R4EEA32A.d11	: 7.1.7000.5
R4EED32A.d11	: 7.1.7000.5
R4EEG32A.d11	: 7.1.7000.5
R4EEL32A.d11	: 7.1.7000.5
R4EEP32A.d11	: 7.1.7000.5
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.142
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.198
RtkApoApi.d11	: 1.0.0.33
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.1.2
RtkGuiCompLib.d11	: 1.0.0.2
RtkPgExt.d11	: 6.0.6000.190
Rt1CPAPI.d11	: 1.0.2.4
SFAPO.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.11
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.2.2.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.0.0
WavesLib.d11	: 5.9.7.0

Readme.txt

Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.6299
AERTSr64.exe : 1.0.64.10
FMAPP.exe : 1.64.0.1
RAVBg64.exe : 1.0.0.58
RAVCp164.exe : 1.0.0.637
RtkAudioService64.exe : 1.0.0.27
RtkNGUI64.exe : 1.0.0.96
RtlUpd64.exe : 2.8.0.3
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.40
GWfilt64.sys : 6.10.0.3
mbfilt64.sys : 6.10.0.8
RTSnMg64.cpl : 1.0.0.19
AERTAC64.d11 : 2.0.64.13
AERTAR64.d11 : 1.0.64.9
BlackSkinImages64.d11 : 1.0.0.96
DarkSkinImages64.d11 : 1.0.0.96
DTSBassEnhancementDLL64.d11 : 1.0.0.1
DTSBoostDLL64.d11 : 1.0.0.1
DTSGainCompensatorDLL64.d11 : 1.0.0.1
DTSGFXAPO64.d11 : 1.0.0.3
DTSGFXAPONS64.d11 : 1.0.0.3
DTSLFXAPO64.d11 : 1.0.0.3
DTSLimiterDLL64.d11 : 1.0.0.1
DTSNeoPCDLL64.d11 : 1.0.0.1
DTSS2HeadphoneDLL64.d11 : 1.0.0.1
DTSS2SpeakerDLL64.d11 : 1.0.0.1
DTSSymmetryDLL64.d11 : 1.0.0.1
DTSVoiceClarityDLL64.d11 : 1.0.0.1
FMAPO64.d11 : 42.6.38.65
GrayJadeSkinImages64.d11 : 1.0.0.96
LightSkinImages64.d11 : 1.0.0.96
MaxxAudioAPO20.d11 : 2.2.9.0
MaxxAudioAPO30.d11 : 3.2.1.1
MaxxAudioEQ.d11 : 5.9.7.0
MaxxAudioRealtek.d11 : 1.2.0.0
MaxxAudioRealtek2.d11 : 1.0.7.0
MaxxVolumeSDAPO.d11 : 3.1.0.0
MBAPO32.d11 : 1.0.43.0
MBAPO64.d11 : 1.0.43.0
MBPPCn64.d11 : 1.0.0.110
MBppld64.d11 : 1.0.43.0
MBTHX32.d11 : 1.0.15.129
MBTHX64.d11 : 1.0.15.129
MBWrp64.d11 : 1.0.0.180
R4EEA64A.d11 : 7.1.7000.5
R4EED64A.d11 : 7.1.7000.5
R4EEG64A.d11 : 7.1.7000.5
R4EEL64A.d11 : 7.1.7000.5
R4EEP64A.d11 : 7.1.7000.5
RCoInst64.d11 : 1.1.1.2
RP3DAA64.d11 : 6.0.6001.18
RP3DHT64.d11 : 6.0.6001.18
RtCOM64.d11 : 2.0.0.142
RTCOMDLL.d11 : 2.0.0.142

Readme.txt

RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.33
RtkAPO64.d11	: 11.0.6000.198
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkGuiCompLib.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.190
SFAPO64.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.11
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.11
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.11110
slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.2.2.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6251
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.1.1.2
RHDMIExt.d11	: 6.0.6000.172
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.183
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6251

Readme.txt

RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.1.2
RHDMEx64.d11 : 6.0.6000.172
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.183

XP/2K x86:
RtkHDMI.sys : 5.10.0.6251
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2

Driver Setup Program : 3.15

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.56

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262,ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267,ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6278
RtkHDAud.sys : 5.10.0.6278
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.8.0
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19

Readme.txt

RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
AMBFt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.6
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.1.1.2
RTCOMDLL.d11	: 1.0.0.112
RtkCoInstXP.d11	: 1.1.1.2
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : -----	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6278
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.55
RtHDVCpl.exe	: 1.0.0.629
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.89
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.89
DarkSkinImages.d11	: 1.0.0.89
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3
DTSLFXAPO.d11	: 1.0.0.3
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 43.5.7.65
GrayJadeSkinImages.d11	: 1.0.0.89
LightSkinImages.d11	: 1.0.0.89
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1

Readme.txt

MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.127
MBWrp32.d11	: 1.0.0.180
R4EEA32A.d11	: 7.1.7000.5
R4EED32A.d11	: 7.1.7000.5
R4EEG32A.d11	: 7.1.7000.5
R4EEL32A.d11	: 7.1.7000.5
R4EEP32A.d11	: 7.1.7000.5
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.142
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.193
RtkApoApi.d11	: 1.0.0.32
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.1.2
RtkGuiCompLib.d11	: 1.0.0.2
RtkPgExt.d11	: 6.0.6000.181
Rt1CPAPI.d11	: 1.0.2.4
SFAPO.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.11
slcc3d32.d11	: 1.0.0.100
slcshp32.d11	: 1.0.3.0
slcsii32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slhlim32.d11	: 2.1.0.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.2.1.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 2.2.0.0
slvipp32.d11	: 1.0.1.0
slviq32.d11	: 2.1.0.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.0.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6278

Readme.txt

AERTSr64.exe	: 1.0.64.10
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.55
RAVCp164.exe	: 1.0.0.629
RtkAudioService64.exe	: 1.0.0.27
RtkNGUI64.exe	: 1.0.0.89
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.40
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.19
AERTAC64.d11	: 2.0.64.13
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.89
DarkSkinImages64.d11	: 1.0.0.89
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.3
DTS GFXAPONS64.d11	: 1.0.0.3
DTS LFXAPO64.d11	: 1.0.0.3
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 43.6.7.65
GrayJadeSkinImages64.d11	: 1.0.0.89
LightSkinImages64.d11	: 1.0.0.89
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0
MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.43.0
MBAPO64.d11	: 1.0.43.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.43.0
MBTHX32.d11	: 1.0.15.127
MBTHX64.d11	: 1.0.15.127
MBWrp64.d11	: 1.0.0.180
R4EEA64A.d11	: 7.1.7000.5
R4EED64A.d11	: 7.1.7000.5
R4EEG64A.d11	: 7.1.7000.5
R4EEL64A.d11	: 7.1.7000.5
R4EEP64A.d11	: 7.1.7000.5
RCoInst64.d11	: 1.1.1.2
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.142
RTCOMDLL.d11	: 2.0.0.142
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33

Readme.txt

RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.32
RtkAPO64.d11	: 11.0.6000.193
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkGuiCompLib.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.181
SFAPO64.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.11
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.11
SFProc64.d11	: 2.0.0.13
SFSAP064.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.11110
slcc3d64.d11	: 1.0.0.100
slcshp64.d11	: 1.0.3.0
slcsii64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slhlim64.d11	: 2.1.0.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.2.1.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 2.2.0.0
slvipp64.d11	: 1.0.1.0
slviq64.d11	: 2.1.0.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6251
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.1.1.2
RHDMIExt.d11	: 6.0.6000.172
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.183
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6251
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3

Readme.txt

RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.1.1.2
RHDME64.d11 : 6.0.6000.172
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.183

XP/2K x86:
RtkHDMI.sys : 5.10.0.6251
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2

Driver Setup Program : 3.14

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.55

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262,ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267,ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6257
RtkHDAud.sys : 5.10.0.6257
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.7.5
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19

Readme.txt

RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.3
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64XP.d11	: 1.1.1.2
RTCOMDLL.d11	: 1.0.0.112
RtkCoInstXP.d11	: 1.1.1.2
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : -----	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6257
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.54
RtHDVCpl.exe	: 1.0.0.617
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.81
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.81
DarkSkinImages.d11	: 1.0.0.81
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3
DTSLFXAPO.d11	: 1.0.0.3
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 43.5.7.65
GrayJadeSkinImages.d11	: 1.0.0.81
LightSkinImages.d11	: 1.0.0.81
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.2.0.0

Readme.txt

MaxxAudioRealtek2.d11	: 1.0.7.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.41.0
MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.41.0
MBTHX32.d11	: 1.0.15.123
MBWrp32.d11	: 1.0.0.180
R4EEA32A.d11	: 7.1.7000.5
R4EED32A.d11	: 7.1.7000.5
R4EEG32A.d11	: 7.1.7000.5
R4EEL32A.d11	: 7.1.7000.5
R4EEP32A.d11	: 7.1.7000.5
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.142
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.184
RtkApoApi.d11	: 1.0.0.32
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.1.2
RtkGuiCompLib.d11	: 1.0.0.2
RtkPgExt.d11	: 6.0.6000.173
Rt1CPAPI.d11	: 1.0.2.4
SFAPO.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAPO.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.11
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 1.8.34.0
slvipp32.d11	: 1.0.1.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.0.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6257
AERTSr64.exe	: 1.0.64.10
FMAPP.exe	: 1.64.0.1
RAVBg64.exe	: 1.0.0.54
RAVCp164.exe	: 1.0.0.617
RtkAudioService64.exe	: 1.0.0.27
RtkNGUI64.exe	: 1.0.0.81

Readme.txt

RtlUpd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.40
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.d11 : 2.0.64.13
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.81
 DarkSkinImages64.d11 : 1.0.0.81
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 43.6.7.65
 GrayJadeSkinImages64.d11 : 1.0.0.81
 LightSkinImages64.d11 : 1.0.0.81
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.2.0.0
 MaxxAudioRealtek2.d11 : 1.0.7.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.41.0
 MBAPO64.d11 : 1.0.41.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.41.0
 MBTHX32.d11 : 1.0.15.123
 MBTHX64.d11 : 1.0.15.123
 MBWrp64.d11 : 1.0.0.180
 R4EEA64A.d11 : 7.1.7000.5
 R4EED64A.d11 : 7.1.7000.5
 R4EEG64A.d11 : 7.1.7000.5
 R4EEL64A.d11 : 7.1.7000.5
 R4EEP64A.d11 : 7.1.7000.5
 RCoInst64.d11 : 1.1.1.2
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.142
 RTCOMDLL.d11 : 2.0.0.142
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.32
 RtkAPO64.d11 : 11.0.6000.184
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2

Readme.txt

RtkGuiCompLib.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.173
SFAPO64.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.11
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.11
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.11110
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 1.8.34.0
slvipp64.d11	: 1.0.1.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6251
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.1.1.2
RHDMIExt.d11	: 6.0.6000.172
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.183
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6251
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.1.1.2
RHDMEx64.d11	: 6.0.6000.172
RTEED64H.d11	: 6.1.6001.33
RTEEG64H.d11	: 6.1.6001.33
RTEEL64H.d11	: 6.1.6001.33
RTEEP64H.d11	: 6.1.6001.33
RtkHDM64.d11	: 11.0.6000.183

Readme.txt

XP/2K x86:
RtkHDMI.sys : 5.10.0.6251
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.1.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6251
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.1.1.2

Driver Setup Program : 3.14

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.54

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262,ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC887, ALC888, ALC889, ALC892, ALC899, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC670, ALC680 ALC260, ALC262, ALC267,ALC268, ALC269, ALC270, ALC272, ALC273, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6235
RtkHDAud.sys : 5.10.0.6235
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.7.4
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38
Alcmtr.exe : 1.6.0.4
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Monfilt.sys : 5.10.0.4112

Readme.txt

Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64XP.d11	: 1.1.1.0
RTCOMDLL.d11	: 1.0.0.110
RtkCoInstXP.d11	: 1.1.1.0
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : <hr/>	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6235
AERTSrv.exe	: 1.0.32.10
FMAPP.exe	: 1.32.0.1
RtHDVBg.exe	: 1.0.0.51
RtHDVCpl.exe	: 1.0.0.603
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.76
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.76
DarkSkinImages.d11	: 1.0.0.76
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.3
DTSGFXAPONS.d11	: 1.0.0.3
DTSLFXAPO.d11	: 1.0.0.3
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 43.5.6.68
GrayJadeSkinImages.d11	: 1.0.0.76
LightSkinImages.d11	: 1.0.0.76
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.1.1
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.1.0.0
MaxxAudioRealtek2.d11	: 1.0.3.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.41.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.41.0
MBTHX32.d11	: 1.0.15.122
MBWrp32.d11	: 1.0.0.180
R4EEA32A.d11	: 7.1.7000.5
R4EED32A.d11	: 7.1.7000.5
R4EEG32A.d11	: 7.1.7000.5

Readme.txt

R4EEL32A.d11 : 7.1.7000.5
 R4EEP32A.d11 : 7.1.7000.5
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.140
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.178
 RtkApoApi.d11 : 1.0.0.31
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.1.1.1
 RtkGuiCompLib.d11 : 1.0.0.2
 RtkPgExt.d11 : 6.0.6000.165
 Rt1CPAPI.d11 : 1.0.2.4
 SFAPO.d11 : 3.0.0.11
 SFCOM.d11 : 3.0.0.11
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13
 SFFXHAPO.d11 : 2.0.0.13
 SFFXProc.d11 : 2.0.0.13
 SFFXSAPO.d11 : 2.0.0.13
 SFNHK.d11 : 3.0.0.11
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.1.2.0
 sltshd32.d11 : 1.2.0.0
 sluapo32.d11 : 1.8.34.0
 slvipp32.d11 : 1.0.1.0
 SRSH360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesGUILib.d11 : 1.1.0.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6235
 AERTSr64.exe : 1.0.64.10
 FMAPP.exe : 1.64.0.1
 RAVBg64.exe : 1.0.0.51
 RAVCp164.exe : 1.0.0.603
 RtkAudioService64.exe : 1.0.0.27
 RtkNGUI64.exe : 1.0.0.76
 Rt1Upd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.40
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.d11 : 2.0.64.13
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.76
 DarkSkinImages64.d11 : 1.0.0.76

Readme.txt

DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.3
 DTSGFXAPONS64.d11 : 1.0.0.3
 DTSLFXAPO64.d11 : 1.0.0.3
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 43.6.6.68
 GrayJadeSkinImages64.d11 : 1.0.0.76
 LightSkinImages64.d11 : 1.0.0.76
 MaxxAudioAPO20.d11 : 2.2.9.0
 MaxxAudioAPO30.d11 : 3.2.1.1
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.1.0.0
 MaxxAudioRealtek2.d11 : 1.0.3.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.41.0
 MBAPO64.d11 : 1.0.41.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.41.0
 MBTHX32.d11 : 1.0.15.122
 MBTHX64.d11 : 1.0.15.122
 MBWrp64.d11 : 1.0.0.180
 R4EEA64A.d11 : 7.1.7000.5
 R4EED64A.d11 : 7.1.7000.5
 R4EEG64A.d11 : 7.1.7000.5
 R4EEL64A.d11 : 7.1.7000.5
 R4EEP64A.d11 : 7.1.7000.5
 RCoInst64.d11 : 1.1.1.1
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.140
 RTCOMDLL.d11 : 2.0.0.140
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.31
 RtkAPO64.d11 : 11.0.6000.178
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 RtkGuiCompLib.d11 : 1.0.0.2
 Rt1CPAPI.d11 : 1.0.2.4
 Rt1CPAPI64.d11 : 1.0.2.4
 RtPgEx64.d11 : 6.0.6000.165
 SFAPO64.d11 : 3.0.0.11
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.11
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13
 SFHAPO64.d11 : 2.0.0.13

Readme.txt

SFNHK64.d11	: 3.0.0.11
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.10280
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 1.8.34.0
slvipp64.d11	: 1.0.1.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.1.0.0
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.8.6
RHDMIExt.d11	: 6.0.6000.127
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.151
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6121
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.8.6
RHDMEx64.d11	: 6.0.6000.127
RTEED64H.d11	: 6.1.6001.33
RTEEG64H.d11	: 6.1.6001.33
RTEEL64H.d11	: 6.1.6001.33
RTEEP64H.d11	: 6.1.6001.33
RtkHDM64.d11	: 11.0.6000.151
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.6121
Rtaupd.exe	: 2.8.0.3
RHCoInstXP.d11	: 1.0.8.6
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.6121
Rtaupd64.exe	: 2.8.0.3
RHCoInst64XP.d11	: 1.0.8.6

Driver Setup Program : 3.13

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.53

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6215
RtkHDAud.sys	: 5.10.0.6215
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.7.2
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64.dll	: 1.1.0.3
RCoInst64XP.dll	: 1.1.0.4
RTCOMDLL.dll	: 1.0.0.108
RtkCoInst.dll	: 1.1.0.3
RtkCoInstXP.dll	: 1.1.0.4
Rt1CPAPI.dll	: 1.0.2.3

Vista/Win7 driver : _____

Readme.txt

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6215
AERTSrv.exe	: 1.0.32.10
RtHDVbg.exe	: 1.0.0.46
RtHDVCpl.exe	: 1.0.0.590
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.65
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.65
DarkSkinImages.d11	: 1.0.0.65
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSAFXAPO.d11	: 1.0.0.3
DTSAFXAPONS.d11	: 1.0.0.3
DTSAFXAPO.d11	: 1.0.0.3
DTS LimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.35.67
GrayJadeSkinImages.d11	: 1.0.0.65
LightSkinImages.d11	: 1.0.0.65
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.9.0
MaxxAudioAPO30.d11	: 3.2.0.2
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.0.0.0
MaxxAudioRealtek2.d11	: 1.0.2.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.41.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.41.0
MBTHX32.d11	: 1.0.15.122
MBWrp32.d11	: 1.0.0.180
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.137
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.168
RtkApoApi.d11	: 1.0.0.28
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.0.8
RtkGuiCompLib.d11	: 1.0.0.2
RtkPgExt.d11	: 6.0.6000.159

Readme.txt

RtlCPAPI.d11	: 1.0.2.4
SFAPO.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFFXComm.d11	: 2.0.0.13
SFFXDAPO.d11	: 2.0.0.13
SFFXHAP0.d11	: 2.0.0.13
SFFXProc.d11	: 2.0.0.13
SFFXSAPO.d11	: 2.0.0.13
SFNHK.d11	: 3.0.0.11
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 1.8.34.0
slvipp32.d11	: 1.0.1.0
SRSH360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesGUILib.d11	: 1.0.0.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6215
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.46
RAVCp164.exe	: 1.0.0.590
RtkAudioService64.exe	: 1.0.0.27
RtkNGUI64.exe	: 1.0.0.65
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.40
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.19
AERTAC64.d11	: 2.0.64.13
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.65
DarkSkinImages64.d11	: 1.0.0.65
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.3
DTSGFXAPONS64.d11	: 1.0.0.3
DTSLFXAPO64.d11	: 1.0.0.3
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 42.6.35.67
GrayJadeSkinImages64.d11	: 1.0.0.65
LightSkinImages64.d11	: 1.0.0.65
MaxxAudioAPO20.d11	: 2.2.9.0

Readme.txt

MaxxAudioAPO30.d11	: 3.2.0.2
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.0.0.0
MaxxAudioRealtek2.d11	: 1.0.2.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.41.0
MBAPO64.d11	: 1.0.41.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.41.0
MBTHX32.d11	: 1.0.15.122
MBTHX64.d11	: 1.0.15.122
MBWrp64.d11	: 1.0.0.180
RCoInst64.d11	: 1.1.0.8
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.137
RTCOMDLL.d11	: 2.0.0.137
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.28
RtkAPO64.d11	: 11.0.6000.168
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkGuiCompLib.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.159
SFAPO64.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.11
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.11
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.8310
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 1.8.34.0
slvipp64.d11	: 1.0.1.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.0.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23

Readme.txt

RtkUpd.exe : 2.8.0.3
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.8.6
RHDMIExt.d11 : 6.0.6000.127
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.151

Vista/Win7 x64:

RtHDMIVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.8.6
RHDMEx64.d11 : 6.0.6000.127
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.151

XP/2K x86:

RtkHDMI.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.0.8.6

XP/2K x64:

RtkHDMIX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.0.8.6

Driver Setup Program : 3.10

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.52

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

- 1.) Driver :
 - 1. Customizations.

Windows 2000/XP :

Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.6194
RtkHDAud.sys	: 5.10.0.6194
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.6.9
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.3
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.6
RCoInst64.dll	: 1.1.0.3
RCoInst64XP.dll	: 1.1.0.3
RTCOMDLL.dll	: 1.0.0.108
RtkCoInst.dll	: 1.1.0.3
RtkCoInstXP.dll	: 1.1.0.3
RtlCPAPI.dll	: 1.0.2.3

Vista/Win7 driver :

Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6194
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.41
RtHDVCpl.exe	: 1.0.0.576
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.57
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.40
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.dll	: 2.0.32.13
AERTARen.dll	: 1.0.32.9
BlackSkinImages.dll	: 1.0.0.57
DarkSkinImages.dll	: 1.0.0.57
DTSBassEnhancementDLL.dll	: 1.0.0.1
DTSBoostDLL.dll	: 1.0.0.1
DTSGainCompensatorDLL.dll	: 1.0.0.1
DTSGFXAPO.dll	: 1.0.0.2
DTSGFXAPONS.dll	: 1.0.0.2

Readme.txt

DTSLFXAPO.d11 : 1.0.0.2
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 42.5.35.66
 GrayJadeSkinImages.d11 : 1.0.0.57
 LightSkinImages.d11 : 1.0.0.57
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.8.0
 MaxxAudioAPO30.d11 : 3.2.0.2
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.0.0.0
 MaxxAudioRealtek2.d11 : 1.0.2.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.40.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.40.0
 MBTHX32.d11 : 1.0.15.120
 MBWrp32.d11 : 1.0.0.180
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.137
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.165
 RtkApoApi.d11 : 1.0.0.24
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.1.0.3
 RtkGuiCompLib.d11 : 1.0.0.2
 RtkPgExt.d11 : 6.0.6000.152
 Rt1CPAPI.d11 : 1.0.2.4
 SFAPO.d11 : 3.0.0.11
 SFCOM.d11 : 3.0.0.11
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13
 SFFXHAPO.d11 : 2.0.0.13
 SFFXProc.d11 : 2.0.0.13
 SFFXSAPO.d11 : 2.0.0.13
 SFNHK.d11 : 3.0.0.11
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.1.2.0
 sltshd32.d11 : 1.2.0.0
 sluapo32.d11 : 1.8.34.0
 slvippp32.d11 : 1.0.1.0
 SRSH360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0

Readme.txt

WavesGUILib.d11 : 1.0.0.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6194
 AERTSr64.exe : 1.0.64.10
 RAVBg64.exe : 1.0.0.41
 RAVCp164.exe : 1.0.0.576
 RtkAudioService64.exe : 1.0.0.27
 RtkNGUI64.exe : 1.0.0.57
 RtlUpd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.40
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.d11 : 2.0.64.13
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.57
 DarkSkinImages64.d11 : 1.0.0.57
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.2
 DTSGFXAPONS64.d11 : 1.0.0.2
 DTSLFXAPO64.d11 : 1.0.0.2
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 42.6.35.66
 GrayJadeSkinImages64.d11 : 1.0.0.57
 LightSkinImages64.d11 : 1.0.0.57
 MaxxAudioAPO20.d11 : 2.2.8.0
 MaxxAudioAPO30.d11 : 3.2.0.2
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.0.0.0
 MaxxAudioRealtek2.d11 : 1.0.2.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.40.0
 MBAPO64.d11 : 1.0.40.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.40.0
 MBTHX32.d11 : 1.0.15.120
 MBTHX64.d11 : 1.0.15.120
 MBWrp64.d11 : 1.0.0.180
 RCoInst64.d11 : 1.1.0.3
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.137
 RTCOMDLL.d11 : 2.0.0.137
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33

Readme.txt

RtkApi64.d11	: 1.0.0.24
RtkAPO64.d11	: 11.0.6000.165
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkGuiCompLib.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.152
SFAPO64.d11	: 3.0.0.11
SFCOM.d11	: 3.0.0.11
SFCOM64.d11	: 3.0.0.11
SFComm64.d11	: 2.0.0.13
SFDAPO64.d11	: 2.0.0.13
SFHAP064.d11	: 2.0.0.13
SFNHK64.d11	: 3.0.0.11
SFProc64.d11	: 2.0.0.13
SFSAPO64.d11	: 2.0.0.13
SFSS_APO.d11	: 1.0.0.8020
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 1.8.34.0
slvipp64.d11	: 1.0.1.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.0.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.8.6
RHDMIExt.d11	: 6.0.6000.127
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.151
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6121
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.8.6
RHDMEx64.d11	: 6.0.6000.127
RTEED64H.d11	: 6.1.6001.33
RTEEG64H.d11	: 6.1.6001.33

Readme.txt

RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.151

XP/2K x86:
RtkHDMI.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.0.8.6

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.0.8.6

Driver Setup Program : 3.07

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.51

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6167
RtkHDAud.sys : 5.10.0.6167
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.6.2
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38

Readme.txt

AMBfilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.5
RCoInst64XP.d11	: 1.0.9.9
RTCOMDLL.d11	: 1.0.0.108
RtkCoInstXP.d11	: 1.0.9.9
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : <hr/>	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6167
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.40
RtHDVCpl.exe	: 1.0.0.553
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.53
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.13
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.53
DarkSkinImages.d11	: 1.0.0.53
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.2
DTSGFXAPONS.d11	: 1.0.0.2
DTSLFXAPO.d11	: 1.0.0.2
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.32.66
GrayJadeSkinImages.d11	: 1.0.0.53
LightSkinImages.d11	: 1.0.0.53
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.8.0
MaxxAudioAPO30.d11	: 3.2.0.2
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.0.0.0
MaxxAudioRealtek2.d11	: 1.0.0.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.115
MBWrp32.d11	: 1.0.0.180
RP3DAA32.d11	: 6.0.6001.18

Readme.txt

RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.136
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.160
 RtkApoApi.d11 : 1.0.0.21
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.1.0.0
 RtkGuiCompLib.d11 : 1.0.0.1
 RtkPgExt.d11 : 6.0.6000.141
 Rt1CPAPI.d11 : 1.0.2.4
 SFAPO.d11 : 3.0.0.11
 SFCOM.d11 : 3.0.0.11
 SFFXComm.d11 : 2.0.0.13
 SFFXDAPO.d11 : 2.0.0.13
 SFFXHAPO.d11 : 2.0.0.13
 SFFXProc.d11 : 2.0.0.13
 SFFXSAPO.d11 : 2.0.0.13
 SFNHK.d11 : 3.0.0.11
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.1.2.0
 sltshd32.d11 : 1.2.0.0
 sluapo32.d11 : 1.8.34.0
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesGUILib.d11 : 1.0.0.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6167
 AERTSr64.exe : 1.0.64.10
 RAVBg64.exe : 1.0.0.40
 RAVCp164.exe : 1.0.0.553
 RtkAudioService64.exe : 1.0.0.27
 RtkNGUI64.exe : 1.0.0.53
 Rt1Upd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.38
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.d11 : 2.0.64.13
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.53
 DarkSkinImages64.d11 : 1.0.0.53
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSTBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.2
 DTSGFXAPONS64.d11 : 1.0.0.2

Readme.txt

DTSLFXAPO64.d11 : 1.0.0.2
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 42.6.32.66
 GrayJadeSkinImages64.d11 : 1.0.0.53
 LightSkinImages64.d11 : 1.0.0.53
 MaxxAudioAPO20.d11 : 2.2.8.0
 MaxxAudioAPO30.d11 : 3.2.0.2
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.0.0.0
 MaxxAudioRealtek2.d11 : 1.0.0.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.19.0
 MBAPO64.d11 : 1.0.19.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.15.115
 MBTHX64.d11 : 1.0.15.115
 MBWrp64.d11 : 1.0.0.180
 RCoInst64.d11 : 1.1.0.0
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.136
 RTCOMDLL.d11 : 2.0.0.136
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.21
 RtkAPO64.d11 : 11.0.6000.160
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 RtkGuiCompLib.d11 : 1.0.0.1
 Rt1CPAPI.d11 : 1.0.2.4
 Rt1CPAPI64.d11 : 1.0.2.4
 RtPgEx64.d11 : 6.0.6000.141
 SFAPO64.d11 : 3.0.0.11
 SFCOM.d11 : 3.0.0.11
 SFCOM64.d11 : 3.0.0.11
 SFComm64.d11 : 2.0.0.13
 SFDAPO64.d11 : 2.0.0.13
 SFHAPO64.d11 : 2.0.0.13
 SFNHK64.d11 : 3.0.0.11
 SFProc64.d11 : 2.0.0.13
 SFSAPO64.d11 : 2.0.0.13
 slcshp64.d11 : 1.0.3.0
 slgeq64.d11 : 1.0.1.0
 slh36064.d11 : 1.0.2.0
 slInit64.d11 : 1.1.3.0
 slmaxv64.d11 : 1.1.2.0
 sltshd64.d11 : 1.2.0.0
 sluapo64.d11 : 1.8.34.0

Readme.txt

SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
WavesGUILib.d11 : 1.0.0.0

HDMI Driver : -----
Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.6121
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.3
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.8.6
RHDMIExt.d11 : 6.0.6000.127
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.151

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.8.6
RHDMEx64.d11 : 6.0.6000.127
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.151

XP/2K x86:
RtkHDMI.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.0.8.6

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.0.8.6

Driver Setup Program : 3.06

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====
Driver Package R2.50

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267,

Readme.txt

- ALC268, ALC269, ALC270, ALC272, ALC273, ALC887,ALC670, ALC275, ALC680
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267,ALC268, ALC269, ALC270, ALC272, ALC273, ALC887,ALC670, ALC275, ALC680
 3. HDMI Device WHQL Support: ATI HDMI Devices
 4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
 5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
 6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6151
RTKHDAUD.sys	: 5.10.0.6151
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.4
RTHDCPL.exe	: 2.3.6.1
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.3
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.5
RCoInst64XP.d11	: 1.0.9.9
RTCOMDLL.d11	: 1.0.0.108
RtkCoInstXP.d11	: 1.0.9.9
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6151
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.38
RtHDVCpl.exe	: 1.0.0.545
RtkAudioService.exe	: 1.0.0.27
RtkNGUI.exe	: 1.0.0.52
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.11
AERTARen.d11	: 1.0.32.9

Readme.txt

BlackSkinImages.d11	: 1.0.0.52
DarkSkinImages.d11	: 1.0.0.52
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.2
DTSGFXAPONS.d11	: 1.0.0.2
DTSLFXAPO.d11	: 1.0.0.2
DTS LimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.32.66
GrayJadeSkinImages.d11	: 1.0.0.52
LightSkinImages.d11	: 1.0.0.52
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.8.0
MaxxAudioAPO30.d11	: 3.1.0.0
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.0.0.0
MaxxAudioRealtek2.d11	: 1.0.0.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.115
MBWrp32.d11	: 1.0.0.180
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.135
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.156
RtkApoApi.d11	: 1.0.0.21
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.1.0.0
RtkGuiCompLib.d11	: 1.0.0.1
RtkPgExt.d11	: 6.0.6000.138
Rt1CPAPI.d11	: 1.0.2.4
SFAPO.d11	: 3.0.0.8
SFCOM.d11	: 3.0.0.8
SFFXComm.d11	: 2.0.0.12
SFFXDAPO.d11	: 2.0.0.12
SFFXHAPO.d11	: 2.0.0.12
SFFXProc.d11	: 2.0.0.12
SFFXSAPO.d11	: 2.0.0.12
SFNHK.d11	: 3.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0

Readme.txt

sltshd32.d11 : 1.2.0.0
 sluapo32.d11 : 1.8.34.0
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesGUILib.d11 : 1.0.0.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6151
 AERTSr64.exe : 1.0.64.10
 RAVBg64.exe : 1.0.0.38
 RAVCp164.exe : 1.0.0.545
 RtkAudioService64.exe : 1.0.0.27
 RtkNGUI64.exe : 1.0.0.52
 RtlUpd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.38
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.19
 AERTAC64.d11 : 2.0.64.11
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.52
 DarkSkinImages64.d11 : 1.0.0.52
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.2
 DTSGFXAPONS64.d11 : 1.0.0.2
 DTSLFXAPO64.d11 : 1.0.0.2
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 42.6.32.66
 GrayJadeSkinImages64.d11 : 1.0.0.52
 LightSkinImages64.d11 : 1.0.0.52
 MaxxAudioAPO20.d11 : 2.2.8.0
 MaxxAudioAPO30.d11 : 3.1.0.0
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.0.0.0
 MaxxAudioRealtek2.d11 : 1.0.0.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.19.0
 MBAPO64.d11 : 1.0.19.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.15.115
 MBTHX64.d11 : 1.0.15.115
 MBWrp64.d11 : 1.0.0.180
 RCoInst64.d11 : 1.1.0.0
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18

Readme.txt

RtCOM64.d11	: 2.0.0.135
RTCOMDLL.d11	: 2.0.0.135
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.21
RtkAPO64.d11	: 11.0.6000.156
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
RtkGuiCompLib.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.138
SFAPO64.d11	: 3.0.0.8
SFCOM.d11	: 3.0.0.8
SFCOM64.d11	: 3.0.0.8
SFComm64.d11	: 2.0.0.12
SFDAPO64.d11	: 2.0.0.12
SFHAP064.d11	: 2.0.0.12
SFNHK64.d11	: 3.0.0.8
SFProc64.d11	: 2.0.0.12
SFSAP064.d11	: 2.0.0.12
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 1.8.34.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.0.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.8.6
RHDMIExt.d11	: 6.0.6000.127
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.151
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6121
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18

Readme.txt

RHCoInst64.d11 : 1.0.8.6
RHDMEx64.d11 : 6.0.6000.127
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.151

XP/2K x86:
RtkHDMI.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.0.8.6

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.0.8.6

Driver Setup Program : 3.01

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package –KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.49

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.6132
RTKHDAUD.sys : 5.10.0.6132
MicCal.exe : 1.1.2.4
RTHDCPL.exe : 2.3.5.5
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.3
RtlUpd.exe : 2.8.0.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32

Readme.txt

vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.5
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.9.2
RTCOMDLL.d11	: 1.0.0.108
RtkCoInstXP.d11	: 1.0.9.2
Rt1CPAPI.d11	: 1.0.2.3
Vista/Win7 driver : -----	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6132
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.26
RtHDVCpl.exe	: 1.0.0.530
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 1.0.0.48
Rt1Upd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.19
AERTACap.d11	: 2.0.32.11
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.48
DarkSkinImages.d11	: 1.0.0.48
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.1
DTSGFXAPONS.d11	: 1.0.0.1
DTSLFXAPO.d11	: 1.0.0.1
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.32.66
LightSkinImages.d11	: 1.0.0.48
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.8.0
MaxxAudioAPO30.d11	: 3.1.0.0
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.0.0.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.112

Readme.txt

MBWrp32.d11	: 1.0.0.160
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.134
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.152
RtkApoApi.d11	: 1.0.0.21
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.0.9.2
RtkPgExt.d11	: 6.0.6000.130
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.12
SFFXDAPO.d11	: 2.0.0.12
SFFXHAPO.d11	: 2.0.0.12
SFFXProc.d11	: 2.0.0.12
SFFXSAPO.d11	: 2.0.0.12
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.2.0.0
sluapo32.d11	: 1.8.34.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesGUILib.d11	: 1.0.0.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6132
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.26
RAVCp164.exe	: 1.0.0.530
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 1.0.0.48
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.19
AERTAC64.d11	: 2.0.64.11
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.48
DarkSkinImages64.d11	: 1.0.0.48
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.1
DTS GFXAPONS64.d11	: 1.0.0.1
DTS LFXAPO64.d11	: 1.0.0.1
DTS LimiterDLL64.d11	: 1.0.0.1

Readme.txt

DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 42.6.32.66
LightSkinImages64.d11	: 1.0.0.48
MaxxAudioAPO20.d11	: 2.2.8.0
MaxxAudioAPO30.d11	: 3.1.0.0
MaxxAudioEQ.d11	: 5.9.7.0
MaxxAudioRealtek.d11	: 1.0.0.0
MaxxVolumeSDAPO.d11	: 3.1.0.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.112
MBTHX64.d11	: 1.0.15.112
MBWrp64.d11	: 1.0.0.160
RCoInst64.d11	: 1.0.9.2
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.134
RTCOMDLL.d11	: 2.0.0.134
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.21
RtkAPO64.d11	: 11.0.6000.152
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.130
SFComm64.d11	: 2.0.0.12
SFDAPO64.d11	: 2.0.0.12
SFHAP064.d11	: 2.0.0.12
SFProc64.d11	: 2.0.0.12
SFSAPO64.d11	: 2.0.0.12
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.2.0.0
sluapo64.d11	: 1.8.34.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.0.0.0

HDMI Driver : _____

Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6121
RtkAudioSrvATI.exe	: 1.0.0.23

Readme.txt

RtkUpd.exe : 2.8.0.3
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.8.6
RHDMIExt.d11 : 6.0.6000.127
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.151

Vista/Win7 x64:

RtHDMIVX.sys : 6.0.1.6121
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.8.6
RHDMEx64.d11 : 6.0.6000.127
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.151

XP/2K x86:

RtkHDMI.sys : 5.10.0.6121
Rtaupd.exe : 2.8.0.3
RHCoInstXP.d11 : 1.0.8.6

XP/2K x64:

RtkHDMIX.sys : 5.10.0.6121
Rtaupd64.exe : 2.8.0.3
RHCoInst64XP.d11 : 1.0.8.6

Driver Setup Program : 2.99

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.48

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

- 1.) Driver :
 - 1. Customizations.

Windows 2000/XP :

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6101
RTKHDAUD.sys	: 5.10.0.6101
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.3
RTHDCPL.exe	: 2.3.4.9
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.3
RtlUpd64.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.d11	: 1.0.8.6
RTCOMDLL.d11	: 1.0.0.107
RtkCoInstXP.d11	: 1.0.8.6
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver :

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6101
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.18
RtHDVCpl.exe	: 1.0.0.513
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 1.0.0.39
RtlUpd.exe	: 2.8.0.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.11
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.39
DarkSkinImages.d11	: 1.0.0.39
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.1
DTSGFXAPONS.d11	: 1.0.0.1
DTSLFXAPO.d11	: 1.0.0.1
DTSLimiterDLL.d11	: 1.0.0.1

Readme.txt

DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 42.5.32.66
 LightSkinImages.d11 : 1.0.0.39
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.8.0
 MaxxAudioAPO30.d11 : 3.1.0.0
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.0.0.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.19.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.15.110
 MBWrp32.d11 : 1.0.0.110
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.130
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.149
 RtkApoApi.d11 : 1.0.0.21
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.0.8.7
 RtkPgExt.d11 : 6.0.6000.122
 Rt1CPAPI.d11 : 1.0.2.4
 SFFXComm.d11 : 2.0.0.12
 SFFXDAPO.d11 : 2.0.0.12
 SFFXHAPO.d11 : 2.0.0.12
 SFFXProc.d11 : 2.0.0.12
 SFFXSAPO.d11 : 2.0.0.12
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.1.2.0
 sltshd32.d11 : 1.1.1.0
 sluapo32.d11 : 1.8.24.0
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesGUILib.d11 : 1.0.0.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6101
 AERTSr64.exe : 1.0.64.10
 RAVBg64.exe : 1.0.0.18
 RAVCp164.exe : 1.0.0.513
 RtkAudioService64.exe : 1.0.0.24
 RtkNGUI64.exe : 1.0.0.39

Readme.txt

RtlUpd64.exe : 2.8.0.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.38
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.18
 AERTAC64.d11 : 2.0.64.11
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 1.0.0.39
 DarkSkinImages64.d11 : 1.0.0.39
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.1
 DTSGFXAPONS64.d11 : 1.0.0.1
 DTSLFXAPO64.d11 : 1.0.0.1
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSSymmetryDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 42.6.32.66
 LightSkinImages64.d11 : 1.0.0.39
 MaxxAudioAPO20.d11 : 2.2.8.0
 MaxxAudioAPO30.d11 : 3.1.0.0
 MaxxAudioEQ.d11 : 5.9.7.0
 MaxxAudioRealtek.d11 : 1.0.0.0
 MaxxVolumeSDAPO.d11 : 3.1.0.0
 MBAPO32.d11 : 1.0.19.0
 MBAPO64.d11 : 1.0.19.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.15.110
 MBTHX64.d11 : 1.0.15.110
 MBWrp64.d11 : 1.0.0.110
 RCoInst64.d11 : 1.0.8.7
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.130
 RTCOMDLL.d11 : 2.0.0.130
 RTEED64A.d11 : 6.1.6001.33
 RTEEG64A.d11 : 6.1.6001.33
 RTEEL64A.d11 : 6.1.6001.33
 RTEEP64A.d11 : 6.1.6001.33
 RtkApi64.d11 : 1.0.0.21
 RtkAPO64.d11 : 11.0.6000.149
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.2
 Rt1CPAPI.d11 : 1.0.2.4
 Rt1CPAPI64.d11 : 1.0.2.4
 RtPgEx64.d11 : 6.0.6000.122
 SFComm64.d11 : 2.0.0.12
 SFDAPO64.d11 : 2.0.0.12
 SFHAPO64.d11 : 2.0.0.12
 SFProc64.d11 : 2.0.0.12

Readme.txt

SFSAP064.d11	: 2.0.0.12
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.0.0.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.8.2
RHDMIExt.d11	: 6.0.6000.113
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.132
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6034
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.8.2
RHDMEx64.d11	: 6.0.6000.113
RTEED64H.d11	: 6.1.6001.33
RTEEG64H.d11	: 6.1.6001.33
RTEEL64H.d11	: 6.1.6001.33
RTEEP64H.d11	: 6.1.6001.33
RtkHDM64.d11	: 11.0.6000.132
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.6034
Rtaupd.exe	: 2.8.0.1
RHCoInstXP.d11	: 1.0.8.2
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.6034
Rtaupd64.exe	: 2.8.0.1
RHCoInst64XP.d11	: 1.0.8.2
Driver Setup Program	: 2.99
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package – KB888111	

Readme.txt

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.47

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6083
RTKHDAUD.sys	: 5.10.0.6083
MicCal.exe	: 1.1.2.3
RTHDCPL.exe	: 2.3.4.7
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.1
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.8.6
RTCOMDLL.d11	: 1.0.0.107
RtkCoInstXP.d11	: 1.0.8.6
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6083
AERTSrv.exe	: 1.0.32.10
RtHDVbg.exe	: 1.0.0.13
RtHDVCpl.exe	: 1.0.0.504
RtkAudioService.exe	: 1.0.0.24

Readme.txt

RtkNGUI.exe	: 1.0.0.38
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.11
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.38
DarkSkinImages.d11	: 1.0.0.38
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTS GFXAPO.d11	: 1.0.0.1
DTS GFXAPONS.d11	: 1.0.0.1
DTS LFXAPO.d11	: 1.0.0.1
DTS LimiterDLL.d11	: 1.0.0.1
DTS NeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.30.65
LightSkinImages.d11	: 1.0.0.38
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.108
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.130
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.145
RtkApoApi.d11	: 1.0.0.21
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.0.8.6
RtkPgExt.d11	: 6.0.6000.120
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.12
SFFXDAPO.d11	: 2.0.0.12
SFFXHAPO.d11	: 2.0.0.12
SFFXProc.d11	: 2.0.0.12
SFFXSAPO.d11	: 2.0.0.12
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0

Readme.txt

sluapo32.d11 : 1.8.24.0
SRSHp360.d11 : 1.1.0.0
SRSTSHD.d11 : 1.1.4.0
SRSTSXT.d11 : 3.2.0.0
Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.6083
AERTSr64.exe : 1.0.64.10
RAVBg64.exe : 1.0.0.13
RAVCp164.exe : 1.0.0.504
RtkAudioService64.exe : 1.0.0.24
RtkNGUI64.exe : 1.0.0.38
RtlUpd64.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.38
GWfilt64.sys : 6.10.0.3
mbfilt64.sys : 6.10.0.8
RTSnMg64.cpl : 1.0.0.18
AERTAC64.d11 : 2.0.64.11
AERTAR64.d11 : 1.0.64.9
BlackSkinImages64.d11 : 1.0.0.38
DarkSkinImages64.d11 : 1.0.0.38
DTSBassEnhancementDLL64.d11 : 1.0.0.1
DTSBoostDLL64.d11 : 1.0.0.1
DTSGainCompensatorDLL64.d11 : 1.0.0.1
DTSGFXAPO64.d11 : 1.0.0.1
DTSGFXAPONS64.d11 : 1.0.0.1
DTSLFXAPO64.d11 : 1.0.0.1
DTSLimiterDLL64.d11 : 1.0.0.1
DTSNeoPCDLL64.d11 : 1.0.0.1
DTSS2HeadphoneDLL64.d11 : 1.0.0.1
DTSS2SpeakerDLL64.d11 : 1.0.0.1
DTSSymmetryDLL64.d11 : 1.0.0.1
DTSVoiceClarityDLL64.d11 : 1.0.0.1
FMAPO64.d11 : 42.6.30.65
LightSkinImages64.d11 : 1.0.0.38
MaxxAudioAPO20.d11 : 2.2.7.0
MaxxAudioEQ.d11 : 5.9.7.0
MBAPO32.d11 : 1.0.19.0
MBAPO64.d11 : 1.0.19.0
MBPPCn64.d11 : 1.0.0.110
MBppld64.d11 : 1.0.22.0
MBTHX32.d11 : 1.0.15.108
MBTHX64.d11 : 1.0.15.108
MBWrp64.d11 : 1.0.0.110
RCoInst64.d11 : 1.0.8.6
RP3DAA64.d11 : 6.0.6001.18
RP3DHT64.d11 : 6.0.6001.18
RtCOM64.d11 : 2.0.0.130
RTCOMDLL.d11 : 2.0.0.130
RTEED64A.d11 : 6.1.6001.33
RTEEG64A.d11 : 6.1.6001.33
RTEEL64A.d11 : 6.1.6001.33
RTEEP64A.d11 : 6.1.6001.33
RtkApi64.d11 : 1.0.0.21
RtkAPO64.d11 : 11.0.6000.145
RtkCfg.d11 : 1.0.0.1

Readme.txt

RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.120
SFComm64.d11	: 2.0.0.12
SFDAPO64.d11	: 2.0.0.12
SFHAP064.d11	: 2.0.0.12
SFProc64.d11	: 2.0.0.12
SFSAPO64.d11	: 2.0.0.12
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.3.4
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.8.2
RHDMIExt.d11	: 6.0.6000.113
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.132
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6034
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.8.2
RHDMEx64.d11	: 6.0.6000.113
RTEED64H.d11	: 6.1.6001.33
RTEEG64H.d11	: 6.1.6001.33
RTEEL64H.d11	: 6.1.6001.33
RTEEP64H.d11	: 6.1.6001.33
RtkHDM64.d11	: 11.0.6000.132
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.6034
Rtaupd.exe	: 2.8.0.1
RHCoInstXP.d11	: 1.0.8.2
XP/2K x64:	

Readme.txt

RtkHDMIX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.d11 : 1.0.8.2

Driver Setup Program : 2.97

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.46

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix BSOD issue under Windows 2000. (Issue happened from driver

V6066).

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6077
RTKHDAUD.sys : 5.10.0.6077
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.4.6
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.1
RtlUpd64.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.38
vncutil64.exe : 1.0.0.38
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Monfilt.sys : 5.10.0.4112
Monft64.sys : 5.10.0.4115
OA017Afx.sys : 1.0.7.3
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.4
RCoInst64XP.d11 : 1.0.8.6

Readme.txt

RTCOMDLL.d11	: 1.0.0.107
RtkCoInstXP.d11	: 1.0.8.6
Rt1CPAPI.d11	: 1.0.2.3
Vista/Win7 driver : -----	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6077
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.9
RtHDVCpl.exe	: 1.0.0.501
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 1.0.0.35
Rt1Upd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.11
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.35
DarkSkinImages.d11	: 1.0.0.35
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSAFXAPO.d11	: 1.0.0.1
DTSAFXAPONS.d11	: 1.0.0.1
DTSAFXAPO.d11	: 1.0.0.1
DTS LimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.29.67
LightSkinImages.d11	: 1.0.0.35
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.108
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.130
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.144
RtkApoApi.d11	: 1.0.0.20
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.0.8.6
RtkPgExt.d11	: 6.0.6000.119
Rt1CPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.12

Readme.txt

SFFXDAPO.d11	: 2.0.0.12
SFFXHAP0.d11	: 2.0.0.12
SFFXProc.d11	: 2.0.0.12
SFFXSAP0.d11	: 2.0.0.12
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.8.24.0
SRSHp360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6077
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.9
RAVCp164.exe	: 1.0.0.501
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 1.0.0.35
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.d11	: 2.0.64.11
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.35
DarkSkinImages64.d11	: 1.0.0.35
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.1
DTSGFXAPONS64.d11	: 1.0.0.1
DTSLFXAPO64.d11	: 1.0.0.1
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 42.6.29.67
LightSkinImages64.d11	: 1.0.0.35
MaxxAudioAPO20.d11	: 2.2.7.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.108
MBTHX64.d11	: 1.0.15.108
MBWrp64.d11	: 1.0.0.110

Readme.txt

RCoInst64.d11	: 1.0.8.6
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.130
RTCOMDLL.d11	: 2.0.0.130
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.20
RtkAPO64.d11	: 11.0.6000.144
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.119
SFComm64.d11	: 2.0.0.12
SFDAPO64.d11	: 2.0.0.12
SFHAP064.d11	: 2.0.0.12
SFProc64.d11	: 2.0.0.12
SFSAP064.d11	: 2.0.0.12
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.3.4
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.8.2
RHDMIExt.d11	: 6.0.6000.113
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.132
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6034
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.8.2
RHDMEx64.d11	: 6.0.6000.113

Readme.txt

RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.132

XP/2K x86:
RtkHDMI.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.d11 : 1.0.8.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.d11 : 1.0.8.2

Driver Setup Program : 2.97

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.45

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6069
RTKHDAUD.sys : 5.10.0.6069
MicCal.exe : 1.1.2.3
RTHDCPL.exe : 2.3.4.2
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.1
RtlUpd.exe : 2.8.0.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.38
vncutil.exe : 1.0.0.38

Readme.txt

Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.8.6
RTCOMDLL.d11	: 1.0.0.107
RtkCoInstXP.d11	: 1.0.8.6
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : <hr/>	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6069
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.9
RtHDVCpl.exe	: 1.0.0.500
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 1.0.0.31
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.11
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.31
DarkSkinImages.d11	: 1.0.0.31
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSAFXAPO.d11	: 1.0.0.1
DTSAFXAPONS.d11	: 1.0.0.1
DTSAFXAPO.d11	: 1.0.0.1
DTS LimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.29.67
LightSkinImages.d11	: 1.0.0.31
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.108
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.129
RTEED32A.d11	: 6.1.6001.33

Readme.txt

RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.144
RtkApoApi.d11	: 1.0.0.20
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.0.8.6
RtkPgExt.d11	: 6.0.6000.119
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.12
SFFXDAPO.d11	: 2.0.0.12
SFFXHAP0.d11	: 2.0.0.12
SFFXProc.d11	: 2.0.0.12
SFFXSAPO.d11	: 2.0.0.12
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.8.24.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6069
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.9
RAVCp164.exe	: 1.0.0.500
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 1.0.0.31
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.d11	: 2.0.64.11
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.31
DarkSkinImages64.d11	: 1.0.0.31
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.1
DTSGFXAPONS64.d11	: 1.0.0.1
DTSLFXAPO64.d11	: 1.0.0.1
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 42.6.29.67

Readme.txt

LightSkinImages64.d11	: 1.0.0.31
MaxxAudioAPO20.d11	: 2.2.7.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.108
MBTHX64.d11	: 1.0.15.108
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.8.6
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.129
RTCOMDLL.d11	: 2.0.0.129
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.20
RtkAPO64.d11	: 11.0.6000.144
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.119
SFComm64.d11	: 2.0.0.12
SFDAPO64.d11	: 2.0.0.12
SFHAP064.d11	: 2.0.0.12
SFProc64.d11	: 2.0.0.12
SFSAP064.d11	: 2.0.0.12
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.3.4
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.8.2
RHDMIExt.d11	: 6.0.6000.113
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33

Readme.txt

RtkHDMI.d11 : 11.0.6000.132

Vista/Win7 x64:

RtHDMIVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.8.2
RHDMEx64.d11 : 6.0.6000.113
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.132

XP/2K x86:

RtkHDMI.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.d11 : 1.0.8.2

XP/2K x64:

RtkHDMIX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.d11 : 1.0.8.2

Driver Setup Program : 2.96

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.44

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6066
RTKHDAUD.sys : 5.10.0.6066
MicCal.exe : 1.1.2.3

Readme.txt

RTHDCPL.exe	: 2.3.4.0
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.1
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
AMBFt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.8.6
RTCOMDLL.d11	: 1.0.0.107
RtkCoInstXP.d11	: 1.0.8.6
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : _____	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.6066
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.9
RtHDVCpl.exe	: 1.0.0.499
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 1.0.0.29
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.11
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 1.0.0.29
DarkSkinImages.d11	: 1.0.0.29
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.1
DTSGFXAPONS.d11	: 1.0.0.1
DTSLFXAPO.d11	: 1.0.0.1
DTSLimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSSymmetryDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.28.65
LightSkinImages.d11	: 1.0.0.29
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0

Readme.txt

MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.108
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.128
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.142
RtkApoApi.d11	: 1.0.0.20
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.0.8.6
RtkPgExt.d11	: 6.0.6000.119
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.12
SFFXDAPO.d11	: 2.0.0.12
SFFXHAPO.d11	: 2.0.0.12
SFFXProc.d11	: 2.0.0.12
SFFXSAPO.d11	: 2.0.0.12
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.8.24.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6066
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.9
RAVCp164.exe	: 1.0.0.499
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 1.0.0.29
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.d11	: 2.0.64.11
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 1.0.0.29
DarkSkinImages64.d11	: 1.0.0.29
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1

Readme.txt

DTSAFXAPO64.d11	: 1.0.0.1
DTSAFXAPONS64.d11	: 1.0.0.1
DTSLFXAPO64.d11	: 1.0.0.1
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 42.6.28.65
LightSkinImages64.d11	: 1.0.0.29
MaxxAudioAPO20.d11	: 2.2.7.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.108
MBTHX64.d11	: 1.0.15.108
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.8.6
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.128
RTCOMDLL.d11	: 2.0.0.128
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.20
RtkAPO64.d11	: 11.0.6000.142
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.119
SFComm64.d11	: 2.0.0.12
SFDAPO64.d11	: 2.0.0.12
SFHAP064.d11	: 2.0.0.12
SFProc64.d11	: 2.0.0.12
SFSAPO64.d11	: 2.0.0.12
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.3.4
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6034

Readme.txt

RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.8.2
RHDMIExt.d11 : 6.0.6000.113
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.132

Vista/Win7 x64:

RtHDMIVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.8.2
RHDMEx64.d11 : 6.0.6000.113
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.132

XP/2K x86:

RtkHDMI.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.d11 : 1.0.8.2

XP/2K x64:

RtkHDMIX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.d11 : 1.0.8.2

Driver Setup Program : 2.96

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.43

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6050
RTKHDAUD.sys	: 5.10.0.6050
MicCal.exe	: 1.1.2.3
RTHDCPL.exe	: 2.3.3.8
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.1
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OA017Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.8.4
RTCOMDLL.d11	: 1.0.0.106
RtkCoInstXP.d11	: 1.0.8.4
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6050
AERTSrv.exe	: 1.0.32.10
RtHDVBg.exe	: 1.0.0.8
RtHDVCpl.exe	: 1.0.0.489
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 0.0.0.25
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.11
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 0.0.0.25
DarkSkinImages.d11	: 0.0.0.25
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSGFXAPO.d11	: 1.0.0.1
DTSGFXAPONS.d11	: 1.0.0.1
DTSLFXAPO.d11	: 1.0.0.1

Readme.txt

DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 42.5.26.65
 LightSkinImages.d11 : 0.0.0.25
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.6.0
 MaxxAudioEQ.d11 : 5.9.7.0
 MBAPO32.d11 : 1.0.19.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.15.106
 MBWrp32.d11 : 1.0.0.110
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.128
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.137
 RtkApoApi.d11 : 1.0.0.20
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.0.8.4
 RtkPgExt.d11 : 6.0.6000.116
 Rt1CPAPI.d11 : 1.0.2.4
 SFFXComm.d11 : 2.0.0.9
 SFFXDAPO.d11 : 2.0.0.9
 SFFXHAPO.d11 : 2.0.0.9
 SFFXProc.d11 : 2.0.0.9
 SFFXSAPO.d11 : 2.0.0.9
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.1.2.0
 sltshd32.d11 : 1.1.1.0
 sluapo32.d11 : 1.8.24.0
 SRSH360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6050
 AERTSr64.exe : 1.0.64.10
 RAVBg64.exe : 1.0.0.8
 RAVCp164.exe : 1.0.0.489
 RtkAudioService64.exe : 1.0.0.24
 RtkNGUI64.exe : 0.0.0.25
 Rt1Upd64.exe : 2.8.0.1
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.38

Readme.txt

GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.d11	: 2.0.64.11
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 0.0.0.25
DarkSkinImages64.d11	: 0.0.0.25
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTS GFXAPO64.d11	: 1.0.0.1
DTS GFXAPONS64.d11	: 1.0.0.1
DTS LFXAPO64.d11	: 1.0.0.1
DTS LimiterDLL64.d11	: 1.0.0.1
DTS NeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 42.6.26.65
LightSkinImages64.d11	: 0.0.0.25
MaxxAudioAPO20.d11	: 2.2.7.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.106
MBTHX64.d11	: 1.0.15.106
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.8.4
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.128
RTCOMDLL.d11	: 2.0.0.128
RTEED64A.d11	: 6.1.6001.33
RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.20
RtkAPO64.d11	: 11.0.6000.137
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.116
SFComm64.d11	: 2.0.0.9
SFDAPO64.d11	: 2.0.0.9
SFHAP064.d11	: 2.0.0.9
SFProc64.d11	: 2.0.0.9
SFSAP064.d11	: 2.0.0.9
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0

Readme.txt

s1tshd64.d11 : 1.1.1.0
sluapo64.d11 : 1.8.24.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
WavesGUILib.d11 : 1.2.3.4

HDMI Driver :

Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.6034
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.8.2
RHDMIExt.d11 : 6.0.6000.113
RTEED32H.d11 : 6.1.6001.33
RTEEG32H.d11 : 6.1.6001.33
RTEEL32H.d11 : 6.1.6001.33
RTEEP32H.d11 : 6.1.6001.33
RtkHDMI.d11 : 11.0.6000.132

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.6034
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.8.2
RHDMEx64.d11 : 6.0.6000.113
RTEED64H.d11 : 6.1.6001.33
RTEEG64H.d11 : 6.1.6001.33
RTEEL64H.d11 : 6.1.6001.33
RTEEP64H.d11 : 6.1.6001.33
RtkHDM64.d11 : 11.0.6000.132

XP/2K x86:
RtkHDMI.sys : 5.10.0.6034
Rtaupd.exe : 2.8.0.1
RHCoInstXP.d11 : 1.0.8.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.6034
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.d11 : 1.0.8.2

Driver Setup Program : 2.95

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.42

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

Readme.txt

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6043
RTKHDAUD.sys	: 5.10.0.6043
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.3
RTHDCPL.exe	: 2.3.3.6
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.1
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.d11	: 1.0.8.2
RTCOMDLL.d11	: 1.0.0.105
RtkCoInstXP.d11	: 1.0.8.2
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6043
AERTSrv.exe	: 1.0.32.10
RtHDVbg.exe	: 1.0.0.8
RtHDVCpl.exe	: 1.0.0.484
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 0.0.0.24
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18

Readme.txt

AERTACap.d11 : 2.0.32.11
 AERTARen.d11 : 1.0.32.9
 BlackSkinImages.d11 : 0.0.0.24
 DarkSkinImages.d11 : 0.0.0.24
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.1
 DTSGFXAPONS.d11 : 1.0.0.1
 DTSLFXAPO.d11 : 1.0.0.1
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 42.5.26.65
 LightSkinImages.d11 : 0.0.0.24
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.6.0
 MaxxAudioEQ.d11 : 5.9.7.0
 MBAPO32.d11 : 1.0.19.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.15.106
 MBWrp32.d11 : 1.0.0.110
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.127
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.134
 RtkApoApi.d11 : 1.0.0.20
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.0.8.4
 RtkPgExt.d11 : 6.0.6000.114
 Rt1CPAPI.d11 : 1.0.2.4
 SFFXComm.d11 : 2.0.0.9
 SFFXDAPO.d11 : 2.0.0.9
 SFFXHAPO.d11 : 2.0.0.9
 SFFXProc.d11 : 2.0.0.9
 SFFXSAPO.d11 : 2.0.0.9
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.1.2.0
 sltshd32.d11 : 1.1.1.0
 sluapo32.d11 : 1.8.24.0
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesLib.d11 : 5.9.7.0

Readme.txt

Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.6043
AERTSr64.exe : 1.0.64.10
RAVBg64.exe : 1.0.0.8
RAVCp164.exe : 1.0.0.484
RtkAudioService64.exe : 1.0.0.24
RtkNGUI64.exe : 0.0.0.24
RtlUpd64.exe : 2.8.0.1
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.38
GWfilt64.sys : 6.10.0.3
mbfilt64.sys : 6.10.0.8
RTSnMg64.cpl : 1.0.0.18
AERTAC64.d11 : 2.0.64.11
AERTAR64.d11 : 1.0.64.9
BlackSkinImages64.d11 : 0.0.0.24
DarkSkinImages64.d11 : 0.0.0.24
DTSBassEnhancementDLL64.d11 : 1.0.0.1
DTSBoostDLL64.d11 : 1.0.0.1
DTSGainCompensatorDLL64.d11 : 1.0.0.1
DTSGFXAPO64.d11 : 1.0.0.1
DTSGFXAPONS64.d11 : 1.0.0.1
DTSLFXAPO64.d11 : 1.0.0.1
DTSLimiterDLL64.d11 : 1.0.0.1
DTSNeoPCDLL64.d11 : 1.0.0.1
DTSS2HeadphoneDLL64.d11 : 1.0.0.1
DTSS2SpeakerDLL64.d11 : 1.0.0.1
DTSSymmetryDLL64.d11 : 1.0.0.1
DTSVoiceClarityDLL64.d11 : 1.0.0.1
FMAPO64.d11 : 42.6.26.65
LightSkinImages64.d11 : 0.0.0.24
MaxxAudioAPO20.d11 : 2.2.7.0
MaxxAudioEQ.d11 : 5.9.7.0
MBAPO32.d11 : 1.0.19.0
MBAPO64.d11 : 1.0.19.0
MBPPCn64.d11 : 1.0.0.110
MBppld64.d11 : 1.0.22.0
MBTHX32.d11 : 1.0.15.106
MBTHX64.d11 : 1.0.15.106
MBWrp64.d11 : 1.0.0.110
RCoInst64.d11 : 1.0.8.4
RP3DAA64.d11 : 6.0.6001.18
RP3DHT64.d11 : 6.0.6001.18
RtCOM64.d11 : 2.0.0.127
RTCOMDLL.d11 : 2.0.0.127
RTEED64A.d11 : 6.1.6001.33
RTEEG64A.d11 : 6.1.6001.33
RTEEL64A.d11 : 6.1.6001.33
RTEEP64A.d11 : 6.1.6001.33
RtkApi64.d11 : 1.0.0.20
RtkAPO64.d11 : 11.0.6000.134
RtkCfg.d11 : 1.0.0.1
RtkCfg64.d11 : 1.0.0.2
Rt1CPAPI.d11 : 1.0.2.4
Rt1CPAPI64.d11 : 1.0.2.4
RtPgEx64.d11 : 6.0.6000.114

Readme.txt

SFComm64.d11	: 2.0.0.9
SFDAPO64.d11	: 2.0.0.9
SFHAP064.d11	: 2.0.0.9
SFProc64.d11	: 2.0.0.9
SFSAPO64.d11	: 2.0.0.9
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.3.4
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.6034
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.8.2
RHDMIExt.d11	: 6.0.6000.113
RTEED32H.d11	: 6.1.6001.33
RTEEG32H.d11	: 6.1.6001.33
RTEEL32H.d11	: 6.1.6001.33
RTEEP32H.d11	: 6.1.6001.33
RtkHDMI.d11	: 11.0.6000.132
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.6034
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.8.2
RHDMEx64.d11	: 6.0.6000.113
RTEED64H.d11	: 6.1.6001.33
RTEEG64H.d11	: 6.1.6001.33
RTEEL64H.d11	: 6.1.6001.33
RTEEP64H.d11	: 6.1.6001.33
RtkHDM64.d11	: 11.0.6000.132
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.6034
Rtaupd.exe	: 2.8.0.1
RHCoInstXP.d11	: 1.0.8.2
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.6034
Rtaupd64.exe	: 2.8.0.1
RHCoInst64XP.d11	: 1.0.8.2

Driver Setup Program : 2.94

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
 Package file version (kb888111.exe) : 6.1.22.0
 Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.41

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.6029
RTKHDAUD.sys	: 5.10.0.6029
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.3
RTHDCPL.exe	: 2.3.3.2
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.1
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.38
vncutil64.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.d11	: 1.0.8.2
RTCOMDLL.d11	: 1.0.0.104
RtkCoInstXP.d11	: 1.0.8.2
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86
 RTKVHDA.sys : 6.0.1.6029

Readme.txt

AERTSrv.exe : 1.0.32.10
 RtHDVBg.exe : 1.0.0.8
 RtHDVCpl.exe : 1.0.0.477
 RtkAudioService.exe : 1.0.0.24
 RtkNGUI.exe : 0.0.0.22
 Rt1Upd.exe : 2.8.0.1
 SkyTel.exe : 2.0.2.2
 vncutil.exe : 1.0.0.38
 mbfilt32.sys : 6.10.0.8
 RTSndMgr.cpl : 1.0.0.18
 AERTACap.d11 : 2.0.32.9
 AERTARen.d11 : 1.0.32.9
 BlackSkinImages.d11 : 0.0.0.22
 DarkSkinImages.d11 : 0.0.0.22
 DTSBassEnhancementDLL.d11 : 1.0.0.1
 DTSBoostDLL.d11 : 1.0.0.1
 DTSGainCompensatorDLL.d11 : 1.0.0.1
 DTSGFXAPO.d11 : 1.0.0.1
 DTSGFXAPONS.d11 : 1.0.0.1
 DTSLFXAPO.d11 : 1.0.0.1
 DTSLimiterDLL.d11 : 1.0.0.1
 DTSNeoPCDLL.d11 : 1.0.0.1
 DTSS2HeadphoneDLL.d11 : 1.0.0.1
 DTSS2SpeakerDLL.d11 : 1.0.0.1
 DTSSymmetryDLL.d11 : 1.0.0.1
 DTSVoiceClarityDLL.d11 : 1.0.0.1
 FMAPO.d11 : 42.5.24.65
 LightSkinImages.d11 : 0.0.0.22
 MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.6.0
 MaxxAudioEQ.d11 : 5.9.7.0
 MBAPO32.d11 : 1.0.19.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.8.109
 MBWrp32.d11 : 1.0.0.110
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.125
 RTEED32A.d11 : 6.1.6001.33
 RTEEG32A.d11 : 6.1.6001.33
 RTEEL32A.d11 : 6.1.6001.33
 RTEEP32A.d11 : 6.1.6001.33
 RtkAPO.d11 : 11.0.6000.132
 RtkApoApi.d11 : 1.0.0.20
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.0.8.3
 RtkPgExt.d11 : 6.0.6000.113
 Rt1CPAPI.d11 : 1.0.2.4
 SFFXComm.d11 : 2.0.0.9
 SFFXDAPO.d11 : 2.0.0.9
 SFFXHAPO.d11 : 2.0.0.9
 SFFXProc.d11 : 2.0.0.9
 SFFXSAPO.d11 : 2.0.0.9
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0

Readme.txt

s1h36032.d11	: 1.0.2.0
s1Init32.d11	: 1.1.3.0
s1maxv32.d11	: 1.1.2.0
s1tshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.8.24.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.6029
AERTSr64.exe	: 1.0.64.10
RAVBg64.exe	: 1.0.0.8
RAVCp164.exe	: 1.0.0.477
RtkAudioService64.exe	: 1.0.0.24
RtkNGUI64.exe	: 0.0.0.22
RtlUpd64.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.38
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.18
AERTAC64.d11	: 2.0.64.9
AERTAR64.d11	: 1.0.64.9
BlackSkinImages64.d11	: 0.0.0.22
DarkSkinImages64.d11	: 0.0.0.22
DTSBassEnhancementDLL64.d11	: 1.0.0.1
DTSBoostDLL64.d11	: 1.0.0.1
DTSGainCompensatorDLL64.d11	: 1.0.0.1
DTSGFXAPO64.d11	: 1.0.0.1
DTSGFXAPONS64.d11	: 1.0.0.1
DTSLFXAPO64.d11	: 1.0.0.1
DTSLimiterDLL64.d11	: 1.0.0.1
DTSNeoPCDLL64.d11	: 1.0.0.1
DTSS2HeadphoneDLL64.d11	: 1.0.0.1
DTSS2SpeakerDLL64.d11	: 1.0.0.1
DTSSymmetryDLL64.d11	: 1.0.0.1
DTSVoiceClarityDLL64.d11	: 1.0.0.1
FMAPO64.d11	: 42.6.24.65
LightSkinImages64.d11	: 0.0.0.22
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.109
MBTHX64.d11	: 1.0.8.109
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.8.3
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.125
RTCOMDLL.d11	: 2.0.0.125
RTEED64A.d11	: 6.1.6001.33

Readme.txt

RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.20
RtkAPO64.d11	: 11.0.6000.132
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.113
SFComm64.d11	: 2.0.0.9
SFDAPO64.d11	: 2.0.0.9
SFHAP064.d11	: 2.0.0.9
SFProc64.d11	: 2.0.0.9
SFSAPO64.d11	: 2.0.0.9
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.3.4
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5992
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.7.0
RHDMIExt.d11	: 6.0.6000.109
RtkHDMI.d11	: 11.0.6000.126
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.5992
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.7.0
RHDMEx64.d11	: 6.0.6000.109
RtkHDM64.d11	: 11.0.6000.126
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.5992
Rtaupd.exe	: 2.8.0.1
RHCoInstXP.d11	: 1.0.7.0
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.5992
Rtaupd64.exe	: 2.8.0.1

Readme.txt

RHCoInst64XP.d11 : 1.0.7.0

Driver Setup Program : 2.92

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.40

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275, ALC680

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6013

RTKHDAUD.sys : 5.10.0.6013

MicCal.exe : 1.1.2.2

RTHDCPL.exe : 2.3.2.8

RtkAudioService64.exe : 1.0.0.19

RtkAudioService.exe : 1.0.0.19

RTLCPLEX.exe : 1.0.1.66

RtlUpd64.exe : 2.8.0.1

RtlUpd.exe : 2.8.0.1

SkyTel.exe : 2.0.2.0

SoundMan.exe : 1.0.0.32

vncutil64.exe : 1.0.0.38

vncutil.exe : 1.0.0.38

Alcmtr.exe : 1.6.0.4

AlcWzrd.exe : 1.1.0.37

Monfilt.sys : 5.10.0.4112

Monft64.sys : 5.10.0.4115

OAO17Afx.sys : 1.0.7.3

AMBFilt.sys : 5.10.0.4240

AMBft64.sys : 5.10.0.4240

RTSndMgr.cpl : 1.0.1.4

ALSndMgr.cpl : 1.0.0.11

RCoInst64XP.d11 : 1.0.7.9

RTCOMDLL.d11 : 1.0.0.103

RtkCoInstXP.d11 : 1.0.7.9

Rt1CPAPI.d11 : 1.0.2.3

Vista/Win7 driver : _____

Readme.txt

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6013
AERTSrv.exe	: 1.0.32.10
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.8
RtHDVCpl.exe	: 1.0.0.463
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 0.0.0.21
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.9
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 0.0.0.21
DarkSkinImages.d11	: 0.0.0.21
DTSBassEnhancementDLL.d11	: 1.0.0.1
DTSBoostDLL.d11	: 1.0.0.1
DTSGainCompensatorDLL.d11	: 1.0.0.1
DTSAFXAPO.d11	: 1.0.0.1
DTSLFXAPO.d11	: 1.0.0.1
DTS LimiterDLL.d11	: 1.0.0.1
DTSNeoPCDLL.d11	: 1.0.0.1
DTSS2HeadphoneDLL.d11	: 1.0.0.1
DTSS2SpeakerDLL.d11	: 1.0.0.1
DTSVoiceClarityDLL.d11	: 1.0.0.1
FMAPO.d11	: 42.5.23.65
LightSkinImages.d11	: 0.0.0.21
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.15.103
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.124
RTEED32A.d11	: 6.1.6001.33
RTEEG32A.d11	: 6.1.6001.33
RTEEL32A.d11	: 6.1.6001.33
RTEEP32A.d11	: 6.1.6001.33
RtkAPO.d11	: 11.0.6000.130
RtkApoApi.d11	: 1.0.0.20
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.0.7.9
RtkPgExt.d11	: 6.0.6000.112
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.9
SFFXDAPO.d11	: 2.0.0.9
SFFXHAPO.d11	: 2.0.0.9
SFFXProc.d11	: 2.0.0.9
SFFXSAPO.d11	: 2.0.0.9
slcshp32.d11	: 1.0.3.0

Readme.txt

slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.1.2.0
 sltshd32.d11 : 1.1.1.0
 sluapo32.d11 : 1.8.24.0
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.6013
 AERTSr64.exe : 1.0.64.10
 APOPCH.exe : 1.0.0.0
 RAVBg64.exe : 1.0.0.8
 RAVCp164.exe : 1.0.0.463
 RtkAudioService64.exe : 1.0.0.24
 RtkNGUI64.exe : 0.0.0.21
 RtlUpd64.exe : 2.8.0.1
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.38
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.18
 AERTAC64.d11 : 2.0.64.9
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 0.0.0.21
 DarkSkinImages64.d11 : 0.0.0.21
 DTSBassEnhancementDLL64.d11 : 1.0.0.1
 DTSBoostDLL64.d11 : 1.0.0.1
 DTSGainCompensatorDLL64.d11 : 1.0.0.1
 DTSGFXAPO64.d11 : 1.0.0.1
 DTSLFXAPO64.d11 : 1.0.0.1
 DTSLimiterDLL64.d11 : 1.0.0.1
 DTSNeoPCDLL64.d11 : 1.0.0.1
 DTSS2HeadphoneDLL64.d11 : 1.0.0.1
 DTSS2SpeakerDLL64.d11 : 1.0.0.1
 DTSVoiceClarityDLL64.d11 : 1.0.0.1
 FMAPO64.d11 : 42.6.23.65
 LightSkinImages64.d11 : 0.0.0.21
 MaxxAudioAPO20.d11 : 2.2.6.0
 MaxxAudioEQ.d11 : 5.9.7.0
 MBAPO32.d11 : 1.0.19.0
 MBAPO64.d11 : 1.0.19.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.15.103
 MBTHX64.d11 : 1.0.15.103
 MBWrp64.d11 : 1.0.0.110
 RCoInst64.d11 : 1.0.7.9
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.123
 RTCOMDLL.d11 : 2.0.0.123
 RTEED64A.d11 : 6.1.6001.33

Readme.txt

RTEEG64A.d11	: 6.1.6001.33
RTEEL64A.d11	: 6.1.6001.33
RTEEP64A.d11	: 6.1.6001.33
RtkApi64.d11	: 1.0.0.20
RtkAPO64.d11	: 11.0.6000.130
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.112
SFComm64.d11	: 2.0.0.9
SFDAPO64.d11	: 2.0.0.9
SFHAP064.d11	: 2.0.0.9
SFProc64.d11	: 2.0.0.9
SFSAP064.d11	: 2.0.0.9
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.3.4
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5992
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.1
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.7.0
RHDMIExt.d11	: 6.0.6000.109
RtkHDMI.d11	: 11.0.6000.126
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.5992
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.1
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.7.0
RHDMEx64.d11	: 6.0.6000.109
RtkHDM64.d11	: 11.0.6000.126
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.5992
Rtaupd.exe	: 2.8.0.1
RHCoInstXP.d11	: 1.0.7.0
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.5992
Rtaupd64.exe	: 2.8.0.1

Readme.txt

RHCoInst64XP.d11 : 1.0.7.0

Driver Setup Program : 2.89

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.39

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.6000

RTKHDAUD.sys : 5.10.0.6000

MicCal.exe : 1.1.2.2

RTHDCPL.exe : 2.3.2.5

RtkAudioService64.exe : 1.0.0.19

RtkAudioService.exe : 1.0.0.19

RTLCPLEX.exe : 1.0.1.66

RtlUpd64.exe : 2.8.0.1

RtlUpd.exe : 2.8.0.1

SkyTel.exe : 2.0.2.0

SoundMan.exe : 1.0.0.32

vncutil64.exe : 1.0.0.38

vncutil.exe : 1.0.0.38

Alcmtr.exe : 1.6.0.4

AlcWzrd.exe : 1.1.0.37

AMBFilt.sys : 5.10.0.4240

AMBft64.sys : 5.10.0.4240

Monfilt.sys : 5.10.0.4112

Monft64.sys : 5.10.0.4115

OAO17Afx.sys : 1.0.7.3

RTSndMgr.cpl : 1.0.1.4

ALSndMgr.cpl : 1.0.0.11

RCoInst64XP.d11 : 1.0.7.8

RTCOMDLL.d11 : 1.0.0.103

RtkCoInstXP.d11 : 1.0.7.8

Rt1CPAPI.d11 : 1.0.2.3

Vista/Win7 driver : _____

Readme.txt

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.6000
AERTSrv.exe	: 1.0.32.10
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.8
RtHDVCpl.exe	: 1.0.0.456
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 0.0.0.17
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.9
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 0.0.0.17
DarkSkinImages.d11	: 0.0.0.17
FMAPO.d11	: 42.5.21.67
LightSkinImages.d11	: 0.0.0.17
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.108
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.124
RTEED32A.d11	: 6.1.6001.32
RTEEG32A.d11	: 6.1.6001.32
RTEEL32A.d11	: 6.1.6001.32
RTEEP32A.d11	: 6.1.6001.32
RtkAPO.d11	: 11.0.6000.129
RtkApoApi.d11	: 1.0.0.19
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.0.7.8
RtkPgExt.d11	: 6.0.6000.112
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.9
SFFXDAPO.d11	: 2.0.0.9
SFFXHAPO.d11	: 2.0.0.9
SFFXProc.d11	: 2.0.0.9
SFFXSAPO.d11	: 2.0.0.9
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.8.24.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0

	Readme.txt	
WavesLib.dll		: 5.9.7.0
Vista/Win7 driver for x64		
RTKVHD64.sys		: 6.0.1.6000
AERTSr64.exe		: 1.0.64.10
APOPCH.exe		: 1.0.0.0
RAVBg64.exe		: 1.0.0.8
RAVCp164.exe		: 1.0.0.456
RtkAudioService64.exe		: 1.0.0.24
RtkNGUI64.exe		: 0.0.0.17
RtlUpd64.exe		: 2.8.0.1
SkyTel.exe		: 2.0.2.2
vncutil64.exe		: 1.0.0.38
GWfilt64.sys		: 6.10.0.3
mbfilt64.sys		: 6.10.0.8
RTSnMg64.cpl		: 1.0.0.18
AERTAC64.dll		: 2.0.64.9
AERTAR64.dll		: 1.0.64.9
BlackSkinImages64.dll		: 0.0.0.17
DarkSkinImages64.dll		: 0.0.0.17
FMAPO64.dll		: 42.6.21.67
LightSkinImages64.dll		: 0.0.0.17
MaxxAudioAPO20.dll		: 2.2.6.0
MaxxAudioEQ.dll		: 5.9.7.0
MBAPO32.dll		: 1.0.19.0
MBAPO64.dll		: 1.0.19.0
MBPPCn64.dll		: 1.0.0.110
MBppld64.dll		: 1.0.22.0
MBTHX32.dll		: 1.0.8.108
MBTHX64.dll		: 1.0.8.108
MBWrp64.dll		: 1.0.0.110
RCoInst64.dll		: 1.0.7.8
RP3DAA64.dll		: 6.0.6001.18
RP3DHT64.dll		: 6.0.6001.18
RtCOM64.dll		: 2.0.0.123
RTCOMDLL.dll		: 2.0.0.123
RTEED64A.dll		: 6.1.6001.32
RTEEG64A.dll		: 6.1.6001.32
RTEEL64A.dll		: 6.1.6001.32
RTEEP64A.dll		: 6.1.6001.32
RtkApi64.dll		: 1.0.0.19
RtkAPO64.dll		: 11.0.6000.129
RtkCfg.dll		: 1.0.0.1
RtkCfg64.dll		: 1.0.0.2
Rt1CPAPI.dll		: 1.0.2.4
Rt1CPAPI64.dll		: 1.0.2.4
RtPgEx64.dll		: 6.0.6000.112
SFComm64.dll		: 2.0.0.9
SFDAPO64.dll		: 2.0.0.9
SFHAP064.dll		: 2.0.0.9
SFProc64.dll		: 2.0.0.9
SFSAP064.dll		: 2.0.0.9
slcshp64.dll		: 1.0.3.0
slgeq64.dll		: 1.0.1.0
slh36064.dll		: 1.0.2.0
slInit64.dll		: 1.1.3.0
slmaxv64.dll		: 1.1.2.0

Readme.txt

sltshd64.d11 : 1.1.1.0
sluapo64.d11 : 1.8.24.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
WavesGUILib.d11 : 1.2.3.4

HDMI Driver :

Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.5992
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.1
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.7.0
RHDMIExt.d11 : 6.0.6000.109
RtkHDMI.d11 : 11.0.6000.126

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.5992
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.1
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.7.0
RHDMEx64.d11 : 6.0.6000.109
RtkHDM64.d11 : 11.0.6000.126

XP/2K x86:
RtkHDMI.sys : 5.10.0.5992
Rtaupd.exe : 2.8.0.1
RHCoInstXP.d11 : 1.0.7.0

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5992
Rtaupd64.exe : 2.8.0.1
RHCoInst64XP.d11 : 1.0.7.0

Driver Setup Program : 2.89

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.38

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

Readme.txt

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support graphic EQ feature.

Windows 2000/XP :

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5995
RTKHDAUD.sys	: 5.10.0.5995
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.2
RTHDCPL.exe	: 2.3.2.4
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.1
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.38
vncutil.exe	: 1.0.0.38
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.d11	: 1.0.7.6
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.7.6
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver :

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.5995
AERTSrv.exe	: 1.0.32.10
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.8
RtHDVCpl.exe	: 1.0.0.453
RtkAudioService.exe	: 1.0.0.24
RtkNGUI.exe	: 0.0.0.15
RtlUpd.exe	: 2.8.0.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.38
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.18
AERTACap.d11	: 2.0.32.9
AERTARen.d11	: 1.0.32.9
BlackSkinImages.d11	: 0.0.0.15
DarkSkinImages.d11	: 0.0.0.15
FMAPO.d11	: 42.5.21.66
LightSkinImages.d11	: 0.0.0.15

Readme.txt

MaxxAudioAPO.d11 : 1.2.2.0
 MaxxAudioAPO20.d11 : 2.2.6.0
 MaxxAudioEQ.d11 : 5.9.7.0
 MBAPO32.d11 : 1.0.19.0
 MBPPCn32.d11 : 1.0.0.110
 MBpp1d32.d11 : 1.0.22.0
 MBTHX32.d11 : 1.0.8.108
 MBWrp32.d11 : 1.0.0.110
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.124
 RTEED32A.d11 : 6.1.6001.32
 RTEEG32A.d11 : 6.1.6001.32
 RTEEL32A.d11 : 6.1.6001.32
 RTEEP32A.d11 : 6.1.6001.32
 RtkAPO.d11 : 11.0.6000.127
 RtkApoApi.d11 : 1.0.0.17
 RtkCfg.d11 : 1.0.0.2
 RtkCoInst.d11 : 1.0.7.7
 RtkPgExt.d11 : 6.0.6000.109
 Rt1CPAPI.d11 : 1.0.2.4
 SFFXComm.d11 : 2.0.0.9
 SFFXDAPO.d11 : 2.0.0.9
 SFFXHAPO.d11 : 2.0.0.9
 SFFXProc.d11 : 2.0.0.9
 SFFXSAPO.d11 : 2.0.0.9
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.1.2.0
 sltshd32.d11 : 1.1.1.0
 sluapo32.d11 : 1.8.24.0
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.5995
 AERTSr64.exe : 1.0.64.10
 APOPCH.exe : 1.0.0.0
 RAVBg64.exe : 1.0.0.8
 RAVCp164.exe : 1.0.0.453
 RtkAudioService64.exe : 1.0.0.24
 RtkNGUI64.exe : 0.0.0.15
 Rt1Upd64.exe : 2.8.0.1
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.38
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.18
 AERTAC64.d11 : 2.0.64.9
 AERTAR64.d11 : 1.0.64.9
 BlackSkinImages64.d11 : 0.0.0.15
 DarkSkinImages64.d11 : 0.0.0.15

Readme.txt

FMAPO64.d11	: 42.6.21.66
LightSkinImages64.d11	: 0.0.0.15
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.108
MBTHX64.d11	: 1.0.8.108
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.7.7
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.123
RTCOMDLL.d11	: 2.0.0.123
RTEED64A.d11	: 6.1.6001.32
RTEEG64A.d11	: 6.1.6001.32
RTEEL64A.d11	: 6.1.6001.32
RTEEP64A.d11	: 6.1.6001.32
RtkApi64.d11	: 1.0.0.17
RtkAPO64.d11	: 11.0.6000.127
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.109
SFComm64.d11	: 2.0.0.9
SFDAPO64.d11	: 2.0.0.9
SFHAPO64.d11	: 2.0.0.9
SFProc64.d11	: 2.0.0.9
SFSAPO64.d11	: 2.0.0.9
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.8.24.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
WavesGUILib.d11	: 1.2.3.4
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5945
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.7.0
RHDMIExt.d11	: 6.0.6000.100
RtkHDMI.d11	: 11.0.6000.113

Vista/Win7 x64:

Readme.txt

RtHDMIVX.sys : 6.0.1.5945
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.7.0
RHDMEx64.d11 : 6.0.6000.100
RtkHDM64.d11 : 11.0.6000.113

XP/2K x86:
RtkHDMI.sys : 5.10.0.5945
Rtaupd.exe : 2.8.0.0
RHCoInstXP.d11 : 1.0.7.0

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5945
Rtaupd64.exe : 2.8.0.0
RHCoInst64XP.d11 : 1.0.7.0

Driver Setup Program : 2.89

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.37

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC892, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5983
RTKHDAUD.sys : 5.10.0.5983
MicCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.2.4
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCP.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0

Readme.txt

SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.37
vncutil.exe	: 1.0.0.37
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
AMBFt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
OAO17Afx.sys	: 1.0.7.3
AMBFilt.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.7.6
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.7.6
Rt1CPAPI.d11	: 1.0.2.3

Vista/Win7 driver :

Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.5983
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.6
RtHDVCpl.exe	: 1.0.0.447
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.37
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.17
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 42.5.21.66
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.107
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.123
RTEED32A.d11	: 6.1.6001.32
RTEEG32A.d11	: 6.1.6001.32
RTEEL32A.d11	: 6.1.6001.32
RTEEP32A.d11	: 6.1.6001.32
RtkAPO.d11	: 11.0.6000.125
RtkApoApi.d11	: 1.0.0.15
RtkCfg.d11	: 1.0.0.2
RtkCoInst.d11	: 1.0.7.6
RtkPgExt.d11	: 6.0.6000.108
Rt1CPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.8
SFFXDAPO.d11	: 2.0.0.8
SFFXHAPO.d11	: 2.0.0.8

Readme.txt

SFFXProc.d11	: 2.0.0.8
SFFXSAPO.d11	: 2.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.8.22.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5983
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.6
RAVCp164.exe	: 1.0.0.447
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.37
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.17
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 42.6.21.66
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.107
MBTHX64.d11	: 1.0.8.107
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.7.6
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.123
RTCOMDLL.d11	: 2.0.0.123
RTEED64A.d11	: 6.1.6001.32
RTEEG64A.d11	: 6.1.6001.32
RTEEL64A.d11	: 6.1.6001.32
RTEEP64A.d11	: 6.1.6001.32
RtkApi64.d11	: 1.0.0.15
RtkAPO64.d11	: 11.0.6000.125
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.2
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.108
SFComm64.d11	: 2.0.0.8

Readme.txt

SFDAPO64.d11 : 2.0.0.8
SFHAPO64.d11 : 2.0.0.8
SFProc64.d11 : 2.0.0.8
SFSAPO64.d11 : 2.0.0.8
slcshp64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slInit64.d11 : 1.1.3.0
slmaxv64.d11 : 1.1.2.0
sltshd64.d11 : 1.1.1.0
sluapo64.d11 : 1.8.22.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
WavesGUILib.d11 : 1.2.3.4

HDMI Driver : -----
Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.5945
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.0
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.7.0
RHDMIExt.d11 : 6.0.6000.100
RtkHDMI.d11 : 11.0.6000.113

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.5945
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.7.0
RHDMEx64.d11 : 6.0.6000.100
RtkHDM64.d11 : 11.0.6000.113

XP/2K x86:
RtkHDMI.sys : 5.10.0.5945
Rtaupd.exe : 2.8.0.0
RHCoInstXP.d11 : 1.0.7.0

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5945
Rtaupd64.exe : 2.8.0.0
RHCoInst64XP.d11 : 1.0.7.0

Driver Setup Program : 2.88

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====
Driver Package R2.36

Readme.txt

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2.) Package :

1. Fix some presentation string of Upgraded dialog in small VGA Mode

Windows 2000/XP :

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5969
RTKHDAUD.sys	: 5.10.0.5969
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.2
RTHDCPL.exe	: 2.3.2.1
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.0
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.33
vncutil.exe	: 1.0.0.33
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.d11	: 1.0.7.5
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.7.5
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver :

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.5969
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVbg.exe	: 1.0.0.6
RtHDVCpl.exe	: 1.0.0.439
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2

Readme.txt

vncutil.exe	: 1.0.0.33
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.17
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 42.5.21.65
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.107
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.121
RTEED32A.d11	: 6.1.6001.29
RTEEG32A.d11	: 6.1.6001.29
RTEEL32A.d11	: 6.1.6001.29
RTEEP32A.d11	: 6.1.6001.29
RtkAPO.d11	: 11.0.6000.121
RtkApoApi.d11	: 1.0.0.13
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.7.5
RtkPgExt.d11	: 6.0.6000.108
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.8
SFFXDAPO.d11	: 2.0.0.8
SFFXHAPO.d11	: 2.0.0.8
SFFXProc.d11	: 2.0.0.8
SFFXSAPO.d11	: 2.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5969
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.6
RAVCp164.exe	: 1.0.0.439
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.33
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8

Readme.txt

RTSnMg64.cpl	: 1.0.0.17
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 42.6.21.65
MaxxAudioAPO20.d11	: 2.2.6.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.107
MBTHX64.d11	: 1.0.8.107
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.7.5
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.121
RTCOMDLL.d11	: 2.0.0.121
RTEED64A.d11	: 6.1.6001.29
RTEEG64A.d11	: 6.1.6001.29
RTEEL64A.d11	: 6.1.6001.29
RTEEP64A.d11	: 6.1.6001.29
RtkApi64.d11	: 1.0.0.13
RtkAPO64.d11	: 11.0.6000.121
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.108
SFComm64.d11	: 2.0.0.8
SFDAPO64.d11	: 2.0.0.8
SFHAP064.d11	: 2.0.0.8
SFProc64.d11	: 2.0.0.8
SFSAPO64.d11	: 2.0.0.8
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.4.8.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5945
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.7.0
RHDMIExt.d11	: 6.0.6000.100
RtkHDMI.d11	: 11.0.6000.113
Vista/Win7 x64:	

Readme.txt

RtHDMIVX.sys : 6.0.1.5945
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.7.0
RHDMEx64.d11 : 6.0.6000.100
RtkHDM64.d11 : 11.0.6000.113

XP/2K x86:
RtkHDMI.sys : 5.10.0.5945
Rtaupd.exe : 2.8.0.0
RHCoInstXP.d11 : 1.0.7.0

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5945
Rtaupd64.exe : 2.8.0.0
RHCoInst64XP.d11 : 1.0.7.0

Driver Setup Program : 2.86

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.35

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2.) Package :

1. Fix some presentation of Spanish language .

2. Add "Windows Server 2008 x64 R2" identification folder.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5953
RTKHDAUD.sys : 5.10.0.5953
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.1.8
RtkAudioService64.exe : 1.0.0.19

Readme.txt

RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.0
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.32
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.d11	: 1.0.7.0
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.7.0
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : <hr/>	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.5953
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.6
RtHDVCpl.exe	: 1.0.0.426
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.32
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.17
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 42.5.19.65
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.103
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.120
RTEED32A.d11	: 6.1.6001.29
RTEEG32A.d11	: 6.1.6001.29
RTEEL32A.d11	: 6.1.6001.29
RTEEP32A.d11	: 6.1.6001.29
RtkAPO.d11	: 11.0.6000.116
RtkApoApi.d11	: 1.0.0.13
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.7.1
RtkPgExt.d11	: 6.0.6000.103
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.8

Readme.txt

SFFXDAPO.d11	: 2.0.0.8
SFFXHAP0.d11	: 2.0.0.8
SFFXProc.d11	: 2.0.0.8
SFFXSAP0.d11	: 2.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5953
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.6
RAVCp164.exe	: 1.0.0.426
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.32
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.17
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 42.6.19.65
MaxxAudioAPO20.d11	: 2.2.6.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.22.0
MBTHX32.d11	: 1.0.8.103
MBTHX64.d11	: 1.0.8.103
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.7.1
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.120
RTCOMDLL.d11	: 2.0.0.120
RTEED64A.d11	: 6.1.6001.29
RTEEG64A.d11	: 6.1.6001.29
RTEEL64A.d11	: 6.1.6001.29
RTEEP64A.d11	: 6.1.6001.29
RtkApi64.d11	: 1.0.0.13
RtkAPO64.d11	: 11.0.6000.116
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.103

Readme.txt

SFComm64.d11 : 2.0.0.8
SFDAPO64.d11 : 2.0.0.8
SFHAPO64.d11 : 2.0.0.8
SFProc64.d11 : 2.0.0.8
SFSAPO64.d11 : 2.0.0.8
slcshp64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slInit64.d11 : 1.1.3.0
slmaxv64.d11 : 1.1.2.0
sltshd64.d11 : 1.1.1.0
sluapo64.d11 : 1.4.8.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :

Vista/Win7 x86:

RtHDMIV.sys : 6.0.1.5945
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.0
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.7.0
RHDMIExt.d11 : 6.0.6000.100
RtkHDMI.d11 : 11.0.6000.113

Vista/Win7 x64:

RtHDMIVX.sys : 6.0.1.5945
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.7.0
RHDMEx64.d11 : 6.0.6000.100
RtkHDM64.d11 : 11.0.6000.113

XP/2K x86:

RtkHDMI.sys : 5.10.0.5945
Rtaupd.exe : 2.8.0.0
RHCoInstXP.d11 : 1.0.7.0

XP/2K x64:

RtkHDMIX.sys : 5.10.0.5945
Rtaupd64.exe : 2.8.0.0
RHCoInst64XP.d11 : 1.0.7.0

Driver Setup Program : 2.85

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====
Driver Package R2.34

Readme.txt

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC270, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5943
RTKHDAUD.sys	: 5.10.0.5943
MicCal.exe	: 1.1.2.2
RTHDCPL.exe	: 2.3.1.4
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.0
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.31
vncutil.exe	: 1.0.0.31
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.7.0
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.7.0
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.5943
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.6
RtHDVCpl.exe	: 1.0.0.422
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.31
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.17
AERTACap.d11	: 2.0.32.8

Readme.txt

AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 42.5.18.67
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.19.0
MBTHX32.d11	: 1.0.8.102
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.120
RTEED32A.d11	: 6.1.6001.29
RTEEG32A.d11	: 6.1.6001.29
RTEEL32A.d11	: 6.1.6001.29
RTEEP32A.d11	: 6.1.6001.29
RtkAPO.d11	: 11.0.6000.113
RtkApoApi.d11	: 1.0.0.13
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.7.0
RtkPgExt.d11	: 6.0.6000.99
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.8
SFFXDAPO.d11	: 2.0.0.8
SFFXHAPO.d11	: 2.0.0.8
SFFXProc.d11	: 2.0.0.8
SFFXSAPO.d11	: 2.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5943
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.6
RAVCp164.exe	: 1.0.0.422
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.31
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.17
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 42.6.18.67

Readme.txt

MaxxAudioAPO20.d11	: 2.2.6.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBpp1d64.d11	: 1.0.19.0
MBTHX32.d11	: 1.0.8.102
MBTHX64.d11	: 1.0.8.102
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.7.0
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.120
RTCOMDLL.d11	: 2.0.0.120
RTEED64A.d11	: 6.1.6001.29
RTEEG64A.d11	: 6.1.6001.29
RTEEL64A.d11	: 6.1.6001.29
RTEEP64A.d11	: 6.1.6001.29
RtkApi64.d11	: 1.0.0.13
RtkAPO64.d11	: 11.0.6000.113
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.99
SFComm64.d11	: 2.0.0.8
SFDAPO64.d11	: 2.0.0.8
SFHAP064.d11	: 2.0.0.8
SFProc64.d11	: 2.0.0.8
SFSAP064.d11	: 2.0.0.8
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.4.8.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5897
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.6.4
RHDMIExt.d11	: 6.0.6000.82
RtkHDMI.d11	: 11.0.6000.101
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.5897
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.0

Readme.txt

RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.6.4
RHDMEx64.d11 : 6.0.6000.82
RtkHDM64.d11 : 11.0.6000.101

XP/2K x86:
RtkHDMI.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1
XP/2K x64:
RtkHDMIX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.84

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.33

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5936
RTKHDAUD.sys : 5.10.0.5936
MicCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.1.2
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.29
vncutil.exe : 1.0.0.29
Alcmtr.exe : 1.6.0.4

Readme.txt

AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBFt64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.6.9
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.6.9
Rt1CPAPI.d11	: 1.0.2.3
Vista/Win7 driver : <hr/>	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.5936
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.6
RtHDVCpl.exe	: 1.0.0.418
RtkAudioService.exe	: 1.0.0.24
Rt1Upd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.29
RTSndMgr.cpl	: 1.0.0.17
mbfilt32.sys	: 6.10.0.8
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 42.5.18.65
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.6.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.19.0
MBTHX32.d11	: 1.0.8.102
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.120
RTEED32A.d11	: 6.1.6001.29
RTEEG32A.d11	: 6.1.6001.29
RTEEL32A.d11	: 6.1.6001.29
RTEEP32A.d11	: 6.1.6001.29
RtkAPO.d11	: 11.0.6000.109
RtkApoApi.d11	: 1.0.0.13
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.6.9
RtkPgExt.d11	: 6.0.6000.96
Rt1CPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.8
SFFXDAPO.d11	: 2.0.0.8
SFFXHAPO.d11	: 2.0.0.8
SFFXProc.d11	: 2.0.0.8
SFFXSAPO.d11	: 2.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0

Readme.txt

slInit32.d11 : 1.1.3.0
slmaxv32.d11 : 1.1.2.0
sltshd32.d11 : 1.1.1.0
sluapo32.d11 : 1.4.8.0
SRSHp360.d11 : 1.1.0.0
SRSTSHD.d11 : 1.1.4.0
SRSTSXT.d11 : 3.2.0.0
SRSWOW.d11 : 1.1.3.0
WavesLib.d11 : 5.9.7.0
Vista/Win7 driver for x64
RTKVHD64.sys : 6.0.1.5936
AERTSr64.exe : 1.0.64.9
APOPCH.exe : 1.0.0.0
RAVBg64.exe : 1.0.0.6
RAVCp164.exe : 1.0.0.418
RtkAudioService64.exe : 1.0.0.24
RtlUpd64.exe : 2.8.0.0
SkyTel.exe : 2.0.2.2
vncutil64.exe : 1.0.0.29
GWfilt64.sys : 6.10.0.3
mbfilt64.sys : 6.10.0.8
RTSnMg64.cpl : 1.0.0.17
AERTAC64.d11 : 2.0.64.8
AERTAR64.d11 : 1.0.64.8
FMAPO64.d11 : 42.6.18.65
MaxxAudioAPO20.d11 : 2.2.6.0
MBAPO32.d11 : 1.0.19.0
MBAPO64.d11 : 1.0.19.0
MBPPCn64.d11 : 1.0.0.110
MBppld64.d11 : 1.0.19.0
MBTHX32.d11 : 1.0.8.102
MBTHX64.d11 : 1.0.8.102
MBWrp64.d11 : 1.0.0.110
RCoInst64.d11 : 1.0.6.9
RP3DAA64.d11 : 6.0.6001.18
RP3DHT64.d11 : 6.0.6001.18
RtCOM64.d11 : 2.0.0.120
RTCOMDLL.d11 : 2.0.0.120
RTEED64A.d11 : 6.1.6001.29
RTEEG64A.d11 : 6.1.6001.29
RTEEL64A.d11 : 6.1.6001.29
RTEEP64A.d11 : 6.1.6001.29
RtkApi64.d11 : 1.0.0.13
RtkAPO64.d11 : 11.0.6000.109
RtkCfg.d11 : 1.0.0.1
RtkCfg64.d11 : 1.0.0.1
Rt1CPAPI.d11 : 1.0.2.4
Rt1CPAPI64.d11 : 1.0.2.4
RtPgEx64.d11 : 6.0.6000.96
SFComm64.d11 : 2.0.0.8
SFDAP064.d11 : 2.0.0.8
SFHAP064.d11 : 2.0.0.8
SFProc64.d11 : 2.0.0.8
SFSAP064.d11 : 2.0.0.8
slcshp64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0

Readme.txt

slh36064.d11 : 1.0.2.0
slInit64.d11 : 1.1.3.0
slmaxv64.d11 : 1.1.2.0
sltshd64.d11 : 1.1.1.0
sluapo64.d11 : 1.4.8.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver : -----
Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.5897
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.0
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.6.4
RHDMIExt.d11 : 6.0.6000.82
RtkHDMI.d11 : 11.0.6000.101

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.5897
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.6.4
RHDMEx64.d11 : 6.0.6000.82
RtkHDM64.d11 : 11.0.6000.101

XP/2K x86:
RtkHDMI.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.84

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.32

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260,

Readme.txt

ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5928
RTKHDAUD.sys	: 5.10.0.5928
MicCal.exe	: 1.1.2.2
RTHDCPL.exe	: 2.3.1.0
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.0
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.27
vncutil.exe	: 1.0.0.27
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.6.5
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.6.5
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.5928
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.6
RtHDVCpl.exe	: 1.0.0.411
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.27
mbfilt32.sys	: 6.10.0.8
RTSndMgr.cpl	: 1.0.0.17
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 42.5.17.68
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.19.0

Readme.txt

MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.19.0
MBTHX32.d11	: 1.0.8.0
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.119
RTEED32A.d11	: 6.1.6001.29
RTEEG32A.d11	: 6.1.6001.29
RTEEL32A.d11	: 6.1.6001.29
RTEEP32A.d11	: 6.1.6001.29
RtkAPO.d11	: 11.0.6000.106
RtkApoApi.d11	: 1.0.0.12
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.6.7
RtkPgExt.d11	: 6.0.6000.93
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.8
SFFXDAPO.d11	: 2.0.0.8
SFFXHAPO.d11	: 2.0.0.8
SFFXProc.d11	: 2.0.0.8
SFFXSAPO.d11	: 2.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5928
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.6
RAVCp164.exe	: 1.0.0.411
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.27
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.8
RTSnMg64.cpl	: 1.0.0.17
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 42.6.17.68
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.19.0
MBAPO64.d11	: 1.0.19.0
MBPPCn64.d11	: 1.0.0.110
MBpp1d64.d11	: 1.0.19.0
MBTHX32.d11	: 1.0.8.0

Readme.txt

MBTHX64.d11	: 1.0.8.0
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.6.7
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.119
RTCOMDLL.d11	: 2.0.0.119
RTEED64A.d11	: 6.1.6001.29
RTEEG64A.d11	: 6.1.6001.29
RTEEL64A.d11	: 6.1.6001.29
RTEEP64A.d11	: 6.1.6001.29
RtkApi64.d11	: 1.0.0.12
RtkAPO64.d11	: 11.0.6000.106
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.93
SFComm64.d11	: 2.0.0.8
SFDAPO64.d11	: 2.0.0.8
SFHAP064.d11	: 2.0.0.8
SFProc64.d11	: 2.0.0.8
SFSAP064.d11	: 2.0.0.8
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.4.8.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5897
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.6.4
RHDMIExt.d11	: 6.0.6000.82
RtkHDMI.d11	: 11.0.6000.101
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.5897
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.0
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.6.4
RHDMEx64.d11	: 6.0.6000.82
RtkHDM64.d11	: 11.0.6000.101

Readme.txt

XP/2K x86:
RtkHDMI.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1
XP/2K x64:
RtkHDMIX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.83

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.31

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix DTM KS position testing fail issue when turn on Microphone effect under Win7.

2.) Package

1. Reboot message in log file. (WILL_REBOOT)

2. Copy all of AP files to system.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5919
RTKHDAUD.sys : 5.10.0.5919
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.2
RTHDCPL.exe : 2.3.0.9
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.8.0.0
RtlUpd.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.24
vncutil.exe : 1.0.0.25

Readme.txt

AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.4
RCoInst64XP.d11	: 1.0.6.5
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.6.5
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : <hr/>	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.5919
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.5
RtHDVCpl.exe	: 1.0.0.401
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.25
mbfilt32.sys	: 6.10.0.6
RTSndMgr.cpl	: 1.0.0.17
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 42.5.1.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.9.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.9.0
MBTHX32.d11	: 1.0.8.0
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.117
RtkAPO.d11	: 11.0.6000.104
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.6.7
RtkPgExt.d11	: 6.0.6000.89
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.8
SFFXDAPO.d11	: 2.0.0.8
SFFXHAPO.d11	: 2.0.0.8
SFFXProc.d11	: 2.0.0.8
SFFXSAPO.d11	: 2.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0

Readme.txt

SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.5919
 AERTSr64.exe : 1.0.64.9
 APOPCH.exe : 1.0.0.0
 RAVBg64.exe : 1.0.0.5
 RAVCp164.exe : 1.0.0.401
 RtkAudioService64.exe : 1.0.0.24
 RtlUpd64.exe : 2.8.0.0
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.24
 GWfilt64.sys : 6.10.0.3
 mbfilt64.sys : 6.10.0.8
 RTSnMg64.cpl : 1.0.0.17
 AERTAC64.d11 : 2.0.64.8
 AERTAR64.d11 : 1.0.64.8
 FMAPO64.d11 : 42.6.1.1
 MaxxAudioAPO20.d11 : 2.2.2.0
 MBAPO32.d11 : 1.0.19.0
 MBAPO64.d11 : 1.0.19.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.19.0
 MBTHX32.d11 : 1.0.8.0
 MBTHX64.d11 : 1.0.8.0
 MBWrp64.d11 : 1.0.0.110
 RCoInst64.d11 : 1.0.6.7
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.117
 RTCOMDLL.d11 : 2.0.0.117
 RtkApi64.d11 : 1.0.0.10
 RtkAPO64.d11 : 11.0.6000.104
 RtkCfg.d11 : 1.0.0.1
 RtkCfg64.d11 : 1.0.0.1
 Rt1CPAPI.d11 : 1.0.2.4
 Rt1CPAPI64.d11 : 1.0.2.4
 RtPgEx64.d11 : 6.0.6000.89
 SFComm64.d11 : 2.0.0.8
 SFDAPO64.d11 : 2.0.0.8
 SFHAPO64.d11 : 2.0.0.8
 SFProc64.d11 : 2.0.0.8
 SFSAPO64.d11 : 2.0.0.8
 slcshp64.d11 : 1.0.3.0
 slgeq64.d11 : 1.0.1.0
 slh36064.d11 : 1.0.2.0
 slInit64.d11 : 1.1.3.0
 slmaxv64.d11 : 1.1.2.0
 sltshd64.d11 : 1.1.1.0
 sluapo64.d11 : 1.4.8.0
 SRSHP64.d11 : 1.1.0.0
 SRSTSH64.d11 : 1.1.4.0
 SRSTSX64.d11 : 3.2.0.0
 SRSWOW64.d11 : 1.1.3.0

Readme.txt

HDMI Driver : -----
Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.5897
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.0
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.6.4
RHDMIExt.d11 : 6.0.6000.82
RtkHDMI.d11 : 11.0.6000.101

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.5897
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.6.4
RHDMEx64.d11 : 6.0.6000.82
RtkHDM64.d11 : 11.0.6000.101

XP/2K x86:
RtkHDMI.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1
XP/2K x64:
RtkHDMIX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.83

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.30

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670, ALC275

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix DTM testing issue under Win7.

Readme.txt

Windows 2000/XP :	
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5911
RTKHDAUD.sys	: 5.10.0.5911
MicCal.exe	: 1.1.2.2
RTHDCPL.exe	: 2.3.0.7
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.8.0.0
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.4
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.6.5
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.6.5
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver :	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.5911
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.5
RtHDVCpl.exe	: 1.0.0.395
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
mbfilt32.sys	: 6.10.0.6
RTSndMgr.cpl	: 1.0.0.17
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 42.5.1.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.9.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.9.0
MBTHX32.d11	: 1.0.8.0
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.117
RtkAPO.d11	: 11.0.6000.101

Readme.txt

RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.6.5
RtkPgExt.d11	: 6.0.6000.87
Rt1CPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.8
SFFXDAPO.d11	: 2.0.0.8
SFFXHAP0.d11	: 2.0.0.8
SFFXProc.d11	: 2.0.0.8
SFFXSAPO.d11	: 2.0.0.8
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5911
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.5
RAVCp164.exe	: 1.0.0.395
RtkAudioService64.exe	: 1.0.0.24
Rt1Upd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.6
RTSnMg64.cpl	: 1.0.0.17
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 42.6.1.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.9.0
MBAPO64.d11	: 1.0.9.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.9.0
MBTHX32.d11	: 1.0.8.0
MBTHX64.d11	: 1.0.8.0
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.6.5
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.117
RTCOMDLL.d11	: 2.0.0.117
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.101
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4

Readme.txt

Rt1CPAPI64.d11 : 1.0.2.4
RtPgEx64.d11 : 6.0.6000.87
SFComm64.d11 : 2.0.0.8
SFDAPO64.d11 : 2.0.0.8
SFHAPO64.d11 : 2.0.0.8
SFProc64.d11 : 2.0.0.8
SFSAPO64.d11 : 2.0.0.8
slcshp64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slInit64.d11 : 1.1.3.0
slmaxv64.d11 : 1.1.2.0
sltshd64.d11 : 1.1.1.0
sluapo64.d11 : 1.4.8.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :

Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.5897
RtkAudioSrvATI.exe : 1.0.0.23
RtkUpd.exe : 2.8.0.0
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.6.4
RHDMIExt.d11 : 6.0.6000.82
RtkHDMI.d11 : 11.0.6000.101

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.5897
RtkAudioSrvATI64.exe : 1.0.0.23
RtkUpd64.exe : 2.8.0.0
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.6.4
RHDMEx64.d11 : 6.0.6000.82
RtkHDM64.d11 : 11.0.6000.101

XP/2K x86:
RtkHDMI.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.81

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

Readme.txt

//=====

Driver Package R2.29

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC886, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5898
RTKHDAUD.sys	: 5.10.0.5898
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.3.0.0
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.8.0.0
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.23
vncutil64.exe	: 1.0.0.23
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.3
RCoInst64XP.d11	: 1.0.6.3
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.6.3
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : -----

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.5898
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVbg.exe	: 1.0.0.5
RtHDVCpl.exe	: 1.0.0.386
RtkAudioService.exe	: 1.0.0.24
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23

Readme.txt

mbfilt32.sys	: 6.10.0.6
RTSndMgr.cpl	: 1.0.0.16
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 0.0.18.2
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.9.0
MBPPCn32.d11	: 1.0.0.110
MBpp1d32.d11	: 1.0.9.0
MBTHX32.d11	: 1.0.6.0
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.117
RtkAPO.d11	: 11.0.6000.101
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.6.4
RtkPgExt.d11	: 6.0.6000.84
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.6
SFFXDAPO.d11	: 2.0.0.6
SFFXHAPO.d11	: 2.0.0.6
SFFXProc.d11	: 2.0.0.6
SFFXSAPO.d11	: 2.0.0.6
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5898
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.5
RAVCp164.exe	: 1.0.0.386
RtkAudioService64.exe	: 1.0.0.24
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
mbfilt64.sys	: 6.10.0.6
RTSnMg64.cpl	: 1.0.0.16
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 0.0.18.2
MaxxAudioAPO20.d11	: 2.2.2.0

Readme.txt

MBAPO32.d11	: 1.0.9.0
MBAPO64.d11	: 1.0.9.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.9.0
MBTHX32.d11	: 1.0.6.0
MBTHX64.d11	: 1.0.6.0
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.6.4
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.117
RTCOMDLL.d11	: 2.0.0.117
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.101
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.4
RtlCPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.84
SFComm64.d11	: 2.0.0.6
SFDAPO64.d11	: 2.0.0.6
SFHAP064.d11	: 2.0.0.6
SFProc64.d11	: 2.0.0.6
SFSAPO64.d11	: 2.0.0.6
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.4.8.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5897
RtkAudioSrvATI.exe	: 1.0.0.23
RtkUpd.exe	: 2.8.0.0
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.6.4
RHDMIExt.d11	: 6.0.6000.82
RtkHDMI.d11	: 11.0.6000.101
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.5897
RtkAudioSrvATI64.exe	: 1.0.0.23
RtkUpd64.exe	: 2.8.0.0
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.6.4
RHDMEx64.d11	: 6.0.6000.82
RtkHDM64.d11	: 11.0.6000.101

Readme.txt

XP/2K x86:
RtkHDMI.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1
XP/2K x64:
RtkHDMIX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.81

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.28

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887, ALC670
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 - 2.) Package :
 1. Fix uninstallation driver issue under Windows x64 system .

Windows 2000/XP : _____

Windows 2000/XP :
Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5888
RTKHDAUD.sys : 5.10.0.5888
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.9.7
RtkAudioService.exe : 1.0.0.19
RtkAudioService64.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.8.0.0
RtlUpd64.exe : 2.8.0.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil.exe : 1.0.0.23
vncutil64.exe : 1.0.0.23
AMBFilt.sys : 5.10.0.4240

Readme.txt

AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.3
RCoInst64XP.d11	: 1.0.6.2
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.6.2
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : <hr/>	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.5888
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVBg.exe	: 1.0.0.5
RtHDVCpl.exe	: 1.0.0.376
RtkAudioService.exe	: 1.0.0.22
RtlUpd.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 0.0.18.2
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.9.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.9.0
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.116
RtkAPO.d11	: 11.0.6000.101
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.6.2
RtkPgExt.d11	: 6.0.6000.82
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.6
SFFXDAPO.d11	: 2.0.0.6
SFFXHAPO.d11	: 2.0.0.6
SFFXProc.d11	: 2.0.0.6
SFFXSAPO.d11	: 2.0.0.6
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0

Readme.txt

WavesLib.d11	: 5.9.7.0
RCORES.dat	: 1.0.0.5
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5888
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVBg64.exe	: 1.0.0.5
RAVCp164.exe	: 1.0.0.376
RtkAudioService64.exe	: 1.0.0.22
RtlUpd64.exe	: 2.8.0.0
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 0.0.18.2
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.9.0
MBAPO64.d11	: 1.0.9.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.9.0
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.6.2
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.116
RTCOMDLL.d11	: 2.0.0.116
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.101
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.4
RtlCPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.82
SFComm64.d11	: 2.0.0.6
SFDAPO64.d11	: 2.0.0.6
SFHAPO64.d11	: 2.0.0.6
SFProc64.d11	: 2.0.0.6
SFSAPO64.d11	: 2.0.0.6
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.4.8.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
RCORES64.dat	: 1.0.0.5
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5880
RtkUpd.exe	: 2.7.1.3

Readme.txt

RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.6.0
RHDMIExt.d11 : 6.0.6000.82
RtkHDMI.d11 : 11.0.6000.100

Vista/Win7 x64:

RtHDMIVX.sys : 6.0.1.5880
RtkUpd64.exe : 2.7.1.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.6.0
RHDMEx64.d11 : 6.0.6000.82
RtkHDM64.d11 : 11.0.6000.100

XP/2K x86:

RtkHDMI.sys : 5.10.0.5880
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1

XP/2K x64:

RtkHDMIX.sys : 5.10.0.5880
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.80

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.27

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix GUI issue which can't launch Windows MediaPlayer under Win7

OS.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5874
RTKHDAUD.sys : 5.10.0.5874

Readme.txt

MicCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.2.9.2
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.4
RtlUpd.exe	: 2.7.1.4
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.3
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.5.9
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.5.9
RtlCPAPI.d11	: 1.0.2.3
Vista/Win7 driver : _____	
Vista/Win7 driver for x86	
RTKVHDA.sys	: 6.0.1.5874
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.366
RtkAudioService.exe	: 1.0.0.21
RtlUpd.exe	: 2.7.1.4
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.9.0
MBPPCn32.d11	: 1.0.0.110
MBppld32.d11	: 1.0.9.0
MBWrp32.d11	: 1.0.0.110
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.113
RtkAPO.d11	: 11.0.6000.100
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.6.0
RtkPgExt.d11	: 6.0.6000.82
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.6
SFFXDAPO.d11	: 2.0.0.6
SFFXHAPO.d11	: 2.0.0.6

Readme.txt

SFFXProc.d11	: 2.0.0.6
SFFXSAPO.d11	: 2.0.0.6
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.2.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.8.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5874
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVCp164.exe	: 1.0.0.366
RtkAudioService64.exe	: 1.0.0.21
RtlUpd64.exe	: 2.7.1.4
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.9.0
MBAPO64.d11	: 1.0.9.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.9.0
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.6.0
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.113
RTCOMDLL.d11	: 2.0.0.113
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.100
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.82
SFComm64.d11	: 2.0.0.6
SFDAPO64.d11	: 2.0.0.6
SFHAP064.d11	: 2.0.0.6
SFProc64.d11	: 2.0.0.6
SFSAP064.d11	: 2.0.0.6
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.1.2.0

Readme.txt

sltshd64.d11 : 1.1.1.0
sluapo64.d11 : 1.4.8.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver : -----
Vista/Win7 x86:
RtHDMIV.sys : 6.0.1.5857
RtkUpd.exe : 2.7.1.3
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.4.9
RHDMIExt.d11 : 6.0.6000.79
RtkHDMI.d11 : 11.0.6000.99

Vista/Win7 x64:
RtHDMIVX.sys : 6.0.1.5857
RtkUpd64.exe : 2.7.1.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.4.4
RHDMEx64.d11 : 6.0.6000.79
RtkHDM64.d11 : 11.0.6000.99

XP/2K x86:
RtkHDMI.sys : 5.10.0.5857
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5857
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.77

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.26

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

Readme.txt

- 1.) Driver :
 1. Customizations.
 2. Update SRS components.

Windows 2000/XP :

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5864
RTKHDAUD.sys : 5.10.0.5864
MicCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.9.0
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.3
RtlUpd.exe : 2.7.1.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
AMBFt64.sys : 5.10.0.4240
Monfilt.sys : 5.10.0.4112
Monft64.sys : 5.10.0.4115
AMBFilt.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.3
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.d11 : 1.0.5.6
RTCOMDLL.d11 : 1.0.0.103
RtkCoInstXP.d11 : 1.0.5.6
RtlCPAPI.d11 : 1.0.2.3

Vista/Win7 driver :

Vista/Win7 driver for x86
RTKVHDA.sys : 6.0.1.5864
AERTSrv.exe : 1.0.32.9
APOPCH.exe : 1.0.0.0
RtHDVCpl.exe : 1.0.0.356
RtkAudioService.exe : 1.0.0.19
RtlUpd.exe : 2.7.1.3
SkyTel.exe : 2.0.2.2
vncutil.exe : 1.0.0.23
RTSndMgr.cpl : 1.0.0.15
AERTACap.d11 : 2.0.32.8
AERTARen.d11 : 1.0.32.8
FMAPO.d11 : 0.0.14.1
MaxxAudioAPO.d11 : 1.2.2.0
MaxxAudioAPO20.d11 : 2.2.2.0
MaxxAudioEQ.d11 : 5.9.7.0
MBAPO32.d11 : 1.0.9.0
MBPPCn32.d11 : 1.0.0.110
MBppld32.d11 : 1.0.9.0
MBWrp32.d11 : 1.0.0.110
RP3DAA32.d11 : 6.0.6001.18
RP3DHT32.d11 : 6.0.6001.18
RTCOMDLL.d11 : 2.0.0.113
RtkAPO.d11 : 11.0.6000.99

Readme.txt

RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.5.8
RtkPgExt.d11	: 6.0.6000.79
Rt1CPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.6
SFFXDAPO.d11	: 2.0.0.6
SFFXHAP0.d11	: 2.0.0.6
SFFXProc.d11	: 2.0.0.6
SFFXSAPO.d11	: 2.0.0.6
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.4.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista/Win7 driver for x64	
RTKVHD64.sys	: 6.0.1.5864
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVCp164.exe	: 1.0.0.356
RtkAudioService64.exe	: 1.0.0.19
Rt1Upd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.9.0
MBAPO64.d11	: 1.0.9.0
MBPPCn64.d11	: 1.0.0.110
MBppld64.d11	: 1.0.9.0
MBWrp64.d11	: 1.0.0.110
RCoInst64.d11	: 1.0.5.8
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.113
RTCOMDLL.d11	: 2.0.0.113
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.99
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.79
SFComm64.d11	: 2.0.0.6
SFDAPO64.d11	: 2.0.0.6

Readme.txt

SFHAP064.d11 : 2.0.0.6
SFProc64.d11 : 2.0.0.6
SFSAP064.d11 : 2.0.0.6
slcshp64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slInit64.d11 : 1.1.3.0
slmaxv64.d11 : 1.1.1.0
sltshd64.d11 : 1.1.1.0
sluapo64.d11 : 1.4.6.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :

Vista/Win7 x86:

RtHDMIV.sys : 6.0.1.5857
RtkUpd.exe : 2.7.1.3
RH3DAA32.d11 : 6.0.6001.18
RH3DHT32.d11 : 6.0.6001.18
RHCoInst.d11 : 1.0.4.9
RHDMIExt.d11 : 6.0.6000.79
RtkHDMI.d11 : 11.0.6000.99

Vista/Win7 x64:

RtHDMIVX.sys : 6.0.1.5857
RtkUpd64.exe : 2.7.1.3
RH3DAA64.d11 : 6.0.6001.18
RH3DHT64.d11 : 6.0.6001.18
RHCoInst64.d11 : 1.0.4.4
RHDMEx64.d11 : 6.0.6000.79
RtkHDM64.d11 : 11.0.6000.99

XP/2K x86:

RtkHDMI.sys : 5.10.0.5857
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1

XP/2K x64:

RtkHDMIX.sys : 5.10.0.5857
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.76

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.25

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista/Windows 7 WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

Readme.txt

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Windows 7 WHQL Driver.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5859
RTKHDAUD.sys	: 5.10.0.5859
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.2.9.0
RtkAudioService.exe	: 1.0.0.19
RtkAudioService64.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.7.1.3
RtlUpd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.23
vncutil64.exe	: 1.0.0.23
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.3
RCoInst64XP.d11	: 1.0.5.6
RTCOMDLL.d11	: 1.0.0.103
RtkCoInstXP.d11	: 1.0.5.6
RtlCPAPI.d11	: 1.0.2.3

Vista/Win7 driver : _____

Vista/Win7 driver for x86

RTKVHDA.sys	: 6.0.1.5859
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.353
RtkAudioService.exe	: 1.0.0.19
RtlUpd.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0

Readme.txt

MBAPO32.d11 : 1.0.9.0
 MBPPCn32.d11 : 1.0.0.110
 MBppld32.d11 : 1.0.9.0
 MBWrp32.d11 : 1.0.0.110
 RP3DAA32.d11 : 6.0.6001.18
 RP3DHT32.d11 : 6.0.6001.18
 RTCOMDLL.d11 : 2.0.0.113
 RtkAPO.d11 : 11.0.6000.99
 RtkApoApi.d11 : 1.0.0.10
 RtkCfg.d11 : 1.0.0.1
 RtkCoInst.d11 : 1.0.5.8
 RtkPgExt.d11 : 6.0.6000.79
 RtlCPAPI.d11 : 1.0.2.4
 SFFXComm.d11 : 2.0.0.6
 SFFXDAPO.d11 : 2.0.0.6
 SFFXHAP0.d11 : 2.0.0.6
 SFFXProc.d11 : 2.0.0.6
 SFFXSAPO.d11 : 2.0.0.6
 slcshp32.d11 : 1.0.3.0
 slgeq32.d11 : 1.0.1.0
 slh36032.d11 : 1.0.2.0
 slInit32.d11 : 1.1.3.0
 slmaxv32.d11 : 1.0.4.0
 sltshd32.d11 : 1.1.1.0
 sluapo32.d11 : 1.3.4.0
 SRSHP360.d11 : 1.1.0.0
 SRSTSHD.d11 : 1.1.4.0
 SRSTSXT.d11 : 3.2.0.0
 SRSWOW.d11 : 1.1.3.0
 WavesLib.d11 : 5.9.7.0
 Vista/Win7 driver for x64
 RTKVHD64.sys : 6.0.1.5859
 AERTSr64.exe : 1.0.64.9
 APOPCH.exe : 1.0.0.0
 RAVCp164.exe : 1.0.0.353
 RtkAudioService64.exe : 1.0.0.19
 RtlUpd64.exe : 2.7.1.3
 SkyTel.exe : 2.0.2.2
 vncutil64.exe : 1.0.0.23
 GWfilt64.sys : 6.10.0.3
 RTSnMg64.cpl : 1.0.0.15
 AERTAC64.d11 : 2.0.64.8
 AERTAR64.d11 : 1.0.64.8
 FMAPO64.d11 : 0.0.14.1
 MaxxAudioAPO20.d11 : 2.2.2.0
 MBAPO32.d11 : 1.0.9.0
 MBAPO64.d11 : 1.0.9.0
 MBPPCn64.d11 : 1.0.0.110
 MBppld64.d11 : 1.0.9.0
 MBWrp64.d11 : 1.0.0.110
 RCoInst64.d11 : 1.0.5.8
 RP3DAA64.d11 : 6.0.6001.18
 RP3DHT64.d11 : 6.0.6001.18
 RtCOM64.d11 : 2.0.0.113
 RTCOMDLL.d11 : 2.0.0.113
 RtkApi64.d11 : 1.0.0.10

Readme.txt

RtkAPO64.d11	: 11.0.6000.99
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.79
SFComm64.d11	: 2.0.0.6
SFDAPO64.d11	: 2.0.0.6
SFHAP064.d11	: 2.0.0.6
SFProc64.d11	: 2.0.0.6
SFSAPO64.d11	: 2.0.0.6
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.0.4.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.3.4.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista/Win7 x86:	
RtHDMIV.sys	: 6.0.1.5857
RtkUpd.exe	: 2.7.1.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.4.9
RHDMIExt.d11	: 6.0.6000.79
RtkHDMI.d11	: 11.0.6000.99
Vista/Win7 x64:	
RtHDMIVX.sys	: 6.0.1.5857
RtkUpd64.exe	: 2.7.1.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.4.4
RHDMEx64.d11	: 6.0.6000.79
RtkHDM64.d11	: 11.0.6000.99
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.5857
RtkUpd.exe	: 2.7.1.3
RHCoInstXP.d11	: 1.0.5.1
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.5857
RtkUpd64.exe	: 2.7.1.3
RHCoInst64XP.d11	: 1.0.5.1
Driver Setup Program	: 2.76
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package – KB888111	
Package file version (kb888111.exe) : 6.1.22.0	

Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.24

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 - x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5854
RTKHDAUD.sys	: 5.10.0.5854
MicCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.2.8.8
RtkAudioService64.exe	: 1.0.0.19
RtkAudioService.exe	: 1.0.0.19
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.3
RtlUpd.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.3
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.5.6
RTCOMDLL.d11	: 1.0.0.102
RtkCoInstXP.d11	: 1.0.5.6
RtlCPAPI.d11	: 1.0.2.3

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5854
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.352
RtkAudioService.exe	: 1.0.0.19
RtlUpd.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23

Readme.txt

RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBpp1d32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.113
RtkAPO.d11	: 11.0.6000.99
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.5.7
RtkPgExt.d11	: 6.0.6000.79
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.6
SFFXDAPO.d11	: 2.0.0.6
SFFXHAPO.d11	: 2.0.0.6
SFFXProc.d11	: 2.0.0.6
SFFXSAPO.d11	: 2.0.0.6
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.0.4.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.3.4.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5854
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVCp164.exe	: 1.0.0.352
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBpp1d64.d11	: 1.0.0.630

Readme.txt

MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.5.7
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.113
RTCOMDLL.d11	: 2.0.0.113
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.99
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.79
SFComm64.d11	: 2.0.0.6
SFDAPO64.d11	: 2.0.0.6
SFHAP064.d11	: 2.0.0.6
SFProc64.d11	: 2.0.0.6
SFSAPO64.d11	: 2.0.0.6
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.0.4.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.3.4.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5832
RtkUpd.exe	: 2.7.1.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.4.9
RHDMIExt.d11	: 6.0.6000.75
RtkHDMI.d11	: 11.0.6000.95
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5832
RtkUpd64.exe	: 2.7.1.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.4.4
RHDMEx64.d11	: 6.0.6000.75
RtkHDM64.d11	: 11.0.6000.95
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.5832
RtkUpd.exe	: 2.7.1.3
RHCoInstXP.d11	: 1.0.5.1
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.5832
RtkUpd64.exe	: 2.7.1.3

Readme.txt

RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.76

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.23

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix DTM 1.4 lullaby test & wave pull mode test issue.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5845

RTKHDAUD.sys : 5.10.0.5845

Alcmtr.exe : 1.6.0.4

AlcWzrd.exe : 1.1.0.37

MicCal.exe : 1.1.2.1

RTHDCPL.exe : 2.2.8.4

RtkAudioService64.exe : 1.0.0.19

RtkAudioService.exe : 1.0.0.19

RTLCPPL.exe : 1.0.1.66

RtlUpd64.exe : 2.7.1.3

RtlUpd.exe : 2.7.1.3

SkyTel.exe : 2.0.2.0

SoundMan.exe : 1.0.0.32

vncutil64.exe : 1.0.0.23

vncutil.exe : 1.0.0.23

AMBFilt.sys : 5.10.0.4240

AMBft64.sys : 5.10.0.4240

Monfilt.sys : 5.10.0.4112

Monft64.sys : 5.10.0.4115

ALSndMgr.cpl : 1.0.0.11

RTSndMgr.cpl : 1.0.1.3

RCoInst64XP.d11 : 1.0.5.3

RTCOMDLL.d11 : 1.0.0.102

RtkCoInstXP.d11 : 1.0.5.3

Rt1CPAPI.d11 : 1.0.2.3

Vista driver : _____

Vista driver for x86

Readme.txt

RTKVHDA.sys	: 6.0.1.5845
AERTSrv.exe	: 1.0.32.9
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.345
RtkAudioService.exe	: 1.0.0.19
RtlUpd.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.8
AERTARen.d11	: 1.0.32.8
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBppld32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.113
RtkAPO.d11	: 11.0.6000.98
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.5.5
RtkPgExt.d11	: 6.0.6000.78
RtlCPAPI.d11	: 1.0.2.4
SFFXComm.d11	: 2.0.0.6
SFFXDAPO.d11	: 2.0.0.6
SFFXHAPO.d11	: 2.0.0.6
SFFXProc.d11	: 2.0.0.6
SFFXSAPO.d11	: 2.0.0.6
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.0.4.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.3.4.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5845
AERTSr64.exe	: 1.0.64.9
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.345
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15

Readme.txt

AERTAC64.d11	: 2.0.64.8
AERTAR64.d11	: 1.0.64.8
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBpp1d64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.5.5
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.113
RTCOMDLL.d11	: 2.0.0.113
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.98
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.4
Rt1CPAPI64.d11	: 1.0.2.4
RtPgEx64.d11	: 6.0.6000.78
SFComm64.d11	: 2.0.0.6
SFDAPO64.d11	: 2.0.0.6
SFHAPO64.d11	: 2.0.0.6
SFProc64.d11	: 2.0.0.6
SFSAPO64.d11	: 2.0.0.6
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.0.4.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.3.4.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5832
RtkUpd.exe	: 2.7.1.3
RH3DAA32.d11	: 6.0.6001.18
RH3DHT32.d11	: 6.0.6001.18
RHCoInst.d11	: 1.0.4.9
RHDMIExt.d11	: 6.0.6000.75
RtkHDMI.d11	: 11.0.6000.95
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5832
RtkUpd64.exe	: 2.7.1.3
RH3DAA64.d11	: 6.0.6001.18
RH3DHT64.d11	: 6.0.6001.18
RHCoInst64.d11	: 1.0.4.4
RHDMEx64.d11	: 6.0.6000.75
RtkHDM64.d11	: 11.0.6000.95

Readme.txt

XP/2K x86:
RtkHDMI.sys : 5.10.0.5832
RtkUpd.exe : 2.7.1.3
RHCoInstXP.d11 : 1.0.5.1

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5832
RtkUpd64.exe : 2.7.1.3
RHCoInst64XP.d11 : 1.0.5.1

Driver Setup Program : 2.75

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.22

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5832
RTKHDAUD.sys : 5.10.0.5832
MicCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.7.8
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.3
RtlUpd.exe : 2.7.1.3
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
Monfilt.sys : 5.10.0.4112
Monft64.sys : 5.10.0.4115
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
RTSndMgr.cpl : 1.0.1.2

Readme.txt

ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.5.0
RTCOMDLL.d11	: 1.0.0.101
RtkCoInstXP.d11	: 1.0.5.0
Rt1CPAPI.d11	: 1.0.2.2
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5832
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.334
RtkAudioService.exe	: 1.0.0.19
Rt1Upd.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.7
AERTARen.d11	: 1.0.32.7
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBppld32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RP3DAA32.d11	: 6.0.6001.18
RP3DHT32.d11	: 6.0.6001.18
RTCOMDLL.d11	: 2.0.0.111
RtkAPO.d11	: 11.0.6000.95
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.5.2
RtkPgExt.d11	: 6.0.6000.75
Rt1CPAPI.d11	: 1.0.2.2
SFCPStr.d11	: 1.1.0.3
SFFXComm.d11	: 1.1.0.3
SFFXCP.d11	: 1.1.0.3
SFFXLAPO.d11	: 1.1.0.3
SFFXProc.d11	: 1.1.0.3
SFFXSAPO.d11	: 1.1.0.3
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.0.4.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.3.4.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5832
AERTSr64.exe	: 1.0.64.8

Readme.txt

APOPCH.exe	: 1.0.0.0
RAVCp164.exe	: 1.0.0.334
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.3
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.7
AERTAR64.d11	: 1.0.64.7
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBppld64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.5.2
RP3DAA64.d11	: 6.0.6001.18
RP3DHT64.d11	: 6.0.6001.18
RtCOM64.d11	: 2.0.0.111
RTCOMDLL.d11	: 2.0.0.111
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.95
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.2
RtlCPAPI64.d11	: 1.0.2.2
RtPgEx64.d11	: 6.0.6000.75
SFComm64.d11	: 1.1.0.3
SFCP64.d11	: 1.1.0.3
SFCPStr.d11	: 1.1.0.3
SFLAPO64.d11	: 1.1.0.3
SFProc64.d11	: 1.1.0.3
SFSAPO64.d11	: 1.1.0.3
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.0.4.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.3.4.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5796
RtkUpd.exe	: 2.7.1.2
AHPCEE32.d11	: 6.0.6001.17
RHCoInst.d11	: 1.0.4.4
RHDMIExt.d11	: 6.0.6000.69
RtkHDMI.d11	: 11.0.6000.88
Vista x64:	

Readme.txt

RtHDMIVX.sys : 6.0.1.5796
RtkUpd64.exe : 2.7.1.2
AHPCEE64.d11 : 6.0.6001.17
RHCoInst64.d11 : 1.0.4.4
RHDMEx64.d11 : 6.0.6000.69
RtkHDM64.d11 : 11.0.6000.88

XP/2K x86:
RtkHDMI.sys : 5.10.0.5796
RtkUpd.exe : 2.7.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5796
RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.75

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.21

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Support ALC275.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5821
RTKHDAUD.sys : 5.10.0.5821
MicCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.7.5
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.2
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
Alcmtr.exe : 1.6.0.4

Readme.txt

AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.2
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.5.0
RTCOMDLL.d11	: 1.0.0.100
RtkCoInstXP.d11	: 1.0.5.0
RtlCPAPI.d11	: 1.0.2.2
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5821
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.323
RtkAudioService.exe	: 1.0.0.19
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.7
AERTARen.d11	: 1.0.32.7
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBppld32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RTCOMDLL.d11	: 2.0.0.110
RtkAPO.d11	: 11.0.6000.90
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.5.0
RtkPgExt.d11	: 6.0.6000.70
RtlCPAPI.d11	: 1.0.2.2
RTPCEE32.d11	: 6.0.6001.17
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.3.0
slmaxv32.d11	: 1.0.4.0
sltshd32.d11	: 1.1.1.0
sluapo32.d11	: 1.3.4.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5821
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0

Readme.txt

RAVCp164.exe	: 1.0.0.323
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.7
AERTAR64.d11	: 1.0.64.7
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBpp1d64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.5.0
RtCOM64.d11	: 2.0.0.110
RTCOMDLL.d11	: 2.0.0.110
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.90
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.2
RtlCPAPI64.d11	: 1.0.2.2
RTPCEE64.d11	: 6.0.6001.17
RtPgEx64.d11	: 6.0.6000.70
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.3.0
slmaxv64.d11	: 1.0.4.0
sltshd64.d11	: 1.1.1.0
sluapo64.d11	: 1.3.4.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5796
RtkUpd.exe	: 2.7.1.2
AHPCEE32.d11	: 6.0.6001.17
RHCoInst.d11	: 1.0.4.4
RHDMIExt.d11	: 6.0.6000.69
RtkHDMI.d11	: 11.0.6000.88
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5796
RtkUpd64.exe	: 2.7.1.2
AHPCEE64.d11	: 6.0.6001.17
RHCoInst64.d11	: 1.0.4.4
RHDMEx64.d11	: 6.0.6000.69
RtkHDM64.d11	: 11.0.6000.88
XP/2K x86:	

Readme.txt

RtkHDMI.sys : 5.10.0.5796
RtkUpd.exe : 2.7.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5796
RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.74

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.20

Realtek HD Audio Driver support all of Realtek HD Audio Codec .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Windows Server 2003, Vista, Windows Server 2008, Windows7 – x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5817
RTKHDAUD.sys : 5.10.0.5817
Alcmtr.exe : 1.6.0.4
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.1
RTHDCPL.exe : 2.2.7.4
RtkAudioService64.exe : 1.0.0.19
RtkAudioService.exe : 1.0.0.19
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.2
RtlUpd.exe : 2.7.1.2
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
AMBFilt.sys : 5.10.0.4240
AMBft64.sys : 5.10.0.4240
Monfilt.sys : 5.10.0.4112
Monft64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.2
RCoInst64XP.d11 : 1.0.5.0

Readme.txt

RTCOMDLL.d11	: 1.0.0.99
RtkCoInstXP.d11	: 1.0.5.0
Rt1CPAPI.d11	: 1.0.2.2
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5817
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.319
RtkAudioService.exe	: 1.0.0.19
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.5
AERTARen.d11	: 1.0.32.7
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBppld32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RTCOMDLL.d11	: 2.0.0.109
RtkAPO.d11	: 11.0.6000.90
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.5.0
RtkPgExt.d11	: 6.0.6000.70
Rt1CPAPI.d11	: 1.0.2.2
RTPCEE32.d11	: 6.0.6001.17
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5817
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.319
RtkAudioService64.exe	: 1.0.0.19
RtlUpd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7

Readme.txt

FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBppld64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.5.0
RtCOM64.d11	: 2.0.0.109
RTCOMDLL.d11	: 2.0.0.109
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.90
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.2
Rt1CPAPI64.d11	: 1.0.2.2
RTPCEE64.d11	: 6.0.6001.17
RtPgEx64.d11	: 6.0.6000.70
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0
sltshd64.d11	: 1.1.0.0
sluapo64.d11	: 1.2.6.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5796
RtkUpd.exe	: 2.7.1.2
AHPCEE32.d11	: 6.0.6001.17
RHCoInst.d11	: 1.0.4.4
RHDMIExt.d11	: 6.0.6000.69
RtkHDMI.d11	: 11.0.6000.88
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5796
RtkUpd64.exe	: 2.7.1.2
AHPCEE64.d11	: 6.0.6001.17
RHCoInst64.d11	: 1.0.4.4
RHDMEx64.d11	: 6.0.6000.69
RtkHDM64.d11	: 11.0.6000.88
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.5796
RtkUpd.exe	: 2.7.1.2
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.5796
RtkUpd64.exe	: 2.7.1.2
Driver Setup Program	: 2.74
Windows 2000/XP Operate on :	

Readme.txt

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.19

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista, Windows7 x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2.) Package :

1. Fix upgraded warning dialog for Small VGA mode .

2. Add failed run installation by count .

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5809
RTKHDAUD.sys	: 5.10.0.5809
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.1
RTHDCPL.exe	: 2.2.7.1
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.2
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RCoInst64XP.d11	: 1.0.4.9
RTCOMDLL.d11	: 1.0.0.99
RtkCoInstXP.d11	: 1.0.4.9
RtlCPAPI.d11	: 1.0.2.2

Vista driver : _____

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5809
AERTSrv.exe	: 1.0.32.8

Readme.txt

APOPCH.exe	: 1.0.0.0
RtHdVcPl.exe	: 1.0.0.314
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBppld32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RTCOMDLL.d11	: 2.0.0.109
RtkAPO.d11	: 11.0.6000.89
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.9
RtkPgExt.d11	: 6.0.6000.70
RtlCPAPI.d11	: 1.0.2.2
RTPCEE32.d11	: 6.0.6001.17
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5809
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.314
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBppld64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80

Readme.txt

RCoInst64.d11 : 1.0.4.9
RtCOM64.d11 : 2.0.0.109
RTCOMDLL.d11 : 2.0.0.109
RtkApi64.d11 : 1.0.0.10
RtkAPO64.d11 : 11.0.6000.89
RtkCfg.d11 : 1.0.0.1
RtkCfg64.d11 : 1.0.0.1
Rt1CPAPI.d11 : 1.0.2.2
Rt1CPAPI64.d11 : 1.0.2.2
RTPCEE64.d11 : 6.0.6001.17
RtPgEx64.d11 : 6.0.6000.70
slcshp64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slInit64.d11 : 1.1.1.0
sltshd64.d11 : 1.1.0.0
sluapo64.d11 : 1.2.6.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :
Vista x86:
RtHDMIV.sys : 6.0.1.5796
RtkUpd.exe : 2.7.1.2
AHPCEE32.d11 : 6.0.6001.17
RHCoInst.d11 : 1.0.4.4
RHDMIExt.d11 : 6.0.6000.69
RtkHDMI.d11 : 11.0.6000.88

Vista x64:
RtHDMIVX.sys : 6.0.1.5796
RtkUpd64.exe : 2.7.1.2
AHPCEE64.d11 : 6.0.6001.17
RHCoInst64.d11 : 1.0.4.4
RHDMEx64.d11 : 6.0.6000.69
RtkHDM64.d11 : 11.0.6000.88

XP/2K x86:
RtkHDMI.sys : 5.10.0.5796
RtkUpd.exe : 2.7.1.2

XP/2K x64:
RtkHDMIX.sys : 5.10.0.5796
RtkUpd64.exe : 2.7.1.2

Driver Setup Program : 2.73

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.18

Realtek HD Audio Driver support all of Realtek HD Audio Codec in

Readme.txt

Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista, Windows7 x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2.) Package :

1. Support driver folder of Windows Server 2008 in package .

2. Disable Status Dialog when small VGA Mode enabled .

3. Fix CreativeUp folder disappear issue .

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5804
RTKHDAUD.sys	: 5.10.0.5804
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.6.9
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.2
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.4
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.4.8
RTCOMDLL.d11	: 1.0.0.98
RtkCoInstXP.d11	: 1.0.4.8
RtlCPAPI.d11	: 1.0.2.1

Vista driver : _____

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5804
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.311
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23

Readme.txt

RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBpp1d32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RTCOMDLL.d11	: 2.0.0.108
RtkAPO.d11	: 11.0.6000.89
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.8
RtkPgExt.d11	: 6.0.6000.69
RtlCPAPI.d11	: 1.0.2.1
RTPCEE32.d11	: 6.0.6001.17
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5804
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0
RAVCpl64.exe	: 1.0.0.311
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBpp1d64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.4.8
RtCOM64.d11	: 2.0.0.108
RTCOMDLL.d11	: 2.0.0.108
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.89
RtkCfg.d11	: 1.0.0.1

Readme.txt

RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.1
Rt1CPAPI64.d11	: 1.0.2.1
RTPCEE64.d11	: 6.0.6001.17
RtPgEx64.d11	: 6.0.6000.69
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0
sltshd64.d11	: 1.1.0.0
sluapo64.d11	: 1.2.6.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
HDMI Driver : -----	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5796
RtkUpd.exe	: 2.7.1.2
AHPCEE32.d11	: 6.0.6001.17
RHCoInst.d11	: 1.0.4.4
RHDMIExt.d11	: 6.0.6000.69
RtkHDMI.d11	: 11.0.6000.88
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5796
RtkUpd64.exe	: 2.7.1.2
AHPCEE64.d11	: 6.0.6001.17
RHCoInst64.d11	: 1.0.4.4
RHDMEx64.d11	: 6.0.6000.69
RtkHDM64.d11	: 11.0.6000.88
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.5796
RtkUpd.exe	: 2.7.1.2
XP/2K x64:	
RtkHDMIX.sys	: 5.10.0.5796
RtkUpd64.exe	: 2.7.1.2
Driver Setup Program	: 2.72
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package - KB888111	
Package file version (kb888111.exe) : 6.1.22.0	
Hdaudiobus.sys version : 5.10.00.5013	

//=====

Driver Package R2.17

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262,

Readme.txt

ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista, Windows7
x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5794
RTKHDAUD.sys	: 5.10.0.5794
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.6.5
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.2
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.4.8
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.4.8
RtlCPAPI.d11	: 1.0.2.1

Vista driver : _____

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5794
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.306
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBppld32.d11	: 1.0.0.630

Readme.txt

MBWrp32.d11	: 1.0.0.80
RTCOMDLL.d11	: 2.0.0.106
RtkAPO.d11	: 11.0.6000.88
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.8
RtkPgExt.d11	: 6.0.6000.69
Rt1CPAPI.d11	: 1.0.2.1
RTPCEE32.d11	: 6.0.6001.17
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5794
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0
RAVCp164.exe	: 1.0.0.306
RtkAudioService64.exe	: 1.0.0.17
Rt1Upd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBpp1d64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.4.8
RtCOM64.d11	: 2.0.0.106
RTCOMDLL.d11	: 2.0.0.106
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.88
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.1
Rt1CPAPI64.d11	: 1.0.2.1
RTPCEE64.d11	: 6.0.6001.17
RtPgEx64.d11	: 6.0.6000.69
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0
sltshd64.d11	: 1.1.0.0

Readme.txt

sluapo64.d11 : 1.2.6.0
SRSHp64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :
Vista x86:
RtHDMIV.sys : 6.0.1.5766
RtkUpd.exe : 2.7.1.1
RHCoInst.d11 : 1.0.3.2
RHDMIExt.d11 : 6.0.6000.66
RtkHDMI.d11 : 11.0.6000.85

Vista x64:
RtHDMIVX.sys : 6.0.1.5766
RtkUpd64.exe : 2.7.1.1
RHCoInst64.d11 : 1.0.3.2
RHDMEx64.d11 : 6.0.6000.66
RtkHDM64.d11 : 11.0.6000.85

XP/2K x86:
RtkHDMI.sys : 5.10.0.5766
RtkUpd.exe : 2.7.1.1

XP/2K x64:
RtHDMIX.sys : 5.10.0.5766
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.70

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.16

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista, Windows7 x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Update directsound acceleration engine for XP driver.

Windows 2000/XP :

Windows 2000/XP :

Readme.txt

RTKHDA64.sys	: 5.10.0.5791
RTKHDAUD.sys	: 5.10.0.5791
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.6.3
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.2
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.4.8
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.4.8
RtlCPAPI.d11	: 1.0.2.1
<hr/>	
Vista driver :	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5791
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.304
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.15
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
FMAPO.d11	: 0.0.14.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBppld32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RTCOMDLL.d11	: 2.0.0.106
RtkAPO.d11	: 11.0.6000.88
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.8
RtkPgExt.d11	: 6.0.6000.69
RtlCPAPI.d11	: 1.0.2.1
RTPCEE32.d11	: 6.0.6001.17
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0

Readme.txt

s1h36032.d11	: 1.0.2.0
s1Init32.d11	: 1.1.1.0
s1tshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5791
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0
RAVCp164.exe	: 1.0.0.304
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.15
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
FMAPO64.d11	: 0.0.14.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBppld64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.4.8
RtCOM64.d11	: 2.0.0.106
RTCOMDLL.d11	: 2.0.0.106
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.88
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.1
Rt1CPAPI64.d11	: 1.0.2.1
RTPCEE64.d11	: 6.0.6001.17
RtPgEx64.d11	: 6.0.6000.69
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
s1h36064.d11	: 1.0.2.0
s1Init64.d11	: 1.1.1.0
s1tshd64.d11	: 1.1.0.0
sluapo64.d11	: 1.2.6.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5766
RtkUpd.exe	: 2.7.1.1
RHCoInst.d11	: 1.0.3.2
RHDMIExt.d11	: 6.0.6000.66

Readme.txt

RtkHDMI.d11 : 11.0.6000.85

Vista x64:
RtHDMIVX.sys : 6.0.1.5766
RtkUpd64.exe : 2.7.1.1
RHCoInst64.d11 : 1.0.3.2
RHDMEx64.d11 : 6.0.6000.66
RtkHDM64.d11 : 11.0.6000.85

XP/2K x86:
RtkHDMI.sys : 5.10.0.5766
RtkUpd.exe : 2.7.1.1

XP/2K x64:
RtHDMIX.sys : 5.10.0.5766
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.70

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.15

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Change Creative components for the certain customers.

2.) Package :

1. Change Japanese language on finish Dialog of installation .

2. Fix DCC uninstalled issue. Both MSI and GUID uninstillation

procedure supported .

3. Fix uninstall problem in Windows 7 . The DIFxAPI DLL file

supported in Windows 7 .

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5783

RTKHDAUD.sys : 5.10.0.5783

MicCal.exe : 1.1.2.0

RTHDCPL.exe : 2.2.6.2

RtkAudioService64.exe : 1.0.0.17

RtkAudioService.exe : 1.0.0.16

Readme.txt

RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.2
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
Monfilt.sys	: 5.10.0.4112
Monft64.sys	: 5.10.0.4115
AMBFilt.sys	: 5.10.0.4240
AMBft64.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.4.8
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.4.8
RtlCPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5783
AERTSrv.exe	: 1.0.32.8
APOPCH.exe	: 1.0.0.0
RtHDVCpl.exe	: 1.0.0.300
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.13
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
FMAPO.d11	: 0.0.12.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
MBAPO32.d11	: 1.0.0.630
MBPPCn32.d11	: 1.0.0.80
MBppld32.d11	: 1.0.0.630
MBWrp32.d11	: 1.0.0.80
RTCOMDLL.d11	: 2.0.0.106
RtkAPO.d11	: 11.0.6000.87
RtkApoApi.d11	: 1.0.0.10
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.8
RtkPgExt.d11	: 6.0.6000.67
RtlCPAPI.d11	: 1.0.2.1
RTPCEE32.d11	: 6.0.6001.14
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0

Readme.txt

SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5783
AERTSr64.exe	: 1.0.64.8
APOPCH.exe	: 1.0.0.0
RAVCp164.exe	: 1.0.0.300
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.2
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.13
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
FMAPO64.d11	: 0.0.12.1
MaxxAudioAPO20.d11	: 2.2.2.0
MBAPO32.d11	: 1.0.0.630
MBAPO64.d11	: 1.0.0.630
MBPPCn64.d11	: 1.0.0.80
MBppld64.d11	: 1.0.0.630
MBWrp64.d11	: 1.0.0.80
RCoInst64.d11	: 1.0.4.8
RtCOM64.d11	: 2.0.0.106
RTCOMDLL.d11	: 2.0.0.106
RtkApi64.d11	: 1.0.0.10
RtkAPO64.d11	: 11.0.6000.87
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.1
RtlCPAPI64.d11	: 1.0.2.1
RTPCEE64.d11	: 6.0.6001.14
RtPgEx64.d11	: 6.0.6000.67
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0
sltshd64.d11	: 1.1.0.0
sluapo64.d11	: 1.2.6.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5766
RtkUpd.exe	: 2.7.1.1
RHCoInst.d11	: 1.0.3.2
RHDMIExt.d11	: 6.0.6000.66
RtkHDMI.d11	: 11.0.6000.85
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5766
RtkUpd64.exe	: 2.7.1.1
RHCoInst64.d11	: 1.0.3.2

Readme.txt

RHDMEx64.d11 : 6.0.6000.66
RtkHDM64.d11 : 11.0.6000.85

XP/2K x86:
RtkHDMI.sys : 5.10.0.5766
RtkUpd.exe : 2.7.1.1

XP/2K x64:
RtHDMIX.sys : 5.10.0.5766
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.70

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.14

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272,
ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Change EAPD control method for the certain codecs.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5772
RTKHDAUD.sys : 5.10.0.5772
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.5.9
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.1
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.23
vncutil.exe : 1.0.0.23
AMBFilt64.sys : 5.10.0.4240
AMBFilt.sys : 5.10.0.4240
Monfilt64.sys : 5.10.0.4115

Readme.txt

Monfilt.sys	: 5.10.0.4112
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RCoInst64XP.d11	: 1.0.4.4
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.4.4
RtlCPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5772
AERTSrv.exe	: 1.0.32.8
RtHdVcpl.exe	: 1.0.0.291
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.13
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 0.0.12.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RTCOMDLL.d11	: 2.0.0.105
RtkAPO.d11	: 11.0.6000.85
RtkApoApi.d11	: 1.0.0.9
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.4
RtkPgExt.d11	: 6.0.6000.66
RtlCPAPI.d11	: 1.0.2.1
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5772
AERTSr64.exe	: 1.0.64.8
RAVCpl64.exe	: 1.0.0.291
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.13
AERTAC64.d11	: 2.0.64.1

Readme.txt

AERTAR64.d11	: 1.0.64.7
CTAPO32.d11	: 1.0.0.530
CTAPO64.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO64.d11	: 0.0.12.1
MaxxAudioAPO20.d11	: 2.2.2.0
ppchain.d11	: 1.0.0.70
RCoInst64.d11	: 1.0.4.4
RtCOM64.d11	: 2.0.0.105
RTCOMDLL.d11	: 2.0.0.105
RtkApi64.d11	: 1.0.0.9
RtkAPO64.d11	: 11.0.6000.85
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.1
Rt1CPAPI64.d11	: 1.0.2.1
RtPgEx64.d11	: 6.0.6000.66
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0
sltshd64.d11	: 1.1.0.0
sluapo64.d11	: 1.2.6.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5766
RtkUpd.exe	: 2.7.1.1
RHCoInst.d11	: 1.0.3.2
RHDMIExt.d11	: 6.0.6000.66
RtkHDMI.d11	: 11.0.6000.85
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5766
RtkUpd64.exe	: 2.7.1.1
RHCoInst64.d11	: 1.0.3.2
RHDMEx64.d11	: 6.0.6000.66
RtkHDM64.d11	: 11.0.6000.85
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.5766
RtkUpd.exe	: 2.7.1.1
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5766
RtkUpd64.exe	: 2.7.1.1
Driver Setup Program	: 2.69
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package – KB888111	
Package file version (kb888111.exe) :	6.1.22.0

Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.13

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : -----

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5767
RTKHDAUD.sys	: 5.10.0.5767
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.5.8
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
Monfilt64.sys	: 5.10.0.4115
Monfilt.sys	: 5.10.0.4112
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.4.3
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.4.3
RtlCPAPI.d11	: 1.0.1.9

Vista driver : -----

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5767
AERTSrv.exe	: 1.0.32.8
RtHDVCpl.exe	: 1.0.0.288
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.13

Readme.txt

AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 0.0.12.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RTCOMDLL.d11	: 2.0.0.105
RtkAPO.d11	: 11.0.6000.85
RtkApoApi.d11	: 1.0.0.9
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.3
RtkPgExt.d11	: 6.0.6000.66
RtlCPAPI.d11	: 1.0.2.1
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5767
AERTSr64.exe	: 1.0.64.8
RAVCp164.exe	: 1.0.0.288
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.13
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
CTAPO32.d11	: 1.0.0.530
CTAPO64.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO64.d11	: 0.0.12.1
MaxxAudioAPO20.d11	: 2.2.2.0
ppchain.d11	: 1.0.0.70
RCoInst64.d11	: 1.0.4.3
RtCOM64.d11	: 2.0.0.105
RTCOMDLL.d11	: 2.0.0.105
RtkApi64.d11	: 1.0.0.9
RtkAPO64.d11	: 11.0.6000.85
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.1
RtlCPAPI64.d11	: 1.0.2.1

Readme.txt

RtPgEx64.d11	: 6.0.6000.66
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0
sltshd64.d11	: 1.1.0.0
sluapo64.d11	: 1.2.6.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
HDMI Driver : -----	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5766
RtkUpd.exe	: 2.7.1.1
RHCoInst.d11	: 1.0.3.2
RHDMIExt.d11	: 6.0.6000.66
RtkHDMI.d11	: 11.0.6000.85
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5766
RtkUpd64.exe	: 2.7.1.1
RHCoInst64.d11	: 1.0.3.2
RHDMEx64.d11	: 6.0.6000.66
RtkHDM64.d11	: 11.0.6000.85
XP/2K x86:	
RtkHDMI.sys	: 5.10.0.5766
RtkUpd.exe	: 2.7.1.1
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5766
RtkUpd64.exe	: 2.7.1.1
Driver Setup Program	: 2.69
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package – KB888111	
Package file version (kb888111.exe) : 6.1.22.0	
Hdaudio.sys version : 5.10.00.5013	

//=====

Driver Package R2.12

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

Readme.txt

1. Customizations.
2. Support encryption feature for ALC670.

Windows 2000/XP :	-----
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5764
RTKHDAUD.sys	: 5.10.0.5764
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.5.6
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.23
vncutil.exe	: 1.0.0.23
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
Monfilt64.sys	: 5.10.0.4115
Monfilt.sys	: 5.10.0.4112
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RCoInst64XP.d11	: 1.0.4.3
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.4.3
RtlCPAPI.d11	: 1.0.1.9
Vista driver :	-----
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5764
AERTSrv.exe	: 1.0.32.8
RtHDVCpl.exe	: 1.0.0.286
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.13
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 0.0.12.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RTCOMDLL.d11	: 2.0.0.105
RtkAPO.d11	: 11.0.6000.85
RtkApoApi.d11	: 1.0.0.9
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.3

Readme.txt

RtkPgExt.d11	: 6.0.6000.66
Rt1CPAPI.d11	: 1.0.2.1
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5764
AERTSr64.exe	: 1.0.64.8
RAVCp164.exe	: 1.0.0.286
RtkAudioService64.exe	: 1.0.0.17
Rt1Upd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.13
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
CTAPO32.d11	: 1.0.0.530
CTAPO64.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO64.d11	: 0.0.12.1
MaxxAudioAPO20.d11	: 2.2.2.0
ppchain.d11	: 1.0.0.70
RCoInst64.d11	: 1.0.4.3
RtCOM64.d11	: 2.0.0.105
RTCOMDLL.d11	: 2.0.0.105
RtkApi64.d11	: 1.0.0.9
RtkAPO64.d11	: 11.0.6000.85
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
Rt1CPAPI.d11	: 1.0.2.1
Rt1CPAPI64.d11	: 1.0.2.1
RtPgEx64.d11	: 6.0.6000.66
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0
sltshd64.d11	: 1.1.0.0
sluapo64.d11	: 1.2.6.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5735
RtkUpd.exe	: 2.7.1.1

Readme.txt

RHCoInst.d11 : 1.0.3.2
RHDMIExt.d11 : 6.0.6000.64
RtkHDMI.d11 : 11.0.6000.80

Vista x64:

RtHDMIVX.sys : 6.0.1.5735
RtkUpd64.exe : 2.7.1.1
RHCoInst64.d11 : 1.0.3.2
RHDMEx64.d11 : 6.0.6000.64
RtkHDM64.d11 : 11.0.6000.80

XP/2K x86:

RtHDMI.sys : 5.10.0.5735
RtkUpd.exe : 2.7.1.1

XP/2K x64:

RtHDMIX.sys : 5.10.0.5735
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.11

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272,
ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Add DisplayVersion registry key in INF files.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5755
RTKHDAUD.sys : 5.10.0.5755
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.5.5
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCP.exe : 1.0.1.66

Readme.txt

RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.22
vncutil.exe	: 1.0.0.22
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
Monfilt64.sys	: 5.10.0.4115
Monfilt.sys	: 5.10.0.4112
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RCoInst64XP.d11	: 1.0.4.1
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.4.1
RtlCPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5755
AERTSrv.exe	: 1.0.32.8
RtHdVCpl.exe	: 1.0.0.281
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.23
RTSndMgr.cpl	: 1.0.0.13
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 0.0.12.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RTCOMDLL.d11	: 2.0.0.103
RtkAPO.d11	: 11.0.6000.81
RtkApoApi.d11	: 1.0.0.9
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.1
RtkPgExt.d11	: 6.0.6000.65
RtlCPAPI.d11	: 1.0.2.1
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5755

Readme.txt

AERTSr64.exe	: 1.0.64.8
RAVCp164.exe	: 1.0.0.281
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.23
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.13
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
CTAPO32.d11	: 1.0.0.530
CTAPO64.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO64.d11	: 0.0.12.1
MaxxAudioAPO20.d11	: 2.2.2.0
ppchain.d11	: 1.0.0.70
RCoInst64.d11	: 1.0.4.1
RtCOM64.d11	: 2.0.0.103
RTCOMDLL.d11	: 2.0.0.103
RtkApi64.d11	: 1.0.0.9
RtkAPO64.d11	: 11.0.6000.81
RtkCfg.d11	: 1.0.0.1
RtkCfg64.d11	: 1.0.0.1
RtlCPAPI.d11	: 1.0.2.1
RtlCPAPI64.d11	: 1.0.2.1
RtPgEx64.d11	: 6.0.6000.65
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0
sltshd64.d11	: 1.1.0.0
sluapo64.d11	: 1.2.6.0
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5735
RtkUpd.exe	: 2.7.1.1
RHCoInst.d11	: 1.0.3.2
RHDMIExt.d11	: 6.0.6000.64
RtkHDMI.d11	: 11.0.6000.80
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5735
RtkUpd64.exe	: 2.7.1.1
RHCoInst64.d11	: 1.0.3.2
RHDMEx64.d11	: 6.0.6000.64
RtkHDM64.d11	: 11.0.6000.80
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5735
RtkUpd.exe	: 2.7.1.1

Readme.txt

XP/2K x64:
RtHDMIX.sys : 5.10.0.5735
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.10

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC665, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272,
ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC665, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Support ALC665.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5745
RTKHDAUD.sys : 5.10.0.5745
MicCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.5.2
RtkAudioService64.exe : 1.0.0.17
RtkAudioService.exe : 1.0.0.16
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.1
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
vncutil64.exe : 1.0.0.22
vncutil.exe : 1.0.0.22
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
AMBFilt64.sys : 5.10.0.4240
AMBFilt.sys : 5.10.0.4240
Monfilt64.sys : 5.10.0.4115
Monfilt.sys : 5.10.0.4112
RTSndMgr.cpl : 1.0.1.0
ALSndMgr.cpl : 1.0.0.11
RCoInst64XP.d11 : 1.0.4.1
RTCOMDLL.d11 : 1.0.0.97

Readme.txt

RtkCoInstXP.d11	: 1.0.4.1
RtlCPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5745
AERTSrv.exe	: 1.0.32.8
RtHDVCpl.exe	: 1.0.0.273
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil.exe	: 1.0.0.22
RTSndMgr.cpl	: 1.0.0.13
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 0.0.12.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RCoInst64.d11	: 1.0.4.0
RTCOMDLL.d11	: 2.0.0.103
RtkAPO.d11	: 11.0.6000.81
RtkApoApi.d11	: 1.0.0.9
RtkCfg.d11	: 1.0.0.1
RtkCoInst.d11	: 1.0.4.1
RtkPgExt.d11	: 6.0.6000.65
RtlCPAPI.d11	: 1.0.2.1
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5745
AERTSr64.exe	: 1.0.64.8
RAVCpl64.exe	: 1.0.0.273
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.2
vncutil64.exe	: 1.0.0.22
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.13
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
CTAPO32.d11	: 1.0.0.530
CTAPO64.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530

Readme.txt

DaisyWrp.d11 : 1.0.0.70
FMAPO64.d11 : 0.0.12.1
MaxxAudioAPO20.d11 : 2.2.2.0
ppchain.d11 : 1.0.0.70
RCoInst64.d11 : 1.0.4.1
RtCOM64.d11 : 2.0.0.103
RTCOMDLL.d11 : 2.0.0.103
RtkApi64.d11 : 1.0.0.9
RtkAPO64.d11 : 11.0.6000.81
RtkCfg.d11 : 1.0.0.1
RtkCfg64.d11 : 1.0.0.1
RtkCoInst.d11 : 1.0.4.0
Rt1CPAPI.d11 : 1.0.2.1
Rt1CPAPI64.d11 : 1.0.2.1
RtPgEx64.d11 : 6.0.6000.65
slcshp64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slInit64.d11 : 1.1.1.0
sltshd64.d11 : 1.1.0.0
sluapo64.d11 : 1.2.6.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :
Vista x86:
RtHDMIV.sys : 6.0.1.5735
RtkUpd.exe : 2.7.1.1
RHCoInst.d11 : 1.0.3.2
RHDMIExt.d11 : 6.0.6000.64
RtkHDMI.d11 : 11.0.6000.80

Vista x64:
RtHDMIVX.sys : 6.0.1.5735
RtkUpd64.exe : 2.7.1.1
RHCoInst64.d11 : 1.0.3.2
RHDMEx64.d11 : 6.0.6000.64
RtkHDM64.d11 : 11.0.6000.80

XP/2K x86:
RtHDMI.sys : 5.10.0.5735
RtkUpd.exe : 2.7.1.1
XP/2K x64:
RtHDMIX.sys : 5.10.0.5735
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.69

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Readme.txt

Driver Package R2.09

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5735
RTKHDAUD.sys	: 5.10.0.5735
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.5.1
RtkAudioService.exe	: 1.0.0.16
RtkAudioService64.exe	: 1.0.0.17
RTLCPPL.exe	: 1.0.1.66
RtlUpd.exe	: 2.7.1.1
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil.exe	: 1.0.0.22
vncutil64.exe	: 1.0.0.22
AMBFilt.sys	: 5.10.0.4240
AMBFilt64.sys	: 5.10.0.4240
Monfilt.sys	: 5.10.0.4112
Monfilt64.sys	: 5.10.0.4115
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RCoInst64XP.d11	: 1.0.3.9
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.3.9
RtlCPAPI.d11	: 1.0.1.9

Vista driver : _____

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5735
AERTSrv.exe	: 1.0.32.8
RtHDVCpl.exe	: 1.0.0.264
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.22
RTSndMgr.cpl	: 1.0.0.13
AERTACap.d11	: 2.0.32.1

Readme.txt

AERTARen.d11	: 1.0.32.7
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 0.0.12.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.2.2.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RTCOMDLL.d11	: 2.0.0.100
RtkAPO.d11	: 11.0.6000.80
RtkApoApi.d11	: 1.0.0.8
RtkCoInst.d11	: 1.0.3.9
RtkPgExt.d11	: 6.0.6000.64
Rt1CPAPI.d11	: 1.0.1.9
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5735
AERTSr64.exe	: 1.0.64.8
RAVCp164.exe	: 1.0.0.264
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil64.exe	: 1.0.0.22
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.13
AERTAC64.d11	: 2.0.64.1
AERTAR64.d11	: 1.0.64.7
CTAPO32.d11	: 1.0.0.530
CTAPO64.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO64.d11	: 0.0.12.1
MaxxAudioAPO20.d11	: 2.2.2.0
ppchain.d11	: 1.0.0.70
RCoInst64.d11	: 1.0.3.9
RtCOM64.d11	: 2.0.0.100
RTCOMDLL.d11	: 2.0.0.100
RtkApi64.d11	: 1.0.0.8
RtkAPO64.d11	: 11.0.6000.80
Rt1CPAPI.d11	: 1.0.1.9
RtPgEx64.d11	: 6.0.6000.64
slcshp64.d11	: 1.0.3.0
slgeq64.d11	: 1.0.1.0
slh36064.d11	: 1.0.2.0
slInit64.d11	: 1.1.1.0

Readme.txt

sltshd64.d11 : 1.1.0.0
sluapo64.d11 : 1.2.6.0
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver : -----
Vista x86:
RtHDMIV.sys : 6.0.1.5735
RtkUpd.exe : 2.7.1.1
RHCoInst.d11 : 1.0.3.2
RHDMIExt.d11 : 6.0.6000.64
RtkHDMI.d11 : 11.0.6000.80

Vista x64:
RtHDMIVX.sys : 6.0.1.5735
RtkUpd64.exe : 2.7.1.1
RHCoInst64.d11 : 1.0.3.2
RHDMEx64.d11 : 6.0.6000.64
RtkHDM64.d11 : 11.0.6000.80

XP/2K x86:
RtHDMI.sys : 5.10.0.5735
RtkUpd.exe : 2.7.1.1
XP/2K x64:
RtHDMIX.sys : 5.10.0.5735
RtkUpd64.exe : 2.7.1.1

Driver Setup Program : 2.67

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.08

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Support Andrea microphone effect mixer type GUI.

2.) Package:

1. Change setup program install location to meet the requirements of

OEM Ready Certification Tool 1.1.0.1101

Readme.txt

Windows 2000/XP :	
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5730
RTKHDAUD.sys	: 5.10.0.5730
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.4.9
RtkAudioService64.exe	: 1.0.0.17
RtkAudioService.exe	: 1.0.0.16
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
vncutil64.exe	: 1.0.0.22
vncutil.exe	: 1.0.0.22
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
Monfilt64.sys	: 5.10.0.4115
Monfilt.sys	: 5.10.0.4112
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RCoInst64XP.d11	: 1.0.3.8
RTCOMDLL.d11	: 1.0.0.97
RtkCoInstXP.d11	: 1.0.3.8
RtlCPAPI.d11	: 1.0.1.9

Vista driver :	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5730
AERTSrv.exe	: 1.0.32.8
RtHDVCpl.exe	: 1.0.0.257
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.22
RTSndMgr.cpl	: 1.0.0.10
AERTACap.d11	: 2.0.32.1
AERTARen.d11	: 1.0.32.7
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 0.0.12.1
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RTCOMDLL.d11	: 2.0.0.100
RtkAPO.d11	: 11.0.6000.79
RtkApoApi.d11	: 1.0.0.8
RtkCoInst.d11	: 1.0.3.8
RtkPgExt.d11	: 6.0.6000.64
RtlCPAPI.d11	: 1.0.1.9

Readme.txt

slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.1.0
sltshd32.dll	: 1.1.0.0
sluapo32.dll	: 1.2.6.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5730
AERTSr64.exe	: 1.0.64.8
RAVCp164.exe	: 1.0.0.257
RtkAudioService64.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil64.exe	: 1.0.0.22
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.10
AERTAC64.dll	: 2.0.64.1
AERTAR64.dll	: 1.0.64.7
CTAPO32.dll	: 1.0.0.530
CTAPO64.dll	: 1.0.0.530
ctppld.dll	: 1.0.0.530
DaisyWrp.dll	: 1.0.0.70
FMAPO64.dll	: 0.0.12.1
MaxxAudioAPO20.dll	: 2.0.12.0
ppchain.dll	: 1.0.0.70
RCoInst64.dll	: 1.0.3.8
RtCOM64.dll	: 2.0.0.100
RTCOMDLL.dll	: 2.0.0.100
RtkApi64.dll	: 1.0.0.8
RtkAPO64.dll	: 11.0.6000.79
RtlCPAPI.dll	: 1.0.1.9
RtPgEx64.dll	: 6.0.6000.64
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.1.0
sltshd64.dll	: 1.1.0.0
sluapo64.dll	: 1.2.6.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5692
RtkUpd.exe	: 2.7.1.0
RHCoInst.dll	: 1.0.3.2
RHDMIExt.dll	: 6.0.6000.54
RtkHDMI.dll	: 11.0.6000.72
Vista x64:	

Readme.txt

RtHDMIVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.d11 : 1.0.3.2
RHDMEx64.d11 : 6.0.6000.54
RtkHDM64.d11 : 11.0.6000.72

XP/2K x86:
RtHDMI.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMIX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.67

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.07

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273,
ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5717
RTKHDAUD.sys : 5.10.0.5717
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.2.0
RTHDCPL.exe : 2.2.4.8
RTLCPPL.exe : 1.0.1.66
RtlUpd.exe : 2.7.1.1
RtlUpd64.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
AMBFilt.sys : 5.10.0.4240
AMBFilt64.sys : 5.10.0.4240
Monfilt.sys : 5.10.0.4112
Monfilt64.sys : 5.10.0.4115
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0

Readme.txt

RTCOMDLL.d11	: 1.0.0.97
Rt1CPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5717
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.251
RtkAudioService.exe	: 1.0.0.17
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.22
RTSndMgr.cpl	: 1.0.0.10
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RTCOMDLL.d11	: 2.0.0.100
RtkAPO.d11	: 11.0.6000.78
RtkApoApi.d11	: 1.0.0.6
RtkCoInst.d11	: 1.0.3.7
RtkPgExt.d11	: 6.0.6000.61
Rt1CPAPI.d11	: 1.0.1.9
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5717
AERTSr64.exe	: 1.0.64.7
RAVCpl64.exe	: 1.0.0.251
RtkAudioService.exe	: 1.0.0.17
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.22
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.10
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
CTAPO32.d11	: 1.0.0.530
CTAPO64.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO64.d11	: 40.59.0.0

Readme.txt

MaxxAudioAPO20.d11 : 2.0.12.0
ppchain.d11 : 1.0.0.70
RCoInst64.d11 : 1.0.3.7
RtCOM64.d11 : 2.0.0.100
RTCOMDLL.d11 : 2.0.0.100
RtkApi64.d11 : 1.0.0.6
RtkAPO64.d11 : 11.0.6000.78
Rt1CPAPI.d11 : 1.0.1.9
RtPgEx64.d11 : 6.0.6000.61
slcshp64.d11 : 1.0.3.0
slgeq64.d11 : 1.0.1.0
slh36064.d11 : 1.0.2.0
slInit64.d11 : 1.1.1.0
sltshd64.d11 : 1.1.0.0
sluapo64.d11 : 1.2.6.0
SRSHp64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :
Vista x86:
RtHDMIV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.d11 : 1.0.3.2
RHDMIExt.d11 : 6.0.6000.54
RtkHDMI.d11 : 11.0.6000.72

Vista x64:
RtHDMIVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.d11 : 1.0.3.2
RHDMEx64.d11 : 6.0.6000.54
RtkHDM64.d11 : 11.0.6000.72

XP/2K x86:
RtHDMI.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMIX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.06

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262,

Readme.txt

ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5713
RTKHDAUD.sys	: 5.10.0.5713
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.2.0
RTHDCPL.exe	: 2.2.4.6
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.1
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
Monfilt64.sys	: 5.10.0.4115
Monfilt.sys	: 5.10.0.4112
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.97
RtlCPAPI.dll	: 1.0.1.9

Vista driver : _____

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5713
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.248
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.22
RTSndMgr.cpl	: 1.0.0.10
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
CTAPO32.dll	: 1.0.0.530
ctppld.dll	: 1.0.0.530
DaisyWrp.dll	: 1.0.0.70
FMAPO.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
ppchain.dll	: 1.0.0.70
RTCOMDLL.dll	: 2.0.0.100
RtkAPO.dll	: 11.0.6000.77
RtkApoApi.dll	: 1.0.0.6
RtkCoInst.dll	: 1.0.3.6
RtkPgExt.dll	: 6.0.6000.61
RtlCPAPI.dll	: 1.0.1.9

Readme.txt

slcshp32.dll	: 1.0.3.0
slgeq32.dll	: 1.0.1.0
slh36032.dll	: 1.0.2.0
slInit32.dll	: 1.1.1.0
sltshd32.dll	: 1.1.0.0
sluapo32.dll	: 1.2.6.0
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5713
AERTSr64.exe	: 1.0.64.7
RAVCp164.exe	: 1.0.0.248
RtkAudioService.exe	: 1.0.0.16
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.22
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.10
AERTAC64.dll	: 1.0.64.7
AERTAR64.dll	: 1.0.64.3
CTAPO32.dll	: 1.0.0.530
CTAPO64.dll	: 1.0.0.530
ctppld.dll	: 1.0.0.530
DaisyWrp.dll	: 1.0.0.70
FMAPO64.dll	: 40.59.0.0
MaxxAudioAPO20.dll	: 2.0.12.0
ppchain.dll	: 1.0.0.70
RCoInst64.dll	: 1.0.3.6
RtCOM64.dll	: 2.0.0.100
RTCOMDLL.dll	: 2.0.0.100
RtkApi64.dll	: 1.0.0.6
RtkAPO64.dll	: 11.0.6000.77
RtlCPAPI.dll	: 1.0.1.9
RtPgEx64.dll	: 6.0.6000.61
slcshp64.dll	: 1.0.3.0
slgeq64.dll	: 1.0.1.0
slh36064.dll	: 1.0.2.0
slInit64.dll	: 1.1.1.0
sltshd64.dll	: 1.1.0.0
sluapo64.dll	: 1.2.6.0
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5692
RtkUpd.exe	: 2.7.1.0
RHCoInst.dll	: 1.0.3.2
RHDMIExt.dll	: 6.0.6000.54
RtkHDMI.dll	: 11.0.6000.72
Vista x64:	

Readme.txt

RtHDMIVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.d11 : 1.0.3.2
RHDMEx64.d11 : 6.0.6000.54
RtkHDM64.d11 : 11.0.6000.72

XP/2K x86:
RtHDMI.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMIX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.05

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273,
ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Meet Microsoft OEM Ready program requirements.

2.) Package :

1. Meet Microsoft OEM Ready program requirements.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5708
RTKHDAUD.sys : 5.10.0.5708
MicCal.exe : 1.1.1.9
RTHDCPL.exe : 2.2.4.5
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.1
RtlUpd.exe : 2.7.1.1
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
Monfilt64.sys : 5.10.0.4115
Monfilt.sys : 5.10.0.4112
AMBFilt64.sys : 5.10.0.4240

Readme.txt

AMBFilt.sys	: 5.10.0.4240
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RTCOMDLL.d11	: 1.0.0.97
RtlCPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5708
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.246
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.21
RTSndMgr.cpl	: 1.0.0.10
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
CTAPO32.d11	: 1.0.0.530
ctppld.d11	: 1.0.0.530
DaisyWrp.d11	: 1.0.0.70
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
ppchain.d11	: 1.0.0.70
RTCOMDLL.d11	: 2.0.0.100
RtkAPO.d11	: 11.0.6000.76
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.3.5
RtkPgExt.d11	: 6.0.6000.60
RtlCPAPI.d11	: 1.0.1.9
slcshp32.d11	: 1.0.3.0
slgeq32.d11	: 1.0.1.0
slh36032.d11	: 1.0.2.0
slInit32.d11	: 1.1.1.0
sltshd32.d11	: 1.1.0.0
sluapo32.d11	: 1.2.6.0
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5708
AERTSr64.exe	: 1.0.64.7
RAVCpl64.exe	: 1.0.0.246
RtkAudioService.exe	: 1.0.0.16
RtlUpd64.exe	: 2.7.1.1
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.21
GWfilt64.sys	: 6.10.0.3
RTSnMg64.cpl	: 1.0.0.10
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
CTAPO32.d11	: 1.0.0.530
CTAPO64.d11	: 1.0.0.530

Readme.txt

ctppld.dll : 1.0.0.530
DaisyWrp.dll : 1.0.0.70
FMAPO64.dll : 40.59.0.0
MaxxAudioAPO20.dll : 2.0.12.0
ppchain.dll : 1.0.0.70
RCoInst64.dll : 1.0.3.5
RtCOM64.dll : 2.0.0.100
RTCOMDLL.dll : 2.0.0.100
RtkApi64.dll : 1.0.0.4
RtkAPO64.dll : 11.0.6000.76
Rt1CPAPI.dll : 1.0.1.9
RtPgEx64.dll : 6.0.6000.60
slcshp64.dll : 1.0.3.0
slgeq64.dll : 1.0.1.0
slh36064.dll : 1.0.2.0
slInit64.dll : 1.1.1.0
sltshd64.dll : 1.1.0.0
sluapo64.dll : 1.2.6.0
SRSHP64.dll : 1.1.0.0
SRSTSH64.dll : 1.1.4.0
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0

HDMI Driver :
Vista x86:
RtHDMIV.sys : 6.0.1.5692
RtkUpd.exe : 2.7.1.0
RHCoInst.dll : 1.0.3.2
RHDMIExt.dll : 6.0.6000.54
RtkHDMI.dll : 11.0.6000.72

Vista x64:
RtHDMIVX.sys : 6.0.1.5692
RtkUpd64.exe : 2.7.1.0
RHCoInst64.dll : 1.0.3.2
RHDMEx64.dll : 6.0.6000.54
RtkHDM64.dll : 11.0.6000.72

XP/2K x86:
RtHDMI.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0

XP/2K x64:
RtHDMIX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.64

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R2.04

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273,

Readme.txt

ALC887

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273, ALC887

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Support ALC887.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys	: 5.10.0.5700
RTKHDAUD.sys	: 5.10.0.5700
Alcmtr.exe	: 1.6.0.3
AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.4.0
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.1.0
RtlUpd.exe	: 2.7.1.0
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.32
AMBFilt64.sys	: 5.10.0.4240
AMBFilt.sys	: 5.10.0.4240
Monfilt64.sys	: 5.10.0.4115
Monfilt.sys	: 5.10.0.4112
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.dll	: 1.0.0.97
RtlCPAPI.dll	: 1.0.1.9

Vista driver : _____

Vista driver for x86

RTKVHDA.sys	: 6.0.1.5700
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.240
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.1.0
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.21
RTSndMgr.cpl	: 1.0.0.9
AERTACap.dll	: 1.0.32.7
AERTARen.dll	: 1.0.32.3
CTAPO32.dll	: 1.0.0.520
ctppld.dll	: 1.0.0.510
DaisyWrp.dll	: 1.0.0.70
FMAPO.dll	: 40.59.0.0
MaxxAudioAPO.dll	: 1.2.2.0
MaxxAudioAPO20.dll	: 2.0.13.0
MaxxAudioEQ.dll	: 5.9.7.0
ppchain.dll	: 1.0.0.70
RTCOMDLL.dll	: 2.0.0.100
RtkAPO.dll	: 11.0.6000.74

Readme.txt

RtkApoApi.dll	: 1.0.0.4
RtkCoInst.dll	: 1.0.3.2
RtkPgExt.dll	: 6.0.6000.56
Rt1CPAPI.dll	: 1.0.1.9
SRSHP360.dll	: 1.1.0.0
SRSTSHD.dll	: 1.1.4.0
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
WavesLib.dll	: 5.9.7.0
Vista driver for x64	
GWfilt64.sys	: 6.10.0.3
RTKVHD64.sys	: 6.0.1.5700
AERTSr64.exe	: 1.0.64.7
RAVCp164.exe	: 1.0.0.240
RtkAudioService.exe	: 1.0.0.16
Rt1Upd64.exe	: 2.7.1.0
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.21
RTSnMg64.cpl	: 1.0.0.9
AERTAC64.dll	: 1.0.64.7
AERTAR64.dll	: 1.0.64.3
CTAPO32.dll	: 1.0.0.520
CTAPO64.dll	: 1.0.0.520
ctppld.dll	: 1.0.0.510
DaisyWrp.dll	: 1.0.0.70
FMAPO64.dll	: 40.59.0.0
MaxxAudioAPO20.dll	: 2.0.12.0
ppchain.dll	: 1.0.0.70
RCoInst64.dll	: 1.0.3.2
RtCOM64.dll	: 2.0.0.100
RTCOMDLL.dll	: 2.0.0.100
RtkApi64.dll	: 1.0.0.4
RtkAPO64.dll	: 11.0.6000.74
Rt1CPAPI.dll	: 1.0.1.9
RtPgEx64.dll	: 6.0.6000.56
SRSHP64.dll	: 1.1.0.0
SRSTSH64.dll	: 1.1.4.0
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
HDMI Driver : <hr/>	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5692
RtkUpd.exe	: 2.7.1.0
RHCoInst.dll	: 1.0.3.2
RHDMIExt.dll	: 6.0.6000.54
RtkHDMI.dll	: 11.0.6000.72
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5692
RtkUpd64.exe	: 2.7.1.0
RHCoInst64.dll	: 1.0.3.2
RHDMEx64.dll	: 6.0.6000.54
RtkHDM64.dll	: 11.0.6000.72
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5692

Readme.txt

RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMIX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.62

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.03

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5694
RTKHDAUD.sys : 5.10.0.5694
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.8
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.0
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.32
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9

Vista driver : _____

Vista driver for x86

RTKVHDA.sys : 6.0.1.5694
AERTSrv.exe : 1.0.32.7
RtHDVCpl.exe : 1.0.0.235
RtkAudioService.exe : 1.0.0.16
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.1
vncutil.exe : 1.0.0.21
RTSndMgr.cpl : 1.0.0.9
AERTACap.dll : 1.0.32.7

Readme.txt

AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.99
RtkAPO.d11	: 11.0.6000.72
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.3.2
RtkPgExt.d11	: 6.0.6000.54
Rt1CPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5694
AERTSr64.exe	: 1.0.64.7
RAVCp164.exe	: 1.0.0.235
RtkAudioService.exe	: 1.0.0.16
Rt1Upd64.exe	: 2.7.1.0
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.21
RTSnMg64.cpl	: 1.0.0.9
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0
RCoInst64.d11	: 1.0.3.2
RtCOM64.d11	: 2.0.0.99
RTCOMDLL.d11	: 2.0.0.99
RtkApi64.d11	: 1.0.0.4
RtkAPO64.d11	: 11.0.6000.72
Rt1CPAPI.d11	: 1.0.1.9
RtPgEx64.d11	: 6.0.6000.54
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
HDMI Driver :	<hr/>
Vista x86:	
RtHDMIV.sys	: 6.0.1.5692
RtkUpd.exe	: 2.7.1.0
RHCoInst.d11	: 1.0.3.2
RHDMIExt.d11	: 6.0.6000.54
RtkHDMI.d11	: 11.0.6000.72
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5692
RtkUpd64.exe	: 2.7.1.0
RHCoInst64.d11	: 1.0.3.2
RHDMEx64.d11	: 6.0.6000.54
RtkHDM64.d11	: 11.0.6000.72
XP/2K x86:	

Readme.txt

RtHDMI.sys : 5.10.0.5692
RtkUpd.exe : 2.7.1.0
XP/2K x64:
RtHDMIX.sys : 5.10.0.5692
RtkUpd64.exe : 2.7.1.0

Driver Setup Program : 2.62

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.02

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC272, ALC273

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Update ForteMedia microphone effect library.

2.) Package :

1. Delete driver file by Rtlupd.exe in Windows 2000/2003/XP System .
(Rtlupd.exe 2.7.1.0)

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5683
RTKHDAUD.sys : 5.10.0.5683
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.3
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.1.0
RtlUpd.exe : 2.7.1.0
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
ALSndMgr.cpl : 1.0.0.11
RTSndMgr.cpl : 1.0.1.0
RTCOMDLL.dll : 1.0.0.97
RtlCPAPI.dll : 1.0.1.9

Vista driver : _____

Vista driver for x86

RTKVHDA.sys : 6.0.1.5683
AERTSrv.exe : 1.0.32.7
RtHDVCpl.exe : 1.0.0.227

Readme.txt

RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.1.0
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.19
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.99
RtkAPO.d11	: 11.0.6000.71
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.3.2
RtkPgExt.d11	: 6.0.6000.53
RtlCPAPI.d11	: 1.0.1.9
SRSH360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5683
AERTSr64.exe	: 1.0.64.7
RAVCpl64.exe	: 1.0.0.227
RtkAudioService.exe	: 1.0.0.16
RtlUpd64.exe	: 2.7.1.0
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.19
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0
RCoInst64.d11	: 1.0.3.2
RtCOM64.d11	: 2.0.0.99
RTCOMDLL.d11	: 2.0.0.99
RtkApi64.d11	: 1.0.0.4
RtkAPO64.d11	: 11.0.6000.71
RtlCPAPI.d11	: 1.0.1.9
RtPgEx64.d11	: 6.0.6000.53
SRSH64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
HDMI Driver :	<hr/>
Vista x86:	
RtHDMIV.sys	: 6.0.1.5668
RtkUpd.exe	: 2.7.0.9
RHCoInst.d11	: 1.0.2.9
RHDMIExt.d11	: 6.0.6000.52
RtkHDMI.d11	: 11.0.6000.69
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5668

Readme.txt

RtkUpd64.exe : 2.7.0.9
RHCoInst64.d11 : 1.0.2.9
RHDMEx64.d11 : 6.0.6000.52
RtkHDM64.d11 : 11.0.6000.69

XP/2K x86:
RtHDMI.sys : 5.10.0.5668
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMIX.sys : 5.10.0.5668
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.62

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.01

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272, ALC273

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.
2. Support ALC273.

2.) Package :

1. Change warning message for upgrade driver .
2. ChCfg.exe add version and manifest embedded feature .
3. Add Manifest to Rtlupd.exe and HideWin.exe .
4. The SetCDFmt function was included by Rt1ExUpd.d11 Ver.1.0.1.1

Windows 2000/XP : _____

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5680
RTKHDAUD.sys : 5.10.0.5680
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.3
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
ALSndMgr.cpl : 1.0.0.11

Readme.txt

RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.d11	: 1.0.0.97
Rt1CPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5680
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.224
RtkAudioService.exe	: 1.0.0.16
Rt1Upd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.19
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.99
RtkAPO.d11	: 11.0.6000.71
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.3.2
RtkPgExt.d11	: 6.0.6000.53
Rt1CPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5680
AERTSr64.exe	: 1.0.64.7
RAVCpl64.exe	: 1.0.0.224
RtkAudioService.exe	: 1.0.0.16
Rt1Upd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.19
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0
RCoInst64.d11	: 1.0.3.2
RtCOM64.d11	: 2.0.0.99
RTCOMDLL.d11	: 2.0.0.99
RtkApi64.d11	: 1.0.0.4
RtkAPO64.d11	: 11.0.6000.71
Rt1CPAPI.d11	: 1.0.1.9
RtPgEx64.d11	: 6.0.6000.53
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
HDMI Driver : -----	
Vista x86:	

Readme.txt

RtHDMIV.sys : 6.0.1.5668
RtkUpd.exe : 2.7.0.9
RHCoInst.d11 : 1.0.2.9
RHDMIExt.d11 : 6.0.6000.52
RtkHDMI.d11 : 11.0.6000.69

Vista x64:
RtHDMIVX.sys : 6.0.1.5668
RtkUpd64.exe : 2.7.0.9
RHCoInst64.d11 : 1.0.2.9
RHDMEx64.d11 : 6.0.6000.52
RtkHDM64.d11 : 11.0.6000.69

XP/2K x86:
RtHDMI.sys : 5.10.0.5668
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMIX.sys : 5.10.0.5668
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.61

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R2.00

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC272

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5672
RTKHDAUD.sys : 5.10.0.5672
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.1
RTLCPLEX.exe : 1.0.1.66
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31

Readme.txt

ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.d11	: 1.0.0.97
Rt1CPAPI.d11	: 1.0.1.9
Vista driver : <hr/>	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5672
AERTSrv.exe	: 1.0.32.7
RtHDVCpl.exe	: 1.0.0.219
RtkAudioService.exe	: 1.0.0.16
Rt1Upd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.19
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.98
RtkAPO.d11	: 11.0.6000.70
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.3.1
RtkPgExt.d11	: 6.0.6000.53
Rt1CPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5672
AERTSr64.exe	: 1.0.64.7
RAVCpl64.exe	: 1.0.0.219
RtkAudioService.exe	: 1.0.0.16
Rt1Upd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.19
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0
RCoInst64.d11	: 1.0.3.1
RtCOM64.d11	: 2.0.0.98
RTCOMDLL.d11	: 2.0.0.98
RtkApi64.d11	: 1.0.0.4
RtkAPO64.d11	: 11.0.6000.70
Rt1CPAPI.d11	: 1.0.1.9
RtPgEx64.d11	: 6.0.6000.53
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
HDMI Driver : <hr/>	

Readme.txt

Vista x86:
RtHDMIV.sys : 6.0.1.5668
RtkUpd.exe : 2.7.0.9
RHCoInst.d11 : 1.0.2.9
RHDMIExt.d11 : 6.0.6000.52
RtkHDMI.d11 : 11.0.6000.69

Vista x64:
RtHDMIVX.sys : 6.0.1.5668
RtkUpd64.exe : 2.7.0.9
RHCoInst64.d11 : 1.0.2.9
RHDMEx64.d11 : 6.0.6000.52
RtkHDM64.d11 : 11.0.6000.69

XP/2K x86:
RtHDMI.sys : 5.10.0.5668
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMIX.sys : 5.10.0.5668
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.99

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
RTKHDA64.sys : 5.10.0.5667
RTKHDAUD.sys : 5.10.0.5667
MicCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.3.0
RTLCPPL.exe : 1.0.1.66
RtlUpd64.exe : 2.7.0.9
RtlUpd.exe : 2.7.0.9
SkyTel.exe : 2.0.2.0
SoundMan.exe : 1.0.0.31
Alcmtr.exe : 1.6.0.3

Readme.txt

AlcWzrd.exe	: 1.1.0.37
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.11
RTCOMDLL.d11	: 1.0.0.97
Rt1CPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5667
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.215
RtkAudioService.exe	: 1.0.0.16
Rt1Upd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.18
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.98
RtkAPO.d11	: 11.0.6000.69
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.3.1
RtkPgExt.d11	: 6.0.6000.52
Rt1CPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5667
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.215
RtkAudioService.exe	: 1.0.0.16
Rt1Upd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.18
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0
RCoInst64.d11	: 1.0.3.1
RtCOM64.d11	: 2.0.0.98
RTCOMDLL.d11	: 2.0.0.98
RtkApi64.d11	: 1.0.0.4
RtkAPO64.d11	: 11.0.6000.69
Rt1CPAPI.d11	: 1.0.1.9
RtPgEx64.d11	: 6.0.6000.52
SRSHP64.d11	: 1.1.0.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0

Readme.txt

HDMI Driver :

Vista x86:
RtHDMIV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.d11 : 1.0.2.9
RHDMIExt.d11 : 6.0.6000.50
RtkHDMI.d11 : 11.0.6000.67

Vista x64:
RtHDMIVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.d11 : 1.0.2.9
RHDMEx64.d11 : 6.0.6000.50
RtkHDM64.d11 : 11.0.6000.67

XP/2K x86:
RtHDMI.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMIX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.98

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix the potential risk that audio driver can't be installed completely under Vista.

Windows 2000/XP :

Windows 2000/XP :

RTKHDA64.sys : 5.10.0.5657
RTKHDAUD.sys : 5.10.0.5657
Alcmtr.exe : 1.6.0.3
AlcWzrd.exe : 1.1.0.37
MicCal.exe : 1.1.1.8
RTHDCPL.exe : 2.2.2.5
RTLCPPL.exe : 1.0.1.66

Readme.txt

RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.31
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.d11	: 1.0.0.97
RtlCPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5657
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.208
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.14
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.98
RtkAPO.d11	: 11.0.6000.69
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.2.10
RtkPgExt.d11	: 6.0.6000.52
RtlCPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5657
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.208
RtkAudioService.exe	: 1.0.0.16
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.14
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0
RCoInst64.d11	: 1.0.2.10
RtCOM64.d11	: 2.0.0.98
RTCOMDLL.d11	: 2.0.0.98
RtkApi64.d11	: 1.0.0.4
RtkAPO64.d11	: 11.0.6000.69
RtlCPAPI.d11	: 1.0.1.9
RtPgEx64.d11	: 6.0.6000.52
SRSHP64.d11	: 1.1.0.0

Readme.txt

SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :
Vista x86:
RtHDMIV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.d11 : 1.0.2.9
RHDMIExt.d11 : 6.0.6000.50
RtkHDMI.d11 : 11.0.6000.67

Vista x64:
RtHDMIVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.d11 : 1.0.2.9
RHDMEx64.d11 : 6.0.6000.50
RtkHDM64.d11 : 11.0.6000.67

XP/2K x86:
RtHDMI.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMIX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.97
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Add 24-bits recording feature.
 3. Fix EAX direct parameter issue under XP.
 4. Fix dummy noise issue under XP.

Readme.txt

AlcWzrd.exe	: 1.1.0.37
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.2.4
RTLCPPL.exe	: 1.0.1.66
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.31
ALSndMgr.cpl	: 1.0.0.11
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.d11	: 1.0.0.97
RtlCPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5653
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.206
RtkAudioService.exe	: 1.0.0.16
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.12
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.98
RtkAPO.d11	: 11.0.6000.67
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.2.10
RtkPgExt.d11	: 6.0.6000.50
RtlCPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5653
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.206
RtkAudioService.exe	: 1.0.0.16
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.1
vncutil.exe	: 1.0.0.12
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0
RCoInst64.d11	: 1.0.2.10
RtCOM64.d11	: 2.0.0.98
RTCOMDLL.d11	: 2.0.0.98
RtkApi64.d11	: 1.0.0.4

Readme.txt

RtkAPO64.d11 : 11.0.6000.67
Rt1CPAPI.d11 : 1.0.1.9
RtPgEx64.d11 : 6.0.6000.50
SRSH64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :

Vista x86:
RtHDMIV.sys : 6.0.1.5645
RtkUpd.exe : 2.7.0.9
RHCoInst.d11 : 1.0.2.9
RHDMIExt.d11 : 6.0.6000.50
RtkHDMI.d11 : 11.0.6000.67

Vista x64:
RtHDMIVX.sys : 6.0.1.5645
RtkUpd64.exe : 2.7.0.9
RHCoInst64.d11 : 1.0.2.9
RHDMEx64.d11 : 6.0.6000.50
RtkHDM64.d11 : 11.0.6000.67

XP/2K x86:
RtHDMI.sys : 5.10.0.5645
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDMIX.sys : 5.10.0.5645
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.96
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 - 2.) Package :
 1. Fix uninstalled message_2 problem (French language) .

Windows 2000/XP :

Readme.txt

Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5643
RTKHDAUD.sys	: 5.10.0.5643
Alcmtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.1.8
RTLCPPL.exe	: 1.0.1.65
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
ALSndMgr.cpl	: 1.0.0.10
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.d11	: 1.0.0.97
RtlCPAPI.d11	: 1.0.1.9
Vista driver : -----	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5643
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.198
RtkAudioService.exe	: 1.0.0.14
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
vncutil.exe	: 1.0.0.7
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.98
RtkAPO.d11	: 11.0.6000.67
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.2.6
RtkPgExt.d11	: 6.0.6000.49
RtlCPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5643
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.198
RtkAudioService.exe	: 1.0.0.14
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
vncutil.exe	: 1.0.0.7
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0

Readme.txt

RCoInst64.d11 : 1.0.2.6
RtCOM64.d11 : 2.0.0.98
RTCOMDLL.d11 : 2.0.0.98
RtkApi64.d11 : 1.0.0.4
RtkAPO64.d11 : 11.0.6000.67
Rt1CPAPI.d11 : 1.0.1.9
RtPgEx64.d11 : 6.0.6000.49
SRSH64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver : -----
Vista x86:
RtHDMIV.sys : 6.0.1.5633
RtkUpd.exe : 2.7.0.9
RHDMIExt.d11 : 6.0.6000.48
RtkHDMI.d11 : 11.0.6000.66

Vista x64:
RtHDMIVX.sys : 6.0.1.5633
RtkUpd64.exe : 2.7.0.9
RHDMEx64.d11 : 6.0.6000.48
RtkHDM64.d11 : 11.0.6000.66

XP/2K x86:
RtHDMI.sys : 5.10.0.5633
RtkUpd.exe : 2.7.0.9
XP/2K x64:
RtHDMIX.sys : 5.10.0.5633
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.60

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.95
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Fix encryption stream issue for ALC889.
 3. Fix DRM issue.

Readme.txt

Windows 2000/XP :	
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5636
RTKHDAUD.sys	: 5.10.0.5636
Alcmtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.1.6
RTLCPAPI.exe	: 1.0.1.65
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
ALSndMgr.cpl	: 1.0.0.10
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.d11	: 1.0.0.96
RtlCPAPI.d11	: 1.0.1.9
Vista driver :	
RTKVHDA.sys	: 6.0.1.5636
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.192
RtkAudioService.exe	: 1.0.0.12
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
vncutil.exe	: 1.0.0.5
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.98
RtkAPO.d11	: 11.0.6000.66
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.2.5
RtkPgExt.d11	: 6.0.6000.48
RtlCPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5636
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.192
RtkAudioService.exe	: 1.0.0.12
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
vncutil.exe	: 1.0.0.5
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0
MaxxAudioAPO20.d11	: 2.0.12.0

Readme.txt

RCoInst64.d11 : 1.0.2.5
RtCOM64.d11 : 2.0.0.98
RTCOMDLL.d11 : 2.0.0.98
RtkApi64.d11 : 1.0.0.4
RtkAPO64.d11 : 11.0.6000.66
Rt1CPAPI.d11 : 1.0.1.9
RtPgEx64.d11 : 6.0.6000.48
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver : -----
Vista x86:
RtHDMIV.sys : 6.0.1.5612
RtkUpd.exe : 2.7.0.9
RHDMIExt.d11 : 6.0.6000.44
RtkHDMI.d11 : 11.0.6000.63

Vista x64:
RtHDMIVX.sys : 6.0.1.5612
RtkUpd64.exe : 2.7.0.9
RHDMEx64.d11 : 6.0.6000.44
RtkHDM64.d11 : 11.0.6000.63

XP/2K x86:
RtHDMI.sys : 5.10.0.5612
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDMIX.sys : 5.10.0.5612
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.59

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.94
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 2. Zero recorded data for SPDIF-IN copy-protection stream under Vista.

Readme.txt

Windows 2000/XP :	
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5628
RTKHDAUD.sys	: 5.10.0.5628
Alcmtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.1.3
RTLCPPL.exe	: 1.0.1.65
RtlUpd.exe	: 2.7.0.9
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
ALSndMgr.cpl	: 1.0.0.10
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.d11	: 1.0.0.96
RtlCPAPI.d11	: 1.0.1.9
Vista driver :	
RTKVHDA.sys	: 6.0.1.5628
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.188
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSndMgr.cpl	: 1.0.0.8
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.97
RtkAPO.d11	: 11.0.6000.65
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.2.3
RtkPgExt.d11	: 6.0.6000.47
RtlCPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5628
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.188
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSnMg64.cpl	: 1.0.0.8
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 40.59.0.0

Readme.txt

MaxxAudioAPO20.d11 : 2.0.12.0
RCoInst64.d11 : 1.0.2.3
RtCOM64.d11 : 2.0.0.97
RTCOMDLL.d11 : 2.0.0.97
RtkApi64.d11 : 1.0.0.4
RtkAPO64.d11 : 11.0.6000.65
Rt1CPAPI.d11 : 1.0.1.9
RtPgEx64.d11 : 6.0.6000.47
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver : -----
Vista x86:
RtHDMIV.sys : 6.0.1.5612
RtkUpd.exe : 2.7.0.9
RHDMIExt.d11 : 6.0.6000.44
RtkHDMI.d11 : 11.0.6000.63

Vista x64:
RtHDMIVX.sys : 6.0.1.5612
RtkUpd64.exe : 2.7.0.9
RHDMEx64.d11 : 6.0.6000.44
RtkHDM64.d11 : 11.0.6000.63

XP/2K x86:
RtHDMI.sys : 5.10.0.5612
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDMIX.sys : 5.10.0.5612
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.59

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.93
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Customizations.
 - 2.) Package :
 1. Small VGA mode should not be checked in silent installation .

Readme.txt

Windows 2000/XP :	-----
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5624
RTKHDAUD.sys	: 5.10.0.5624
Alcmtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.1.1
RTLCPPL.exe	: 1.0.1.65
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
ALSndMgr.cpl	: 1.0.0.10
RTSndMgr.cpl	: 1.0.1.0
RTCOMDLL.d11	: 1.0.0.96
RtlCPAPI.d11	: 1.0.1.9
Vista driver :	-----
RTKVHDA.sys	: 6.0.1.5624
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.185
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSndMgr.cpl	: 1.0.0.7
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.59.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.97
RtkAPO.d11	: 11.0.6000.65
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.2.3
RtkPgExt.d11	: 6.0.6000.46
RtlCPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.1.0.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5624
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.185
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSnMg64.cpl	: 1.0.0.7
AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3

Readme.txt

FMAPO64.d11 : 40.59.0.0
MaxxAudioAPO20.d11 : 2.0.12.0
RCoInst64.d11 : 1.0.2.3
RtCOM64.d11 : 2.0.0.97
RTCOMDLL.d11 : 2.0.0.97
RtkApi64.d11 : 1.0.0.4
RtkAPO64.d11 : 11.0.6000.65
Rt1CPAPI.d11 : 1.0.1.9
RtPgEx64.d11 : 6.0.6000.46
SRSHP64.d11 : 1.1.0.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver : -----
Vista x86:
RtHDMIV.sys : 6.0.1.5612
RtkUpd.exe : 2.7.0.9
RHDMIExt.d11 : 6.0.6000.44
RtkHDMI.d11 : 11.0.6000.63

Vista x64:
RtHDMIVX.sys : 6.0.1.5612
RtkUpd64.exe : 2.7.0.9
RHDMEx64.d11 : 6.0.6000.44
RtkHDM64.d11 : 11.0.6000.63

XP/2K x86:
RtHDMI.sys : 5.10.0.5612
RtkUpd.exe : 2.7.0.9

XP/2K x64:
RtHDMIX.sys : 5.10.0.5612
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.59

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R1.92
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262,ALC267, ALC268, ALC269, ALC272
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262,
ALC267,ALC268, ALC269, ALC272
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Fix Stereo Mix issue with codec which support capless output pin.
2. Customizations.

Readme.txt

Windows 2000/XP :	
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5618
RTKHDAUD.sys	: 5.10.0.5618
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.1.0
RTLCPPL.exe	: 1.0.1.65
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
Alcmtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.10
RTCOMDLL.d11	: 1.0.0.96
RtlCPAPI.d11	: 1.0.1.9
Vista driver :	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5618
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.183
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSndMgr.cpl	: 1.0.0.7
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 40.58.0.0
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.13.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.97
RtkAPO.d11	: 11.0.6000.64
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.2.1
RtkPgExt.d11	: 6.0.6000.45
RtlCPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.0.1.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5618
AERTSr64.exe	: 1.0.64.2
RAVCpl64.exe	: 1.0.0.183
RtkAudioService.exe	: 1.0.0.12
RtkSmbus.exe	: 1.0.0.2
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSnMg64.cpl	: 1.0.0.7
AERTAC64.d11	: 1.0.64.7

Readme.txt

AERTAR64.d11 : 1.0.64.3
FMAPO64.d11 : 40.58.0.0
MaxxAudioAPO20.d11 : 2.0.12.0
RCoInst64.d11 : 1.0.2.1
RtCOM64.d11 : 2.0.0.97
RTCOMDLL.d11 : 2.0.0.97
RtkApi64.d11 : 1.0.0.4
RtkAPO64.d11 : 11.0.6000.64
Rt1CPAPI.d11 : 1.0.1.9
RtPgEx64.d11 : 6.0.6000.45
SRSHp64.d11 : 1.0.1.0
SRSTSH64.d11 : 1.1.4.0
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0

HDMI Driver :

Vista x86:

RtHDMIV.sys : 6.0.1.5612
RtkUpd.exe : 2.7.0.9
RHDMIExt.d11 : 6.0.6000.44
RtkHDMI.d11 : 11.0.6000.63

Vista x64:

RtHDMIVX.sys : 6.0.1.5612
RtkUpd64.exe : 2.7.0.9
RHDMEx64.d11 : 6.0.6000.44
RtkHDM64.d11 : 11.0.6000.63

XP/2K x86:

RtHDMI.sys : 5.10.0.5612
RtkUpd.exe : 2.7.0.9

XP/2K x64:

RtHDMIX.sys : 5.10.0.5612
RtkUpd64.exe : 2.7.0.9

Driver Setup Program : 2.58

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.91

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD,
ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262,
ALC267, ALC268, ALC269, ALC272

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Fix DTM 1.2 KS topology test fail issue.

2. Customizations.

Windows 2000/XP : <hr/>	
Windows 2000/XP :	
RTKHDA64.sys	: 5.10.0.5605
RTKHDAUD.sys	: 5.10.0.5605
MicCal.exe	: 1.1.1.8
RTHDCPL.exe	: 2.2.0.2
RTLCPPL.exe	: 1.0.1.65
RtlUpd64.exe	: 2.7.0.9
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
SoundMan.exe	: 1.0.0.30
Alcmtr.exe	: 1.6.0.2
AlcWzrd.exe	: 1.1.0.36
RTSndMgr.cpl	: 1.0.1.0
ALSndMgr.cpl	: 1.0.0.10
RTCOMDLL.d11	: 1.0.0.96
RtlCPAPI.d11	: 1.0.1.9
Vista driver : <hr/>	
Vista driver for x86	
RTKVHDA.sys	: 6.0.1.5605
AERTSrv.exe	: 1.0.32.2
RtHDVCpl.exe	: 1.0.0.172
RtkAudioService.exe	: 1.0.0.11
RtkSmbus.exe	: 1.0.0.1
RtlUpd.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSndMgr.cpl	: 1.0.0.7
AERTACap.d11	: 1.0.32.7
AERTARen.d11	: 1.0.32.3
FMAPO.d11	: 6.0.6000.16386
MaxxAudioAPO.d11	: 1.2.2.0
MaxxAudioAPO20.d11	: 2.0.12.0
MaxxAudioEQ.d11	: 5.9.7.0
RTCOMDLL.d11	: 2.0.0.96
RtkAPO.d11	: 11.0.6000.63
RtkApoApi.d11	: 1.0.0.4
RtkCoInst.d11	: 1.0.2.0
RtkPgExt.d11	: 6.0.6000.42
RtlCPAPI.d11	: 1.0.1.9
SRSHP360.d11	: 1.0.1.0
SRSTSHD.d11	: 1.1.4.0
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
WavesLib.d11	: 5.9.7.0
Vista driver for x64	
RTKVHD64.sys	: 6.0.1.5605
AERTSr64.exe	: 1.0.64.2
RAVCp164.exe	: 1.0.0.172
RtkAudioService.exe	: 1.0.0.11
RtkSmbus.exe	: 1.0.0.1
RtlUpd64.exe	: 2.7.0.9
SkyTel.exe	: 2.0.2.0
RTSnMg64.cpl	: 1.0.0.7

Readme.txt

AERTAC64.d11	: 1.0.64.7
AERTAR64.d11	: 1.0.64.3
FMAPO64.d11	: 6.0.6000.16386
MaxxAudioAPO20.d11	: 2.0.12.0
RCoInst64.d11	: 1.0.2.0
RtCOM64.d11	: 2.0.0.96
RTCOMDLL.d11	: 2.0.0.96
RtkApi64.d11	: 1.0.0.4
RtkAPO64.d11	: 11.0.6000.63
Rt1CPAPI.d11	: 1.0.1.9
RtPgEx64.d11	: 6.0.6000.42
SRSHP64.d11	: 1.0.1.0
SRSTSH64.d11	: 1.1.4.0
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
<hr/>	
HDMI Driver :	
Vista x86:	
RtHDMIV.sys	: 6.0.1.5602
RtkUpd.exe	: 2.7.0.9
RHDMIExt.d11	: 6.0.6000.42
RtkHDMI.d11	: 11.0.6000.62
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5602
RtkUpd64.exe	: 2.7.0.9
RHDMEx64.d11	: 6.0.6000.42
RtkHDM64.d11	: 11.0.6000.62
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5602
RtkUpd.exe	: 2.7.0.9
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5602
RtkUpd64.exe	: 2.7.0.9
Driver Setup Program	: 2.58

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.90

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC663, ALC260, ALC262, ALC267, ALC268, ALC269, ALC272

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

Readme.txt

1. Support ALC663/ALC272.
2. Support ForteMedia microphone effect APO feature.
3. Customizations.

Windows 2000/XP : -----	
Windows 2000/XP :	
WDM driver for Win2000/WinXP	: 5.10.0.5591
WDM driver for Winx64	: 5.10.0.5591
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl)	: 1.0.1.0
Realtek Sound Effect Manager (Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager (RTHDCPL)	: 2.1.9.6
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.2.0
Vista driver : -----	
Vista driver for x86	: 6.0.1.5591
RtHDVCpl.exe	: 1.0.0.159
RtkAPO.d11	: 11.0.6000.60
RtkPgExt.d11	: 6.0.6000.40
RTCOMDLL.d11	: 2.0.0.96
Rt1CPAPI.d11	: 1.0.1.8
RTSndMgr.cpl	: 1.0.0.7
RtkCoInst.d11	: 1.0.1.29
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
SRSHP360.d11	: 1.0.1.0
SRSTSHD.d11	: 1.1.4.0
RtkApoApi.d11	: 1.0.0.3
Vista driver for x64	: 6.0.1.5591
RAVCpl64.exe	: 1.0.0.159
RtkAPO64.d11	: 11.0.6000.60
RtPgEx64.d11	: 6.0.6000.40
RTCOMDLL.d11	: 2.0.0.96
Rt1CPAPI.d11	: 1.0.1.8
RTSnMg64.cpl	: 1.0.0.7
RCoInst64.d11	: 1.0.1.29
SRSTX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
SRSHP64.d11	: 1.0.1.0
SRSTSH64.d11	: 1.1.4.0
RtkApi64.d11	: 1.0.0.3
HDMI Driver : -----	
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5575
RtkHDM64.d11	: 6.0.6000.57
RHDMEx64.d11	: 6.0.6000.39
Vista x86:	
RtHDMIV.sys	: 6.0.1.5575
RtkHDMI.d11	: 6.0.6000.57
RHDMIExt.d11	: 6.0.6000.39
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5575
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5575

Readme.txt

Driver Setup Program : 2.57

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.89

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Support "Event/Notification mode" under Vista.

2. Fix Vista GUI issue when video adapter's resolution is low.

3. Customizations.

2.) Package :

1. Uninstallation language selected by OS system .

2. "Uninstall" word issue in Japanese language .

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5582

WDM driver for Winx64 : 5.10.0.5582

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.9.3

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.2.0

Vista driver : -----

Vista driver for x86 : 6.0.1.5582

RtHDVCpl.exe : 1.0.0.153

RtkAPO.dll : 11.0.6000.59

RtkPgExt.dll : 6.0.6000.40

RTCOMDLL.dll : 2.0.0.93

Rt1CPAPI.dll : 1.0.1.7

RTSndMgr.cpl : 1.0.0.7

RtkCoInst.dll : 1.0.1.27

SRSTSXT.dll : 3.2.0.0

SRSWOW.dll : 1.1.3.0

SRSHP360.dll : 1.0.1.0

SRSTSHD.dll : 1.1.4.0

RtkApoApi.dll : 1.0.0.3

Vista driver for x64 : 6.0.1.5582

RAVCp164.exe : 1.0.0.153

Readme.txt

RtkAPO64.d11 : 11.0.6000.59
RtPgEx64.d11 : 6.0.6000.40
RTCOMDLL.d11 : 2.0.0.93
Rt1CPAPI.d11 : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.d11 : 1.0.1.27
SRSTX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
SRSHP64.d11 : 1.0.1.0
SRSTSH64.d11 : 1.1.4.0
RtkApi64.d11 : 1.0.0.3

HDMI Driver :

Vista x64:
RtHDMIVX.sys : 6.0.1.5575
RtkHDM64.d11 : 6.0.6000.57
RHDMEx64.d11 : 6.0.6000.39

Vista x86:
RtHDMIV.sys : 6.0.1.5575
RtkHDMI.d11 : 6.0.6000.57
RHDMIExt.d11 : 6.0.6000.39

XP/2K x64:
RtHDMIX.sys : 5.10.0.5575

XP/2K x86:
RtHDMI.sys : 5.10.0.5575

Driver Setup Program : 2.56

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.88
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Fix BSOD issue for WLK 1.1 System–Common Scenario Stress With IO test and System–Disable Enable With IO test under XP.
 2. Customizations.

Readme.txt

Realtek Sound Effect Manager (RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager (RTHDCPL)	: 2.1.9.1
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.2.0
<hr/>	
Vista driver :	
Vista driver for x86	: 6.0.1.5574
RtHDVCpl.exe	: 1.0.0.145
RtkAPO.d11	: 11.0.6000.58
RtkPgExt.d11	: 6.0.6000.38
RTCOMDLL.d11	: 2.0.0.90
Rt1CPAPI.d11	: 1.0.1.7
RTSndMgr.cpl	: 1.0.0.7
RtkCoInst.d11	: 1.0.1.25
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
SRSHP360.d11	: 1.0.1.0
SRSTSHD.d11	: 1.1.4.0
RtkApoApi.d11	: 1.0.0.3
Vista driver for x64	: 6.0.1.5574
RAVCpl64.exe	: 1.0.0.145
RtkAPO64.d11	: 11.0.6000.58
RtPgEx64.d11	: 6.0.6000.38
RTCOMDLL.d11	: 2.0.0.90
Rt1CPAPI.d11	: 1.0.1.7
RTSnMg64.cpl	: 1.0.0.7
RCoInst64.d11	: 1.0.1.25
SRSTX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
SRSHP64.d11	: 1.0.1.0
SRSTSH64.d11	: 1.1.4.0
RtkApi64.d11	: 1.0.0.3
<hr/>	
HDMI Driver :	
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5413
RtkHDM64.d11	: 6.0.6000.37
RHDMEx64.d11	: 6.0.6000.25
Vista x86:	
RtHDMIV.sys	: 6.0.1.5413
RtkHDMI.d11	: 6.0.6000.37
RHDMIExt.d11	: 6.0.6000.25
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413
Driver Setup Program	: 2.55
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package – KB888111	
Package file version (kb888111.exe) :	6.1.22.0
Hdaudio.sys version :	5.10.00.5013
//=====	
Driver Package R1.87	
Realtek HD Audio Driver support all of Realtek HD Audio Codec in	
Vista/WinXP/Win2000/Win2003 .	

Readme.txt

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Fix recording issue for ALC269.
 2. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5567
WDM driver for Winx64 : 5.10.0.5567
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0

Vista driver : _____

Vista driver for x86 : 6.0.1.5567
RtHDVCpl.exe : 1.0.0.139
RtkAPO.dll : 11.0.6000.56
RtkPgExt.dll : 6.0.6000.35
RTCOMDLL.dll : 2.0.0.89
Rt1CPAPI.dll : 1.0.1.7
RTSndMgr.cpl : 1.0.0.7
RtkCoInst.dll : 1.0.1.25
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSH360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.3
Vista driver for x64 : 6.0.1.5567
RAVCpl64.exe : 1.0.0.139
RtkAPO64.dll : 11.0.6000.56
RtPgEx64.dll : 6.0.6000.35
RTCOMDLL.dll : 2.0.0.89
Rt1CPAPI.dll : 1.0.1.7
RTSnMg64.cpl : 1.0.0.7
RCoInst64.dll : 1.0.1.25
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSH64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.3

HDMI Driver : _____

Vista x64:
RtHDMIVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37

Readme.txt

RHDMEx64.d11 : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.d11 : 6.0.6000.37
RHDMIEExt.d11 : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.54

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.86

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC889, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Fix the issue that SPDIF-out device broadcast 2nd output device's stream when turn on multi-streaming under Windows XP.
 2. Indexed DRC file supported.
 3. Customizations.
 - 2.) Package :
 1. Installer failed code.
 2. Copy .dat file rule.

Windows 2000/XP : _____

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5559
WDM driver for Winx64 : 5.10.0.5559
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.7
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0

Vista driver : _____

Vista driver for x86 : 6.0.1.5559
RtHDVCpl.exe : 1.0.0.132
RtkAPO.d11 : 11.0.6000.54
RtkPgExt.d11 : 6.0.6000.35
RTCOMDLL.d11 : 2.0.0.87

Readme.txt

Rt1CPAPI.d11	: 1.0.1.7
RTSndMgr.cpl	: 1.0.0.7
RtkCoInst.d11	: 1.0.1.25
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
SRSHP360.d11	: 1.0.1.0
SRSTSHD.d11	: 1.1.4.0
RtkApoApi.d11	: 1.0.0.3
Vista driver for x64	: 6.0.1.5559
RAVCp164.exe	: 1.0.0.132
RtkAPO64.d11	: 11.0.6000.54
RtPgEx64.d11	: 6.0.6000.35
RTCOMDLL.d11	: 2.0.0.87
Rt1CPAPI.d11	: 1.0.1.7
RTSnMg64.cpl	: 1.0.0.7
RCoInst64.d11	: 1.0.1.25
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
SRSHP64.d11	: 1.0.1.0
SRSTSH64.d11	: 1.1.4.0
RtkApi64.d11	: 1.0.0.3
<hr/>	
HDMI Driver :	
Vista x64:	
RtHDMI.VX.sys	: 6.0.1.5413
RtkHDM64.d11	: 6.0.6000.37
RHDMEx64.d11	: 6.0.6000.25
Vista x86:	
RtHDMI.V.sys	: 6.0.1.5413
RtkHDMI.d11	: 6.0.6000.37
RHDMIExt.d11	: 6.0.6000.25
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413
Driver Setup Program	: 2.52

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.85

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Fix PC-Beep mute issue for ALC268/ALC267.

2. Fix the potential risk that system-thread is still running when

driver is already unloaded under Vista.

3. Customizations.

Windows 2000/XP : <hr/>	
Windows 2000/XP :	
WDM driver for Win2000/WinXP	: 5.10.0.5548
WDM driver for Winx64	: 5.10.0.5548
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager (RTHDCPL)	: 2.1.8.6
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.2.0
Vista driver : <hr/>	
Vista driver for x86	: 6.0.1.5548
RtHdVcpl.exe	: 1.0.0.128
RtkAPO.dll	: 11.0.6000.51
RtkPgExt.dll	: 6.0.6000.33
RTCOMDLL.dll	: 2.0.0.86
Rt1CPAPI.dll	: 1.0.1.7
RTSndMgr.cpl	: 1.0.0.7
RtkCoInst.dll	: 1.0.1.25
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.3
Vista driver for x64	: 6.0.1.5548
RAVCpl64.exe	: 1.0.0.128
RtkAPO64.dll	: 11.0.6000.51
RtPgEx64.dll	: 6.0.6000.33
RTCOMDLL.dll	: 2.0.0.86
Rt1CPAPI.dll	: 1.0.1.7
RTSnMg64.cpl	: 1.0.0.7
RCoInst64.dll	: 1.0.1.25
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.3
HDMI Driver : <hr/>	
Vista x64:	
RtHDMIvX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25
Vista x86:	
RtHDMIv.sys	: 6.0.1.5413
RtkHDMI.dll	: 6.0.6000.37
RHDMIExt.dll	: 6.0.6000.25
XP/2K x64:	
RtHDMIx.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413

Driver Setup Program : 2.51

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.84

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Fix potential risk for re-direct headphone mode under Vista.

2. Customizations.

Windows 2000/XP : _____

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5532

WDM driver for Winx64 : 5.10.0.5532

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cp1) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.8.2

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.2.0

Vista driver : _____

Vista driver for x86 : 6.0.1.5532

RtHDVCpl.exe : 1.0.0.116

RtkAPO.dll : 11.0.6000.48

RtkPgExt.dll : 6.0.6000.31

RTCOMDLL.dll : 2.0.0.86

Rt1CPAPI.dll : 1.0.1.6

RTSndMgr.cpl : 1.0.0.7

RtkCoInst.dll : 1.0.1.18

SRSTSXT.dll : 3.2.0.0

SRSWOW.dll : 1.1.3.0

SRSHP360.dll : 1.0.1.0

SRSTSHD.dll : 1.1.4.0

RtkApoApi.dll : 1.0.0.2

Vista driver for x64 : 6.0.1.5532

RAVCpl64.exe : 1.0.0.116

RtkAPO64.dll : 11.0.6000.48

RtPgEx64.dll : 6.0.6000.31

RTCOMDLL.dll : 2.0.0.86

Rt1CPAPI.dll : 1.0.1.6

RTSnMg64.cpl : 1.0.0.7

RCoInst64.dll : 1.0.1.18

Readme.txt

SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
SRSH64.d11 : 1.0.1.0
SRSTSH64.d11 : 1.1.4.0
RtkApi64.d11 : 1.0.0.2

HDMI Driver :
Vista x64:
RtHDMIVX.sys : 6.0.1.5413
RtkHDM64.d11 : 6.0.6000.37
RHDMEx64.d11 : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.d11 : 6.0.6000.37
RHDMIExt.d11 : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.51

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.83
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268, ALC269
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Driver :
 1. Support ALC269.
 2. Customizations.
 3. Turn on amplifier mask control for ALC885.
 4. Fix volume issue when turn on "Limited Output" feature under Windows XP.

Windows 2000/XP :
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5523
WDM driver for Winx64 : 5.10.0.5523
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.7
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.2.0

Vista driver :

Readme.txt

Vista driver for x86	: 6.0.1.5523
RtHDVCpl.exe	: 1.0.0.112
RtkAPO.d11	: 11.0.6000.48
RtkPgExt.d11	: 6.0.6000.31
RTCOMDLL.d11	: 2.0.0.85
Rt1CPAPI.d11	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.7
RtkCoInst.d11	: 1.0.1.15
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
SRSHP360.d11	: 1.0.1.0
SRSTSHD.d11	: 1.1.4.0
RtkApoApi.d11	: 1.0.0.2
Vista driver for x64	: 6.0.1.5523
RAVCpl64.exe	: 1.0.0.112
RtkAPO64.d11	: 11.0.6000.48
RtPgEx64.d11	: 6.0.6000.31
RTCOMDLL.d11	: 2.0.0.85
Rt1CPAPI.d11	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.7
RCoInst64.d11	: 1.0.1.15
SRSTX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
SRSHP64.d11	: 1.0.1.0
SRSTSH64.d11	: 1.1.4.0
RtkApi64.d11	: 1.0.0.2
<hr/>	
HDMI Driver :	
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5413
RtkHDM64.d11	: 6.0.6000.37
RHDMEx64.d11	: 6.0.6000.25
Vista x86:	
RtHDMIV.sys	: 6.0.1.5413
RtkHDMI.d11	: 6.0.6000.37
RHDMIExt.d11	: 6.0.6000.25
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413
Driver Setup Program	: 2.51

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.82

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

Readme.txt

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Support IMiniportWaveRTStreamNotification interface under Vista.
2. Customizations.
3. Fix bug for the specific customer.

2.) Installer :

1. Add silent uninstall option .

Windows 2000/XP : _____

Windows 2000/XP :

WDM driver for Win2000/WinXP	: 5.10.0.5512
WDM driver for Winx64	: 5.10.0.5512
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.7.1
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.21

Vista driver : _____

Vista driver for x86	: 6.0.1.5512
RtHDVCpl.exe	: 1.0.0.106
RtkAPO.dll	: 11.0.6000.48
RtkPgExt.dll	: 6.0.6000.31
RTCOMDLL.dll	: 2.0.0.83
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.7
RtkCoInst.dll	: 1.0.1.13
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5512
RAVCpl64.exe	: 1.0.0.106
RtkAPO64.dll	: 11.0.6000.48
RtPgEx64.dll	: 6.0.6000.31
RTCOMDLL.dll	: 2.0.0.83
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.7
RCoInst64.dll	: 1.0.1.13
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.2

HDMI Driver : _____

Vista x64:

RtHDMIVX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25

Vista x86:

RtHDMIV.sys	: 6.0.1.5413
RtkHDMI.dll	: 6.0.6000.37
RHDMIExt.dll	: 6.0.6000.25

Readme.txt

XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.51

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.81

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix

1.) Driver :

1. Support real 2.1 output capability under Vista.
2. Improve Doppler effect for XP driver.
3. Fix Vista DTM topology testing issue.
4. Fix dead lock issue when more than 3 jacks set as headphone

output under XP.

2.) Installer :

1. VSS event error for InstallShield .

Windows 2000/XP : _____

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5506
WDM driver for Winx64 : 5.10.0.5506
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.7.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.21

Vista driver : _____

Vista driver for x86 : 6.0.1.5506
RtHDVCpl.exe : 1.0.0.103
RtkAPO.dll : 11.0.6000.48
RtkPgExt.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.82
Rt1CPAPI.dll : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.dll : 1.0.1.13
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.3.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0

Readme.txt

RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5506
RAVCp164.exe : 1.0.0.103
RtkAPO64.dll : 11.0.6000.48
RtPgEx64.dll : 6.0.6000.31
RTCOMDLL.dll : 2.0.0.82
Rt1CPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RCoInst64.dll : 1.0.1.13
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.3.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2

HDMI Driver : -----
Vista x64:
RtHDMIVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.dll : 6.0.6000.37
RHDMIExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.50

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.80
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262,ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267,ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Driver :
1. Customizations.
2. Add new feature to smooth gap between 2 different output stream
under Vista.
2.) Installer :
1. "Program Compatibility Assistant" issue for InstallShield 11.5 .
2. VSR stop setting .

Windows 2000/XP : -----
Windows 2000/XP :

Readme.txt

WDM driver for Win2000/WinXP	: 5.10.0.5497
WDM driver for Winx64	: 5.10.0.5497
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager (RTHDCPL)	: 2.1.6.7
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.21
<hr/>	
Vista driver :	
Vista driver for x86	: 6.0.1.5497
RtHdVcpl.exe	: 1.0.0.99
RtkAPO.dll	: 11.0.6000.45
RtkPgExt.dll	: 6.0.6000.30
RTCOMDLL.dll	: 2.0.0.80
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.6
RtkCoInst.dll	: 1.0.1.10
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5497
RAVCpl64.exe	: 1.0.0.99
RtkAPO64.dll	: 11.0.6000.45
RtPgEx64.dll	: 6.0.6000.30
RTCOMDLL.dll	: 2.0.0.80
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.6
RCoInst64.dll	: 1.0.1.10
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.2
<hr/>	
HDMI Driver :	
Vista x64:	
RtHdMIVX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25
Vista x86:	
RtHdMIV.sys	: 6.0.1.5413
RtkHDMI.dll	: 6.0.6000.37
RHDMIExt.dll	: 6.0.6000.25
XP/2K x64:	
RtHdMIX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413
Driver Setup Program	: 2.49
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package - KB888111	
Package file version (kb888111.exe)	: 6.1.22.0
Hdaudio.sys version	: 5.10.00.5013

Readme.txt

//=====

Driver Package R1.79

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Driver :

1. Customizations.

2. Fix potential risk from dividing by zero while the input signal power approach zero under Windows XP.

3. Support digital mic software boost for ALC888.

2.) Installer :

1. Remove Realtek registry key in upgrade mode.

2. Change MCE GUI installation procedure for Windows Vista by Microsoft requirement.

3. Add install procedure for VSR feature.

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5490

WDM driver for Winx64 : 5.10.0.5490

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cp1) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.2

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 : 6.0.1.5490

RtHDVCpl.exe : 1.0.0.96

RtkAPO.dll : 11.0.6000.45

RtkPgExt.dll : 6.0.6000.30

RTCOMDLL.dll : 2.0.0.79

Rt1CPAPI.dll : 1.0.1.6

RTSndMgr.cpl : 1.0.0.6

RtkCoInst.dll : 1.0.1.9

SRSTSXT.dll : 3.2.0.0

SRSWOW.dll : 1.1.3.0

SRSHP360.dll : 1.0.1.0

SRSTSHD.dll : 1.1.4.0

RtkApoApi.dll : 1.0.0.2

Vista driver for x64 : 6.0.1.5490

RAVCpl64.exe : 1.0.0.96

RtkAPO64.dll : 11.0.6000.45

RtPgEx64.dll : 6.0.6000.30

RTCOMDLL.dll : 2.0.0.79

Rt1CPAPI.dll : 1.0.1.6

RTSnMg64.cpl : 1.0.0.6

RCoInst64.dll : 1.0.1.9

Readme.txt

SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
SRSHP64.d11 : 1.0.1.0
SRSTSH64.d11 : 1.1.4.0
RtkApi64.d11 : 1.0.0.2

HDMI Driver : -----
Vista x64:
RtHDMIVX.sys : 6.0.1.5413
RtkHDM64.d11 : 6.0.6000.37
RHDMEx64.d11 : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.d11 : 6.0.6000.37
RHDMIExt.d11 : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.47

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R1.78
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262,ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267,ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5485
WDM driver for Winx64 : 5.10.0.5485
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cp1) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.6.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20

Vista driver : -----
Vista driver for x86 : 6.0.1.5485
RtHDVCpl.exe : 1.0.0.92
RtkAPO.d11 : 11.0.6000.45
RtkPgExt.d11 : 6.0.6000.29
RTCOMDLL.d11 : 2.0.0.79

Readme.txt

Rt1CPAPI.d11	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.6
RtkCoInst.d11	: 1.0.1.8
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
SRSHP360.d11	: 1.0.1.0
SRSTSHD.d11	: 1.1.4.0
RtkApoApi.d11	: 1.0.0.2
Vista driver for x64	: 6.0.1.5485
RAVCp164.exe	: 1.0.0.92
RtkAPO64.d11	: 11.0.6000.45
RtPgEx64.d11	: 6.0.6000.29
RTCOMDLL.d11	: 2.0.0.79
Rt1CPAPI.d11	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.6
RCoInst64.d11	: 1.0.1.8
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
SRSHP64.d11	: 1.0.1.0
SRSTSH64.d11	: 1.1.4.0
RtkApi64.d11	: 1.0.0.2
<hr/>	
HDMI Driver :	
Vista x64:	
RtHDMI.VX.sys	: 6.0.1.5413
RtkHDM64.d11	: 6.0.6000.37
RHDMEx64.d11	: 6.0.6000.25
Vista x86:	
RtHDMI.V.sys	: 6.0.1.5413
RtkHDMI.d11	: 6.0.6000.37
RHDMIExt.d11	: 6.0.6000.25
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413
Driver Setup Program	: 2.45

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.77

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.
 - 2.) Uninstall procedure for checking Rtlupd.exe file .

Readme.txt

Windows 2000/XP :	-----
Windows 2000/XP :	
WDM driver for Win2000/WinXP	: 5.10.0.5480
WDM driver for Winx64	: 5.10.0.5480
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager (RTHDCPL)	: 2.1.5.7
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.20
Vista driver :	-----
Vista driver for x86	: 6.0.1.5480
RtHDVCpl.exe	: 1.0.0.90
RtkAPO.dll	: 11.0.6000.45
RtkPgExt.dll	: 6.0.6000.29
RTCOMDLL.dll	: 2.0.0.79
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.6
RtkCoInst.dll	: 1.0.1.7
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5480
RAVCpl64.exe	: 1.0.0.90
RtkAPO64.dll	: 11.0.6000.45
RtPgEx64.dll	: 6.0.6000.29
RTCOMDLL.dll	: 2.0.0.79
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.6
RCoInst64.dll	: 1.0.1.7
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.2
HDMI Driver :	-----
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25
Vista x86:	
RtHDMIV.sys	: 6.0.1.5413
RtkHDMI.dll	: 6.0.6000.37
RHDMIExt.dll	: 6.0.6000.25
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413
Driver Setup Program	: 2.45

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Readme.txt

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.76

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

2.) Installer package language wrong for Japanese translation . (

Upgrade operation for Vista)

Windows 2000/XP : -----

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5477

WDM driver for Winx64 : 5.10.0.5477

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.5

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.1.20

Vista driver : -----

Vista driver for x86 : 6.0.1.5477

RtHDVCpl.exe : 1.0.0.89

RtkAPO.dll : 11.0.6000.45

RtkPgExt.dll : 6.0.6000.29

RTCOMDLL.dll : 2.0.0.79

Rt1CPAPI.dll : 1.0.1.6

RTSndMgr.cpl : 1.0.0.6

RtkCoInst.dll : 1.0.1.7

SRSTSXT.dll : 3.2.0.0

SRSWOW.dll : 1.1.3.0

SRSHP360.dll : 1.0.1.0

SRSTSHD.dll : 1.1.4.0

RtkApoApi.dll : 1.0.0.2

Vista driver for x64 : 6.0.1.5477

RAVCpl64.exe : 1.0.0.89

RtkAPO64.dll : 11.0.6000.45

RtPgEx64.dll : 6.0.6000.29

RTCOMDLL.dll : 2.0.0.79

Rt1CPAPI.dll : 1.0.1.6

RTSnMg64.cpl : 1.0.0.6

RCoInst64.dll : 1.0.1.7

SRSTSX64.dll : 3.2.0.0

SRSWOW64.dll : 1.1.3.0

SRSHP64.dll : 1.0.1.0

SRSTSH64.dll : 1.1.4.0

RtkApi64.dll : 1.0.0.2

Readme.txt

HDMI Driver : -----
Vista x64:
RtHDMIVX.sys : 6.0.1.5413
RtkHDM64.d11 : 6.0.6000.37
RHDMEx64.d11 : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.d11 : 6.0.6000.37
RHDMIExt.d11 : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.44

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.75

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5473
WDM driver for Winx64 : 5.10.0.5473
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.5.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.20

Vista driver : -----
Vista driver for x86 : 6.0.1.5473
RtHDVCpl.exe : 1.0.0.88
RtkAPO.d11 : 11.0.6000.44
RtkPgExt.d11 : 6.0.6000.29

Readme.txt

RTCOMDLL.d11	: 2.0.0.79
Rt1CPAPI.d11	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.6
RtkCoInst.d11	: 1.0.1.7
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.1.3.0
SRSHP360.d11	: 1.0.1.0
SRSTSHD.d11	: 1.1.4.0
RtkApoApi.d11	: 1.0.0.2
Vista driver for x64	: 6.0.1.5473
RAVCp164.exe	: 1.0.0.88
RtkAPO64.d11	: 11.0.6000.44
RtPgEx64.d11	: 6.0.6000.29
RTCOMDLL.d11	: 2.0.0.79
Rt1CPAPI.d11	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.6
RtkCoInst.d11	: 1.0.1.7
SRSTX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.1.3.0
SRSHP64.d11	: 1.0.1.0
SRSTSH64.d11	: 1.1.4.0
RtkApi64.d11	: 1.0.0.2
<hr/>	
HDMI Driver :	
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5413
RtkHDM64.d11	: 6.0.6000.37
RHDMEx64.d11	: 6.0.6000.25
Vista x86:	
RtHDMIV.sys	: 6.0.1.5413
RtkHDMI.d11	: 6.0.6000.37
RHDMIExt.d11	: 6.0.6000.25
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413
Driver Setup Program	: 2.42

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.74

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

Readme.txt

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :	-----
Windows 2000/XP :	
WDM driver for Win2000/WinXP	: 5.10.0.5470
WDM driver for Winx64	: 5.10.0.5470
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager (RTHDCPL)	: 2.1.5.2
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.20
Vista driver :	-----
Vista driver for x86	: 6.0.1.5470
RtHDVCpl.exe	: 1.0.0.87
RtkAPO.dll	: 11.0.6000.44
RtkPgExt.dll	: 6.0.6000.28
RTCOMDLL.dll	: 2.0.0.79
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.6
RtkCoInst.dll	: 1.0.1.7
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.3.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5470
RAVCpl64.exe	: 1.0.0.87
RtkAPO64.dll	: 11.0.6000.44
RtPgEx64.dll	: 6.0.6000.28
RTCOMDLL.dll	: 2.0.0.79
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.6
RtkCoInst.dll	: 1.0.1.7
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.3.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.2
HDMI Driver :	-----
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5413
RtkHDM64.dll	: 6.0.6000.37
RHDMEx64.dll	: 6.0.6000.25
Vista x86:	
RtHDMIV.sys	: 6.0.1.5413
RtkHDMI.dll	: 6.0.6000.37
RHDMIExt.dll	: 6.0.6000.25
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5413
XP/2K x86:	

Readme.txt

RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.40

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R1.73

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP : _____

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5464

WDM driver for Winx64 : 5.10.0.5464

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.4.9

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.1.20

Vista driver : _____

Vista driver for x86 : 6.0.1.5464

RtHDVCpl.exe : 1.0.0.84

RtkAPO.dll : 11.0.6000.43

RtkPgExt.dll : 6.0.6000.27

RTCOMDLL.dll : 2.0.0.76

Rt1CPAPI.dll : 1.0.1.6

RTSndMgr.cpl : 1.0.0.6

RtkCoInst.dll : 1.0.1.7

SRSTSXT.dll : 3.2.0.0

SRSWOW.dll : 1.1.3.0

SRSHP360.dll : 1.0.1.0

SRSTSHD.dll : 1.1.4.0

RtkApoApi.dll : 1.0.0.2

Vista driver for x64 : 6.0.1.5464

RAVCp164.exe : 1.0.0.84

RtkAPO64.dll : 11.0.6000.43

Readme.txt

RtPgEx64.d11 : 6.0.6000.27
RTCOMDLL.d11 : 2.0.0.76
Rt1CPAPI.d11 : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkCoInst.d11 : 1.0.1.7
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.3.0
SRSHP64.d11 : 1.0.1.0
SRSTSH64.d11 : 1.1.4.0
RtkApi64.d11 : 1.0.0.2

HDMI Driver : -----
Vista x64:
RtHDMIVX.sys : 6.0.1.5413
RtkHDM64.d11 : 6.0.6000.37
RHDMEx64.d11 : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.d11 : 6.0.6000.37
RHDMIExt.d11 : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.38

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.72
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262,ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267,ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP : -----
Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5449
WDM driver for Winx64 : 5.10.0.5449
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Readme.txt

Realtek Sound Effect Manager (RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl) : 1.0.1.65
Realtek Sound Effect Manager (RTHDCPL) : 2.1.4.2
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.19

Vista driver :

Vista driver for x86 : 6.0.1.5449
RtHDVCpl.exe : 1.0.0.73
RtkAPO.d11 : 11.0.6000.41
RtkPgExt.d11 : 6.0.6000.27
RTCOMDLL.d11 : 2.0.0.76
Rt1CPAPI.d11 : 1.0.1.6
RTSndMgr.cpl : 1.0.0.6
RtkCoInst.d11 : 1.0.1.7
SRSTSXT.d11 : 3.2.0.0
SRSWOW.d11 : 1.1.2.0
SRSHP360.d11 : 1.0.1.0
SRSTSHD.d11 : 1.1.4.0
RtkApoApi.d11 : 1.0.0.2
Vista driver for x64 : 6.0.1.5449
RAVCpl64.exe : 1.0.0.73
RtkAPO64.d11 : 11.0.6000.41
RtPgEx64.d11 : 6.0.6000.27
RTCOMDLL.d11 : 2.0.0.76
Rt1CPAPI.d11 : 1.0.1.6
RTSnMg64.cpl : 1.0.0.6
RtkCoInst.d11 : 1.0.1.7
SRSTX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.1.2.0
SRSHP64.d11 : 1.0.1.0
SRSTSH64.d11 : 1.1.4.0
RtkApi64.d11 : 1.0.0.2

HDMI Driver :

Vista x64:
RtHDMIVX.sys : 6.0.1.5413
RtkHDM64.d11 : 6.0.6000.37
RHDMEx64.d11 : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.d11 : 6.0.6000.37
RHDMIExt.d11 : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.36

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.71

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

Readme.txt

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :	-----
WDM driver for Win2000/WinXP	: 5.10.0.5443
WDM driver for Winx64	: 5.10.0.5443
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.4.2
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.19
Vista driver :	-----
Vista driver for x86	: 6.0.1.5443
RtHDVCpl.exe	: 1.0.0.73
RtkAPO.dll	: 11.0.6000.40
RtkPgExt.dll	: 6.0.6000.27
RTCOMDLL.dll	: 2.0.0.74
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.6
RtkCoInst.dll	: 1.0.1.7
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.2.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.4.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5443
RAVCpl64.exe	: 1.0.0.73
RtkAPO64.dll	: 11.0.6000.40
RtPgEx64.dll	: 6.0.6000.27
RTCOMDLL.dll	: 2.0.0.74
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.6
RtkCoInst.dll	: 1.0.1.7
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.2.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.4.0
RtkApi64.dll	: 1.0.0.2
HDMI Driver :	-----
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5413

Readme.txt

RtkHDM64.d11 : 6.0.6000.37
RHDMEx64.d11 : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.d11 : 6.0.6000.37
RHDMIExt.d11 : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.36

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.70

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262,ALC267, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267,ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP : _____

WDM driver for Win2000/WinXP : 5.10.0.5436

WDM driver for Winx64 : 5.10.0.5436

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.9

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.1.19

Vista driver : _____

Vista driver for x86 : 6.0.1.5436

RtHDVCpl.exe : 1.0.0.69

RtkAPO.d11 : 11.0.6000.38

RtkPgExt.d11 : 6.0.6000.27

RTCOMDLL.d11 : 2.0.0.74

Rt1CPAPI.d11 : 1.0.1.6

RTSndMgr.cpl : 1.0.0.5

RtkCoInst.d11 : 1.0.1.5

Readme.txt

SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.1.2.0
SRSHP360.dll : 1.0.1.0
SRSTSHD.dll : 1.1.4.0
RtkApoApi.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5436
RAVCp164.exe : 1.0.0.69
RtkAPO64.dll : 11.0.6000.38
RtPgEx64.dll : 6.0.6000.27
RTCOMDLL.dll : 2.0.0.74
Rt1CPAPI.dll : 1.0.1.6
RTSnMg64.cpl : 1.0.0.5
RtkCoInst.dll : 1.0.1.5
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.1.2.0
SRSHP64.dll : 1.0.1.0
SRSTSH64.dll : 1.1.4.0
RtkApi64.dll : 1.0.0.2

HDMI Driver : -----
Vista x64:
RtHDMIVX.sys : 6.0.1.5413
RtkHDM64.dll : 6.0.6000.37
RHDMEx64.dll : 6.0.6000.25
Vista x86:
RtHDMIV.sys : 6.0.1.5413
RtkHDMI.dll : 6.0.6000.37
RHDMIExt.dll : 6.0.6000.25
XP/2K x64:
RtHDMIX.sys : 5.10.0.5413
XP/2K x86:
RtHDMI.sys : 5.10.0.5413

Driver Setup Program : 2.35

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.69
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267,ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :		-----
WDM driver for Win2000/WinXP	:	5.10.0.5433
WDM driver for Winx64	:	5.10.0.5433
Realtek Soundman	:	1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl)	:	1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl)	:	1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl)	:	1.0.1.65
Realtek Sound Effect Manager (RTHDCPL)	:	2.1.3.6
Alcwzrd.exe	:	1.1.0.36
SkyTel.exe	:	2.0.1.17
Vista driver :		-----
Vista driver for x86	:	6.0.1.5433
RtHDVCpl.exe	:	1.0.0.68
RtkAPO.dll	:	11.0.6000.38
RtkPgExt.dll	:	6.0.6000.27
RTCOMDLL.dll	:	2.0.0.74
Rt1CPAPI.dll	:	1.0.1.6
RTSndMgr.cpl	:	1.0.0.5
RtkCoInst.dll	:	1.0.1.5
SRSTSXT.dll	:	3.2.0.0
SRSWOW.dll	:	1.1.2.0
SRSHP360.dll	:	1.0.1.0
SRSTSHD.dll	:	1.1.4.0
RtkApoApi.dll	:	1.0.0.2
Vista driver for x64	:	6.0.1.5433
RAVCpl64.exe	:	1.0.0.68
RtkAPO64.dll	:	11.0.6000.38
RtPgEx64.dll	:	6.0.6000.27
RTCOMDLL.dll	:	2.0.0.74
Rt1CPAPI.dll	:	1.0.1.6
RTSnMg64.cpl	:	1.0.0.5
RtkCoInst.dll	:	1.0.1.5
SRSTX64.dll	:	3.2.0.0
SRSWOW64.dll	:	1.1.2.0
SRSHP64.dll	:	1.0.1.0
SRSTSH64.dll	:	1.1.4.0
RtkApi64.dll	:	1.0.0.2
HDMI Driver :		-----
Vista x64:		
RtHDMI.VX.sys	:	6.0.1.5413
RtkHDM64.dll	:	6.0.6000.37
RHDMEx64.dll	:	6.0.6000.25
Vista x86:		
RtHDMI.V.sys	:	6.0.1.5413
RtkHDMI.dll	:	6.0.6000.37
RHDMIExt.dll	:	6.0.6000.25
XP/2K x64:		
RtHDMIX.sys	:	5.10.0.5413
XP/2K x86:		
RtHDMI.sys	:	5.10.0.5413
Driver Setup Program	:	2.34
Windows 2000/XP Operate on :		

Readme.txt

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.68

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP : _____

WDM driver for Win2000/WinXP : 5.10.0.5413

WDM driver for Winx64 : 5.10.0.5413

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.2

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.1.12

Vista driver : _____

Vista driver for x86 : 6.0.1.5413

RtHDVCpl.exe : 1.0.0.60

RtkAPO.dll : 11.0.6000.37

RtkPgExt.dll : 6.0.6000.25

RTCOMDLL.dll : 2.0.0.73

Rt1CPAPI.dll : 1.0.1.6

RTSndMgr.cpl : 1.0.0.5

RtkCoInst.dll : 1.0.1.2

SRSTSXT.dll : 3.2.0.0

SRSWOW.dll : 1.1.2.0

SRSHP360.dll : 1.0.1.0

SRSTSHD.dll : 1.1.3.0

RtkApoApi.dll : 1.0.0.2

Vista driver for x64 : 6.0.1.5413

RAVCpl64.exe : 1.0.0.60

RtkAPO64.dll : 11.0.6000.37

RtPgEx64.dll : 6.0.6000.25

RTCOMDLL.dll : 2.0.0.73

Rt1CPAPI.dll : 1.0.1.6

RTSnMg64.cpl : 1.0.0.5

RtkCoInst.dll : 1.0.1.2

SRSTSX64.dll : 3.2.0.0

Readme.txt

SRSWOW64.d11	: 1.1.2.0
SRSHP64.d11	: 1.0.1.0
SRSTSH64.d11	: 1.1.3.0
RtkApi64.d11	: 1.0.0.2
<hr/>	
HDMI Driver :	
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5413
RtkHDM64.d11	: 6.0.6000.37
RHDMEx64.d11	: 6.0.6000.25
Vista x86:	
RtHDMIV.sys	: 6.0.1.5413
RtkHDMI.d11	: 6.0.6000.37
RHDMIExt.d11	: 6.0.6000.25
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5413
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5413
Driver Setup Program	: 2.33
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package –KB888111	
Package file version (kb888111.exe) :	6.1.22.0
Hdaudio.sys version :	5.10.00.5013
//=====	
Driver Package R1.67	
Realtek HD Audio Driver support all of Realtek HD Audio Codec in	
Vista/WinXP/Win2000/Win2003 .	
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,	
ALC662, ALC260, ALC262, ALC268	
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,	
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267,ALC268	
3. HDMI Device WHQL Support: ATI HDMI Devices	
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64	
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)	
6. Add/Fix	
1.) Customization.	
For New architecture:	
1.) Customization .	
CPL :	
1.) Customization.	
Windows 2000/XP :	
<hr/>	
WDM driver for Win2000/WinXP	: 5.10.0.5413
WDM driver for Winx64	: 5.10.0.5413
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cp1)	: 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.3.2
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.12
<hr/>	
Vista driver :	
Vista driver for x86	: 6.0.1.5413

Readme.txt

RtHdVcpl.exe	: 1.0.0.60
RtkAPO.dll	: 11.0.6000.37
RtkPgExt.dll	: 6.0.6000.25
RTCOMDLL.dll	: 2.0.0.73
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.5
RtkCoInst.dll	: 1.0.1.2
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.2.0
SRSHP360.dll	: 1.0.1.0
SRSTSHD.dll	: 1.1.3.0
RtkApoApi.dll	: 1.0.0.2
Vista driver for x64	: 6.0.1.5413
RAVCpl64.exe	: 1.0.0.60
RtkAPO64.dll	: 11.0.6000.37
RtPgEx64.dll	: 6.0.6000.25
RTCOMDLL.dll	: 2.0.0.73
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.5
RtkCoInst.dll	: 1.0.1.2
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.2.0
SRSHP64.dll	: 1.0.1.0
SRSTSH64.dll	: 1.1.3.0
RtkApi64.dll	: 1.0.0.2
<hr/>	
HDMI Driver :	
Vista x64:	
RtHdMIVX.sys	: 6.0.1.5368
RtkHdM64.dll	: 6.0.6000.26
RHdMEx64.dll	: 6.0.6000.20
Vista x86:	
RtHdMIV.sys	: 6.0.1.5368
RtkHdMI.dll	: 6.0.6000.26
RHdMIExt.dll	: 6.0.6000.20
XP/2K x64:	
RtHdMIX.sys	: 5.10.0.5368
XP/2K x86:	
RtHdMI.sys	: 5.10.0.5368
Driver Setup Program	: 2.32

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.66

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix
 1.) Customization.

For New architecture:
 1.) Customization .

CPL :
 1.) Customization.

Windows 2000/XP : <hr/>	
WDM driver for Win2000/WinXP	: 5.10.0.5404
WDM driver for Winx64	: 5.10.0.5404
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl)	: 1.0.1.65
Realtek Sound Effect Manager (RTHDCPL)	: 2.1.3.2
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 2.0.1.11
Vista driver : <hr/>	
Vista driver for x86	: 6.0.1.5404
RtHDVCpl.exe	: 1.0.0.54
RtkAPO.dll	: 11.0.6000.35
RtkPgExt.dll	: 6.0.6000.24
RTCOMDLL.dll	: 2.0.0.72
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.5
RtkCoInst.dll	: 1.0.1.1
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.1.2.0
SRSHP360.dll	: 1.0.0.0
SRSTSHD.dll	: 1.1.2.0
Vista driver for x64	: 6.0.1.5404
RAVCpl64.exe	: 1.0.0.54
RtkAPO64.dll	: 11.0.6000.35
RtPgEx64.dll	: 6.0.6000.24
RTCOMDLL.dll	: 2.0.0.72
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.5
RtkCoInst.dll	: 1.0.1.1
SRSTX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.1.2.0
SRSHP64.dll	: 1.0.0.0
SRSTSH64.dll	: 1.1.2.0
HDMI Driver : <hr/>	
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5368
RtkHDM64.dll	: 6.0.6000.26
RHDME64.dll	: 6.0.6000.20
Vista x86:	
RtHDMIV.sys	: 6.0.1.5368
RtkHDMI.dll	: 6.0.6000.26
RHDMIEExt.dll	: 6.0.6000.20
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5368
XP/2K x86:	

Readme.txt

RtHDMI.sys : 5.10.0.5368

Driver Setup Program : 2.32

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.65

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP : _____

WDM driver for Win2000/WinXP : 5.10.0.5397

WDM driver for Winx64 : 5.10.0.5397

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65

Realtek Sound Effect Manager(RTHDCPL) : 2.1.3.0

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 2.0.1.9

Vista driver : _____

Vista driver for x86 : 6.0.1.5397

RtHDVCpl.exe : 1.0.0.50

RtkAPO.dll : 11.0.6000.32

RtkPgExt.dll : 6.0.6000.22

RTCOMDLL.dll : 2.0.0.70

Rt1CPAPI.dll : 1.0.1.6

RTSndMgr.cpl : 1.0.0.5

RtkCoInst.dll : 1.0.1.1

SRSTSXT.dll : 3.2.0.0

SRSWOW.dll : 1.0.6.0

Vista driver for x64 : 6.0.1.5397

RAVCpl64.exe : 1.0.0.50

RtkAPO64.dll : 11.0.6000.32

RtPgEx64.dll : 6.0.6000.22

RTCOMDLL.dll : 2.0.0.70

Rt1CPAPI.dll : 1.0.1.6

RTSnMg64.cpl : 1.0.0.5

Readme.txt

RtkCoInst.d11 : 1.0.1.1
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.0.6.0

HDMI Driver :
Vista x64:
RtHDMIVX.sys : 6.0.1.5368
RtkHDM64.d11 : 6.0.6000.26
RHDMEx64.d11 : 6.0.6000.20
Vista x86:
RtHDMIV.sys : 6.0.1.5368
RtkHDMI.d11 : 6.0.6000.26
RHDMIExt.d11 : 6.0.6000.20
XP/2K x64:
RtHDMIX.sys : 5.10.0.5368
XP/2K x86:
RtHDMI.sys : 5.10.0.5368

Driver Setup Program : 2.31

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.64
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267,ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5391
WDM driver for Winx64 : 5.10.0.5391
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.65
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.9
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 2.0.1.7

Vista driver :
Vista driver for x86 : 6.0.1.5391
RtHDVCpl.exe : 1.0.0.46

Readme.txt

RtkAPO.d11	: 11.0.6000.31
RtkPgExt.d11	: 6.0.6000.22
RTCOMDLL.d11	: 2.0.0.69
Rt1CPAPI.d11	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.5
RtkCoInst.d11	: 1.0.0.12
SRSTSXT.d11	: 3.2.0.0
SRSWOW.d11	: 1.0.6.0
Vista driver for x64	: 6.0.1.5391
RAVCp164.exe	: 1.0.0.46
RtkAPO64.d11	: 11.0.6000.31
RtPgEx64.d11	: 6.0.6000.22
RTCOMDLL.d11	: 2.0.0.69
Rt1CPAPI.d11	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.5
RtkCoInst.d11	: 1.0.0.12
SRSTSX64.d11	: 3.2.0.0
SRSWOW64.d11	: 1.0.6.0
<hr/>	
HDMI Driver :	
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5368
RtkHDM64.d11	: 6.0.6000.26
RHDMEx64.d11	: 6.0.6000.20
Vista x86:	
RtHDMIV.sys	: 6.0.1.5368
RtkHDMI.d11	: 6.0.6000.26
RHDMIExt.d11	: 6.0.6000.20
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5368
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5368
Driver Setup Program	: 2.30

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.63

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

1.) Customization.

```

Windows 2000/XP : -----
WDM driver for Win2000/WinXP           : 5.10.0.5377
WDM driver for Winx64                   : 5.10.0.5377
Realtek Soundman                         : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cp1) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cp1) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cp1)     : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)    : 2.1.2.4
Alcwzrd.exe                             : 1.1.0.36
SkyTel.exe                               : 1.0.0.0
Vista driver : -----
Vista driver for x86                     : 6.0.1.5386
RtHDVCpl.exe                             : 1.0.0.43
RtkAPO.dll                               : 11.0.6000.29
RtkPgExt.dll                             : 6.0.6000.22
RTCOMDLL.dll                             : 2.0.0.69
Rt1CPAPI.dll                             : 1.0.1.6
RTSndMgr.cp1                             : 1.0.0.4
RtkCoInst.dll                            : 1.0.0.9
SRSTSXT.dll                              : 3.2.0.0
SRSWOW.dll                               : 1.0.6.0
Vista driver for x64                     : 6.0.1.5386
RAVCpl64.exe                             : 1.0.0.43
RtkAPO64.dll                             : 11.0.6000.29
RtPgEx64.dll                             : 6.0.6000.22
RTCOMDLL.dll                             : 2.0.0.69
Rt1CPAPI.dll                             : 1.0.1.6
RTSnMg64.cp1                             : 1.0.0.4
RtkCoInst.dll                            : 1.0.0.9
SRSTSX64.dll                             : 3.2.0.0
SRSWOW64.dll                             : 1.0.6.0
HDMI Driver : -----
Vista x64:
RtHDMI.VX.sys                            : 6.0.1.5368
RtkHDM64.dll                             : 6.0.6000.26
RHDMEx64.dll                             : 6.0.6000.20
Vista x86:
RtHDMI.V.sys                             : 6.0.1.5368
RtkHDMI.dll                              : 6.0.6000.26
RHDMIExt.dll                             : 6.0.6000.20
XP/2K x64:
RtHDMIX.sys                              : 5.10.0.5368
XP/2K x86:
RtHDMI.sys                               : 5.10.0.5368

Driver Setup Program                      : 2.30

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

```

//=====

Driver Package R1.62

Realtek HD Audio Driver support all of Realtek HD Audio Codec in

Readme.txt

Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : _____

WDM driver for Win2000/WinXP	: 5.10.0.5377
WDM driver for Winx64	: 5.10.0.5377
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.2.4
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0

Vista driver : _____

Vista driver for x86	: 6.0.1.5384
RtHDVCpl.exe	: 1.0.0.41
RtkAPO.dll	: 11.0.6000.28
RtkPgExt.dll	: 6.0.6000.21
RTCOMDLL.dll	: 2.0.0.69
Rt1CPAPI.dll	: 1.0.1.6
RTSndMgr.cpl	: 1.0.0.4
RtkCoInst.dll	: 1.0.0.9
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.0.6.0
Vista driver for x64	: 6.0.1.5384
RAVCpl64.exe	: 1.0.0.41
RtkAPO64.dll	: 11.0.6000.28
RtPgEx64.dll	: 6.0.6000.21
RTCOMDLL.dll	: 2.0.0.69
Rt1CPAPI.dll	: 1.0.1.6
RTSnMg64.cpl	: 1.0.0.4
RtkCoInst.dll	: 1.0.0.9
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.0.6.0

HDMI Driver : _____

Vista x64:	
RtHDMI.VX.sys	: 6.0.1.5368
RtkHDM64.dll	: 6.0.6000.26
RHDMEx64.dll	: 6.0.6000.20
Vista x86:	
RtHDMI.V.sys	: 6.0.1.5368
RtkHDMI.dll	: 6.0.6000.26

Readme.txt

RHDMIEExt.d11 : 6.0.6000.20
XP/2K x64:
RtHDMIX.sys : 5.10.0.5368
XP/2K x86:
RtHDMI.sys : 5.10.0.5368

Driver Setup Program : 2.30

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.61

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : _____

WDM driver for Win2000/WinXP : 5.10.0.5377
WDM driver for Winx64 : 5.10.0.5377
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0

Vista driver : _____

Vista driver for x86 : 6.0.1.5377
RtHDVCpl.exe : 1.0.0.38
RtkAPO.d11 : 11.0.6000.26
RtkPgExt.d11 : 6.0.6000.20
RTCOMDLL.d11 : 2.0.0.68
Rt1CPAPI.d11 : 1.0.1.5
RTSndMgr.cpl : 1.0.0.4
RtkCoInst.d11 : 1.0.0.7
SRSTSXT.d11 : 3.2.0.0
SRSWOW.d11 : 1.0.6.0
Vista driver for x64 : 6.0.1.5377
RAVCp164.exe : 1.0.0.38
RtkAPO64.d11 : 11.0.6000.26

Readme.txt

RtPgEx64.d11 : 6.0.6000.20
RTCOMDLL.d11 : 2.0.0.68
Rt1CPAPI.d11 : 1.0.1.5
RTSnMg64.cpl : 1.0.0.4
RtkCoInst.d11 : 1.0.0.7
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.0.6.0

HDMI Driver :

Vista x64:
RtHDMIVX.sys : 6.0.1.5356
RtkHDM64.d11 : 6.0.6000.20
RHDMEx64.d11 : 6.0.6000.17
Vista x86:
RtHDMIV.sys : 6.0.1.5356
RtkHDMI.d11 : 6.0.6000.20
RHDMIExt.d11 : 6.0.6000.17
XP/2K x64:
RtHDMIX.sys : 5.10.0.5356
XP/2K x86:
RtHDMI.sys : 5.10.0.5356

Driver Setup Program : 2.30

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R1.60
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5366
WDM driver for Winx64 : 5.10.0.5366
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0
Alcwzrd.exe : 1.1.0.36

Readme.txt

SkyTel.exe : 1.0.0.0

Vista driver :
Vista driver for x86 : 6.0.1.5374
RtHDVCpl.exe : 1.0.0.36
RtkAPO.dll : 11.0.6000.25
RtkPgExt.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.66
Rt1CPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSXT.dll : 3.2.0.0
SRSWOW.dll : 1.0.6.0
Vista driver for x64 : 6.0.1.5374
RAVCpl64.exe : 1.0.0.36
RtkAPO64.dll : 11.0.6000.25
RtPgEx64.dll : 6.0.6000.20
RTCOMDLL.dll : 2.0.0.65
Rt1CPAPI.dll : 1.0.1.5
RTSnMg64.cpl : 1.0.0.4
RtkCoInst.dll : 1.0.0.7
SRSTSX64.dll : 3.2.0.0
SRSWOW64.dll : 1.0.6.0

HDMI Driver :
Vista x64:
RtHDMIVX.sys : 6.0.1.5356
RtkHDM64.dll : 6.0.6000.20
RHDMEx64.dll : 6.0.6000.17
Vista x86:
RtHDMIV.sys : 6.0.1.5356
RtkHDMI.dll : 6.0.6000.20
RHDMIExt.dll : 6.0.6000.17
XP/2K x64:
RtHDMIX.sys : 5.10.0.5356
XP/2K x86:
RtHDMI.sys : 5.10.0.5356

Driver Setup Program : 2.28

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.59

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

Readme.txt

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :	-----
WDM driver for Win2000/WinXP	: 5.10.0.5366
WDM driver for Winx64	: 5.10.0.5366
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager (RTHDCPL)	: 2.1.2.0
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Vista driver :	-----
Vista driver for x86	: 6.0.1.5372
RtHDVCpl.exe	: 1.0.0.33
RtkAPO.dll	: 11.0.6000.25
RtkPgExt.dll	: 6.0.6000.20
RTCOMDLL.dll	: 2.0.0.66
Rt1CPAPI.dll	: 1.0.1.5
RTSndMgr.cpl	: 1.0.0.4
RtkCoInst.dll	: 1.0.0.7
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.0.6.0
Vista driver for x64	: 6.0.1.5372
RAVCpl64.exe	: 1.0.0.33
RtkAPO64.dll	: 11.0.6000.25
RtPgEx64.dll	: 6.0.6000.20
RTCOMDLL.dll	: 2.0.0.65
Rt1CPAPI.dll	: 1.0.1.5
RTSnMg64.cpl	: 1.0.0.4
RtkCoInst.dll	: 1.0.0.7
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.0.6.0
HDMI Driver :	-----
Vista x64:	
RtHDMIVX.sys	: 6.0.1.5356
RtkHDM64.dll	: 6.0.6000.20
RHDMEx64.dll	: 6.0.6000.17
Vista x86:	
RtHDMIV.sys	: 6.0.1.5356
RtkHDMI.dll	: 6.0.6000.20
RHDMIExt.dll	: 6.0.6000.17
XP/2K x64:	
RtHDMIX.sys	: 5.10.0.5356
XP/2K x86:	
RtHDMI.sys	: 5.10.0.5356
Driver Setup Program	: 2.28
Windows 2000/XP Operate on :	
Microsoft High Definition Audio Driver Package - KB888111	
Package file version (kb888111.exe) :	6.1.22.0

Readme.txt

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.58

Realtek HD Audio Driver support all of Realtek HD Audio Codec in Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. HDMI Device WHQL Support: ATI HDMI Devices
4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
6. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP : -----

WDM driver for Win2000/WinXP	: 5.10.0.5366
WDM driver for Winx64	: 5.10.0.5366
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.1.2.0
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0

Vista driver : -----

Vista driver for x86	: 6.0.1.5371
RtHDVCpl.exe	: 1.0.0.32
RtkAPO.dll	: 11.0.6000.25
RtkPgExt.dll	: 6.0.6000.20
RTCOMDLL.dll	: 2.0.0.66
Rt1CPAPI.dll	: 1.0.1.5
RTSndMgr.cpl	: 1.0.0.4
RtkCoInst.dll	: 1.0.0.7
SRSTSXT.dll	: 3.2.0.0
SRSWOW.dll	: 1.0.6.0
Vista driver for x64	: 6.0.1.5371
RAVCpl64.exe	: 1.0.0.32
RtkAPO64.dll	: 11.0.6000.25
RtPgEx64.dll	: 6.0.6000.20
RTCOMDLL.dll	: 2.0.0.65
Rt1CPAPI.dll	: 1.0.1.5
RTSnMg64.cpl	: 1.0.0.4
RtkCoInst.dll	: 1.0.0.7
SRSTSX64.dll	: 3.2.0.0
SRSWOW64.dll	: 1.0.6.0

HDMI Driver : -----

Vista x64:	
RtHDMIVX.sys	: 6.0.1.5356
RtkHDM64.dll	: 6.0.6000.20

Readme.txt

RHDMEx64.d11 : 6.0.6000.17
Vista x86:
RtHDMIV.sys : 6.0.1.5356
RtkHDMI.d11 : 6.0.6000.20
RHDMIEExt.d11 : 6.0.6000.17
XP/2K x64:
RtHDMIX.sys : 5.10.0.5356
XP/2K x86:
RtHDMI.sys : 5.10.0.5356

Driver Setup Program : 2.28

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.57

Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .

1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC268

2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. HDMI Device WHQL Support: ATI HDMI Devices

4. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

5. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

6. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP : _____

WDM driver for Win2000/WinXP : 5.10.0.5366

WDM driver for Winx64 : 5.10.0.5366

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64

Realtek Sound Effect Manager(RTHDCPL) : 2.1.2.0

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 1.0.0.0

Vista driver : _____

Vista driver for x86 : 6.0.1.5361

RtHDVCpl.exe : 1.0.0.27

RtkAPO.d11 : 11.0.6000.20

RtkPgExt.d11 : 6.0.6000.17

RTCOMDLL.d11 : 2.0.0.65

Rt1CPAPI.d11 : 1.0.1.5

RTSndMgr.cpl : 1.0.0.1

RtkCoInst.d11 : 1.0.0.6

SRSTSXT.d11 : 3.2.0.0

Readme.txt

SRSWOW.d11 : 1.0.6.0
Vista driver for x64 : 6.0.1.5361
RAVCp164.exe : 1.0.0.27
RtkAPO64.d11 : 11.0.6000.20
RtPgEx64.d11 : 6.0.6000.17
RTCOMDLL.d11 : 2.0.0.65
Rt1CPAPI.d11 : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.d11 : 1.0.0.6
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.0.6.0

HDMI Driver :
Vista x64:
RtHDMIVX.sys : 6.0.1.5356
RtkHDM64.d11 : 6.0.6000.20
RHDMEx64.d11 : 6.0.6000.17
Vista x86:
RtHDMIV.sys : 6.0.1.5356
RtkHDMI.d11 : 6.0.6000.20
RHDMIExt.d11 : 6.0.6000.17
XP/2K x64:
RtHDMIX.sys : 5.10.0.5356
XP/2K x86:
RtHDMI.sys : 5.10.0.5356

Driver Setup Program : 2.27

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudiobus.sys version : 5.10.00.5013

//=====

Driver Package R1.56
Realtek HD Audio Driver support all of Realtek HD Audio Codec in
Vista/WinXP/Win2000/Win2003 .
1. Vista WHQL Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660,
ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP WHQL Supporting: ALC880, ALC882, ALC883, ALC885, ALC888,
ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267,ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
1.) Customization.

For New architecture:
1.) Customization .

CPL :
1.) Customization.

Windows 2000/XP :
WDM driver for Win2000/WinXP : 5.10.0.5345
WDM driver for Winx64 : 5.10.0.5345
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Readme.txt

Realtek Sound Effect Manager(Rt1Cp1) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5361
RtHDVCpl.exe : 1.0.0.27
RtkAPO.d11 : 11.0.6000.20
RtkPgExt.d11 : 6.0.6000.17
RTCOMDLL.d11 : 2.0.0.65
Rt1CPAPI.d11 : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkCoInst.d11 : 1.0.0.6
SRSTSXT.d11 : 3.2.0.0
SRSWOW.d11 : 1.0.6.0
Vista driver for x64 : 6.0.1.5361
RAVCpl64.exe : 1.0.0.27
RtkAPO64.d11 : 11.0.6000.20
RtPgEx64.d11 : 6.0.6000.17
RTCOMDLL.d11 : 2.0.0.65
Rt1CPAPI.d11 : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.d11 : 1.0.0.6
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.0.6.0

Driver Setup Program : 2.27

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.55

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5345
WDM driver for Winx64 : 5.10.0.5345
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cp1) : 1.0.1.64

Readme.txt

Realtek Sound Effect Manager (RTHDCPL) : 2.1.1.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5350
RtHDVCpl.exe : 1.0.0.21
RtkAPO.d11 : 11.0.6000.16
RtkPgExt.d11 : 6.0.6000.15
RTCOMDLL.d11 : 2.0.0.65
Rt1CPAPI.d11 : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkCoInst.d11 : 1.0.0.3
SRSTSXT.d11 : 3.2.0.0
SRSWOW.d11 : 1.0.6.0
Vista driver for x64 : 6.0.1.5350
RAVCpl64.exe : 1.0.0.21
RtkAPO64.d11 : 11.0.6000.16
RtPgEx64.d11 : 6.0.6000.15
RTCOMDLL.d11 : 2.0.0.65
Rt1CPAPI.d11 : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.d11 : 1.0.0.4
SRSTSX64.d11 : 3.2.0.0
SRSWOW64.d11 : 1.0.6.0

Driver Setup Program : 2.24

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.54

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5345
WDM driver for Winx64 : 5.10.0.5345
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager (ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager (Rt1Cpl) : 1.0.1.64
Realtek Sound Effect Manager (RTHDCPL) : 2.1.1.4

Readme.txt

Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5334
RtHDVCpl.exe : 1.0.0.11
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
Rt1CPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5334
RAVCpl64.exe : 1.0.0.11
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
Rt1CPAPI.dll : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.2

Driver Setup Program : 2.23

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.53

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

5. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

2.) Fixed issue -> DTM Test \ Hal timer issue for V5331 Vista driver (Potential risk).

CPL :

1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5324

WDM driver for Winx64 : 5.10.0.5324

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64

Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 1.0.0.0

Vista driver :

Readme.txt

Vista driver for x86 : 6.0.1.5334
RtHDVCpl.exe : 1.0.0.11
RtkAPO.dll : 11.0.5600.13
RtkPgExt.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
Rt1CPAPI.dll : 1.0.1.5
RTSndMgr.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.2
Vista driver for x64 : 6.0.1.5334
RAVCpl64.exe : 1.0.0.11
RtkAPO64.dll : 11.0.5600.13
RtPgEx64.dll : 6.0.5600.12
RTCOMDLL.dll : 1.0.0.63
Rt1CPAPI.dll : 1.0.1.5
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.dll : 1.0.0.2

Driver Setup Program : 2.21

Windows 2000/XP Operate on :
Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.52

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Known issue -> DTM Test \ Hal timer issue for V5331 Vista driver (Potential risk).

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5324
WDM driver for Winx64 : 5.10.0.5324
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5331
RtHDVCpl.exe : 1.0.0.9
RtkAPO.dll : 11.0.5600.13

Readme.txt

RtkPgExt.d11 : 6.0.5600.12
RTCOMDLL.d11 : 1.0.0.63
Rt1CPAPI.d11 : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
RtkCoInst.d11 : 1.0.0.1
Vista driver for x64 : 6.0.1.5331
RAVCp164.exe : 1.0.0.9
RtkAPO64.d11 : 11.0.5600.13
RtPgEx64.d11 : 6.0.5600.12
RTCOMDLL.d11 : 1.0.0.63
Rt1CPAPI.d11 : 1.0.0.7
RTSnMg64.cpl : 1.0.0.1
RtkCoInst.d11 : 1.0.0.1

Driver Setup Program : 2.20

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.51

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC267, ALC268

3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

5. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5324

WDM driver for Winx64 : 5.10.0.5324

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64

Realtek Sound Effect Manager(RTHDCPL) : 2.1.1.1

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 1.0.0.0

Vista driver :

Vista driver for x86 : 6.0.1.5322

RtHDVCpl.exe : 1.0.0.7

RtkAPO.d11 : 11.0.5600.13

RtkPgExt.d11 : 6.0.5600.12

RTCOMDLL.d11 : 1.0.0.63

Rt1CPAPI.d11 : 1.0.0.7

RTSndMgr.cpl : 1.0.0.1

Vista driver for x64 : 6.0.1.5322

Readme.txt

RAVCp164.exe : 1.0.0.7
RtkAPO64.d11 : 11.0.5600.13
RtPgEx64.d11 : 6.0.5600.12
RTCOMDLL.d11 : 1.0.0.63
Rt1CPAPI.d11 : 1.0.0.7
RTSnMg64.cpl : 1.0.0.1
Driver Setup Program : 2.20

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.50

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268
3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64
4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
5. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5319
WDM driver for Winx64 : 5.10.0.5319
Realtek Soundman : 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.1.0.8
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Vista driver :
Vista driver for x86 : 6.0.1.5322
RtHDVCpl.exe : 1.0.0.7
RtkAPO.d11 : 11.0.5600.13
RtkPgExt.d11 : 6.0.5600.12
RTCOMDLL.d11 : 1.0.0.63
Rt1CPAPI.d11 : 1.0.0.7
RTSndMgr.cpl : 1.0.0.1
Vista driver for x64 : 6.0.1.5322
RAVCp164.exe : 1.0.0.7
RtkAPO64.d11 : 11.0.5600.13
RtPgEx64.d11 : 6.0.5600.12
RTCOMDLL.d11 : 1.0.0.63
Rt1CPAPI.d11 : 1.0.0.7
RTSnMg64.cpl : 1.0.0.1
Driver Setup Program : 2.19

Readme.txt

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.49

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

2. Windows 2000/XP logo Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861VC, ALC861VD, ALC660, ALC662, ALC260, ALC262, ALC268

3. OS Supporting: Microsoft Windows XP, Windows 2000, Vista x86/x64

4. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

5. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

Windows 2000/XP :

WDM driver for Win2000/WinXP : 5.10.0.5319

WDM driver for Winx64 : 5.10.0.5319

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.9

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64

Realtek Sound Effect Manager(RTHDCPL) : 2.1.0.8

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 1.0.0.0

Vista driver :

Vista driver for x86 : 6.0.1.5317

RtHDVCpl.exe : 1.0.0.6

RtkAPO.dll : 11.0.5600.12

RtkPgExt.dll : 6.0.5600.12

RTCOMDLL.dll : 1.0.0.63

Rt1CPAPI.dll : 1.0.0.7

RTSndMgr.cpl : 1.0.0.1

Vista driver for x64 : 6.0.1.5317

RAVCpl64.exe : 1.0.0.6

RtkAPO64.dll : 11.0.5600.12

RtPgEx64.dll : 6.0.5600.12

RTCOMDLL.dll : 1.0.0.63

Rt1CPAPI.dll : 1.0.0.7

RTSnMg64.cpl : 1.0.0.1

Driver Setup Program : 2.19

Windows 2000/XP Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.48

Vista driver Version: 5.10.0.5317

1. Vista logo Codec Supporting: ALC882, ALC883, ALC885, ALC888, ALC861VD,

Readme.txt

ALC660, ALC662, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft Windows Vista x86/x64

Vista driver for x86	: 6.10.0.5317
RtHDVCpl.exe	: 1.0.0.6
RtkAPO.dll	: 11.0.5600.12
RtkPgExt.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
Rt1CPAPI.dll	: 1.0.0.7
RTSndMgr.cpl	: 1.0.0.1
Vista driver for x64	: 6.10.0.5317
RAVCpl64.exe	: 1.0.0.6
RtkAPO64.dll	: 11.0.5600.12
RtPgEx64.dll	: 6.0.5600.12
RTCOMDLL.dll	: 1.0.0.63
Rt1CPAPI.dll	: 1.0.0.7
RTSnMg64.cpl	: 1.0.0.1
Driver Setup Program	: 2.19

//=====

Driver Package R1.47

RtkHDAud.sys Version: 5.10.0.5296

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5296
WDM driver for Winx64	: 5.10.0.5296
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.9.8
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.46

RtkHDAud.sys Version: 5.10.0.5294

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

- 4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5294
WDM driver for Winx64	: 5.10.0.5294
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.9.6
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.16

Operate on :

Microsoft High Definition Audio Driver Package –KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.45

RtkHDAud.sys Version: 5.10.0.5288

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

- 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5288
WDM driver for Winx64	: 5.10.0.5288
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.9
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.9.1
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Operate on :

Microsoft High Definition Audio Driver Package –KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Readme.txt

Driver Package R1.44

RtkHDAud.sys Version: 5.10.0.5286

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5286
WDM driver for Winx64	: 5.10.0.5286
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.8.7
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.43

RtkHDAud.sys Version: 5.10.0.5283

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

WDM driver for Win2000/WinXP	: 5.10.0.5283
WDM driver for Winx64	: 5.10.0.5283
Realtek Soundman	: 1.0.0.30
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.8.3
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.15

Readme.txt

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.42

RtkHDAud.sys Version: 5.10.0.5282

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

2.) Fix some game issue .

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5282

WDM driver for Winx64 : 5.10.0.5282

Realtek Soundman : 1.0.0.30

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10

Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8

Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64

Realtek Sound Effect Manager(RTHDCPL) : 2.0.8.0

Alcwzrd.exe : 1.1.0.36

SkyTel.exe : 1.0.0.0

Driver Setup Program : 2.15

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.41

RtkHDAud.sys Version: 5.10.0.5273

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268

2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization.

CPL :

1.) Customization.

WDM driver for Win2000/WinXP : 5.10.0.5273

WDM driver for Winx64 : 5.10.0.5273

Realtek Soundman : 1.0.0.29

Readme.txt

Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.7.3
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.14

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.40

RtkHDAud.sys Version: 5.10.0.5268

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC660, ALC260, ALC262, ALC268
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Correct present driver version in "Add or Remove Programs \ Support Information" .
- 2.) Windows 2000 installation reboot twice problem .

WDM driver for Win2000/WinXP : 5.10.0.5268
WDM driver for Winx64 : 5.10.0.5268
Realtek Soundman : 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.7.0
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.14

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.39

RtkHDAud.sys Version: 5.10.0.5265

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC861VD, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix

Readme.txt

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

2.) Add support for left panel and right panel config.

InstallShield package :

1.) Copy file rule in Vista system .

2.) Show driver version in "Add or Remove Programs \ Support Information" .

WDM driver for Win2000/WinXP	: 5.10.0.5265
WDM driver for Winx64	: 5.10.0.5265
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.6.9
Alcwzrd.exe	: 1.1.0.36
SkyTel.exe	: 1.0.0.0
Driver Setup Program	: 2.13

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.38

RtkHDAud.sys Version: 5.10.0.5257

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262

2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64

3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

4. Add/Fix

1.) Customization.

For New architecture:

1.) Customization .

CPL :

1.) Customization.

InstallShield package :

1.) Add "XP2K" and "Vista" folder name for installation .

2.) Abort flag setting .

WDM driver for Win2000/WinXP	: 5.10.0.5257
WDM driver for Winx64	: 5.10.0.5257
Realtek Soundman	: 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.6.6

Readme.txt

Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.11

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.37

RtkHDAud.sys Version: 5.10.0.5253

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Upgrade to IS11.5 .

WDM driver for Win2000/WinXP : 5.10.0.5253
WDM driver for Winx64 : 5.10.0.5253
Realtek Soundman : 1.0.0.29
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.64
Realtek Sound Effect Manager(RTHDCPL) : 2.0.6.4
Alcwzrd.exe : 1.1.0.36
SkyTel.exe : 1.0.0.0
Driver Setup Program : 2.09

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.36

RtkHDAud.sys Version: 5.10.0.5247

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC888, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Add ALC888 .

Readme.txt

CPL :
1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP	: 5.10.0.5247
WDM driver for Winx64	: 5.10.0.5247
Realtek Soundman	: 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.62
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.5.9
Alcwzrd.exe	: 1.1.0.35
Driver Setup Program	: 2.06

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.35

RtkHDAud.sys Version: 5.10.0.5242

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :
1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP	: 5.10.0.5242
WDM driver for Winx64	: 5.10.0.5242
Realtek Soundman	: 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.62
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.5.4
Alcwzrd.exe	: 1.1.0.35
Driver Setup Program	: 2.06

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.34

RtkHDAud.sys Version: 5.10.0.5233

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)

Readme.txt

4. Add/Fix

- 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Fixed Adobe Premiere Pro 1.5 Crash issue .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Rtlupd termination return error code .
- 2.) Receive error code rule from Rtlupd SetupAPI .
- 3.) SetupCopyOEM install rule .

WDM driver for Win2000/WinXP	: 5.10.0.5233
WDM driver for Winx64	: 5.10.0.5233
Realtek Soundman	: 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.62
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.4.9
Alcwzrd.exe	: 1.1.0.35
Driver Setup Program	: 2.06

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.33

RtkHDAud.sys Version: 5.10.0.5229

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Bus driver detect issue .

WDM driver for Win2000/WinXP	: 5.10.0.5229
WDM driver for Winx64	: 5.10.0.5229
Realtek Soundman	: 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.61
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.4.7
Alcwzrd.exe	: 1.1.0.34
Driver Setup Program	: 2.05

Readme.txt

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.32

RtkHDAud.sys Version: 5.10.0.5224

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .

CPL :

- 1.) Customization.

InstallShield package :

- 1.) Report installation progress and result to "C:\RTHSetup.log" within silent mode .
- 2.) Rtlupd setup API will not appear message dialog in silent mode .

WDM driver for Win2000/WinXP	: 5.10.0.5224
WDM driver for Winx64	: 5.10.0.5224
Realtek Soundman	: 1.0.0.28
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.8
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.61
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.4.4
Alcwzrd.exe	: 1.1.0.34
Driver Setup Program	: 2.04

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.31

RtkHDAud.sys Version: 5.10.0.5221

1. Codec Supporting: ALC880, ALC882, ALC883, ALC885, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Add ALC885 HD Audio Codec for WHQL .

CPL :

- 1.) Customization.

InstallShield package :

Readme.txt

WDM driver for Win2000/WinXP : 5.10.0.5221
WDM driver for Winx64 : 5.10.0.5221
Realtek Soundman : 1.0.0.27
Realtek Sound Effect Manager (ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager (Rt1Cpl) : 1.0.1.60
Realtek Sound Effect Manager (RTHDCPL) : 2.0.4.2
Alcwzrd.exe : 1.1.0.33
Driver Setup Program : 2.03

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.30

RtkHDAud.sys Version: 5.10.0.5211

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization .
- 2.) Bug fixed when recording AEC device failed on 880 .

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP : 5.10.0.5211
WDM driver for Winx64 : 5.10.0.5211
Realtek Soundman : 1.0.0.24
Realtek Sound Effect Manager (ALSndMgr.cpl) : 1.0.0.10
Realtek Sound Effect Manager (RTSndMgr.cpl) : 1.0.0.8
Realtek Sound Effect Manager (Rt1Cpl) : 1.0.1.58
Realtek Sound Effect Manager (RTHDCPL) : 2.0.3.9
Alcwzrd.exe : 1.1.0.31
Driver Setup Program : 2.03

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.29

RtkHDAud.sys Version: 5.10.0.5202

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

Readme.txt

For New architecture:

- 1.) Customization.

CPL :

- 1.) Customization.

InstallShield package :

WDM driver for Win2000/WinXP	: 5.10.0.5202
WDM driver for Winx64	: 5.10.0.5202
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.54
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.3.4
Alcwzrd.exe	: 1.1.0.29
Driver Setup Program	: 2.02c

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.28

RtkHDAud.sys Version: 5.10.0.5200

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Add ALC265 .

CPL :

- 1.) Side speaker testing has no sound when 3D engine is disabled.

InstallShield package :

- 1.) Add Chipset ID VEN_1002&DEV_4383 .

WDM driver for Win2000/WinXP	: 5.10.0.5200
WDM driver for Winx64	: 5.10.0.5200
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.53
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.3.2
Alcwzrd.exe	: 1.1.0.28
Driver Setup Program	: 2.02c

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Readme.txt

Driver Package R1.27

RtkHDAud.sys Version: 5.10.0.5188

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Add installation file "RTHDAEQ*.dat" .
2. Add Package version in setup.ini .
3. Manual installation setting for InstallShield .

WDM driver for Win2000/WinXP	: 5.10.0.5188
WDM driver for Winx64	: 5.10.0.5188
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.53
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.2.6
Alcwzrd.exe	: 1.1.0.28
Driver Setup Program	: 2.02a

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.26

RtkHDAud.sys Version: 5.10.0.5178

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Set rebooting twice for installation UAA QFE on Win2000 .

WDM driver for Win2000/WinXP	: 5.10.0.5178
WDM driver for Winx64	: 5.10.0.5178
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.6
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.52
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.2.1
Alcwzrd.exe	: 1.1.0.28
Driver Setup Program	: 2.00

Readme.txt

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.25

RtkHDAud.sys Version: 5.10.0.5172

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

Fix :

1. Rtlupd.exe(2.5.0.5) fixed roll-back problem (It can not delete oem.inf file before update driver).
2. Change Azalia name in setup.ini file .
3. Don't popup Rtlupd dialog when you select "No" on Hotfix installation dialog .

Add :

1. System language identifier .
2. Change pop-up dialog Product name (Azalia→High Definition) .

WDM driver for Win2000/WinXP	: 5.10.0.5172
WDM driver for Winx64	: 5.10.0.5172
Realtek Soundman	: 1.0.0.21
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.10
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.6
Realtek Sound Effect Manager(Rt1Cpl)	: 1.0.1.51
Realtek Sound Effect Manager(RTHDCPL)	: 2.0.1.7
Alcwzrd.exe	: 1.1.0.27
Driver Setup Program	: 1.99

Operate on :

Microsoft High Definition Audio Driver Package – KB888111

Package file version (kb888111.exe) : 6.1.22.0

Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.24

RtkHDAud.sys Version: 5.10.0.5152

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support 192KHz sample rate output.

InstallShield package :

Readme.txt

Fix :

1. Reboot timing after installation MS QFE (UAA driver) .
2. Uninstallation dialog description .

Add :

1. MS hotfix KB901105 can be included by HD package (If get MS licence) .
2. Hotfix KB901105 Warning message .

WDM driver for Win2000/WinXP : 5.10.0.5152
WDM driver for Winx64 : 5.10.0.5152
Realtek Soundman : 1.0.0.18
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.4
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.46
Realtek Sound Effect Manager(RTHDCPL) : 2.0.0.8
Alcwzrd.exe : 1.1.0.24
Driver Setup Program : 1.96

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.23

RtkHDAud.sys Version: 5.10.0.5136

1. Codec Supporting: ALC880, ALC882, ALC883, ALC861, ALC260, ALC262
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support new codec ALC262, ALC883

InstallShield package :

- 1.) Check OS service pack number with InstallShield .
- 2.) Change audio wizard quitting procedure .

WDM driver for Win2000/WinXP : 5.10.0.5136
WDM driver for Winx64 : 5.10.0.5136
Realtek Soundman : 1.0.0.17
Realtek Sound Effect Manager(ALSndMgr.cpl) : 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl) : 1.0.0.4
Realtek Sound Effect Manager(Rt1Cpl) : 1.0.1.43
Realtek Sound Effect Manager(RTHDCPL) : 1.1.2.3
Alcwzrd.exe : 1.1.0.23
Driver Setup Program : 1.92

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.22

RtkHDAud.sys Version: 5.10.0.5128

Readme.txt

1. Codec Supporting: ALC880, ALC882, ALC861, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.

InstallShield package :

- 1.) Setup progress backward .
- 2.) Driver size on Add and remove programs .
- 3.) Refresh driver size on Add and Remove Programs .
- 4.) Check RtlExupd.dll version .
- 5.) Check RtlHDCpl.exe version .

WDM driver for Win2000/WinXP	: 5.10.0.5128
WDM driver for Winx64	: 5.10.0.5128
Realtek Soundman	: 1.0.0.17
Realtek Sound Effect Manager(ALSndMgr.cpl)	: 1.0.0.7
Realtek Sound Effect Manager(RTSndMgr.cpl)	: 1.0.0.4
Realtek Sound Effect Manager(RtlCpl)	: 1.0.1.40
Realtek Sound Effect Manager(RTHDCPL)	: 1.1.1.9
Alcwzrd.exe	: 1.1.0.20
Driver Setup Program	: 1.91

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.21

RtkHDAud.sys Version: 5.10.0.5127

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Support DTS Encoder and DTS Neo for special version codec .

SoundMan.exe Version: 1.0.0.17

ALSndMgr.cpl Version: 1.0.0.7

Rtlcpl.exe Version: 1.0.1.40

Alcwzrd.exe Version: 1.1.0.20

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.20

RtkHDAud.sys Version: 5.10.0.5125

1. Codec Supporting: ALC880, ALC882, ALC260

Readme.txt

2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 - 1.) Customization.

For New architecture:

- 1.) Customization.
- 2.) Fixed the issue of SPDIF-In capture

SoundMan.exe Version: 1.0.0.17
ALSndMgr.cpl Version: 1.0.0.7
Rtlcpl.exe Version: 1.0.1.40
Alcwzrd.exe Version: 1.1.0.20

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.19

RtkHDAud.sys Version: 5.10.0.5123

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000, Winx64
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 1. Customization.
 2. Avoid Pop noise when toggle output sampling rate for ALC260.
 3. Restore the original timer resolution first before check the original system timer resolution.

For New architecture:

- 1.) Customization.
- 2.) Driver store mixer setting after windows reboot

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.39
Alcwzrd.exe Version: 1.1.0.19

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.18

RtkHDAud.sys Version: 5.10.0.5122

1. Codec Supporting: ALC880, ALC882, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 1. Customization.
 2. Add 2 default values of codec subsystem ID for ALC260.

For New architecture:

- 1.) Customization.
- 2.) Fixed the issue of uncontinuous sound after suspend on some

Readme.txt

machine.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.38
Alcwzrd.exe Version: 1.1.0.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.17

RtkHDAud.sys Version: 5.10.0.5120

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 1. Customization.
 2. Restore certain register value when resume from system suspend.

For New architecture:

- 1.) Customization.
- 2.) Improve reliability for switching multiple streaming.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.38
Alcwzrd.exe Version: 1.1.0.18

Operate on :

Microsoft High Definition Audio Driver Package - KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.16

RtkHDAud.sys Version: 5.10.0.5119

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1.0a(5013)
4. Add/Fix
 1. Customization.
 2. Fix initial noise issue for the certain models.
 3. Check codec SubsystemID verb to decide the driver path when driver initialize.
 4. Don't modify Configuration byte Verbs when driver initialize.
 5. Fix Buffer size un-alignment issue.

For New architecture:

- 1.) Customization.
- 2.) Fix the problem when play AC-3 stream by SPDIF interface
- 3.) Change device name for multiple streaming issue.

SoundMan.exe Version: 1.0.0.14
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.38

Readme.txt

Alcwzrd.exe Version: 1.1.0.17

Operate on :

Microsoft High Definition Audio Driver Package – KB888111
Package file version (kb888111.exe) : 6.1.22.0
Hdaudio.sys version : 5.10.00.5013

//=====

Driver Package R1.15

RtkHDAud.sys Version: 5.10.0.5116

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1.) Customization.
 - 2.) Auto lock SPDIF-in signal when SPDIF-in signal is unlocked.
 - 3.) Fix SPDIF out copy protection issue.
 - 4.) Add patch code for ALC260 potential risk.

For New architecture:

- 1.) Customization.
- 2.) Fix new feature problem on multiple streaming.
- 3.) Fix capture problem on ALC882.

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.38

Alcwzrd.exe Version: 1.1.0.17

Operate on :

Microsoft High Definition Audio Driver Package – KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.14

RtkHDAud.sys Version: 5.10.0.5109

1. Codec Supporting: ALC880, ALC882, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1.) Customization.
 - 2.) Reduce delay time when volume is adjusted.
 - 3.) Fix hang up issue when system resume from S3.

For New architecture:

- 1.) New architecture of HD audio driver formal release.

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.4

Rtlcpl.exe Version: 1.0.1.37

Alcwzrd.exe Version: 1.1.0.16

Operate on :

Microsoft High Definition Audio Driver Package – KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Readme.txt

Driver Package R1.13

RtkHDAud.sys Version: 5.10.0.5038

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1) Reduce initialize noise

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.36

Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package – KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.12

RtkHDAud.sys Version: 5.10.0.5037

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1) Improve recording performance.
 - 2) Reduce initialize noise

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.36

Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package – KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.11

RtkHDAud.sys Version: 5.10.0.5036

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix

SoundMan.exe Version: 1.0.0.14

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.35

Alcwzrd.exe Version: 1.1.0.15

Operate on :

Microsoft High Definition Audio Driver Package – KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.10

RtkHDAud.sys Version: 5.10.0.5034

Readme.txt

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio UAAV1(5011)
4. Add/Fix
 - 1) Fix the problem that there is little noise when start stream playing
 - 2) Fix the problem that in WinDVD, the SPDIF option still exist even there is no SPDIF

SoundMan.exe Version: 1.0.0.14

- 1.Set the default recording device as "Realtek HD Audio rear input" device

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.34

Alcwzrd.exe Version: 1.1.0.15

- 1.Keep previous Jack setting.
- 2.Check whether have any jack plugin when restart OS,and popup the device window if wizard detect any new device plugin.

Operate on :

- Microsoft High Definition Audio Driver Package – KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5011

//=====

Driver Package R1.09

RtkHDAud.sys Version: 5.10.0.5033

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0

SoundMan.exe Version: 1.0.0.14

- 1.Set the default recording device as "Realtek HD Audio rear input" device

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.33

Alcwzrd.exe Version: 1.1.0.14

Operate on :

- Microsoft High Definition Audio Driver Package – KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.08

RtkHDAud.sys Version: 5.10.0.5032

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.33

Alcwzrd.exe Version: 1.1.0.14

Operate on :

Readme.txt

Microsoft High Definition Audio Driver Package – KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.07

RtkHDAud.sys Version: 5.10.0.5031

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
 - 1) Fix the problem when playback with sound recorder, when change frequency from 48k to 44.1k in SPDIF page, playback will stop
 - 2) Support for ALC880G, ALC880D, ALC260D
 - 3) Fix the problem that system will hang up while perform audio test in 3DMark 2003

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.5

Rtlcpl.exe Version: 1.0.1.32

1.Fix word collision problem in Multi-Language.

Alcwzrd.exe Version: 1.1.0.13

1.Restore previous jack setting when reboot system.

Operate on :

Microsoft High Definition Audio Driver Package – KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.06

RtkHDAud.sys Version: 5.10.0.5030

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.12

ALSndMgr.cpl Version: 1.0.0.3

Rtlcpl.exe Version: 1.0.1.31

Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package – KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.05

RtkHDAud.sys Version: 5.10.0.5029

1. Codec Supporting: ALC880, ALC260, ALC861
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
 - 1) Add support for ALC861
 - 2) Fix the noise problem that when recording from SPDIF In at 96khz

Readme.txt

SoundMan.exe Version: 1.0.0.12
ALSndMgr.cpl Version: 1.0.0.5
Rtlcpl.exe Version: 1.0.1.31
Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package – KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.04

RtkHDAud.sys Version: 5.10.0.5028

1. Codec Supporting: ALC880, ALC260
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix
 - 1) For UAJ A to A volume line, change type from KSNODETYPE_MICROPHONE to KSNODETYPE_ANALOG_CONNECTOR
 - 2) Fix the problem that SPDIF out no sound in WinDVD
 - 3) Fix the problem that there is balance control in Center and Subwoofer volume line in W2k
 - 4) Change the component type of SPDIF-In from "KSNODETYPE_ANALOG_CONNECTOR" to "KSNODETYPE_SPDIF_INTERFACE"
 - 5) Fix the problem that mute SPDIF out in mixer doesn't work

SoundMan.exe Version: 1.0.0.12
ALSndMgr.cpl Version: 1.0.0.3

Rtlcpl.exe Version: 1.0.1.31
1.Turn off all sound effect when speaker test!

Alcwzrd.exe Version: 1.1.0.12

Operate on :

Microsoft High Definition Audio Driver Package – KB835221
Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.03

RtkHDAud.sys Version: 5.10.0.5027

SoundMan.exe Version: 1.0.0.4
ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.29

- 1.Sync the status which Enable/Disable wizard with alcwzrd
- 2.Make the tab of "Audio Wizard" independent from menu tabs.
- 3.Stop the play sound when menu tab is change.

Alcwzrd.exe Version: 1.1.0.12

- 1.Fixed broken wizard image.
- 2.Sync the status which Enable/Disable wizard with rtlcpl.

Operate on :

Microsoft High Definition Audio Driver Package – KB835221

Readme.txt

Package file version (kb835221.exe) : 6.1.1.0
Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.01/R1.02

RtkHDAud.sys Version: 5.10.0.5022

1. Codec Supporting:
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.23

Alcwzrd.exe Version: 1.1.0.5

Operate on :

Microsoft High Definition Audio Driver Package – KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010

//=====

Driver Package R1.0

RtkHDAud.sys Version: 5.10.0.5017

1. Codec Supporting: Add ALC880/ALC880M Rev.F Rev.G, ALC860
2. OS Supporting: Microsoft Windows XP, Windows 2000
3. Pack with Microsoft High Definition Audio OOB Binaries V1.0
4. Add/Fix

SoundMan.exe Version: 1.0.0.4

ALSndMgr.cpl Version: 1.0.0.2

Rtlcpl.exe Version: 1.0.1.23

Alcwzrd.exe Version: 1.1.0.5

Operate on :

Microsoft High Definition Audio Driver Package – KB835221

Package file version (kb835221.exe) : 6.1.1.0

Hdaudio.sys version : 5.10.00.5010